

BUILDING INSPECTION REPORT AND ASBESTOS MANAGEMENT PLAN

BUILDING NAME: Building 39
HOMOGENEOUS AREA #: 18
MATERIAL DESCRIPTION: Roofing tar
ACM OR ACE PRESENT: No

DATE SURVEYED: 8/24/90 DRAWING REF. #: N/A

TYPE OF MATERIAL: Miscellaneous

APPROXIMATE QTY. OF ACM OR ACE: No asbestos detected

OBSTACLES: N/A

SURFACE TYPE UNDER ASBESTOS: N/A

ENCAPSULANT USED: N/A

AVERAGE THICKNESS: N/A

MATERIAL LOCATION(S): Roof

SAMPLE #	SAMPLE LOCATION	ANALYSIS RESULTS
39-R-18-01	Roof	No asbestos detected
39-R-18-02	Roof	No asbestos detected
39-R-18-03	Roof	No asbestos detected

CONDITION OF ACM OR ACE:

Percent N/A damage: N/A
Type of damage: N/A
Overall rating: N/A

POTENTIAL FOR DISTURBANCE OF ACM OR ACE:	HIGH	1	2	3	4	5	LOW
Potential for contact:	—	—	—	—	—	—	—
Influence of vibration:	—	—	—	—	—	—	—
Potential for air erosion:	—	—	—	—	—	—	—

IS MATERIAL ACCESSIBLE?: Yes

IS MATERIAL LOCATED IN AN AIR PLENUM?: No

MANAGEMENT PLANNER'S HAZARD ASSESSMENT:

8. No asbestos detected in suspect material.

MANAGEMENT PLANNER'S RECOMMENDED RESPONSE ACTION:

6. No asbestos detected. No action required.

INSPECTOR'S COMMENTS: None

BUILDING INSPECTION REPORT AND ASBESTOS MANAGEMENT PLAN

BUILDING NAME: Building 39
HOMOGENEOUS AREA #: 21
MATERIAL DESCRIPTION: Downspout tar
ACM OR ACE PRESENT: Yes

DATE SURVEYED: 8/24/90 DRAWING REF. #: N/A

TYPE OF MATERIAL: Miscellaneous

APPROXIMATE QTY. OF ACM OR ACE: 6 EA

OBSTACLES: None

SURFACE TYPE UNDER ASBESTOS: Metal downspout

ENCAPSULANT USED: None

AVERAGE THICKNESS: 1/8"

MATERIAL LOCATION(S): Downspout joints

SAMPLE #	SAMPLE LOCATION	ANALYSIS RESULTS
12-0-5-01	Building 12	40% chrysotile
18-0-17-01	Building 18	35% chrysotile
40-0-22-01	Building 40	No asbestos detected
46-0-14-01	Building 46	35% chrysotile

CONDITION OF ACM OR ACE:

Percent Distributed damage: 5%
Type of damage: Deterioration
Overall rating: Good

POTENTIAL FOR DISTURBANCE OF ACM OR ACE:	HIGH	1	2	3	4	5	LOW
Potential for contact:	—	X	—	—	—	—	—
Influence of vibration:	—	—	X	—	—	—	—
Potential for air erosion:	—	—	X	—	—	—	—

IS MATERIAL ACCESSIBLE?: Yes

IS MATERIAL LOCATED IN AN AIR PLENUM?: No

MANAGEMENT PLANNER'S HAZARD ASSESSMENT:

7. Any remaining friable ACM or friable suspected ACM or ACE

MANAGEMENT PLANNER'S RECOMMENDED RESPONSE ACTION:

2. Repair and O&M Program

INSPECTOR'S COMMENTS: None