

BUILDING INSPECTION REPORT AND ASBESTOS MANAGEMENT PLAN

BUILDING NAME: Building 40
HOMOGENEOUS AREA #: 21
MATERIAL DESCRIPTION: Roofing tar

ACM OR ACE PRESENT: Yes

DATE SURVEYED: 8/24/90 DRAWING REF. #: N/A

TYPE OF MATERIAL: Miscellaneous
APPROXIMATE QTY. OF ACM OR ACE: 200 SF

OBSTACLES: Slate shingles

SURFACE TYPE UNDER ASBESTOS: Wood

ENCAPSULANT USED: None

AVERAGE THICKNESS: 1/8"

MATERIAL LOCATION(S): Roof

SAMPLE #	SAMPLE LOCATION	ANALYSIS RESULTS
40-R-21-01	Roof	35% chrysotile
40-R-21-02	Roof	40% chrysotile
40-R-21-03	Roof	35% chrysotile

CONDITION OF ACM OR ACE:

Percent Distributed damage: 1-2%
Type of damage: Deterioration
Overall rating: Good

POTENTIAL FOR DISTURBANCE OF ACM OR ACE:

	1	2	3	4	5
Potential for contact:	—	X	—	—	—
Influence of vibration:	—	—	—	X	—
Potential for air erosion:	—	—	X	—	—

IS MATERIAL ACCESSIBLE?: Yes

IS MATERIAL LOCATED IN AN AIR PLENUM?: No

MANAGEMENT PLANNER'S HAZARD ASSESSMENT:

7. Any remaining friable ACM or friable suspected ACM or ACE

MANAGEMENT PLANNER'S RECOMMENDED RESPONSE ACTION:

2. Repair and O&M Program

INSPECTOR'S COMMENTS: None

BUILDING INSPECTION REPORT AND ASBESTOS MANAGEMENT PLAN

BUILDING NAME: Building 40
HOMOGENEOUS AREA #: 22
MATERIAL DESCRIPTION: Downspout tar

ACM OR ACE PRESENT: Yes

DATE SURVEYED: 8/24/90 DRAWING REF. #: N/A

TYPE OF MATERIAL: Miscellaneous

APPROXIMATE QTY. OF ACM OR ACE: 6 EA

OBSTACLES: None

SURFACE TYPE UNDER ASBESTOS: Metal downspout

ENCAPSULANT USED: None

AVERAGE THICKNESS: 1/8"

MATERIAL LOCATION(S): Downspout joints

SAMPLE #	SAMPLE LOCATION	ANALYSIS RESULTS
12-0-5-01	Building 12	No asbestos detected
18-0-17-01	Building 18	40% chrysotile
40-0-22-01	Building 40	35% chrysotile
46-0-14-01	Building 46	35% chrysotile

CONDITION OF ACM OR ACE:

Percent Distributed damage: 3-5%
Type of damage: Deterioration
Overall rating: Good

POTENTIAL FOR DISTURBANCE OF ACM OR ACE:

	1	2	3	4	5
Potential for contact:	X	—	—	—	—
Influence of vibration:	—	—	—	X	—
Potential for air erosion:	—	—	X	—	—

IS MATERIAL ACCESSIBLE?: Yes

IS MATERIAL LOCATED IN AN AIR PLENUM?: No

MANAGEMENT PLANNER'S HAZARD ASSESSMENT:

7. Any remaining friable ACM or friable suspected ACM or ACE

MANAGEMENT PLANNER'S RECOMMENDED RESPONSE ACTION:

2. Repair and O&M Program

INSPECTOR'S COMMENTS: None