

OLIN E. TEAGUE V. A. MEDICAL CENTER
2009 THREE-YEAR ASBESTOS REINSPECTION
SUMMARY OF BULK SAMPLES TAKEN TO DATE

Red = Asbestos-Containing Material (ACM) Blue = Non ACM Green = Non Asbestos-Containing Material
(determined by Point Count Analysis)

Building	Floor	Room	Sample ID	Material Description
162	1	F124	OT-09-293-0330	Layer 2 - black mastic
162	1	F124	OT-09-293-0331	Layer 1 - white linoleum
162	1	F124	OT-09-293-0331	Layer 2 - black mastic
162	1	Hall	OT-09-293-0332	White 2x4 ceiling tile
162	1	Hall	OT-09-293-0333	White caulking, white wrap, foil backing, yellow fiberglass insulation
162	1	Hall	OT-09-293-0334	Layer 1 - 6" elbow - white block insulation
162	1	Hall	OT-09-293-0334	Layer 2 - 6" elbow - white wrap
162	1	Hall	OT-09-293-0335	6" vertical pipe - white wrap, yellow fiberglass insulation
162	1	F126C	OT-09-293-0390	Layer 1 - 1" elbow - white wrap
162	1	F126C	OT-09-293-0390	Layer 2 - 1" elbow - white block insulation
162	1	F126C	OT-09-293-0391	1" horizontal pipe - white wrap, yellow fiberglass insulation
162	1	F126C	OT-09-293-0392	Yellow carpet adhesive, black mastic
162	1	South Hall	OT-09-293-0393	Layer 1 - brown 12x12 floor tile
162	1	South Hall	OT-09-293-0393	Layer 2 - black mastic
162	1	F141	OT-09-293-0394	Tan 12x12 floor tile, yellow mastic
162	1	F140	OT-09-293-0395	Layer 1 - tan 12x12 floor tile
162	1	F140	OT-09-293-0395	Layer 2 - yellow mastic, black mastic
162	1	F140	OT-09-293-0396	Brown fire door paper insulation
162	1	F140	OT-09-293-0397	White sheetrock tape, mud
162	1	E138K	OT-09-293-0398	Light brown 12x12 floor tile, yellow mastic
162	1	E138J	OT-09-293-0399	White 2x2 ceiling tile
162	1	E138J	OT-09-293-0400	Layer 1 - 8" elbow - white wrap
162	1	E138J	OT-09-293-0400	Layer 2 - 8" elbow - white wrap
162	1	E138J	OT-09-293-0401	8" horizontal pipe - white wrap, yellow fiberglass insulation
162	1	B-Hall	OT-09-293-0402	White 2x4 ceiling tile
162	1	B-Hall	OT-09-293-0403	White plaster wall material
162	1	B-Hall	OT-09-293-0404	Layer 1 - brown 12x12 floor tile
162	1	B-Hall	OT-09-293-0404	Layer 2 - black mastic
162	1	B-Hall	OT-09-293-0405	2" horizontal pipe - white wrap, foil backing, tan block insulation
162	1	B-Hall	OT-09-293-0406	Black mastic piping tape
162	1	B158	OT-09-293-0407	Tan cove molding, yellow mastic
162	1	B156	OT-09-293-0408	8" horizontal pipe - white tape, foil backing, black rock insulation
162	1	B156	OT-09-293-0409	Layer 1 - yellow carpet mastic
162	1	B156	OT-09-293-0409	Layer 2 - brown 12x12 floor tile
162	1	B156	OT-09-293-0409	Layer 3 - black mastic
162	1	B154	OT-09-293-0410	Brown cove molding, yellow mastic
162	1	B167	OT-09-293-0411	Layer 1 - white 12x12 floor tile
162	1	B167	OT-09-293-0411	Layer 2 - yellow mastic
162	1	B150	OT-09-293-0412	Black sink undercoating

OLIN E. TEAGUE V. A. MEDICAL CENTER
2009 THREE-YEAR ASBESTOS REINSPECTION
SUMMARY OF BULK SAMPLES TAKEN TO DATE

Red = Asbestos-Containing Material (ACM) Blue = Non ACM Green = Non Asbestos-Containing Material
(determined by Point Count Analysis)

Building	Floor	Room	Sample ID	Material Description
162	1	B140A	OT-09-293-0413	Layer 1 - 1" elbow - white wrap
162	1	B140A	OT-09-293-0413	Layer 2 - 1" elbow - white block insulation
162	1	B140A	OT-09-293-0414	1" horizontal pipe - white wrap, yellow fiberglass insulation
162	1	B140A	OT-09-293-0415	Layer 1 - 10" elbow - white wrap
162	1	B140A	OT-09-293-0415	Layer 2 - 10" elbow - white block insulation
162	1	B140A	OT-09-293-0416	10" horizontal pipe - white wrap, yellow fiberglass insulation
162	1	B140A	OT-09-293-0417	Black sink undercoating
162	1	B140A	OT-09-293-0418	Layer 1 - brown 9x9 floor tile
162	1	B140A	OT-09-293-0418	Layer 2 - black mastic
162	1	B140A	OT-09-293-0419	Layer 1 - brown 12x12 floor tile
162	1	B140A	OT-09-293-0419	Layer 2 - black mastic
162	1	B149	OT-09-293-0420	Sheetrock tape, mud
162	1	B124	OT-09-293-0421	12" horizontal pipe - white tape, foil backing, pink foam insulation
162	1	B124	OT-09-293-0422	Layer 1 - white 12x12 floor tile
162	1	B124	OT-09-293-0422	Layer 2 - yellow mastic
162	1	B132	OT-09-293-0423	White wall plaster material
162	1	B132	OT-09-293-0424	Plaster overspray
162	1	B130	OT-09-293-0425	Blue 12x12 floor tile, yellow mastic
162	1	B130	OT-09-293-0426	Brown cove molding, yellow mastic
162	1	B153	OT-09-293-0427	10" elbow - white wrap, yellow fiberglass insulation
162	1	B153	OT-09-293-0428	10" horizontal pipe - white wrap, foil backing, yellow fiberglass insulation
162	1	B129	OT-09-293-0429	Blue 12x12 floor tile, yellow mastic
162	1	B129	OT-09-293-0430	Layer 1 - 2" elbow - white wrap
162	1	B129	OT-09-293-0430	Layer 2 - 2" elbow - white block insulation
162	1	B129	OT-09-293-0431	2" horizontal pipe - white wrap, white block insulation
162	1	B128A	OT-09-293-0432	Black sink undercoating
162	1	B128A	OT-09-293-0433	Layer 1 - brown 9x9 floor tile
162	1	B128A	OT-09-293-0433	Layer 2 - black mastic
162	1	B-Hall	OT-09-293-0434	White 2x4 ceiling tile
162	1	B-Hall	OT-09-293-0435	Sheetrock tape, mud
162	1	B122	OT-09-293-0436	Layer 1 - white 12x12 floor tile
162	1	B122	OT-09-293-0436	Layer 2 - yellow mastic
162	1	E139	OT-09-293-0437	14" coupling horizontal pipe - white wrap, foil backing, foam insulation
162	1	A133A	OT-09-293-0438	Brown fire door panel
162	1	A133A	OT-09-293-0439	White 2x4 ceiling tile
162	1	F144	OT-09-293-0440	White spray-on insulation
162	1	F144	OT-09-293-0441	Gray 12x12 floor tile, black mastic
162	1	E141	OT-09-293-0442	Layer 1 - white 12x12 floor tile
162	1	E141	OT-09-293-0442	Layer 2 - black mastic
162	1	E100	OT-09-293-0443	Gray insulation, cloth backing panels

OLIN E. TEAGUE V. A. MEDICAL CENTER
2009 THREE-YEAR ASBESTOS REINSPECTION
SUMMARY OF BULK SAMPLES TAKEN TO DATE

Red = Asbestos-Containing Material (ACM) Blue = Non ACM Green = Non Asbestos-Containing Material
(determined by Point Count Analysis)

Building	Floor	Room	Sample ID	Material Description
162	1	E100	OT-09-293-0444	White tape, foil backing, yellow fiberglass duct insulation
162	1	E100	OT-09-293-0445	12" elbow - white wrap, pink foam insulation
162	1	E100	OT-09-293-0446	12" horizontal pipe - white wrap, foil backing, pink foam insulation
162	1	E100	OT-09-293-0447	48" tank - white wrap, foil backing, brown paper foil backing, white fiberglass insulation
162	1	E100	OT-09-293-0448	1" horizontal pipe - white wrap, yellow fiberglass insulation
162	1	E137A	OT-09-293-0449	Layer 1 - brown 9x9 floor tile
162	1	E137A	OT-09-293-0449	Layer 2 - black mastic
162	1	E99	OT-09-293-0450	Layer 1 - brown 9x9 floor tile
162	1	E99	OT-09-293-0450	Layer 2 - black mastic
162	1	E128	OT-09-293-0451	8" elbow - white block insulation
162	1	E127	OT-09-293-0452	White 2x4 ceiling tile
162	1	E127	OT-09-293-0453	Tan cove molding, yellow mastic
162	1	E104	OT-09-293-0454	2" horizontal pipe - white wrap, yellow fiberglass insulation
162	1	E103	OT-09-293-0455	Layer 1 - 2" T - white wrap
162	1	E103	OT-09-293-0455	2" T - foil backing
162	1	E103	OT-09-293-0455	2" T - yellow fiberglass insulation
162	1	E103	OT-09-293-0456	2" vertical pipe - white wrap, foil backing, yellow fiberglass insulation
162	1	Clo.	OT-09-293-0457	Layer 1 - brown 12x12 floor tile
162	1	Clo.	OT-09-293-0457	Layer 2 - black mastic
162	1	E105	OT-09-293-0458	Black mastic on piping
162	1	E108	OT-09-293-0459	Sheetrock tape, mud
162	1	E120	OT-09-293-0460	2" horizontal pipe, white wrap, yellow fiberglass insulation
162	1	E120	OT-09-293-0461	6" vertical pipe - white wrap, yellow fiberglass insulation
162	1	E120	OT-09-293-0462	White tape, foil backing, yellow fiberglass duct insulation
162	1	C130	OT-09-293-0463	Blue 12x12 floor tile, yellow mastic
162	1	C129	OT-09-293-0464	1" elbow - white wrap, white block insulation
162	1	C129	OT-09-293-0465	1" horizontal pipe - white wrap, yellow fiberglass insulation
162	1	C129	OT-09-293-0466	4" horizontal pipe - white wrap, yellow fiberglass insulation
162	1	C129	OT-09-293-0467	2" horizontal pipe - white wrap, white block insulation
162	1	C128	OT-09-293-0468	Layer 1 - yellow carpet mastic
162	1	C128	OT-09-293-0468	Layer 2 - brown 12x12 floor tile
162	1	C128	OT-09-293-0468	Layer 3 - black mastic
162	1	C100	OT-09-293-0469	Wall plaster material
162	1	C117	OT-09-293-0470	8" elbow - white wrap, yellow foam insulation

OLIN E. TEAGUE V. A. MEDICAL CENTER
2009 THREE-YEAR ASBESTOS REINSPECTION
SUMMARY OF BULK SAMPLES TAKEN TO DATE

Red = Asbestos-Containing Material (ACM) Blue = Non ACM Green = Non Asbestos-Containing Material
(determined by Point Count Analysis)

Building	Floor	Room	Sample ID	Material Description
162	1	C117	OT-09-293-0471	8" horizontal pipe - white wrap, foil backing, yellow foam insulation
162	1	C121	OT-09-293-0472	8" elbow - white wrap, white block insulation
162	1	C Hall West	OT-09-293-0473	Layer 1 - yellow carpet mastic
162	1	C Hall West	OT-09-293-0473	Layer 2 - brown 12x12 floor tile
162	1	C Hall West	OT-09-293-0473	Layer 3 - black mastic
162	1	C Hall West	OT-09-293-0474	Gray cove molding, yellow mastic
162	1	C122	OT-09-293-0475	Plaster wall overspray material
162	1	C123A	OT-09-293-0476	8" elbow - white wrap, black mastic, yellow fiberglass insulation
162	1	C123	OT-09-293-0477	1" elbow - white wrap, white block insulation
162	1	C123	OT-09-293-0478	3" valve - white wrap, white block insulation
162	1	C123	OT-09-293-0479	3" horizontal pipe hanger - white wrap, white block insulation
162	1	C123	OT-09-293-0480	2" elbow - white wrap, white block insulation
162	1	C123	OT-09-293-0481	2" horizontal pipe - white wrap, yellow fiberglass insulation
162	1	C144	OT-09-293-0482	4" elbow - white wrap, white block insulation
162	1	C144	OT-09-293-0483	4" horizontal pipe - white wrap, yellow fiberglass insulation
162	1	C144	OT-09-293-0484	2" elbow - white wrap, white block insulation
162	1	C144	OT-09-293-0485	2" horizontal pipe - white wrap, yellow fiberglass insulation
162	1	C144	OT-09-293-0486	1" elbow - white wrap, white block insulation
162	1	C144	OT-09-293-0487	1" horizontal pipe - white wrap, yellow fiberglass insulation
162	1	C144	OT-09-293-0488	Red 12x12 floor tile, yellow mastic
162	1	C144	OT-09-293-0489	Light blue 12x12 floor tile, yellow mastic
162	1	C145	OT-09-293-0490	2" valve - black mastic pipe tape
162	1	C145	OT-09-293-0491	8" elbow - white wrap, white block insulation
162	1	C147	OT-09-293-0492	6" horizontal pipe - white foil-backed wrap, black mastic, black rock insulation
162	1	C138	OT-09-293-0493	1" elbow - white wrap, white block insulation
102	1	C138	OT-09-293-0494	1" horizontal pipe - white wrap, yellow fiberglass insulation
162	1	C151	OT-09-293-0495	4" horizontal pipe - brown foil-backed wrap, black mastic, black rock insulation
162	1	Entry Hall	OT-09-293-0496	Layer 1 - light gray 12x12 floor tile
162	1	Entry Hall	OT-09-293-0496	Layer 2 - yellow mastic
162	1	Entry Hall	OT-09-293-0496	Layer 3 - brown 12x12 floor tile
162	1	Entry Hall	OT-09-293-0496	Layer 4 - black mastic
162	1	C161	OT-09-293-0497	2" elbow - plaster spray-on, white wrap, white block and yellow fiberglass insulation
162	1	C161	OT-09-293-0498	2" horizontal pipe - white foil-backed wrap, yellow fiberglass insulation

OLIN E. TEAGUE V. A. MEDICAL CENTER
2009 THREE-YEAR ASBESTOS REINSPECTION
SUMMARY OF BULK SAMPLES TAKEN TO DATE

Red = Asbestos-Containing Material (ACM) Blue = Non ACM Green = Non Asbestos-Containing Material
(determined by Point Count Analysis)

Building	Floor	Room	Sample ID	Material Description
162	1	C161	OT-09-293-0499	Layer 1 - light gray 12x12 floor tile
162	1	C161	OT-09-293-0499	Layer 2 - yellow mastic
162	1	C161	OT-09-293-0499	Layer 3 - brown 12x12 floor tile
162	1	C161	OT-09-293-0499	Layer 4 - black mastic
162	1	C157	OT-09-293-0500	Yellow carpet mastic, white 12x12 floor tile, yellow mastic
162	1	C156	OT-09-293-0701	2" elbow - white wrap, yellow fiberglass insulation
162	1	C156	OT-09-293-0702	8" elbow - white wrap, yellow fiberglass insulation
162	1	C156	OT-09-293-0703	8" horizontal pipe - brown foil-backed wrap, yellow fiberglass insulation
162	1	C156	OT-09-293-0704	White 2x4 ceiling tile
162	1	C160	OT-09-293-0705	Light gray 12x12 floor tile, yellow mastic
162	1	C139	OT-09-293-0706	1" elbow - white wrap, white block insulation
162	1	C139	OT-09-293-0707	1" horizontal pipe - white wrap, yellow fiberglass insulation
162	1	E101	OT-09-293-0708	16" elbow - white wrap, black mastic, black rock insulation
162	1	E101	OT-09-293-0709	14" horizontal pipe - white foil-backed wrap, black mastic, black rock insulation
162	1	North Hall	OT-09-293-0710	Layer 1 - white 12x12 floor tile
162	1	North Hall	OT-09-293-0710	Layer 2 - yellow mastic, black mastic
162	1	C111	OT-09-293-0711	2" elbow - white wrap, white block insulation
162	1	C111	OT-09-293-0712	2" horizontal pipe - white wrap, yellow fiberglass insulation
162	1	C111	OT-09-293-0713	Layer 1 - 10" elbow - white wrap
162	1	C111	OT-09-293-0713	Layer 2 - 10" elbow - white block insulation
162	1	C111	OT-09-293-0714	10" horizontal pipe - white wrap, yellow fiberglass insulation
162	1	E109	OT-09-293-0715	Gray transite vent hood
162	1	E109	OT-09-293-0716	Black lab top
162	1	E109	OT-09-293-0717	Black sink backsplash board
162	1	E109	OT-09-293-0718	Black sink coating
162	1	E110	OT-09-293-0719	Gray transite vent hood
162	1	E110	OT-09-293-0720	Black lab top
162	1	E110	OT-09-293-0721	Black sink backsplash
162	1	A129	OT-09-293-0722	2" elbow - white block insulation
162	1	Hall	OT-09-293-0723	Layer 1 - 10" elbow - white wrap
162	1	Hall	OT-09-293-0723	Layer 2 - 10" elbow - white block insulation
162	1	Fire	OT-09-293-0724	Layer 1 - brown 12x12 floor tile
162	1	Fire	OT-09-293-0724	Layer 2 - black mastic
162	1	Fire	OT-09-293-0725	Brown cove molding, yellow mastic
162	1	West Hall	OT-09-293-0726	1" elbow - white block insulation
162	1	West Hall	OT-09-293-0727	Layer 1 - 1" horizontal pipe - white foil-backed wrap
162	1	West Hall	OT-09-293-0727	Layer 2 - 1" horizontal pipe - foil backing
162	1	West Hall	OT-09-293-0727	Layer 3 - 1" horizontal pipe - black mastic

OLIN E. TEAGUE V. A. MEDICAL CENTER
2009 THREE-YEAR ASBESTOS REINSPECTION
SUMMARY OF BULK SAMPLES TAKEN TO DATE

Red = Asbestos-Containing Material (ACM) Blue = Non ACM Green = Non Asbestos-Containing Material
(determined by Point Count Analysis)

Building	Floor	Room	Sample ID	Material Description
162	1	West Hall	OT-09-293-0727	Layer 4 - 1" horizontal pipe - yellow fiberglass insulation
162	1	A140	OT-09-293-0728	White 2x4 ceiling tile
162	1	A99	OT-09-293-0729	10" elbow - white wrap, white block insulation
162	1	A99	OT-09-293-0730	10" horizontal pipe - white wrap, yellow fiberglass insulation
162	1	A99	OT-09-293-0731	Layer 1 - 4" elbow - white wrap
162	1	A99	OT-09-293-0731	Layer 2 - 4" elbow - white block insulation
162	1	A99	OT-09-293-0732	4" horizontal pipe - white wrap, yellow fiberglass insulation
162	1	A99	OT-09-293-0733	Sheetrock tape, mud
162	1	A99A	OT-09-293-0734	Light gray 12x12 floor tile, yellow mastic
162	1	A176	OT-09-293-0735	White 2x2 ceiling tile
162	1	A173	OT-09-293-0736	White sink undercoating
162	1	A173	OT-09-293-0737	White 12x12 floor tile, black mastic
162	1	A185	OT-09-293-0738	Light brown 12x12 floor tile, black mastic
162	1	A160A	OT-09-293-0739	Layer 1 - White caulking
162	1	A160A	OT-09-293-0739	Layer 2 - white wall plaster
162	1	A160A	OT-09-293-0739	Layer 3 - gray base coat
162	1	A157	OT-09-293-0740	Light brown 12x12 floor tile, yellow mastic
162	1	A110	OT-09-293-0741	Layer 1 - brown 12x12 floor tile
162	1	A110	OT-09-293-0741	Layer 2 - black mastic
162	1	A110	OT-09-293-0741	Layer 3 - yellow mastic
162	1	A110	OT-09-293-0742	Tan cove molding, yellow mastic
162	1	A102	OT-09-293-0743	Layer 1 - white 12x12 floor tile
162	1	A102	OT-09-293-0743	Layer 2 - yellow mastic, black mastic
162	1	A101	OT-09-293-0744	Layer 1 - 3" elbow - white wrap
162	1	A101	OT-09-293-0744	Layer 2 - 3" elbow - white block insulation
162	1	A101	OT-09-293-0745	3" horizontal pipe - white wrap, yellow fiberglass insulation
162	1	A101	OT-09-293-0746	2" elbow - white wrap, white block insulation
162	1	A101	OT-09-293-0747	2" horizontal pipe - white wrap, yellow fiberglass insulation
162	1	A101	OT-09-293-0748	Layer 1 - 1" elbow - white wrap, white block insulation
162	1	A101	OT-09-293-0748	Layer 2 - 1" elbow - white wrap, white block insulation
162	1	A101	OT-09-293-0749	1" horizontal pipe - white wrap, yellow fiberglass insulation
162	1	SE Hall	OT-09-293-0750	White 2x4 ceiling tile
162	1	A163	OT-09-293-0751	Black mastic piping tape
162	1	A170	OT-09-293-0752	Green 12x12 floor tile, black mastic
162	1	A116	OT-09-293-0753	Black sink undercoating
162	1	1N78	OT-09-293-0754	White 2x2 ceiling tile
162	1	West Hall	OT-09-293-0755	Layer 1 - brown 12x12 floor tile
162	1	West Hall	OT-09-293-0755	Layer 2 - yellow mastic, black mastic
162	1	South Hall	OT-09-293-0756	White 2x4 ceiling tile

OLIN E. TEAGUE V. A. MEDICAL CENTER
2009 THREE-YEAR ASBESTOS REINSPECTION
SUMMARY OF BULK SAMPLES TAKEN TO DATE

Red = Asbestos-Containing Material (ACM) Blue = Non ACM Green = Non Asbestos-Containing Material
(determined by Point Count Analysis)

Building	Floor	Room	Sample ID	Material Description
162	1	1N51	OT-09-293-0757	White 12x12 floor tile, yellow mastic
162	1	South Hall	OT-09-293-0758	Sheetrock tape, mud
162	1	South Hall	OT-09-293-0759	Brown plaster overspray
162	1	South Hall	OT-09-293-0760	Layer 1 - light brown 12x12 floor tile
162	1	South Hall	OT-09-293-0760	Layer 2 - black mastic
162	1	1N54	OT-09-293-0761	White sink undercoating
162	1	1N75	OT-09-293-0762	Back mastic pipe tape
162	1	1N66	OT-09-293-0763	Layer 1 - light brown 12x12 floor tile
162	1	1N66	OT-09-293-0763	Layer 2 - black mastic
162	1	1N76	OT-09-293-0764	Layer 1 - white 12x12 floor tile
162	1	1N76	OT-09-293-0764	Layer 2 - yellow mastic, black mastic
162	1	1N15	OT-09-293-0765	Light gray 12x12 floor tile, yellow mastic
162	1	1N03	OT-09-293-0766	White 2x4 ceiling tile (sheetrock)
162	1	1N04	OT-09-293-0767	Black lab top
162	1	1N04	OT-09-293-0768	Black sink backsplash
162	1	1N50	OT-09-293-0769	Layer 1 - tan linoleum
162	1	1N50	OT-09-293-0769	Layer 2 - black mastic, yellow mastic
162	1	1N50	OT-09-293-0770	Black lab top
162	Roof	AHU Room	OT-09-293-0771	20" tank end cap - white wrap, white block insulation, yellow fiberglass insulation
162	Roof	AHU Room	OT-09-293-0772	10" elbow - white wrap, white block insulation
162	Roof	AHU Room	OT-09-293-0773	Layer 1 - 14" valve end cap - white wrap
162	Roof	AHU Room	OT-09-293-0773	14" valve end cap - yellow fiberglass insulation
162	Roof	AHU Room	OT-09-293-0774	10" elbow - white wrap, white block insulation
162	Roof	AHU Room	OT-09-293-0775	10" vertical pipe - white foil-backed wrap
162	Roof	AHU Room	OT-09-293-0775	10" vertical pipe - silver foil backing
162	Roof	AHU Room	OT-09-293-0775	10" vertical pipe - yellow fiberglass insulation
162	Roof	AHU Room	OT-09-293-0776	Sheetrock tape, mud
162	Ext	Roof	OT-09-293-0777	Black mastic piping tape
162	Ext	Roof	OT-09-293-0778	Black roofing tar
162	Ext	Roof	OT-09-293-0779	Roofing material
162	Ext	Roof	OT-09-293-0780	Roofing tar
162	Ext	Roof	OT-09-293-0781	14" elbow - white foil-backed wrap, yellow fiberglass insulation
162	Ext	NW Ent	OT-09-293-0782	Black mastic, concrete

ASBESTOS-CONTAINING BULK SAMPLES

OLIN E. TEAGUE V. A. MEDICAL CENTER
2009 THREE-YEAR ASBESTOS REINSPECTION
LIST OF ASBESTOS-CONTAINING SAMPLES

Red = Asbestos-Containing Material (ACM)

Building	Floor	Room	Sample ID	Material Description
162	1	F143	OT-09-293-0306	Layer 1 - brown 12x12 floor tile
162	1	F143	OT-09-293-0306	Layer 2 - black mastic
162	1	Hall	OT-09-293-0320	Layer 2 - black mastic
162	1	F114	OT-09-293-0322	Layer 2 - black mastic
162	1	South Hall	OT-09-293-0393	Layer 2 - black mastic
162	1	B-Hall	OT-09-293-0404	Layer 2 - black mastic
162	1	B156	OT-09-293-0409	Layer 3 - black mastic
162	1	B150	OT-09-293-0412	Black sink undercoating
162	1	B140A	OT-09-293-0417	Black sink undercoating
162	1	B140A	OT-09-293-0418	Layer 1 - brown 9x9 floor tile
162	1	B140A	OT-09-293-0418	Layer 2 - black mastic
162	1	B129	OT-09-293-0431	2" horizontal pipe - white wrap, white block insulation
162	1	B128A	OT-09-293-0432	Black sink undercoating
162	1	B128A	OT-09-293-0433	Layer 1 - brown 9x9 floor tile
162	1	B128A	OT-09-293-0433	Layer 2 - black mastic
162	1	E141	OT-09-293-0442	Layer 2 - black mastic
162	1	E137A	OT-09-293-0449	Layer 1 - brown 9x9 floor tile
162	1	E137A	OT-09-293-0449	Layer 2 - black mastic
162	1	E99	OT-09-293-0450	Layer 1 - brown 9x9 floor tile
162	1	E99	OT-09-293-0450	Layer 2 - black mastic
162	1	E103	OT-09-293-0455	Layer 1 - 2" T - white wrap
162	1	Clo.	OT-09-293-0457	Layer 2 - black mastic
162	1	C129	OT-09-293-0464	1" elbow - white wrap, white block insulation
162	1	C121	OT-09-293-0472	8" elbow - white wrap, white block insulation
162	1	C Hall West	OT-09-293-0473	Layer 3 - black mastic
162	1	C123	OT-09-293-0477	1" elbow - white wrap, white block insulation
162	1	C144	OT-09-293-0482	4" elbow - white wrap, white block insulation
162	1	C144	OT-09-293-0484	2" elbow - white wrap, white block insulation
162	1	C144	OT-09-293-0486	1" elbow - white wrap, white block insulation
162	1	C145	OT-09-293-0490	2" valve - black mastic pipe tape
162	1	C145	OT-09-293-0491	8" elbow - white wrap, white block insulation
162	1	C138	OT-09-293-0493	1" elbow - white wrap, white block insulation
162	1	C139	OT-09-293-0706	1" elbow - white wrap, white block insulation
162	1	C111	OT-09-293-0711	2" elbow - white wrap, white block insulation
162	1	C111	OT-09-293-0713	Layer 2 - 10" elbow - white block insulation
162	1	E109	OT-09-293-0715	Gray transite vent hood
162	1	E109	OT-09-293-0717	Black sink backsplash board
162	1	E110	OT-09-293-0719	Gray transite vent hood
162	1	E110	OT-09-293-0721	Black sink backsplash
162	1	A129	OT-09-293-0722	2" elbow - white block insulation
162	1	West Hall	OT-09-293-0726	1" elbow - white block insulation
162	1	A173	OT-09-293-0736	White sink undercoating
162	1	A110	OT-09-293-0741	Layer 2 - black mastic
162	1	A101	OT-09-293-0746	2" elbow - white wrap, white block insulation
162	1	A116	OT-09-293-0753	Black sink undercoating

**OLIN E. TEAGUE V. A. MEDICAL CENTER
2009 THREE-YEAR ASBESTOS REINSPECTION
LIST OF ASBESTOS-CONTAINING SAMPLES**

Red = Asbestos-Containing Material (ACM)

Building	Floor	Room	Sample ID	Material Description
162	1	South Hall	OT-09-293-0760	Layer 1 - light brown 12x12 floor tile
162	1	South Hall	OT-09-293-0760	Layer 2 - black mastic
162	1	1N54	OT-09-293-0761	White sink undercoating
162	1	1N66	OT-09-293-0763	Layer 1 - light brown 12x12 floor tile
162	1	1N66	OT-09-293-0763	Layer 2 - black mastic

2009 REINSPECTION INSPECTION LOG

ASBESTOS INSPECTION LOG



Client: Central Texas Veterans Health Care System
 Location: Olin E. Teague V. A. Medical Center
 1901 Veterans Memorial Drive, Temple, Texas

Date: October 21, 2009
 Inspector(s): Donald Joiner and Jerald Heidecker

NOTE: Red = Asbestos-containing Material Blue = Non Asbestos-containing Material Green = Non Asbestos-containing Material
 (determined by Point Count analysis)

Sample ID	Material Description	Material Category	Friability	Condition	Building	Floor	Room	Location	Asbestos % Type
OT-09-293-0301	White plaster material	S	F	8	162	1	F110	Southwest quadrant of room	ND
OT-09-293-0302	White sheetrock tape, mud	M	F	8	162	1	F110	Southeast quadrant of room	ND
OT-09-293-0303	White 2x2 ceiling tile	M	F	8	162	1	F110	Southeast quadrant of room	ND
OT-09-293-0304	Gray cove molding, yellow mastic	M	NF	8	162	1	F110	Southeast corner of room	ND
OT-09-293-0305	White 2x4 ceiling tile	M	F	8	162	1	F143	Southeast quadrant of room	ND
OT-09-293-0306	Layer 1 - brown 12x12 floor tile	M	NF	8	162	1	F143	Northwest corner of room	1.5% chry
OT-09-293-0306	Layer 2 - black mastic	M	NF	8	162	1	F143	Northwest corner of room	6.6% chry
OT-09-293-0307	White 12x12 floor tile, yellow mastic	M	NF	8	162	1	F143	Southeast quadrant of room	ND
OT-09-293-0308	Black piping mastic	M	NF	8	162	1	F106	Northwest quadrant of room	0.4% chry
OT-09-293-0309	6" horizontal pipe - white wrap, foil backing, black rock insulation	T	F	8	162	1	Hall	Southwest quadrant of hallway outside room F106	ND
OT-09-293-0310	Yellow carpet mastic, black mastic	M	NF	8	162	1	F105	Northeast corner of room	<1% chry
OT-09-293-0311	8" elbow - white wrap, brown fiberglass insulation	T	F	8	162	1	Hall	Northeast quadrant of hallway above ceiling tile across from room F102	ND

ASBESTOS INSPECTION LOG



Client: Central Texas Veterans Health Care System
 Location: Olin E. Teague V. A. Medical Center
 1901 Veterans Memorial Drive, Temple, Texas

Date: October 21, 2009
 Inspector(s): Donald Joiner and Jerald Heidecker

NOTE: Red = Asbestos-containing Material Blue = Non Asbestos-containing Material Green = Non Asbestos-containing Material
 (determined by Point Count analysis)

Sample ID	Material Description	Material Category	Friability	Condition	Building	Floor	Room	Location	Asbestos % Type
OT-09-293-0312	8" horizontal pipe - white wrap, foil backing, black mastic, black rock insulation	T	F	8	162	1	Hall	Northeast quadrant of hallway above ceiling tile across from room F102	ND
OT-09-293-0313	White wall plaster material	S	F	7	162	1	F102	Northeast quadrant of room above ceiling tile at north wall	ND
OT-09-293-0314	White 2x4 ceiling tile	M	F	8	162	1	F102	Northeast quadrant of room	ND
OT-09-293-0315	Brown plaster overspray	S	F	8	162	1	F102	Northeast quadrant of room above ceiling tile at north wall	ND
OT-09-293-0316	Layer 1 - 6" elbow - gray spray-on	T	F	8	162	1	F103	Northeast corner of room above ceiling tile	ND
OT-09-293-0316	Layer 2 - 6" elbow - white wrap	T	F	8	162	1	F103	Northeast corner of room above ceiling tile	ND
OT-09-293-0316	Layer 3 - 6" elbow - white block insulation	T	F	8	162	1	F103	Northeast corner of room above ceiling tile	<1% chry <1% amos
OT-09-293-0317	6" horizontal pipe - white wrap, yellow fiberglass insulation	T	F	8	162	1	F103	Northeast corner of room above ceiling tile	ND
OT-09-293-0318	Black mastic piping tape	M	NF	8	162	1	F104	Southwest corner of room above ceiling tile	ND
OT-09-293-0319	Yellow carpet mastic, black mastic	M	NF	8	162	1	F123	Northwest corner of room	0.3% chry
OT-09-293-0320	Layer 1 - brown 12x12 floor tile	M	NF	8	162	1	Hall	Northeast quadrant of hallway outside west wall of room F112	ND
OT-09-293-0320	Layer 2 - black mastic	M	NF	8	162	1	Hall	Northeast quadrant of hallway outside west wall of room F112	2.9% chry



ASBESTOS INSPECTION LOG

Client: Central Texas Veterans Health Care System
 Location: Olin E. Teague V. A. Medical Center
 1901 Veterans Memorial Drive, Temple, Texas

Date: October 21, 2009
 Inspector(s): Donald Joiner and Jerald Heidecker

NOTE: Red = Asbestos-containing Material Blue = Non Asbestos-containing Material Green = Non Asbestos-containing Material
 (determined by Point Count analysis)

Sample ID	Material Description	Material Category	Friability	Condition	Building	Floor	Room	Location	Asbestos % Type
OT-09-293-0321	Layer 1 - white caulking	T	F	8	162	1	F112	Northwest corner of room above ceiling tile taken from discarded ductwork	<1% chry
OT-09-293-0321	Layer 2 - white tape	T	F	8	162	1	F112	Northwest corner of room above ceiling tile taken from discarded ductwork	ND
OT-09-293-0321	Layer 3 - pink fiberglass insulation	T	F	8	162	1	F112	Northwest corner of room above ceiling tile taken from discarded ductwork	ND
OT-09-293-0322	Layer 1 - tan 12x12 floor tile	M	NF	8	162	1	F114	Southwest quadrant of room	ND
OT-09-293-0322	Layer 2 - black mastic	M	NF	8	162	1	F114	Southwest quadrant of room	2.3% chry
OT-09-293-0323	Gray cove molding	M	NF	8	162	1	F114	Southwest quadrant of room	ND
OT-09-293-0324	Layer 1 - 6" elbow - spray-on	T	F	8	162	1	F120	Southwest corner of room above ceiling tile	ND
OT-09-293-0324	Layer 2 - 6" elbow - white wrap	T	F	8	162	1	F120	Southwest corner of room above ceiling tile	ND
OT-09-293-0324	Layer 3 - 6" elbow - white block insulation	T	F	8	162	1	F120	Southwest corner of room above ceiling tile	<1% amos
OT-09-293-0325	Layer 1 - 6" horizontal pipe - gray spray-on	T	F	8	162	1	F120	Southwest corner of room above ceiling tile	ND
OT-09-293-0325	Layer 2 - 6" horizontal pipe - white wrap	T	F	8	162	1	F120	Southwest corner of room above ceiling tile	<1% amos
OT-09-293-0325	Layer 3 - 6" horizontal pipe - yellow fiberglass insulation	T	F	8	162	1	F120	Southwest corner of room above ceiling tile	ND



ASBESTOS INSPECTION LOG

Client: Central Texas Veterans Health Care System
 Location: Olin E. Teague V. A. Medical Center
 1901 Veterans Memorial Drive, Temple, Texas

Date: October 21, 2009
 Inspector(s): Donald Joiner and Jerald Heidecker

NOTE: Red = Asbestos-containing Material Blue = Non Asbestos-containing Material Green = Non Asbestos-containing Material
 (determined by Point Count analysis)

Sample ID	Material Description	Material Category	Friability	Condition	Building	Floor	Room	Location	Asbestos % Type
OT-09-293-0326	2x2 ceiling tile	M	F	8	162	1	Lobby	Northwest quadrant of northwest entry way lobby	ND
OT-09-293-0327	Layer 1 - 1" elbow - white block insulation	T	F	8	162	1	F124	Northwest quadrant of room above ceiling tile	<1% amos
OT-09-293-0327	Layer 2 - 1" elbow - white wrap	T	F	8	162	1	F124	Northwest quadrant of room above ceiling tile	ND
OT-09-293-0328	1" horizontal pipe - white wrap, yellow fiberglass insulation	T	F	8	162	1	F124	Northwest quadrant of room above ceiling tile	ND
OT-09-293-0329	Layer 1 - white linoleum	M	NF	8	162	1	F124	Southwest quadrant of room under 2x2 metal panels	ND
OT-09-293-0329	Layer 2 - black mastic	M	NF	8	162	1	F124	Southwest quadrant of room under 2x2 metal panels	<1% chry
OT-09-293-0330	Layer 1 - white linoleum	M	NF	8	162	1	F124	Southeast corner of room under 2x2 metal panels	ND
OT-09-293-0330	Layer 2 - black mastic	M	NF	8	162	1	F124	Southeast corner of room under 2x2 metal panels	<1% chry
OT-09-293-0331	Layer 1 - white linoleum	M	NF	8	162	1	F124	Southeast quadrant of room under 2x2 metal panels	ND
OT-09-293-0331	Layer 2 - black mastic	M	NF	8	162	1	F124	Southeast quadrant of room under 2x2 metal panels	<1% chry
OT-09-293-0332	White 2x4 ceiling tile	M	F	8	162	1	Hall	Northwest quadrant of southeast hallway	ND
OT-09-293-0333	White caulking, white wrap, foil backing, yellow fiberglass insulation	T	F	8	162	1	Hall	Northwest quadrant of southeast hallway	ND



ASBESTOS INSPECTION LOG

Client: Central Texas Veterans Health Care System
 Location: Olin E. Teague V. A. Medical Center
 1901 Veterans Memorial Drive, Temple, Texas

Date: October 21, 2009
 Inspector(s): Donald Joiner and Jerald Heidecker

NOTE: Red = Asbestos-containing Material Blue = Non Asbestos-containing Material Green = Non Asbestos-containing Material
 (determined by Point Count analysis)

Sample ID	Material Description	Material Category	Friability	Condition	Building	Floor	Room	Location	Asbestos % Type
OT-09-293-0334	Layer 1 - 6" elbow - white block insulation	T	F	8	162	1	Hall	Northwest quadrant of southeast hallway	<1% amos
OT-09-293-0334	Layer 2 - 6" elbow - white wrap	T	F	8	162	1	Hall	Northwest quadrant of southeast hallway	ND
OT-09-293-0335	6" vertical pipe - white wrap, yellow fiberglass insulation	T	F	8	162	1	Hall	Northwest quadrant of southeast hallway	ND
OT-09-293-0390	Layer 1 - 1" elbow - white wrap	T	F	8	162	1	F126 C	Southeast corner of room	ND
OT-09-293-0390	Layer 2 - 1" elbow - white block insulation	T	F	8	162	1	F126 C	Southeast corner of room	<1% chry <1% amos
OT-09-293-0391	1" horizontal pipe - white wrap, yellow fiberglass insulation	T	F	8	162	1	F126 C	Southeast corner of room	ND
OT-09-293-0392	Yellow carpet adhesive, black mastic	M	NF	6	162	1	F126 C	Northwest corner of room	0.25% chry
OT-09-293-0393	Layer 1 - brown 12x12 floor tile	M	NF	8	162	1	South Hall	North side outside room F126	ND
OT-09-293-0393	Layer 2 - black mastic	M	NF	8	162	1	South Hall	North side outside room F126	1.9% chry
OT-09-293-0394	Tan 12x12 floor tile, yellow mastic	M	NF	8	162	1	F141	Southeast quadrant of room	ND
OT-09-293-0395	Layer 1 - tan 12x12 floor tile	M	NF	8	162	1	F140	Northwest quadrant of room	ND
OT-09-293-0395	Layer 2 - yellow mastic, black mastic	M	NF	8	162	1	F140	Northwest quadrant of room	0.6% chry



ASBESTOS INSPECTION LOG

Client: Central Texas Veterans Health Care System
 Location: Olin E. Teague V. A. Medical Center
 1901 Veterans Memorial Drive, Temple, Texas

Date: October 21, 2009
 Inspector(s): Donald Joiner and Jerald Heidecker

NOTE: Red = Asbestos-containing Material Blue = Non Asbestos-containing Material Green = Non Asbestos-containing Material
 (determined by Point Count analysis)

Sample ID	Material Description	Material Category	Friability	Condition	Building	Floor	Room	Location	Asbestos % Type
OT-09-293-0396	Brown fire door paper insulation	M	NF	7	162	1	F140	Northwest quadrant of room	ND
OT-09-293-0397	White sheetrock tape, mud	Ss	NF	8	162	1	F140	Northwest quadrant of room	ND
OT-09-293-0398	Light brown 12x12 floor tile, yellow mastic	M	NF	8	162	1	E138K	Northeast quadrant of room	ND
OT-09-293-0399	White 2x2 ceiling tile	M	NF	8	162	1	E138J	Southeast quadrant of room	ND
OT-09-293-0400	Layer 1 - 8" elbow - white wrap	T	F	8	162	1	E138J	Southwest quadrant of room	ND
OT-09-293-0400	Layer 2 - 8" elbow - white wrap	T	F	8	162	1	E138J	Southwest quadrant of room	<1% chry <1% amos
OT-09-293-0401	8" horizontal pipe - white wrap, yellow fiberglass insulation	T	F	8	162	1	E138J	Southwest quadrant of room	ND
OT-09-293-0402	White 2x4 ceiling tile	M	F	8	162	1	B-Hall	Northwest quadrant of hall outside room B157	ND
OT-09-293-0403	White plaster wall material	Ss	F	6	162	1	B-Hall	Northwest quadrant of hall outside room B157	ND
OT-09-293-0404	Layer 1 - brown 12x12 floor tile	M	NF	8	162	1	B-Hall	Northwest corner of hall outside room B157	0.7% chry
OT-09-293-0404	Layer 2 - black mastic	M	NF	8	162	1	B-Hall	Northwest corner of hall outside room B157	1.7% chry
OT-09-293-0405	2" horizontal pipe - white wrap, foil backing, tan block insulation	T	F	8	162	1	B-Hall	Southwest quadrant of hall outside room B156	ND



ASBESTOS INSPECTION LOG

Client: Central Texas Veterans Health Care System
 Location: Olin E. Teague V. A. Medical Center
 1901 Veterans Memorial Drive, Temple, Texas

Date: October 21, 2009
 Inspector(s): Donald Joiner and Jerald Heidecker

NOTE: Red = Asbestos-containing Material Blue = Non Asbestos-containing Material Green = Non Asbestos-containing Material
 (determined by Point Count analysis)

Sample ID	Material Description	Material Category	Friability	Condition	Building	Floor	Room	Location	Asbestos % Type
OT-09-293-0406	Black mastic piping tape	M	NF	8	162	1	B-Hall	Southwest quadrant of hall outside room B156	<1% chry
OT-09-293-0407	Tan cove molding, yellow mastic	M	NF	8	162	1	B158	Northwest quadrant of room	ND
OT-09-293-0408	8" horizontal pipe - white tape, foil backing, black rock insulation	T	F	8	162	1	B156	Southeast quadrant of room above ceiling tile	ND
OT-09-293-0409	Layer 1 - yellow carpet mastic	M	NF	8	162	1	B156	Southeast corner of room	ND
OT-09-293-0409	Layer 2 - brown 12x12 floor tile	M	NF	8	162	1	B156	Southeast corner of room	0.3% chry
OT-09-293-0409	Layer 3 - black mastic	M	NF	8	162	1	B156	Southeast corner of room	2.1% chry
OT-09-293-0410	Brown cove molding, yellow mastic	M	NF	8	162	1	B154	Northeast quadrant of room	ND
OT-09-293-0411	Layer 1 - white 12x12 floor tile	M	NF	8	162	1	B167	Southeast corner of room	ND
OT-09-293-0411	Layer 2 - yellow mastic	M	NF	8	162	1	B167	Southeast corner of room	<1% chry
OT-09-293-0412	Black sink undercoating	M	NF	8	162	1	B150	Northwest quadrant of room	10% chry
OT-09-293-0413	Layer 1 - 1" elbow - white wrap	T	F	8	162	1	B140 A	Northeast corner of room above ceiling tile	ND
OT-09-293-0413	Layer 2 - 1" elbow - white block insulation	T	F	8	162	1	B140 A	Northeast corner of room above ceiling tile	<1% amos <1% chry



ASBESTOS INSPECTION LOG

Client: Central Texas Veterans Health Care System
 Location: Olin E. Teague V. A. Medical Center
 1901 Veterans Memorial Drive, Temple, Texas

Date: October 21, 2009
 Inspector(s): Donald Joiner and Jerald Heidecker

NOTE: Red = Asbestos-containing Material Blue = Non Asbestos-containing Material Green = Non Asbestos-containing Material
 (determined by Point Count analysis)

Sample ID	Material Description	Material Category	Friability	Condition	Building	Floor	Room	Location	Asbestos % Type
OT-09-293-0414	1" horizontal pipe - white wrap, yellow fiberglass insulation	T	F	8	162	1	B140 A	Northeast corner of room above ceiling tile	ND
OT-09-293-0415	Layer 1 - 10" elbow - white wrap	T	F	8	162	1	B140 A	Northeast corner of room above ceiling tile	ND
OT-09-293-0415	Layer 2 - 10" elbow - white block insulation	T	F	8	162	1	B140 A	Northeast corner of room above ceiling tile	<1% chry <1% amos
OT-09-293-0416	10" horizontal pipe - white wrap, yellow fiberglass insulation	T	F	8	162	1	B140 A	Northeast corner of room above ceiling tile	ND
OT-09-293-0417	Black sink undercoating	M	NF	8	162	1	B140 A	Southeast quadrant of room	10% chry
OT-09-293-0418	Layer 1 - brown 9x9 floor tile	M	NF	8	162	1	B140 A	Northeast quadrant of room under counter	1.7% chry
OT-09-293-0418	Layer 2 - black mastic	M	NF	8	162	1	B140 A	Northeast quadrant of room under counter	1.6% chry
OT-09-293-0419	Layer 1 - brown 12x12 floor tile	M	NF	8	162	1	B140 A	Northeast quadrant of room	0.6% chry
OT-09-293-0419	Layer 2 - black mastic	M	NF	8	162	1	B140 A	Northeast quadrant of room	0.6% chry
OT-09-293-0420	Sheetrock tape, mud	M	NF	8	162	1	B149	Southwest corner of room above ceiling tile	ND
OT-09-293-0421	12" horizontal pipe - white tape, foil backing, pink foam insulation	T	F	8	162	1	B124	Southwest quadrant of room above ceiling tile	ND
OT-09-293-0422	Layer 1 - white 12x12 floor tile	M	NF	8	162	1	B124	Southwest quadrant of room	ND



ASBESTOS INSPECTION LOG

Client: Central Texas Veterans Health Care System
 Location: Olin E. Teague V. A. Medical Center
 1901 Veterans Memorial Drive, Temple, Texas

Date: October 21, 2009
 Inspector(s): Donald Joiner and Jerald Heidecker

NOTE: Red = Asbestos-containing Material Blue = Non Asbestos-containing Material Green = Non Asbestos-containing Material
 (determined by Point Count analysis)

Sample ID	Material Description	Material Category	Friability	Condition	Building	Floor	Room	Location	Asbestos % Type
OT-09-293-0422	Layer 2 - yellow mastic	M	NF	8	162	1	B124	Southwest quadrant of room	<1% chry
OT-09-293-0423	White wall plaster material	S	F	8	162	1	B132	Northeast quadrant of room above ceiling tile	ND
OT-09-293-0424	Plaster overspray	S	F	8	162	1	B132	Northeast quadrant of room above ceiling tile	ND
OT-09-293-0425	Blue 12x12 floor tile, yellow mastic	M	NF	8	162	1	B130	Southeast corner of room	ND
OT-09-293-0426	Brown cove molding, yellow mastic	M	NF	8	162	1	B130	Southeast corner of room	ND
OT-09-293-0427	10" elbow - white wrap, yellow fiberglass insulation	T	F	8	162	1	B153	Southeast quadrant of room	ND
OT-09-293-0428	10" horizontal pipe - white wrap, foil backing, yellow fiberglass insulation	T	F	8	162	1	B153	Southeast quadrant of room	ND
OT-09-293-0429	Blue 12x12 floor tile, yellow mastic	M	NF	8	162	1	B129	Northeast corner of room	ND
OT-09-293-0430	Layer 1 - 2" elbow - white wrap	T	F	5	162	1	B129	Southwest quadrant of room	ND
OT-09-293-0430	Layer 2 - 2" elbow - white block insulation	T	F	5	162	1	B129	Southwest quadrant of room	<1% chry <1% amos
OT-09-293-0431	2" horizontal pipe - white wrap, white block insulation	T	F	5	162	1	B129	Southwest quadrant of room	1.25% amos 0.25% chry

ASBESTOS INSPECTION LOG



Client: Central Texas Veterans Health Care System
 Location: Olin E. Teague V. A. Medical Center
 1901 Veterans Memorial Drive, Temple, Texas

Date: October 21, 2009
 Inspector(s): Donald Joiner and Jerald Heidecker

NOTE: Red = Asbestos-containing Material Blue = Non Asbestos-containing Material Green = Non Asbestos-containing Material
 (determined by Point Count analysis)

Sample ID	Material Description	Material Category	Friability	Condition	Building	Floor	Room	Location	Asbestos % Type
OT-09-293-0432	Black sink undercoating	M	NF	8	162	1	B128 A	Southeast quadrant of room	10% chry
OT-09-293-0433	Layer 1 - brown 9x9 floor tile	M	NF	8	162	1	B128 A	Southeast quadrant of room	4.9% chry
OT-09-293-0433	Layer 2 - black mastic	M	NF	8	162	1	B128 A	Southeast quadrant of room	2.8% chry
OT-09-293-0434	White 2x4 ceiling tile	M	NF	8	162	1	B-Hall	Southwest quadrant of hall outside room B101	ND
OT-09-293-0435	Sheetrock tape, mud	M	F	8	162	1	B-Hall	Southwest quadrant of hall outside room B1021	ND
OT-09-293-0436	Layer 1 - white 12x12 floor tile	M	NF	8	162	1	B122	Southwest quadrant of room	ND
OT-09-293-0436	Layer 2 - yellow mastic	M	NF	8	162	1	B122	Southwest quadrant of room	0.7% chry
OT-09-293-0437	14" coupling horizontal pipe - white wrap, foil backing, foam insulation	F	F	8	162	1	E139	Southwest corner of room	ND
OT-09-293-0438	Brown fire door panel	M	NF	8	162	1	A133 A	Southwest corner of room	ND
OT-09-293-0439	White 2x4 ceiling tile	M	F	8	162	1	A133 A	Southwest quadrant of room	ND
OT-09-293-0440	White spray-on insulation	S	F	8	162	1	F144	Northwest quadrant of room above ceiling tile	ND
OT-09-293-0441	Gray 12x12 floor tile, black mastic	M	NF	8	162	1	F144	Southwest quadrant of room	ND



ASBESTOS INSPECTION LOG

Client: Central Texas Veterans Health Care System
 Location: Olin E. Teague V. A. Medical Center
 1901 Veterans Memorial Drive, Temple, Texas

Date: October 21, 2009
 Inspector(s): Donald Joiner and Jerald Heidecker

NOTE: Red = Asbestos-containing Material Blue = Non Asbestos-containing Material Green = Non Asbestos-containing Material
 (determined by Point Count analysis)

Sample ID	Material Description	Material Category	Friability	Condition	Building	Floor	Room	Location	Asbestos % Type
OT-09-293-0442	Layer 1 - white 12x12 floor tile	M	NF	8	162	1	E141	Northeast quadrant of room	0.25% chry
OT-09-293-0442	Layer 2 - black mastic	M	NF	8	162	1	E141	Northeast quadrant of room	1.8% chry
OT-09-293-0443	Gray insulation, cloth backing panels	T	F	8	162	1	E100	Southwest quadrant of room around generator	ND
OT-09-293-0444	White tape, foil backing, yellow fiberglass duct insulation	T	F	8	162	1	E100	Southwest quadrant of room	ND
OT-09-293-0445	12" elbow - white wrap, pink foam insulation	T	F	8	162	1	E100	Southeast quadrant of room	ND
OT-09-293-0446	12" horizontal pipe - white wrap, foil backing, pink foam insulation	T	F	8	162	1	E100	Southeast quadrant of room	ND
OT-09-293-0447	48" tank - white wrap, foil backing, brown paper foil backing, white fiberglass insulation	T	F	8	162	1	E100	Northeast quadrant of room	ND
OT-09-293-0448	1" horizontal pipe - white wrap, yellow fiberglass insulation	T	F	8	162	1	E100	Northeast quadrant of room	ND
OT-09-293-0449	Layer 1 - brown 9x9 floor tile	M	NF	3	162	1	E137 A	Northwest quadrant of room	2.7% chry
OT-09-293-0449	Layer 2 - black mastic	M	NF	3	162	1	E137 A	Northwest quadrant of room	2.4% chry
OT-09-293-0450	Layer 1 - brown 9x9 floor tile	M	NF	8	162	1	E99	Northeast quadrant of room	1.8% chry
OT-09-293-0450	Layer 2 - black mastic	M	NF	8	162	1	E99	Northeast quadrant of room	1% chry



ASBESTOS INSPECTION LOG

Client: Central Texas Veterans Health Care System
 Location: Olin E. Teague V. A. Medical Center
 1901 Veterans Memorial Drive, Temple, Texas

Date: October 21, 2009
 Inspector(s): Donald Joiner and Jerald Heidecker

NOTE: Red = Asbestos-containing Material Blue = Non Asbestos-containing Material Green = Non Asbestos-containing Material
 (determined by Point Count analysis)

Sample ID	Material Description	Material Category	Friability	Condition	Building	Floor	Room	Location	Asbestos % Type
OT-09-293-0451	8" elbow - white block insulation	T	F	8	162	1	E128	Northeast corner of room above ceiling tile	0.25% chry 0.5% amos
OT-09-293-0452	White 2x4 ceiling tile	M	F	8	162	1	E127	Southeast quadrant of room	ND
OT-09-293-0453	Tan cove molding, yellow mastic	M	NF	8	162	1	E127	Southeast corner of room	ND
OT-09-293-0454	2" horizontal pipe - white wrap, yellow fiberglass insulation	T	F	4	162	1	E104	Northeast corner of room	ND
OT-09-293-0455	Layer 1 - 2" T - white wrap	T	F	8	162	1	E103	Southeast quadrant of room	2% chry
OT-09-293-0455	2" T - foil backing	T	F	8	162	1	E103	Southeast quadrant of room	ND
OT-09-293-0455	2" T - yellow fiberglass insulation	T	F	8	162	1	E103	Southeast quadrant of room	ND
OT-09-293-0456	2" vertical pipe - white wrap, foil backing, yellow fiberglass insulation	T	F	8	162	1	E103	Southeast quadrant of room	ND
OT-09-293-0457	Layer 1 - brown 12x12 floor tile	M	NF	8	162	1	Clo.	East end of fire equipment closet	0.25% chry
OT-09-293-0457	Layer 2 - black mastic	M	NF	8	162	1	Clo.	East end of fire equipment closet	1.6% chry
OT-09-293-0458	Black mastic on piping	M	NF	8	162	1	E105	Southeast quadrant of room	ND
OT-09-293-0459	Sheetrock tape, mud	M	F	8	162	1	E108	Northeast quadrant of room	ND



ASBESTOS INSPECTION LOG

Client: Central Texas Veterans Health Care System
 Location: Olin E. Teague V. A. Medical Center
 1901 Veterans Memorial Drive, Temple, Texas

Date: October 21, 2009
 Inspector(s): Donald Joiner and Jerald Heidecker

NOTE: Red = Asbestos-containing Material Blue = Non Asbestos-containing Material Green = Non Asbestos-containing Material
 (determined by Point Count analysis)

Sample ID	Material Description	Material Category	Friability	Condition	Building	Floor	Room	Location	Asbestos % Type
OT-09-293-0460	2" horizontal pipe, white wrap, yellow fiberglass insulation	T	F	7	162	1	E120	Southeast quadrant of room	ND
OT-09-293-0461	6" vertical pipe - white wrap, yellow fiberglass insulation	T	F	7	162	1	E120	Southeast quadrant of room	ND
OT-09-293-0462	White tape, foil backing, yellow fiberglass duct insulation	M	F	8	162	1	E120	Northwest quadrant of room	ND
OT-09-293-0463	Blue 12x12 floor tile, yellow mastic	M	NF	8	162	1	C130	Northwest quadrant of room	ND
OT-09-293-0464	1" elbow - white wrap, white block insulation	T	F	6	162	1	C129	Southwest quadrant of room	3% amos
OT-09-293-0465	1" horizontal pipe - white wrap, yellow fiberglass insulation	T	F	6	162	1	C129	Southwest quadrant of room	ND
OT-09-293-0466	4" horizontal pipe - white wrap, yellow fiberglass insulation	T	F	6	162	1	C129	Southwest quadrant of room	ND
OT-09-293-0467	2" horizontal pipe - white wrap, white block insulation	T	F	4	162	1	C129	Southeast quadrant of room	ND
OT-09-293-0468	Layer 1 - yellow carpet mastic	M	NF	8	162	1	C128	Southwest corner of room	ND
OT-09-293-0468	Layer 2 - brown 12x12 floor tile	M	NF	8	162	1	C128	Southwest corner of room	ND
OT-09-293-0468	Layer 3 - black mastic	M	NF	8	162	1	C128	Southwest corner of room	0.9% chry
OT-09-293-0469	Wall plaster material	S	F	7	162	1	C100	Center of south wall above 2x4 ceiling tile	ND

ASBESTOS INSPECTION LOG



Client: Central Texas Veterans Health Care System
 Location: Olin E. Teague V. A. Medical Center
 1901 Veterans Memorial Drive, Temple, Texas

Date: October 21, 2009
 Inspector(s): Donald Joiner and Jerald Heidecker

NOTE: Red = Asbestos-containing Material Blue = Non Asbestos-containing Material Green = Non Asbestos-containing Material
 (determined by Point Count analysis)

Sample ID	Material Description	Material Category	Friability	Condition	Building	Floor	Room	Location	Asbestos % Type
OT-09-293-0470	8" elbow - white wrap, yellow foam insulation	T	F	8	162	1	C117	Northwest quadrant of room	ND
OT-09-293-0471	8" horizontal pipe - white wrap, foil backing, yellow foam insulation	T	F	8	162	1	C117	Northwest quadrant of room	ND
OT-09-293-0472	8" elbow - white wrap, white block insulation	T	F	8	162	1	C121	Southeast quadrant of room	0.25% chry 3.25% amos
OT-09-293-0473	Layer 1 - yellow carpet mastic	M	NF	8	162	1	C Hall West	Southwest corner of hall outside room C122	ND
OT-09-293-0473	Layer 2 - brown 12x12 floor tile	M	NF	8	162	1	C Hall West	Southwest corner of hall outside room C122	<0.25% chry
OT-09-293-0473	Layer 3 - black mastic	M	NF	8	162	1	C Hall West	Southwest corner of hall outside room C122	1.5% chry
OT-09-293-0474	Gray cove molding, yellow mastic	M	NF	8	162	1	C Hall West	Southwest corner of hall outside room C122	ND
OT-09-293-0475	Plaster wall overspray material	S	F	8	162	1	C122	Southeast quadrant of room	ND
OT-09-293-0476	8" elbow - white wrap, black mastic, yellow fiberglass insulation	T	F	8	162	1	C123 A	Southwest quadrant of room	ND
OT-09-293-0477	1" elbow - white wrap, white block insulation	T	F	8	162	1	C123	Northwest quadrant of room	1.25% amos 0.25% chry
OT-09-293-0478	3" valve - white wrap, white block insulation	T	F	8	162	1	C123	Northwest quadrant of room	ND



ASBESTOS INSPECTION LOG

Client: Central Texas Veterans Health Care System
 Location: Olin E. Teague V. A. Medical Center
 1901 Veterans Memorial Drive, Temple, Texas

Date: October 21, 2009
 Inspector(s): Donald Joiner and Jerald Heidecker

NOTE: Red = Asbestos-containing Material Blue = Non Asbestos-containing Material Green = Non Asbestos-containing Material
 (determined by Point Count analysis)

Sample ID	Material Description	Material Category	Friability	Condition	Building	Floor	Room	Location	Asbestos % Type
OT-09-293-0479	3" horizontal pipe hanger - white wrap, white block insulation	T	F	8	162	1	C123	Northwest quadrant of room	ND
OT-09-293-0480	2"elbow - white wrap, white block insulation	T	F	8	162	1	C123	Northwest quadrant of room	<1% chry <1% amos
OT-09-293-0481	2" horizontal pipe - white wrap, yellow fiberglass insulation	T	F	8	162	1	C123	Northwest quadrant of room	ND
OT-09-293-0482	4" elbow - white wrap, white block insulation	T	F	8	162	1	C144	Southwest quadrant of room C144 above ceiling tile	1.25% amos 0.25% chry
OT-09-293-0483	4"horizontal pipe - white wrap, yellow fiberglass insulation	T	F	8	162	1	C144	Southwest quadrant of room C144 above ceiling tile	ND
OT-09-293-0484	2" elbow - white wrap, white block insulation	T	F	8	162	1	C144	Southwest quadrant of room C144 above ceiling tile	1.5% amos <0.25% chry
OT-09-293-0485	2" horizontal pipe - white wrap, yellow fiberglass insulation	T	F	8	162	1	C144	Southwest quadrant of room C144 above ceiling tile	ND
OT-09-293-0486	1" elbow - white wrap, white block insulation	T	F	8	162	1	C144	Southwest quadrant of room C144 above ceiling tile	1.75% amos 0.25% chry
OT-09-293-0487	1" horizontal pipe - white wrap, yellow fiberglass insulation	T	F	8	162	1	C144	Southwest quadrant of room C144 above ceiling tile	ND
OT-09-293-0488	Red 12x12 floor tile, yellow mastic	M	NF	8	162	1	C144	Southwest quadrant of room	ND

ASBESTOS INSPECTION LOG



Client: Central Texas Veterans Health Care System
 Location: Olin E. Teague V. A. Medical Center
 1901 Veterans Memorial Drive, Temple, Texas

Date: October 21, 2009
 Inspector(s): Donald Joiner and Jerald Heidecker

NOTE: Red = Asbestos-containing Material Blue = Non Asbestos-containing Material Green = Non Asbestos-containing Material
 (determined by Point Count analysis)

Sample ID	Material Description	Material Category	Friability	Condition	Building	Floor	Room	Location	Asbestos % Type
OT-09-293-0489	Light blue 12x12 floor tile, yellow mastic	M	NF	8	162	1	C144	Southwest corner of room	ND
OT-09-293-0490	2" valve - black mastic pipe tape	M	NF	8	162	1	C145	Northeast corner of room above ceiling tile	7% chry
OT-09-293-0491	8" elbow - white wrap, white block insulation	T	F	8	162	1	C145	Southeast quadrant of room above ceiling tile	1.75% amos 0.25% chry
OT-09-293-0492	6" horizontal pipe - white foil-backed wrap, black mastic, black rock insulation	T	F	8	162	1	C147	Northeast quadrant of room above ceiling tile	ND
OT-09-293-0493	1" elbow - white wrap, white block insulation	T	F	8	162	1	C138	Northeast quadrant of room above ceiling tile	1.50% amos 0.25% chry
OT-09-293-0494	1" horizontal pipe - white wrap, yellow fiberglass insulation	T	F	8	102	1	C138	Northeast quadrant of room C138 above ceiling tile	ND
OT-09-293-0495	4" horizontal pipe - brown foil-backed wrap, black mastic, black rock insulation	T	F	8	162	1	C151	Northeast quadrant of room above ceiling tile	ND
OT-09-293-0496	Layer 1 - light gray 12x12 floor tile	M	NF	8	162	1	Entry Hall	Southeast quadrant of east entry between rooms C156 and C157	ND
OT-09-293-0496	Layer 2 - yellow mastic	M	NF	8	162	1	Entry Hall	Southeast quadrant of east entry between rooms C156 and C157	ND
OT-09-293-0496	Layer 3 - brown 12x12 floor tile	M	NF	8	162	1	Entry Hall	Southeast quadrant of east entry between rooms C156 and C157	<0.25% chry
OT-09-293-0496	Layer 4 - black mastic	M	NF	8	162	1	Entry Hall	Southeast quadrant of east entry between rooms C156 and C157	<0.25% chry

ASBESTOS INSPECTION LOG



Client: Central Texas Veterans Health Care System
 Location: Olin E. Teague V. A. Medical Center
 1901 Veterans Memorial Drive, Temple, Texas

Date: October 21, 2009
 Inspector(s): Donald Joiner and Jerald Heidecker

NOTE: Red = Asbestos-containing Material Blue = Non Asbestos-containing Material Green = Non Asbestos-containing Material
 (determined by Point Count analysis)

Sample ID	Material Description	Material Category	Friability	Condition	Building	Floor	Room	Location	Asbestos % Type
OT-09-293-0497	2" elbow - plaster spray-on, white wrap, white block and yellow fiberglass insulation	T	F	8	162	1	C161	Northeast corner of room above ceiling tile	ND
OT-09-293-0498	2" horizontal pipe - white foil-backed wrap, yellow fiberglass insulation	T	F	8	162	1	C161	Northeast corner of room above ceiling tile	ND
OT-09-293-0499	Layer 1 - light gray 12x12 floor tile	M	NF	8	162	1	C161	Northwest corner of room	ND
OT-09-293-0499	Layer 2 - yellow mastic	M	NF	8	162	1	C161	Northwest corner of room	ND
OT-09-293-0499	Layer 3 - brown 12x12 floor tile	M	NF	8	162	1	C161	Northwest corner of room	ND
OT-09-293-0499	Layer 4 - black mastic	M	NF	8	162	1	C161	Northwest corner of room	<1% chry
OT-09-293-0500	Yellow carpet mastic, white 12x12 floor tile, yellow mastic	M	NF	8	162	1	C157	Southeast corner of room	ND
OT-09-293-0701	2"elbow - white wrap, yellow fiberglass insulation	T	F	8	162	1	C156	Southwest corner of room above ceiling tile	ND
OT-09-293-0702	8" elbow - white wrap, yellow fiberglass insulation	T	F	8	162	1	C156	Southwest quadrant of room above ceiling tile	ND
OT-09-293-0703	8" horizontal pipe - brown foil-backed wrap, yellow fiberglass insulation	T	F	8	162	1	C156	Southwest quadrant of room above ceiling tile	ND
OT-09-293-0704	White 2x4 ceiling tile	M	F	8	162	1	C156	Southwest quadrant of room	ND
OT-09-293-0705	Light gray 12x12 floor tile, yellow mastic	M	NF	8	162	1	C160	Northwest quadrant of room	ND

ASBESTOS INSPECTION LOG



Client: Central Texas Veterans Health Care System
 Location: Olin E. Teague V. A. Medical Center
 1901 Veterans Memorial Drive, Temple, Texas

Date: October 21, 2009
 Inspector(s): Donald Joiner and Jerald Heidecker

NOTE: Red = Asbestos-containing Material Blue = Non Asbestos-containing Material Green = Non Asbestos-containing Material
 (determined by Point Count analysis)

Sample ID	Material Description	Material Category	Friability	Condition	Building	Floor	Room	Location	Asbestos % Type
OT-09-293-0706	1" elbow - white wrap, white block insulation	T	F	8	162	1	C139	Northwest quadrant of room above ceiling tile	1.25% chry
OT-09-293-0707	1" horizontal pipe - white wrap, yellow fiberglass insulation	T	F	8	162	1	C139	Northwest quadrant of room above ceiling tile	ND
OT-09-293-0708	16" elbow - white wrap, black mastic, black rock insulation	T	F	8	162	1	E101	Southwest quadrant of room above ceiling tile	ND
OT-09-293-0709	14" horizontal pipe - white foil-backed wrap, black mastic, black rock insulation	T	F	8	162	1	E101	Southwest quadrant of room above ceiling tile	ND
OT-09-293-0710	Layer 1 - white 12x12 floor tile	M	NF	8	162	1	North Hall	Northwest quadrant of hall outside room C109	ND
OT-09-293-0710	Layer 2 - yellow mastic, black mastic	M	NF	8	162	1	North Hall	Northwest quadrant of hall outside room C109	0.6% chry
OT-09-293-0711	2" elbow - white wrap, white block insulation	T	F	7	162	1	C111	Southwest quadrant of room	1.5% amos 0.75% chry
OT-09-293-0712	2" horizontal pipe - white wrap, yellow fiberglass insulation	T	F	7	162	1	C111	Southwest quadrant of room	ND
OT-09-293-0713	Layer 1 - 10" elbow - white wrap	T	F	7	162	1	C111	Southwest quadrant of room	ND
OT-09-293-0713	Layer 2 - 10" elbow - white block insulation	T	F	7	162	1	C111	Southwest quadrant of room	1.25% amos 0.75% chry
OT-09-293-0714	10" horizontal pipe - white wrap, yellow fiberglass insulation	T	F	7	162	1	C111	Southwest quadrant of room	ND



ASBESTOS INSPECTION LOG

Client: Central Texas Veterans Health Care System
 Location: Olin E. Teague V. A. Medical Center
 1901 Veterans Memorial Drive, Temple, Texas

Date: October 21, 2009
 Inspector(s): Donald Joiner and Jerald Heidecker

NOTE: Red = Asbestos-containing Material Blue = Non Asbestos-containing Material Green = Non Asbestos-containing Material
 (determined by Point Count analysis)

Sample ID	Material Description	Material Category	Friability	Condition	Building	Floor	Room	Location	Asbestos % Type
OT-09-293-0715	Gray transite vent hood	M	NF	8	162	1	E109	Northeast quadrant of room	30% chry
OT-09-293-0716	Black lab top	M	NF	7	162	1	E109	Northeast quadrant of room	ND
OT-09-293-0717	Black sink backsplash board	M	NF	7	162	1	E109	Southeast quadrant of room	10% chry
OT-09-293-0718	Black sink coating	M	NF	8	162	1	E109	Southeast quadrant of room	ND
OT-09-293-0719	Gray transite vent hood	M	NF	7	162	1	E110	Southeast quadrant of room	20% chry
OT-09-293-0720	Black lab top	M	NF	7	162	1	E110	Southeast quadrant of room	ND
OT-09-293-0721	Black sink backsplash	M	NF	8	162	1	E110	Southwest quadrant of room	10% chry
OT-09-293-0722	2" elbow - white block insulation	T	F	1	162	1	A129	Southwest quadrant of room above plaster ceiling	40% chry
OT-09-293-0723	Layer 1 - 10" elbow - white wrap	T	F	8	162	1	Hall	Center hallway, southeast quadrant outside room A128A above ceiling tile	ND
OT-09-293-0723	Layer 2 - 10" elbow - white block insulation	T	F	8	162	1	Hall	Center hallway, southeast quadrant outside room A128A above ceiling tile	<1% amos
OT-09-293-0724	Layer 1 - brown 12x12 floor tile	M	NF	8	162	1	Fire	Fire equipment room, northwest quadrant	<0.25% chry
OT-09-293-0724	Layer 2 - black mastic	M	NF	8	162	1	Fire	Fire equipment room, northwest quadrant	0.9% chry



ASBESTOS INSPECTION LOG

Client: Central Texas Veterans Health Care System
 Location: Olin E. Teague V. A. Medical Center
 1901 Veterans Memorial Drive, Temple, Texas

Date: October 21, 2009
 Inspector(s): Donald Joiner and Jerald Heidecker

NOTE: Red = Asbestos-containing Material Blue = Non Asbestos-containing Material Green = Non Asbestos-containing Material
 (determined by Point Count analysis)

Sample ID	Material Description	Material Category	Friability	Condition	Building	Floor	Room	Location	Asbestos % Type
OT-09-293-0725	Brown cove molding, yellow mastic	M	NF	8	162	1	Fire	Fire equipment room, northwest quadrant	ND
OT-09-293-0726	1" elbow - white block insulation	T	F	8	162	1	West Hall	Southwest quadrant of west hallway above ceiling tile outside room A149	50% chry
OT-09-293-0727	Layer 1 - 1" horizontal pipe - white foil-backed wrap	T	F	8	162	1	West Hall	Southwest quadrant of west hallway above ceiling tile outside room A149	<1% chry
OT-09-293-0727	Layer 2 - 1" horizontal pipe - foil backing	T	F	8	162	1	West Hall	Southwest quadrant of west hallway above ceiling tile outside room A149	ND
OT-09-293-0727	Layer 3 - 1" horizontal pipe - black mastic	T	F	8	162	1	West Hall	Southwest quadrant of west hallway above ceiling tile outside room A149	ND
OT-09-293-0727	Layer 4 - 1" horizontal pipe - yellow fiberglass insulation	T	F	8	162	1	West Hall	Southwest quadrant of west hallway above ceiling tile outside room A149	ND
OT-09-293-0728	White 2x4 ceiling tile	M	F	8	162	1	A140	Southeast quadrant of room	ND
OT-09-293-0729	10" elbow - white wrap, white block insulation	T	F	8	162	1	A99	Southeast quadrant of classroom B above ceiling tile	<1% chry <1% amos
OT-09-293-0730	10" horizontal pipe - white wrap, yellow fiberglass insulation	T	F	8	162	1	A99	Southeast quadrant of classroom B above ceiling tile	ND
OT-09-293-0731	Layer 1 - 4" elbow - white wrap	T	F	8	162	1	A99	Southwest quadrant of classroom B above ceiling tile	ND
OT-09-293-0731	Layer 2 - 4" elbow - white block insulation	T	F	8	162	1	A99	Southwest quadrant of classroom B above ceiling tile	<1% amos
OT-09-293-0732	4" horizontal pipe - white wrap, yellow fiberglass insulation	T	F	8	162	1	A99	Southwest quadrant of classroom B above ceiling tile	ND