



LEAD BASED PAINT INSPECTION

**Bob Stump Veterans Affairs Medical Center
Building 117 – Outpatient Clinic**

**500 North Highway 89
Prescott, Arizona**


Order Number VA649-C10326

May 8, 2012

Prepared for:


Richard Trevino
Northern Arizona Veterans Affairs Health Care System
500 North Highway 89
Prescott, Arizona 86313

Prepared by:



Mr. Oulono Folau
EPA Lead Inspector

Reviewed by:



Joseph K. Palermo, REA, LEED® AP
Regional Manager

Project #11P-A3138



Executive Summary

As requested by the Northern Arizona Veterans Affairs Health Care System (NAVAHCS), IHI Environmental (IHI) conducted a Lead-based Paint (LBP) Inspection at the Building 117 – Outpatient Clinic facility located at the Bob Stump Veterans Affairs Medical Center, 500 North Highway 89, Prescott, Arizona.

The Lead-based Paint Inspection was performed to identify and locate lead-based paint at the facility. This inspection included a Paint Condition Inspection to identify Lead Hazards.

The following table summarizes the results.

XRF Samples	691
Positive for Lead (>1 mg/cm²)	11
Components in Poor Condition	0

Based on the results of the survey, lead-based paint was identified on several exterior and interior building components. The paint on all of the components was considered to be in either intact or fair condition, with some exceptions. None of the components containing lead-based paint were considered to be in poor condition. Based on HUD guidelines, all painted components that are considered LBP (>1.0 mg/cm²) and identified as being in poor condition, represent potential lead hazards.

There are no estimated costs for the abatement of lead-based painted components, as none of the components were determined to be in poor condition.

TABLE OF CONTENTS

EXECUTIVE SUMMARY

1.0	INTRODUCTION	1
1.1	Scope of Work	1
2.0	METHODOLOGY.....	1
2.1	Lead-paint Inspection.....	1
2.2	Paint Condition Inspection.....	1
3.0	RESULTS	2
3.1	Summary of LBP Inspection and Condition Results	2
4.0	LEAD HAZARD CONTROLS DISCUSSION	3
4.1	Lead Hazard Controls for LBP Hazards	3
5.0	CONCLUSIONS AND RECOMMENDATIONS.....	4
5.1	Lead-paint Hazards	4
6.0	COST ESTIMATES FOR ABATEMENT	4
7.0	REFERENCES.....	4
8.0	PROJECT LIMITATIONS	4

APPENDICES

Appendix A	Floor Plans
Appendix B	LBP Summary Sheet
Appendix C	XRF Data
Appendix D	Cost Estimates for Abatement
Appendix E	IHI Certification

Abbreviations and Definitions

ADEQ	Arizona Department of Environmental Quality
DEUR	ADEQ's Waste Programs – Remediation and Declaration of Environmental Use Restriction
AWP	ADEQ's Waste Programs
EPA	U.S. Environmental Protection Agency
EPCRA	Emergency Planning and Community Right-to-Know Act
Hazardous substance	A substance defined as a hazardous substance (Section 101(14) of CERCLA). In accordance with ASTM Standard E 1527, this definition includes petroleum products.
HUD	U.S. Department of Housing and Urban Development
HUD guidelines	HUD Guidelines for the Evaluation and Control of Lead-Based Paint Hazards in Housing, June 1995, US Department of Housing and Urban Development, (http://www.hud.gov/offices/lead/lbp/hudguidelines)
LBP	Lead-based Paint. HUD considers paint to be lead-based paint (LBP) if the concentration is 1.0 milligram of lead per square centimeter (1.0 mg/cm ²) or greater, or if the lead concentration is greater than 5,000 parts per million (ppm) or 0.5% by weight.
LBP Hazard	A lead-based paint “hazard” is any condition that causes exposure to lead from lead-contaminated dust, lead-contaminated soil, or lead-contaminated paint that is deteriorated or is present in accessible surfaces, friction surfaces, or impact surfaces that would result in adverse human health effects.
OSHA	Occupational Safety and Health Administration
RCRA	Resource Conservation and Recovery Act. The regulations which govern the identification, management, transportation, and disposal of hazardous wastes from “cradle to grave.”
VRP	ADEQ's Voluntary Remediation Program.

1.0 INTRODUCTION

The Northern Arizona Veterans Affairs Health Care System NAVAHCS retained IHI Environmental (IHI) to conduct a Lead-based Paint Inspection of the Bob Stump Veterans Affairs Medical Center facility, located at 500 North Highway 89, Prescott, Arizona.

1.1 Scope of Work

IHI was retained by NAVAHCS to conduct a Lead-based Paint Inspection (LBP) Inspection using methodology outlined in the HUD guidelines (HUD, 1995). Each painted space was analyzed using an X-ray fluorescence (XRF) spectrometer to determine the presence of lead-based paint. A sufficient number of samples were collected to meet HUD guidelines. This inspection included a Paint Condition Inspection to identify Lead Hazards.

The results, conclusions, and recommendations in this report are based on information identified during the performance of this inspection. If greater certainty or detail is needed to understand the risks associated with the presence of lead at the site, additional evaluation may be required. Floor plans of the building are presented in Appendix A.

2.0 METHODOLOGY

2.1 Lead-paint Inspection

The LBP Inspection was conducted by Mr. Oulono Folau, a Environmental Protection Agency (EPA)-accredited Lead Risk Assessor (PB-1056) on February 9, 2012.

Measurements for lead in paint were made using a *RMD LPA-1 Lead Paint Analyzer* (Serial Number 1195). The RMD non-destructively measures lead concentrations in painted surfaces, regardless of the number of paint layers present. Results are reported in mg/cm^2 .

Quality control procedures included checking the internal calibration of the XRF before and after the testing was completed by taking three consecutive measurements on a National Institute for Standards and Technology (NIST) standard with a known concentration of lead.

2.2 Paint Condition Inspection

IHI inspected the condition of each painted material at the site. The condition of painted surfaces was determined based on the criteria found in Table 1.

Table 1
Paint Conditions
(as defined by HUD)

Type of Building Component¹	Total Area of Deteriorated Paint on Each Component		
	Intact	Fair²	Poor³
Exterior components with large surface areas	Entire surface is intact	Less than or equal to 10 square feet	More than 10 square feet
Interior components with large surface areas (walls, ceilings, floors, doors)	Entire surface is intact	Less than or equal to 2 square feet	More than 2 square feet
Interior and exterior components with small surface areas (window sills, baseboards, soffits, trim)	Entire surface is intact	Less than or equal to 10 percent of the total surface area of the component	More than 10 percent of the total surface area of the component
Notes 1. Building component in this table refers to each individual component or side of building, not the combined surface area of all similar components in a room (e.g., a wall with 1 square foot of deteriorated paint is in “fair” condition, even if the other three walls in a room are intact). 2. Surfaces in “fair” condition should be repaired and/or monitored, but are not considered to be “lead-based paint hazards” as defined in by HUD guidelines. 3. Surfaces in “poor” condition are considered to be “lead-based paint hazards” as defined in HUD guidelines and should be addressed through abatement or interim controls.			

3.0 RESULTS

In accordance with federal law, this Lead-Paint Inspection was conducted by Mr. Oulono Folau. A copy of his current EPA certificate for conducting lead based paint activities is presented in Appendix E.

3.1 Summary of LBP Inspection and Condition Results

A summary of the samples which tested positive as LBP (Appendix B, Summary Report) show 11 components tested positive for LBP. None of the components were identified as both LBP and in poor condition. Based on the HUD guidelines, the components in poor condition represent a lead hazard at the site. A complete set of the XRF data is presented in Appendix C.

4.0 LEAD HAZARD CONTROLS DISCUSSION

As outlined in the HUD guidelines there are two different types of control options for lead hazards. These are interim (temporary) controls or permanent abatement. Interim controls are less expensive initially, but may be more expensive than abatement in the long run since they need to be re-evaluated and maintained more frequently. If all lead-based paint surfaces are abated or replaced, no re-evaluation is needed.

4.1 Lead Hazard Controls for LBP Hazards

As a measure of controlling LBP hazards at this site, there are several interim controls that can be utilized; however, these methods will require ongoing monitoring to assure that the existing hazard has not returned or new hazards developed. A listing of these controls is as follows:

- **Paint film stabilization:** This interim control involves repair or restoration of existing substrate, removal of the loose or deteriorated paint, and applying a new protective coating, such as a sealant or a new coat of non lead-based paint.
- **Lead dust reduction:** This interim control involves the ongoing cleaning of potential lead dust-impacted surfaces through the use of a HEPA vacuum in addition to wet washing the impacted components.
- **Impact surface elimination or reduction:** This interim control involves the reconfiguration of the building components to eliminate impact surfaces. This can include lining window tracks with vinyl guides or the narrowing of doors or windows to eliminate impact surfaces.

As a measure of permanent elimination of the LBP hazard at the site, there are several abatement options that can be selected. These options will eliminate the source of the lead hazard and do not require ongoing monitoring. A listing of permanent abatement measures are as follows:

- **Lead-based paint removal:** This method involves the removal of the lead-based paint from the building components, using approved methods, such as approved low temperature heat guns, wet sanding or scraping, in addition to a HEPA vacuuming, and/or the use of approved chemical strippers. These methods should only be performed by trained lead abatement contractors.
- **Component replacement:** This method involves the removal and complete replacement of impacted building components with non lead-based painted materials.

5.0 CONCLUSIONS AND RECOMMENDATIONS

5.1 Lead-paint Hazards

Based on HUD guidelines, all painted components that are considered LBP ($>1.0 \text{ mg/cm}^2$) and were identified as being in poor condition, represent lead hazards. IHI identified no components that represent a lead hazard at the facility. Recommended Controls for the abatement of components include either lead-based paint removal or component replacement.

6.0 COST ESTIMATES FOR ABATEMENT

Cost Estimates for the abatement of lead-based painted components in poor condition are presented in Appendix D. The cost estimates for the abatement of LBP hazards were derived by use of the RS Means Cost Guide and through IHI's experience in the local and regional markets. The cost estimate provided is for use in long-term budgeting and planning only and does not have a level of accuracy sufficient to be used as construction design cost estimates. The actual cost of LBP abatement is highly dependent on a number of factors such as the size of the job (single room or window, or an entire floor or building); the required time frame for removal; the time of year the job is conducted; and travel time and distance to the job for the contractor. Therefore, actual removal costs could vary significantly from these estimates. Materials replacement and consultant abatement management costs are not included in these estimates and can add 15 - 50% to the project costs.

7.0 REFERENCES

HUD, 1995. *Guidelines for the Evaluation and Control of Lead-Based Paint Hazards in Housing*, June 1995, US Department of Housing and Urban Development, (<http://www.hud.gov/offices/lead/lbp/hudguidelines>).

8.0 PROJECT LIMITATIONS

This project was performed using, as a minimum, practices consistent with standards acceptable within the industry at this time, and a level of diligence typically exercised by EH&S consultants performing similar services.

The procedures used attempt to establish a balance between the competing goals of limiting investigative and reporting costs and time, and reducing the uncertainty about unknown conditions. Therefore, because the findings of this report were derived from the scope, costs, time and other limitations, the conclusions should not be construed as a guarantee that all universal, toxic and/or hazardous wastes have been identified and fully evaluated.


Furthermore, IHI assumes no responsibility for omissions or errors resulting from inaccurate information, or data, provided by sources outside of IHI or from omissions or errors in public records.

It is emphasized that the final decision on how much risk to accept always remains with the client since IHI is not in a position to fully understand all of the client's needs. Clients with a greater aversion to risk may want to take additional actions while others, with less aversion to risk, may want to take no further action.


Appendix A

Floor Plans

V:\- 11 Projects\VA\MC11P-A3138 - VAMC Prescott Asb-LBP Insp\1 Drawings\SR_VA Asbestos Survey CAD\2004\11P-A3138-2-18-12\11P-A3138-Bldg 117.dwg, Attic, Pb, 2/20/2012 10:23:50 AM, mkeeb



Lead Sampling
Reference Key for
Typical Room



PROJECT No:	11P-A3138
SHEET:	AT_Pb
DRAWN BY:	MBradley
DATE:	02-14-12
REVISED BY:	
DATE:	
REVIEWED BY:	
DATE:	

Department of Veterans Affairs
Northern Arizona Veterans Affairs Health Care System (NAVAHCS)
Outpatient Clinic - Building 117
Prescott, Arizona
Lead Sampling Wall Reference Key : Attic Level

Appendix B

LBP Summary Sheet

SUMMARY REPORT OF LEAD PAINT INSPECTION FOR: Building 117 - Outpatient Clinic

Inspection Date: 02/09/12 IHI Environmental #11P-A3138
 Report Date: 4/12/2012 NAVAHCS Prescott, Arizona
 Abatement Level: 1.0
 Report No. 02/09/12 10:14
 Total Readings: 691 Actionable: 11
 Job Started: 02/09/12 10:14
 Job Finished: 02/10/12 13:18

Read No.	Wall	Structure	Location	Member	Paint Cond	Substrate	Paint Color	Lead (mg/cm ²)	Mode
Interior Room 001 1B-138									
007	A	Wall	U Ctr		I	cerami c	Cream	>9.9	QM
008	B	Wall	U Ctr		I	cerami c	Cream	>9.9	QM
009	C	Wall	U Ctr		I	cerami c	Cream	>9.9	QM
010	D	Wall	U Ctr		I	cerami c	Cream	>9.9	QM
Interior Room 028 1B-113									
172	B	Door	Lft	Rgt jamb	I	Metal	Cream	1.0	QM
Interior Room 037 1B-109									
227	A	Door	Ctr	Upper	I	Metal	Lt. Tan	1.5	QM
Interior Room 105 Stair 1									
642	D	Stairs	Ctr	Newel post	I	Metal	Yell ow	1.0	QM
Interior Room 106 Attic-201A									
658	B	Ceiling	Ctr		I	Metal	Cream	1.0	QM
Interior Room 108 Exterior									
689								1.0	Std
690								1.0	Std
683	C	Pipe	Lft		I	Metal	whi te	1.0	QM
Cal i brati on Readings									
----- End of Readings -----									

Appendix C

XRF Data

DETAILED REPORT OF LEAD PAINT INSPECTION FOR: Building 117 - Outpatient Clinic

Inspection Date: 02/09/12 IHI Environmental #11P-A3138
 Report Date: 4/12/2012 NAVAHCS Prescott, Arizona
 Abatement Level: 1.0
 Report No. 02/09/12 10:14
 Total Readings: 691
 Job Started: 02/09/12 10:14
 Job Finished: 02/10/12 13:18

Read No.	Wall	Structure	Location	Member	Paint Cond	Substrate	Paint Color	Lead (mg/cm ²)	Mode
Interior Room 001 1B-138									
007	A	Wall	U Ctr		I	cerami c	Cream	>9.9	QM
008	B	Wall	U Ctr		I	cerami c	Cream	>9.9	QM
009	C	Wall	U Ctr		I	cerami c	Cream	>9.9	QM
010	D	Wall	U Ctr		I	cerami c	Cream	>9.9	QM
011	D	Door	Ctr	Upper	I	Metal	Lt. Tan	0.0	QM
012	D	Door	Ctr	Rgt j amb	I	Metal	Lt. Tan	-0.3	QM
Interior Room 002 1B-139									
013	A	Wall	U Ctr		I	Drywal l	Cream	-0.4	QM
014	B	Wall	U Ctr		I	Drywal l	Cream	-0.2	QM
015	C	Wall	U Ctr		I	Drywal l	Cream	-0.2	QM
016	D	Wall	U Ctr		I	Drywal l	Cream	-0.1	QM
Interior Room 003 1B-140									
017	A	Wall	U Ctr		I	Drywal l	Cream	-0.2	QM
018	B	Wall	U Ctr		I	Drywal l	Cream	-0.1	QM
019	C	Wall	U Ctr		I	Drywal l	Cream	-0.2	QM
021	C	Door	Ctr	Upper	I	Wood	Cream	-0.2	QM
022	C	Door	Ctr	Rgt j amb	I	Wood	Cream	-0.1	QM
020	D	Wall	U Ctr		I	Drywal l	Cream	-0.3	QM
Interior Room 004 1B-143									
023	B	Wall	U Ctr		I	Drywal l	Cream	-0.2	QM
024	C	Wall	U Ctr		I	Drywal l	Cream	-0.1	QM
025	D	Wall	U Ctr		I	Drywal l	Cream	-0.1	QM
Interior Room 005 1B-144									
026	B	Wall	U Ctr		I	Drywal l	Cream	-0.2	QM
027	C	Wall	U Ctr		I	Drywal l	Cream	-0.1	QM
028	D	Wall	U Ctr		I	Drywal l	Cream	-0.3	QM
Interior Room 006 1B-145									
029	A	Wall	U Ctr		I	Drywal l	Cream	-0.3	QM
030	B	Wall	U Ctr		I	Drywal l	Cream	0.0	QM
031	D	Wall	U Ctr		I	Drywal l	Cream	-0.2	QM
Interior Room 007 1B-146									
032	A	Wall	U Ctr		I	Drywal l	Cream	-0.3	QM
033	B	Wall	U Ctr		I	Drywal l	Cream	-0.1	QM
034	C	Wall	U Ctr		I	Drywal l	Cream	0.0	QM
035	D	Wall	U Ctr		I	Drywal l	Cream	0.0	QM
Interior Room 008 1B-146A									
036	A	Wall	U Ctr		I	Drywal l	Cream	-0.1	QM
037	B	Wall	U Ctr		I	Drywal l	Cream	-0.1	QM
040	B	Door	Ctr	Upper	I	Metal	Cream	-0.1	QM

B117D. TXT									
041	B	Door	Ctr	Rgt jamb	I	Metal	Cream	-0.1	QM
038	C	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
039	D	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
Interior Room 009 1B-147									
042	A	Wall	U Ctr		I	Brick	Cream	-0.2	QM
043	B	Wall	U Ctr		I	Brick	Cream	0.0	QM
046	B	Door	Ctr	Upper	I	Metal	Blue	-0.1	QM
047	B	Door	Ctr	Rgt jamb	I	Metal	Tan	0.1	QM
044	C	Wall	U Ctr		I	Brick	Cream	-0.4	QM
045	D	Wall	U Ctr		I	Brick	Cream	-0.3	QM
Interior Room 010 1B-148									
048	A	Wall	U Ctr		I	Drywall	Cream	-0.3	QM
049	B	Wall	U Ctr		I	Drywall	Cream	0.0	QM
052	B	Door	Ctr	Upper	I	Metal	Cream	-0.1	QM
053	B	Door	Ctr	Rgt jamb	I	Metal	Cream	-0.1	QM
050	C	Wall	U Ctr		I	Drywall	Cream	0.0	QM
051	D	Wall	U Ctr		I	Drywall	Cream	-0.3	QM
Interior Room 011 1B-155									
054	A	Wall	U Ctr		I	Drywall	Cream	-0.3	QM
058	A	Door	Ctr	Upper	I	Metal	Cream	-0.2	QM
059	A	Door	Ctr	Rgt jamb	I	Metal	Cream	-0.1	QM
055	B	Wall	U Ctr		I	Drywall	Cream	-0.2	QM
061	B	Door	Ctr	Upper	I	Metal	Cream	-0.3	QM
060	B	Door	Ctr	Lft jamb	I	Metal	Cream	-0.2	QM
056	C	Wall	U Ctr		I	Drywall	Cream	-0.2	QM
057	D	Wall	U Ctr		I	Drywall	Cream	-0.3	QM
Interior Room 012 1B-154									
062	A	Wall	U Ctr		I	Drywall	Cream	-0.2	QM
063	B	Wall	U Ctr		I	Drywall	Cream	-0.3	QM
064	C	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
065	D	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
066	D	Door	Ctr	Upper	I	Metal	Cream	-0.1	QM
067	D	Door	Ctr	Rgt jamb	I	Metal	Cream	-0.2	QM
Interior Room 013 1B-149									
068	B	Wall	U Ctr		I	Drywall	Cream	-0.3	QM
069	C	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
070	D	Wall	U Ctr		I	Drywall	Cream	-0.2	QM
Interior Room 014 1B-151									
071	A	Wall	U Ctr		I	Drywall	Cream	-0.2	QM
072	B	Wall	U Ctr		I	Drywall	Lt. Blue	-0.2	QM
075	B	Door	Ctr	Upper	I	Metal	Cream	-0.2	QM
076	B	Door	Ctr	Rgt jamb	I	Metal	Cream	-0.1	QM
073	C	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
074	D	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
Interior Room 015 1B-162									
077	A	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
081	A	Wall	U Ctr		I	Drywall	Cream	-0.2	QM
078	B	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
082	B	Wall	U Ctr		I	Drywall	Cream	-0.2	QM
085	B	Door	Ctr	Upper	I	Metal	Cream	-0.3	QM
086	B	Door	Ctr	Rgt jamb	I	Metal	Cream	-0.1	QM
079	C	Wall	U Ctr		I	Drywall	Cream	-0.2	QM
083	C	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
080	D	Wall	U Ctr		I	Drywall	Cream	-0.3	QM
084	D	Wall	U Ctr		I	Drywall	Cream	-0.3	QM

B117D.TXT

Interior Room 016 1B-101

087	A	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
091	A	Door	Ctr	Upper	I	Metal	Tan	-0.1	QM
092	A	Door	Ctr	Lft jamb	I	Metal	Gray	-0.1	QM
088	B	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
089	C	Wall	U Ctr		I	Drywall	Cream	0.0	QM
090	D	Wall	U Ctr		I	Drywall	Cream	0.0	QM

Interior Room 017 1B-108

093	A	Wall	U Ctr		I	Drywall	Cream	-0.2	QM
096	A	Door	Ctr	Upper	I	Metal	Tan	0.0	QM
097	A	Door	Ctr	Lft jamb	I	Metal	Gray	-0.1	QM
094	B	Wall	U Ctr		I	Drywall	Cream	-0.2	QM
095	D	Wall	U Ctr		I	Drywall	Cream	-0.2	QM

Interior Room 018 1B-112

098	A	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
099	B	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
100	C	Wall	U Ctr		I	Drywall	Cream	-0.2	QM
101	D	Wall	U Ctr		I	Drywall	Cream	-0.3	QM
102	D	Door	Ctr	Upper	I	Metal	Cream	-0.3	QM
103	D	Door	Ctr	Lft jamb	I	Metal	Cream	-0.1	QM

Interior Room 019 1B-123

104	A	Wall	U Ctr		I	Drywall	Cream	-0.4	QM
105	B	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
106	C	Wall	U Ctr		I	Drywall	Cream	-0.1	QM

Interior Room 020 1B-136

107	A	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
111	A	Door	Ctr	Upper	I	Metal	Gray	-0.2	QM
112	A	Door	Ctr	Rgt jamb	I	Metal	Lt. Blue	-0.1	QM
117	B	Radiator	Ctr		I	Metal	Cream	-0.2	QM
108	B	Wall	U Ctr		I	Drywall	Cream	-0.2	QM
109	C	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
114	C	Door	Ctr	Upper	I	Metal	Cream	-0.2	QM
113	C	Door	Ctr	Rgt jamb	I	Metal	Cream	-0.2	QM
110	D	Wall	U Ctr		I	Drywall	Cream	-0.3	QM
115	D	Door	Ctr	Upper	I	Metal	Gray	0.0	QM
116	D	Door	Ctr	Rgt jamb	I	Metal	Cream	-0.2	QM

Interior Room 021 1B-134

118	A	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
119	B	Wall	U Ctr		I	Drywall	Cream	-0.4	QM
120	C	Wall	U Ctr		I	Drywall	Cream	-0.3	QM
122	C	Door	Ctr	Upper	I	Metal	Cream	-0.1	QM
123	C	Door	Ctr	Rgt jamb	I	Metal	Cream	-0.3	QM
121	D	Wall	U Ctr		I	Drywall	Cream	-0.2	QM

Interior Room 022 1B-152

124	A	Wall	U Ctr		I	Drywall	Cream	0.1	QM
125	B	Wall	U Ctr		I	Drywall	Cream	-0.2	QM
126	C	Wall	U Ctr		I	Drywall	Cream	-0.3	QM
127	D	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
128	D	Door	Ctr	Upper	I	Metal	Cream	0.0	QM
129	D	Door	Ctr	Rgt jamb	I	Metal	Cream	0.4	QM

Interior Room 023 1B-158

130	A	Wall	U Ctr		I	Drywall	Cream	-0.2	QM
131	B	Wall	U Ctr		I	Drywall	Purple	-0.1	QM
132	C	Wall	U Ctr		I	Drywall	Cream	-0.2	QM
133	D	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
134	D	Door	Ctr	Upper	I	Metal	Cream	-0.2	QM

B117D. TXT									
135	D	Door	Ctr	Rgt jamb	I	Metal	Cream	-0.2	QM
Interior Room 024 1B-160									
136	A	Wall	U Ctr		I	Drywall	Cream	-0.3	QM
137	B	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
138	C	Wall	U Ctr		I	Drywall	Cream	0.1	QM
139	D	Wall	U Ctr		I	Drywall	Cream	0.0	QM
140	D	Door	Ctr	Upper	I	Metal	Cream	-0.1	QM
141	D	Door	Ctr	Rgt jamb	I	Metal	Cream	0.0	QM
Interior Room 025 1B-106									
142	A	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
146	A	Door	Ctr	Upper	I	Metal	Cream	0.6	QM
147	A	Door	Ctr	Rgt jamb	I	Metal	Cream	0.0	QM
143	B	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
144	C	Wall	U Ctr		I	Drywall	Cream	-0.2	QM
145	D	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
Interior Room 026 1B-105									
148	A	Wall	U Ctr		I	Drywall	Cream	0.3	QM
149	B	Wall	U Ctr		I	Drywall	Cream	0.3	QM
150	C	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
155	C	Door	Ctr	Upper	I	Metal	Lt. Blue	-0.2	QM
154	C	Door	Ctr	Lft jamb	I	Metal	Tan	0.0	QM
151	D	Wall	U Ctr		I	Drywall	Blue	-0.1	QM
152	D	Door	Ctr	Upper	I	Metal	Cream	0.2	QM
153	D	Door	Ctr	Lft jamb	I	Metal	Tan	-0.2	QM
Interior Room 027 1B-115									
156	A	Wall	U Ctr		I	Drywall	Cream	0.0	QM
157	B	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
161	B	Door	Lft	Upper	I	Metal	Cream	-0.1	QM
162	B	Door	Lft	Rgt jamb	I	Metal	Cream	0.2	QM
158	C	Wall	U Ctr		I	Drywall	Cream	0.1	QM
163	C	Door	Ctr	Rgt jamb	I	Metal	Cream	-0.1	QM
164	C	Door	Ctr	Rgt jamb	I	Metal	Cream	-0.1	QM
159	D	Wall	U Ctr		I	Drywall	Cream	0.0	QM
160	D	Column	Ctr		I	Drywall	Lt. Green	-0.2	QM
Interior Room 028 1B-113									
165	A	Wall	U Ctr		I	Drywall	Cream	0.3	QM
170	A	Door	Lft	Upper	I	Metal	Cream	-0.1	QM
171	A	Door	Lft	Rgt jamb	I	Metal	Cream	-0.1	QM
166	B	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
173	B	Door	Lft	Upper	I	Metal	Cream	0.0	QM
172	B	Door	Lft	Rgt jamb	I	Metal	Cream	1.0	QM
167	C	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
168	D	Wall	U Ctr		I	Drywall	Cream	-0.2	QM
169	D	Column	Ctr		I	Drywall	Cream	-0.3	QM
Interior Room 029 1B-114									
180	A	Truss	Ctr	Upper	I	Metal	Brown	0.2	QM
174	A	Wall	U Ctr		I	Drywall	Cream	-0.3	QM
178	A	Door	Ctr	Upper	I	Metal	Tan	-0.2	QM
179	A	Door	Ctr	Lft jamb	I	Metal	Tan	-0.2	QM
175	B	Wall	U Ctr		I	Drywall	Cream	0.1	QM
181	C	I-beam	Ctr	Upper	I	Metal	Orange	0.5	QM
182	C	I-beam	Ctr	Upper	I	Metal	Orange	0.4	QM
176	C	Wall	U Ctr		I	Drywall	Cream	-0.2	QM
177	D	Wall	U Ctr		I	Drywall	Cream	0.1	QM
Interior Room 030 1B-124									
183	A	Wall	U Ctr		I	Drywall	Cream	-0.1	QM

B117D. TXT									
184	B	Wall	U Ctr		I	Drywall	Cream	0.4	QM
185	C	Wall	U Ctr		I	Drywall	Cream	0.4	QM
187	C	Door	Rgt	Upper	I	Metal	Cream	0.2	QM
188	C	Door	Rgt	Lft casing	I	Metal	Cream	0.0	QM
186	D	Wall	U Ctr		I	Drywall	Cream	0.3	QM
Interior Room 031 1B-126									
189	A	Wall	U Ctr		I	Drywall	Cream	0.1	QM
190	B	Wall	U Ctr		I	Drywall	Cream	0.0	QM
191	C	Wall	U Ctr		I	Drywall	Cream	-0.2	QM
192	D	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
Interior Room 032 1B-127									
193	A	Wall	U Ctr		I	Drywall	Cream	0.1	QM
194	B	Wall	U Ctr		I	Drywall	Cream	0.0	QM
195	C	Wall	U Ctr		I	Drywall	Cream	-0.2	QM
197	C	Door	Ctr	Upper	I	Metal	Cream	0.0	QM
198	C	Door	Ctr	Lft jamb	I	Metal	Cream	-0.2	QM
196	D	Wall	U Ctr		I	Drywall	Cream	0.1	QM
Interior Room 033 1B-128									
199	A	Wall	U Ctr		I	Drywall	Cream	-0.3	QM
200	B	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
201	C	Wall	U Ctr		I	Drywall	Cream	0.0	QM
203	C	Door	Ctr	Upper	I	Metal	Cream	-0.1	QM
204	C	Door	Ctr	Rgt jamb	I	Metal	Cream	-0.2	QM
202	D	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
Interior Room 034 1B-125									
205	A	Wall	U Ctr		I	Drywall	Cream	0.0	QM
209	A	Door	Ctr	Upper	I	Metal	Cream	-0.1	QM
210	A	Door	Ctr	Lft casing	I	Metal	Cream	-0.1	QM
206	B	Wall	U Ctr		I	Drywall	Cream	-0.3	QM
207	C	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
208	D	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
Interior Room 035 1B-136									
211	A	Wall	U Ctr		I	Drywall	Cream	0.1	QM
212	B	Wall	U Ctr		I	Drywall	Cream	-0.2	QM
213	C	Wall	U Ctr		I	Plaster	Cream	-0.3	QM
215	C	Door	Rgt	Upper	I	Metal	Cream	0.0	QM
216	C	Door	Rgt	Lft jamb	I	Metal	Cream	-0.1	QM
214	D	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
Interior Room 036 1B-150									
217	A	Wall	U Ctr		I	Drywall	Green	-0.1	QM
218	B	Wall	U Ctr		I	Drywall	Yellow	-0.3	QM
219	C	Wall	U Ctr		I	Drywall	Yellow	-0.2	QM
220	D	Wall	U Ctr		I	Drywall	Yellow	-0.2	QM
221	D	Door	Ctr	Upper	I	Drywall	Tan	-0.1	QM
222	D	Door	Ctr	Rgt jamb	I	Drywall	Tan	-0.1	QM
Interior Room 037 1B-109									
223	A	Wall	U Ctr		I	Drywall	white	-0.2	QM
227	A	Door	Ctr	Upper	I	Metal	Lt. Tan	1.5	QM
228	A	Door	Ctr	Rgt jamb	I	Metal	Lt. Tan	0.0	QM
224	B	Wall	U Ctr		I	Drywall	white	-0.1	QM
225	C	Wall	U Ctr		I	Drywall	white	0.0	QM
226	D	Wall	U Ctr		I	Drywall	white	0.1	QM
229	D	Door	Ctr	Upper	I	Metal	white	0.2	QM
230	D	Door	Ctr	Rgt jamb	I	Metal	white	0.0	QM
Interior Room 038 1B-111									

B117D. TXT									
231	A	Wall	U Ctr		I	Drywall	Yellow	0.4	QM
232	B	Wall	U Ctr		I	Drywall	Yellow	0.1	QM
235	B	Door	Ctr	Upper	I	Metal	Cream	-0.1	QM
236	B	Door	Ctr	Rgt j amb	I	Metal	Cream	0.2	QM
233	C	Wall	U Ctr		I	Drywall	Yellow	0.0	QM
234	D	Wall	U Ctr		I	Drywall	Yellow	0.0	QM
Interior Room 039 1B-110									
237	A	Wall	U Ctr		I	Drywall	white	0.0	QM
238	B	Wall	U Ctr		I	Drywall	white	-0.1	QM
239	C	Wall	U Ctr		I	Drywall	white	0.0	QM
240	D	Wall	U Ctr		I	Drywall	white	-0.2	QM
241	D	Door	Ctr	Upper	I	Metal	white	-0.1	QM
242	D	Door	Ctr	Rgt j amb	I	Metal	white	-0.2	QM
Interior Room 040 1B-116									
243	A	Wall	U Ctr		I	Drywall	white	-0.1	QM
244	B	Wall	U Ctr		I	Drywall	white	-0.1	QM
247	B	Door	Ctr	Upper	I	Metal	white	-0.1	QM
248	B	Door	Ctr	Rgt j amb	I	Metal	white	-0.2	QM
245	C	Wall	U Ctr		I	Drywall	white	-0.1	QM
246	D	Wall	U Ctr		I	Drywall	white	-0.1	QM
Interior Room 041 1B-117									
249	A	Wall	U Ctr		I	Drywall	Tan	-0.1	QM
255	A	Wall	U Ctr		I	Drywall	white	-0.2	QM
250	B	Wall	U Ctr		I	Drywall	white	-0.1	QM
256	B	Wall	U Ctr		I	Drywall	white	0.1	QM
251	C	Wall	U Ctr		I	Drywall	white	-0.3	QM
257	C	Wall	U Ctr		I	Drywall	white	-0.1	QM
253	C	Door	Ctr	Upper	I	Metal	white	-0.1	QM
254	C	Door	Ctr	Lft j amb	I	Metal	white	-0.2	QM
252	D	Wall	U Ctr		I	Drywall	Tan	-0.2	QM
258	D	Wall	U Ctr		I	Drywall	white	-0.1	QM
Interior Room 042 1B-119									
259	A	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
260	B	Wall	U Ctr		I	Drywall	Cream	-0.2	QM
263	B	Door	Ctr	Upper	I	Metal	Cream	-0.2	QM
264	B	Door	Ctr	Rgt j amb	I	Metal	Cream	-0.1	QM
261	C	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
262	D	Wall	U Ctr		I	Drywall	Cream	-0.2	QM
Interior Room 043 1B-120									
265	B	Door	Ctr	Upper	I	Metal	Pink	-0.2	QM
266	B	Door	Ctr	Rgt j amb	I	Metal	Pink	-0.2	QM
Interior Room 044 1B-121									
267	B	Door	Ctr	Upper	I	Metal	Cream	-0.2	QM
268	B	Door	Ctr	Rgt j amb	I	Metal	Cream	0.2	QM
269	D	Pipe	Ctr		I	Metal	Red	-0.1	QM
Interior Room 045 1B-122									
273	B	Door	Ctr	Upper	I	Metal	Green	0.0	QM
274	B	Door	Ctr	Rgt j amb	I	Metal	Lt. Tan	-0.2	QM
272	C	Wall	U Ctr		I	Drywall	white	-0.2	QM
270	D	Wall	U Ctr		I	Drywall	white	0.1	QM
271	D	Floor	Ctr		I	Concrete	Gray	-0.2	QM
Interior Room 046 1B-129									
275	A	Wall	U Ctr		I	Drywall	Cream	-0.2	QM
279	B	Radiator	Ctr		I	Metal	Cream	-0.2	QM
276	B	Wall	U Ctr		I	Drywall	Cream	-0.1	QM

B117D. TXT									
281	B	Door	Ctr	Upper	I	Wood	Cream	-0.2	QM
280	B	Door	Ctr	Lft jamb	I	Metal	Cream	-0.2	QM
277	C	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
278	D	Wall	U Ctr		I	Drywall	Cream	-0.2	QM
Interior Room 047 1B-133									
282	A	Door	Ctr	Upper	I	Metal	Cream	-0.3	QM
283	A	Door	Ctr	Rgt jamb	I	Metal	Cream	-0.1	QM
Interior Room 048 1B-131									
284	B	Wall	U Ctr		I	Drywall	Cream	-0.3	QM
285	C	Wall	U Ctr		I	Drywall	Cream	-0.2	QM
286	D	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
Interior Room 049 1B-135									
287	A	Wall	U Ctr		I	Drywall	Cream	-0.3	QM
288	B	Wall	U Ctr		I	Drywall	Cream	0.0	QM
289	C	Wall	U Ctr		I	Drywall	Cream	-0.3	QM
291	C	Door	Ctr	Upper	I	Drywall	Cream	-0.1	QM
292	C	Door	Ctr	Lft jamb	I	Drywall	Cream	-0.2	QM
290	D	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
Interior Room 050 1B-132									
293	A	Wall	U Ctr		I	Drywall	Cream	0.0	QM
297	A	Door	Ctr	Upper	I	Wood	Cream	0.0	QM
298	A	Door	Ctr	Rgt jamb	I	Metal	Cream	-0.2	QM
294	B	Wall	U Ctr		I	Drywall	Cream	-0.3	QM
299	C	Radiator	Ctr		I	Metal	Cream	-0.2	QM
295	C	Wall	U Ctr		I	Drywall	Cream	-0.2	QM
296	D	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
Interior Room 051 1B-103									
300	A	Wall	U Ctr		I	Drywall	Green	-0.3	QM
301	B	Wall	U Ctr		I	Drywall	Green	-0.1	QM
302	C	Wall	U Ctr		I	Drywall	Green	-0.3	QM
304	C	Door	Ctr	Upper	I	Metal	Lt. Tan	-0.2	QM
305	C	Door	Ctr	Rgt jamb	I	Metal	Lt. Tan	-0.1	QM
303	D	Wall	U Ctr		I	Drywall	Green	-0.1	QM
Interior Room 052 1B-104									
306	A	Wall	U Ctr		I	Drywall	Green	0.0	QM
307	B	Wall	U Ctr		I	Drywall	Cream	-0.3	QM
308	C	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
310	C	Door	Ctr	Upper	I	Metal	Cream	-0.1	QM
311	C	Door	Ctr	Lft casing	I	Metal	Cream	-0.2	QM
309	D	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
Interior Room 053 1B-141									
312	A	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
313	B	Wall	U Ctr		I	Drywall	Cream	-0.2	QM
314	C	Wall	U Ctr		I	Drywall	Cream	0.0	QM
316	C	Door	Ctr	Upper	I	Metal	Lt. Tan	-0.2	QM
317	C	Door	Ctr	Rgt jamb	I	Metal	Lt. Tan	0.0	QM
315	D	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
Interior Room 054 1A-100									
318	B	Wall	U Ctr		I	Drywall	white	0.1	QM
319	D	Wall	U Ctr		I	Drywall	white	-0.1	QM
Interior Room 055 1A-101									
320	B	Wall	U Ctr		I	Drywall	Cream	0.0	QM
321	C	Wall	U Ctr		I	Drywall	Tan	-0.3	QM
322	D	Railing	Ctr	Balusters	I	Drywall	Cream	0.0	QM

323	D	Rail ling	Ctr	B117D. TXT Bal usters	I	Wood	Varni sh	-0. 2	QM
Interior Room 056 1A-102									
324	A	Wal l	U Ctr		I	Drywal l	Cream	-0. 1	QM
325	B	Wal l	U Ctr		I	Drywal l	Cream	-0. 2	QM
326	C	Wal l	U Ctr		I	Drywal l	Cream	-0. 1	QM
330	D	Chair Rai l	Ctr		I	Wood	Varni sh	-0. 1	QM
327	D	Wal l	U Ctr		I	Drywal l	Cream	-0. 2	QM
329	D	Door	Ctr	Upper	I	Metal	Bl ue	-0. 2	QM
328	D	Door	Ctr	Rgt j amb	I	Metal	Bl ue	-0. 2	QM
Interior Room 057 1A-106									
331	A	Wal l	U Ctr		I	Drywal l	Pi nk	-0. 2	QM
332	B	Wal l	U Ctr		I	Drywal l	Pi nk	-0. 2	QM
333	C	Wal l	U Ctr		I	Drywal l	Pi nk	-0. 1	QM
335	C	Door	Ctr	Upper	I	Metal	Gray	-0. 2	QM
336	C	Door	Ctr	Rgt j amb	I	Metal	Gray	-0. 2	QM
334	D	Wal l	U Ctr		I	Drywal l	Pi nk	-0. 2	QM
Interior Room 058 1A-104									
337	B	Wal l	U Ctr		I	Drywal l	Cream	-0. 3	QM
338	C	Wal l	U Ctr		I	Drywal l	Cream	0. 0	QM
340	C	Door	Ctr	Upper	I	Metal	Gray	-0. 1	QM
341	C	Door	Ctr	Rgt j amb	I	Metal	Gray	-0. 2	QM
339	D	Wal l	U Ctr		I	Drywal l	Cream	0. 1	QM
Interior Room 059 1A-108									
342	A	Wal l	U Ctr		I	Drywal l	Green	-0. 1	QM
343	B	Wal l	U Ctr		I	Drywal l	Cream	-0. 2	QM
344	C	Wal l	U Ctr		I	Drywal l	Cream	-0. 1	QM
346	C	Door	Ctr	Upper	I	Metal	Gray	-0. 1	QM
347	C	Door	Ctr	Lft casing	I	Metal	Gray	-0. 2	QM
345	D	Wal l	U Ctr		I	Drywal l	Cream	-0. 2	QM
Interior Room 060 1A-105									
348	A	Wal l	U Ctr		I	Drywal l	Cream	-0. 1	QM
352	A	Door	Ctr	Upper	I	Metal	Gray	0. 2	QM
355	A	Door	Ctr	Upper	I	Metal	Gray	0. 0	QM
353	A	Door	Ctr	Rgt j amb	I	Metal	Gray	-0. 1	QM
354	A	Door	Ctr	Rgt j amb	I	Metal	Gray	-0. 2	QM
349	B	Wal l	U Ctr		I	Drywal l	Cream	-0. 2	QM
350	C	Wal l	U Ctr		I	Drywal l	Cream	-0. 3	QM
351	D	Wal l	U Ctr		I	Drywal l	Cream	-0. 2	QM
Interior Room 061 1A-107									
356	A	Wal l	U Ctr		I	Drywal l	Cream	-0. 3	QM
361	A	Door	Ctr	Upper	I	Metal	Gray	0. 0	QM
362	A	Door	Ctr	Lft j amb	I	Metal	Gray	-0. 2	QM
357	B	Wal l	U Ctr		I	Drywal l	Cream	-0. 1	QM
358	C	Wal l	U Ctr		I	Drywal l	Cream	-0. 1	QM
359	D	Wal l	U Ctr		I	Drywal l	Cream	-0. 1	QM
360	D	Ceiling	Ctr		I	Drywal l	Cream	-0. 1	QM
Interior Room 062 1A-109									
363	A	Wal l	U Ctr		I	Drywal l	Cream	-0. 1	QM
364	B	Wal l	U Ctr		I	Drywal l	Cream	-0. 1	QM
365	C	Wal l	U Ctr		I	Drywal l	Cream	-0. 1	QM
366	D	Wal l	U Ctr		I	Drywal l	Cream	-0. 1	QM
367	D	Door	Ctr	Upper	I	Metal	Tan	-0. 1	QM
368	D	Door	Ctr	Rgt j amb	I	Metal	Tan	-0. 1	QM
Interior Room 063 1A-110									
369	A	Wal l	U Ctr		I	Drywal l	Yel low	-0. 2	QM

B117D. TXT										
370	B	Wall		U Ctr	Upper		Drywall	Cream	-0.1	QM
371	C	Wall		U Ctr			Drywall	Cream	0.0	QM
373	C	Door		Ctr			Metal	Gray	0.2	QM
372	D	Wall		U Ctr			Drywall	Cream	-0.1	QM
Interior Room 064 1A-111										
374	A	Wall		U Ctr	Upper Rgt jamb		Drywall	Tan	-0.1	QM
375	B	Wall		U Ctr			Drywall	Tan	-0.3	QM
376	C	Wall		U Ctr			Drywall	Tan	-0.2	QM
378	C	Door		Ctr			Metal	Gray	-0.1	QM
379	C	Door		Ctr			Metal	Gray	0.0	QM
377	D	Wall		U Ctr			Drywall	Tan	-0.2	QM
Interior Room 065 1A-112										
380	A	Wall		U Ctr	Upper Rgt jamb		Drywall	Cream	-0.1	QM
381	B	Wall		U Ctr			Drywall	Pink	-0.2	QM
382	C	Wall		U Ctr			Drywall	Cream	0.1	QM
383	D	Wall		U Ctr			Drywall	Cream	-0.1	QM
384	D	Door		Ctr			Metal	Gray	0.0	QM
385	D	Door		Ctr			Metal	Gray	-0.2	QM
Interior Room 066 1A-113										
386	A	Wall		U Ctr	Upper Rgt jamb		Drywall	white	-0.2	QM
387	B	Wall		U Ctr			Drywall	Green	-0.3	QM
388	C	Wall		U Ctr			Drywall	white	-0.3	QM
389	D	Wall		U Ctr			Drywall	white	0.1	QM
390	D	Door		Ctr			Metal	Gray	0.0	QM
391	D	Door		Ctr			Metal	Gray	0.0	QM
Interior Room 067 1A-114										
392	A	Wall		U Ctr	Upper Rgt jamb		Drywall	Cream	-0.1	QM
393	B	Wall		U Ctr			Drywall	Yellow	-0.2	QM
394	C	Wall		U Ctr			Drywall	Cream	-0.1	QM
395	D	Wall		U Ctr			Drywall	Cream	-0.2	QM
396	D	Door		Ctr			Metal	Gray	0.0	QM
397	D	Door		Ctr			Metal	Gray	-0.2	QM
Interior Room 068 1A-116										
398	A	Wall		U Ctr			Drywall	Yellow	-0.1	QM
399	C	Wall		U Ctr			Drywall	Yellow	-0.1	QM
400	D	Wall		U Ctr			Drywall	Yellow	0.0	QM
Interior Room 069 1A-118										
401	A	Wall		U Ctr	Upper Rgt jamb		Drywall	Cream	-0.2	QM
405	A	Door		Ctr			Metal	Gray	0.0	QM
406	A	Door		Ctr			Metal	Gray	-0.1	QM
402	B	Wall		U Ctr			Drywall	Green	-0.1	QM
403	C	Wall		U Ctr			Drywall	Cream	0.0	QM
404	D	Wall		U Ctr			Drywall	Cream	-0.1	QM
Interior Room 070 1A-119										
407	A	Wall		U Ctr	Upper Lft jamb		Drywall	Cream	-0.2	QM
411	A	Door		Ctr			Drywall	Gray	0.0	QM
412	A	Door		Ctr			Drywall	Gray	-0.1	QM
408	B	Wall		U Ctr			Drywall	Cream	-0.1	QM
409	C	Wall		U Ctr			Drywall	Cream	-0.3	QM
410	D	Wall		U Ctr			Drywall	Cream	-0.2	QM
Interior Room 071 1A-120										
413	A	Wall		U Ctr			Drywall	Cream	-0.3	QM
414	B	Wall		U Ctr			Drywall	Cream	-0.2	QM
415	C	Wall		U Ctr			Drywall	Cream	-0.1	QM
416	D	Wall		U Ctr			Drywall	Cream	-0.2	QM

B117D. TXT									
417	D	Door	Ctr	Upper	I	Metal	Gray	0.1	QM
418	D	Door	Ctr	Rgt j amb	I	Metal	Gray	-0.1	QM
Interior Room 072 1A-121									
419	A	Wall	U Ctr		I	Drywall	Cream	-0.2	QM
423	A	Door	Ctr	Upper	I	Metal	Gray	-0.1	QM
424	A	Door	Ctr	Lft j amb	I	Metal	Gray	0.0	QM
420	B	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
421	C	Wall	U Ctr		I	Drywall	Yellow	-0.1	QM
422	D	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
Interior Room 073 1A-122									
425	A	Wall	U Ctr		I	Drywall	Cream	-0.2	QM
426	B	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
427	C	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
429	C	Door	Ctr	Upper	I	Metal	Gray	0.2	QM
430	C	Door	Ctr	Rgt j amb	I	Metal	Gray	-0.1	QM
428	D	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
Interior Room 074 1A-117									
431	A	Wall	U Ctr		I	Drywall	Cream	-0.4	QM
432	B	Wall	U Ctr		I	Drywall	Pink	-0.2	QM
433	C	Wall	U Ctr		I	Drywall	Cream	-0.3	QM
434	D	Wall	U Ctr		I	Drywall	Cream	-0.2	QM
435	D	Door	Ctr	Upper	I	Metal	Gray	-0.1	QM
436	D	Door	Ctr	Rgt j amb	I	Metal	Gray	-0.2	QM
Interior Room 075 1A-123									
437	A	Wall	U Ctr		I	Drywall	Cream	-0.2	QM
443	A	Wall	U Ctr		I	Drywall	Cream	0.0	QM
438	B	Wall	U Ctr		I	Drywall	Cream	0.0	QM
444	B	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
439	C	Wall	U Ctr		I	Drywall	Pink	-0.1	QM
445	C	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
440	D	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
446	D	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
447	D	Ceiling	Ctr		I	Drywall	Cream	0.0	QM
441	D	Door	Ctr	Upper	I	Metal	Gray	-0.1	QM
448	D	Door	Ctr	Upper	I	Metal	Gray	0.3	QM
442	D	Door	Ctr	Rgt j amb	I	Metal	Gray	-0.1	QM
449	D	Door	Ctr	Rgt j amb	I	Metal	Gray	-0.2	QM
Interior Room 076 1A-125									
450	A	Wall	U Ctr		I	Drywall	Cream	0.0	QM
454	A	Door	Ctr	Upper	I	Metal	Gray	-0.1	QM
455	A	Door	Ctr	Lft j amb	I	Metal	Gray	-0.1	QM
451	B	Wall	U Ctr		I	Drywall	Cream	0.0	QM
452	C	Wall	U Ctr		I	Drywall	Green	0.0	QM
453	D	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
Interior Room 077 1A-127									
456	A	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
460	A	Door	Ctr	Upper	I	Metal	Gray	-0.1	QM
461	A	Door	Ctr	Rgt j amb	I	Metal	Gray	-0.1	QM
457	B	Wall	U Ctr		I	Drywall	Cream	-0.2	QM
458	C	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
459	D	Wall	U Ctr		I	Drywall	Cream	0.0	QM
Interior Room 078 1A-128									
462	A	Wall	U Ctr		I	Drywall	Cream	-0.2	QM
463	B	Wall	U Ctr		I	Drywall	Cream	-0.2	QM
468	B	Window	Ctr	Frame	I	Metal	Brown	0.0	QM
464	C	Wall	U Ctr		I	Drywall	Green	-0.2	QM

B117D. TXT									
466	C	Door	Ctr	Upper	I	Metal	Green	-0.1	QM
467	C	Door	Ctr	Rgt jamb	I	Metal	Green	-0.2	QM
465	D	Wall	U Ctr		I	Drywall	Green	-0.3	QM
Interior Room 079 1A-129									
469	A	Wall	U Ctr		I	Drywall	Tan	-0.2	QM
470	B	Wall	U Ctr		I	Drywall	Tan	-0.1	QM
471	C	Wall	U Ctr		I	Drywall	Tan	-0.2	QM
472	D	Wall	U Ctr		I	Drywall	Tan	-0.1	QM
473	D	Door	Ctr	Upper	I	Metal	Gray	-0.1	QM
474	D	Door	Ctr	Lft jamb	I	Metal	Gray	-0.2	QM
Interior Room 080 1A-131									
475	B	Wall	U Ctr		I	Drywall	Cream	-0.2	QM
479	B	Door	Ctr	Upper	I	Metal	Gray	0.2	QM
480	B	Door	Ctr	Lft jamb	I	Metal	Gray	-0.1	QM
478	C	partition	Ctr		I	Metal	Tan	-0.1	QM
476	D	Wall	U Ctr		I	Drywall	Cream	-0.2	QM
477	D	Ceiling	Ctr		I	Drywall	Cream	0.0	QM
Interior Room 081 1A-133									
492							-0.1 Std		
481	A	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
485	A	Door	Ctr	Header	I	Wood	Gray	-0.2	QM
486	A	Door	Ctr	Lft jamb	I	Metal	Gray	-0.1	QM
482	B	Wall	U Ctr		I	Drywall	Cream	-0.2	QM
483	C	Wall	U Ctr		I	Drywall	Cream	0.0	QM
484	D	Wall	U Ctr		I	Drywall	Cream	-0.2	QM
Interior Room 082 1A-135									
496	B	partition	Ctr		I	Metal	Tan	-0.1	QM
493	B	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
494	D	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
495	D	Ceiling	Ctr		I	Drywall	Cream	-0.1	QM
497	D	Door	Rgt	Upper	I	Metal	Tan	-0.1	QM
498	D	Door	Rgt	Lft jamb	I	Metal	Tan	-0.2	QM
Interior Room 083 1A-102A									
499	A	Wall	U Ctr		I	Drywall	Cream	-0.2	QM
504	A	Door	Ctr	Upper	I	Metal	Gray	-0.1	QM
505	A	Door	Ctr	Lft jamb	I	Metal	Gray	-0.2	QM
500	B	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
501	C	Wall	U Ctr		I	Drywall	Cream	-0.2	QM
502	D	Wall	U Ctr		I	Drywall	Cream	-0.3	QM
503	D	Ceiling	Ctr		I	Drywall	Cream	-0.1	QM
Interior Room 084 1A-133									
511	A	Wall	U Ctr		I	Drywall	Cream	0.1	QM
506	B	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
507	C	Wall	U Ctr		I	Drywall	Green	-0.2	QM
508	D	Wall	U Ctr		I	Drywall	Cream	-0.2	QM
509	D	Door	Rgt	Upper	I	Metal	Tan	-0.2	QM
510	D	Door	Rgt	Lft casing	I	Metal	Tan	-0.1	QM
Interior Room 085 1A-134									
512	A	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
513	B	Wall	U Ctr		I	Drywall	Pink	-0.2	QM
514	C	Wall	U Ctr		I	Drywall	Cream	-0.4	QM
516	C	Door	Lft	Upper	I	Metal	Tan	-0.1	QM
517	C	Door	Lft	Rgt jamb	I	Metal	Gray	-0.2	QM
519	C	Door	Rgt	Upper	I	Metal	Tan	-0.2	QM
518	C	Door	Rgt	Rgt jamb	I	Metal	Gray	-0.2	QM
515	D	Wall	U Ctr		I	Drywall	Green	-0.2	QM

B117D.TXT

Interior Room 086 1A-135										
520	A	Wall	U Ctr	Upper Rgt j amb	I	Drywal l	Cream	-0.4	QM	
524	A	Door	Rgt		I	Metal	Tan	-0.1	QM	
525	A	Door	Rgt		I	Metal	Gray	-0.2	QM	
521	B	Wall	U Ctr		I	Drywal l	Cream	-0.1	QM	
522	C	Wall	U Ctr		I	Drywal l	Pi nk	-0.2	QM	
523	D	Wall	U Ctr		I	Drywal l	Cream	-0.2	QM	
Interior Room 087 1A-136										
526	A	Wall	U Ctr	Upper Lft j amb	I	Drywal l	Cream	-0.2	QM	
527	B	Wall	U Ctr		I	Drywal l	Cream	-0.2	QM	
528	C	Wall	U Ctr		I	Drywal l	Cream	-0.1	QM	
531	C	Door	Ctr		I	Metal	Tan	-0.1	QM	
532	C	Door	Ctr		I	Metal	Tan	-0.1	QM	
529	D	Wall	U Ctr		I	Drywal l	Cream	-0.2	QM	
530	D	Ceiling	Ctr		I	Drywal l	Cream	-0.3	QM	
Interior Room 088 1A-137										
533	A	Wall	U Ctr	Upper Lft j amb	I	Drywal l	Cream	-0.1	QM	
537	A	Door	Ctr		I	Metal	Tan	-0.1	QM	
538	A	Door	Ctr		I	Metal	Gray	0.0	QM	
534	B	Wall	U Ctr		I	Drywal l	Cream	-0.3	QM	
535	C	Wall	U Ctr		I	Drywal l	Yel low	-0.4	QM	
536	D	Wall	U Ctr		I	Drywal l	Cream	-0.3	QM	
Interior Room 089 1A-138										
539	A	Wall	U Ctr	Upper Rgt j amb	I	Drywal l	Cream	-0.3	QM	
540	B	Wall	U Ctr		I	Drywal l	Cream	-0.1	QM	
541	C	Wall	U Ctr		I	Drywal l	Cream	-0.2	QM	
543	C	Door	Ctr		I	Metal	Tan	0.0	QM	
544	C	Door	Ctr		I	Metal	Gray	-0.2	QM	
542	D	Wall	U Ctr		I	Drywal l	Cream	-0.1	QM	
Interior Room 090 1A-139										
545	A	Wall	U Ctr	Upper Rgt j amb	I	Drywal l	Cream	-0.1	QM	
549	A	Door	Ctr		I	Metal	Tan	-0.1	QM	
550	A	Door	Ctr		I	Metal	Gray	0.0	QM	
546	B	Wall	U Ctr		I	Drywal l	Cream	-0.1	QM	
547	C	Wall	U Ctr		I	Drywal l	Green	0.1	QM	
548	D	Wall	U Ctr		I	Drywal l	Cream	-0.2	QM	
Interior Room 091 1A-141										
551	A	Wall	U Ctr	Upper Rgt j amb	I	Drywal l	Cream	0.0	QM	
556	A	Door	Ctr		I	Metal	Tan	0.0	QM	
557	A	Door	Ctr		I	Metal	Gray	-0.2	QM	
552	B	Wall	U Ctr		I	Drywal l	Cream	-0.1	QM	
553	C	Wall	U Ctr		I	Drywal l	Cream	-0.1	QM	
555	D	Pi pe	Ctr		I	Metal	Red	-0.2	QM	
554	D	Wall	U Ctr		I	Drywal l	Cream	-0.1	QM	
Interior Room 092 1A-142										
558	A	Wall	U Ctr	Upper Lft j amb	I	Drywal l	Cream	-0.2	QM	
559	B	Wall	U Ctr		I	Drywal l	Cream	-0.1	QM	
562	B	Door	Ctr		I	Drywal l	Tan	0.0	QM	
563	B	Door	Ctr		I	Drywal l	Gray	0.0	QM	
564	B	Door	Ctr		I	Drywal l	Gray	-0.1	QM	
560	C	Wall	U Ctr		I	Drywal l	Cream	-0.5	QM	
561	D	Wall	U Ctr		I	Drywal l	Pi nk	-0.4	QM	
Interior Room 093 1A-143										
565	A	Wall	U Ctr		I	Drywal l	Cream	-0.1	QM	
566	B	Wall	U Ctr		I	Drywal l	Cream	-0.1	QM	

B117D. TXT									
569	B	Door	Ctr	Upper	I	Metal	Tan	-0.2	QM
570	B	Door	Ctr	Rgt j amb	I	Metal	Gray	-0.1	QM
567	C	Wall	U Ctr		I	Drywal I	Cream	-0.1	QM
568	D	Wall	U Ctr		I	Drywal I	Yel low	-0.2	QM
Interior Room 094 1A-144									
571	A	Wall	U Ctr		I	Drywal I	Cream	-0.3	QM
572	B	Wall	U Ctr		I	Drywal I	Cream	-0.4	QM
573	C	Wall	U Ctr		I	Drywal I	Cream	0.0	QM
575	C	Door	Ctr	Upper	I	Metal	Tan	-0.2	QM
576	C	Door	Ctr	Lft j amb	I	Metal	Gray	-0.2	QM
574	D	Wall	U Ctr		I	Drywal I	Cream	-0.1	QM
Interior Room 095 1A-145									
577	A	Wall	U Ctr		I	Drywal I	Cream	-0.3	QM
578	B	Wall	U Ctr		I	Drywal I	Cream	-0.2	QM
579	C	Wall	U Ctr		I	Drywal I	Cream	0.0	QM
581	C	Door	Ctr	Upper	I	Metal	Tan	-0.2	QM
582	C	Door	Ctr	Rgt j amb	I	Metal	Gray	-0.1	QM
580	D	Wall	U Ctr		I	Drywal I	Green	-0.1	QM
Interior Room 096 1A-146									
583	A	Wall	U Ctr		I	Drywal I	Cream	-0.2	QM
584	B	Wall	U Ctr		I	Drywal I	Pi nk	-0.1	QM
585	C	Wall	U Ctr		I	Drywal I	Cream	-0.1	QM
587	C	Door	Ctr	Upper	I	Metal	Tan	-0.1	QM
588	C	Door	Ctr	Rgt j amb	I	Metal	Gray	-0.2	QM
586	D	Wall	U Ctr		I	Drywal I	Cream	-0.3	QM
Interior Room 097 1A-147									
589	A	Wall	U Ctr		I	Drywal I	Cream	-0.2	QM
590	B	Wall	U Ctr		I	Drywal I	Cream	-0.2	QM
593	B	Door	Ctr	Upper	I	Metal	Tan	-0.2	QM
594	B	Door	Ctr	Rgt j amb	I	Metal	Gray	-0.2	QM
591	C	Wall	U Ctr		I	Drywal I	Cream	-0.2	QM
592	D	Wall	U Ctr		I	Drywal I	Yel low	-0.2	QM
Interior Room 098 1A-149									
595	A	Wall	U Ctr		I	Drywal I	Green	-0.1	QM
596	B	Wall	U Ctr		I	Drywal I	Cream	-0.1	QM
597	C	Wall	U Ctr		I	Drywal I	Cream	-0.2	QM
599	C	Door	Ctr	Upper	I	Metal	Tan	-0.1	QM
600	C	Door	Ctr	Rgt j amb	I	Metal	Gray	-0.2	QM
598	D	Wall	U Ctr		I	Drywal I	Cream	-0.1	QM
Interior Room 099 1A-150									
601	A	Wall	U Ctr		I	Drywal I	Cream	-0.2	QM
605	A	Door	Ctr	Upper	I	Metal	Tan	-0.1	QM
606	A	Door	Ctr	Rgt j amb	I	Metal	Gray	-0.1	QM
602	B	Wall	U Ctr		I	Drywal I	Pi nk	-0.2	QM
603	C	Wall	U Ctr		I	Drywal I	Cream	-0.3	QM
604	D	Wall	U Ctr		I	Drywal I	Cream	0.0	QM
Interior Room 100 1A-151									
607	A	Wall	U Ctr		I	Drywal I	Pi nk	-0.3	QM
608	B	Wall	U Ctr		I	Drywal I	Cream	0.2	QM
609	C	Wall	U Ctr		I	Drywal I	Cream	0.5	QM
611	C	Door	Ctr	Upper	I	Metal	Tan	0.0	QM
612	C	Door	Ctr	Rgt j amb	I	Metal	Gray	-0.1	QM
610	D	Wall	U Ctr		I	Drywal I	Cream	0.3	QM
Interior Room 101 1A-152									
613	A	Wall	U Ctr		I	Drywal I	Cream	-0.1	QM

B117D. TXT									
618	A	Door	Ctr	Upper	I	Metal	Tan	0.1	QM
619	A	Door	Ctr	Rgt jamb	I	Metal	Gray	-0.2	QM
614	B	Wall	U Ctr		I	Drywall	Cream	-0.2	QM
615	C	Wall	U Ctr		I	Drywall	Cream	-0.3	QM
616	D	Wall	U Ctr		I	Drywall	Cream	0.0	QM
617	D	Ceiling	Ctr		I	Drywall	Cream	-0.2	QM
Interior Room 102 1A-153									
620	A	Wall	U Ctr		I	Drywall	Yellow	-0.2	QM
621	B	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
622	C	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
624	C	Door	Ctr	Upper	I	Metal	Tan	-0.1	QM
625	C	Door	Ctr	Rgt jamb	I	Metal	Gray	-0.3	QM
623	D	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
Interior Room 103 1A-154									
626	A	Wall	U Ctr		I	Drywall	Green	-0.2	QM
627	B	Wall	U Ctr		I	Drywall	Cream	-0.3	QM
628	C	Wall	U Ctr		I	Drywall	Cream	0.0	QM
630	C	Door	Ctr	Upper	I	Metal	Tan	-0.2	QM
631	C	Door	Ctr	Rgt jamb	I	Metal	Gray	-0.2	QM
629	D	Wall	U Ctr		I	Drywall	Cream	-0.3	QM
Interior Room 104 1A-102									
632	A	Wall	U Ctr		I	Drywall	Pink	-0.1	QM
633	B	Wall	U Ctr		I	Drywall	Cream	0.2	QM
634	C	Wall	U Ctr		I	Drywall	Cream	-0.3	QM
635	D	Wall	U Ctr		I	Drywall	Cream	0.3	QM
Interior Room 105 Stair 1									
636	A	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
645	A	Stairs	Ctr	Stringers	I	Metal	Yellow	0.1	QM
637	B	Wall	U Ctr		I	Drywall	Cream	-0.1	QM
647	B	Door	Ctr	Upper	I	Metal	Yellow	0.1	QM
648	B	Door	Ctr	Rgt jamb	I	Metal	Yellow	-0.1	QM
638	C	Wall	U Ctr		I	Concrete	Cream	0.7	QM
640	C	Stairs	Ctr	Railing	I	Metal	Yellow	0.0	QM
646	C	Stairs	Ctr	Post	I	Metal	white	-0.1	QM
644	C	Stairs	Ctr	Baseboard	I	Metal	Yellow	0.1	QM
641	C	Stairs	Ctr	Balusters	I	Metal	Yellow	-0.1	QM
639	D	Wall	U Ctr		I	Plaster	Cream	-0.1	QM
643	D	Stairs	Ctr	Risers	I	Metal	Yellow	0.2	QM
642	D	Stairs	Ctr	Newel post	I	Metal	Yellow	1.0	QM
Interior Room 106 Attic-201A									
649	A	Wall	U Ctr		I	Drywall	white	-0.2	QM
657	B	Truss	Ctr		I	Metal	Cream	0.0	QM
650	B	Wall	U Ctr		I	Drywall	white	-0.3	QM
658	B	Ceiling	Ctr		I	Metal	Cream	1.0	QM
655	B	Door	Ctr	Upper	I	Metal	Lt. Tan	0.0	QM
656	B	Door	Ctr	threshold	I	Metal	Yellow	-0.2	QM
654	B	Door	Ctr	Rgt jamb	I	Metal	Lt. Tan	-0.2	QM
651	C	Wall	U Ctr		I	Drywall	white	-0.2	QM
652	D	Wall	U Ctr		I	Drywall	white	-0.3	QM
653	D	Floor	Ctr		I	Concrete	Gray	-0.2	QM
Interior Room 107 Attic-201									
659	B	Wall	U Lft	Inner	I	Plaster	Cream	0.3	QM
664	C	Post	Lft		I	Metal	Brown	-0.2	QM
665	C	Post	Rgt		I	Metal	Brown	-0.2	QM
666	C	I-beam	Rgt		I	Metal	Brown	-0.1	QM
660	C	Wall	U Lft	Outer	I	Plaster	Cream	0.4	QM
663	C	Door	Ctr	Rgt jamb	I	Metal	Cream	-0.1	QM

				B117D. TXT					
662	C	Door	Rgt	Upper	I	Metal	Cream	0.3	QM
669	D	Truss	Lft		I	Metal	Brown	0.3	QM
667	D	I-beam	Ctr		I	Metal	Brown	-0.2	QM
668	D	Truss	Ctr		I	Metal	Brown	0.0	QM
661	D	Wall	U Rgt	Inner	I	Drywall	Cream	0.5	QM

Interior Room 108 Exterior

686								-0.1	Std
687								0.1	Std
688								0.0	Std
689								1.0	Std
690								1.0	Std
691								0.9	Std
673	A	Wall	U Lft		I	Stucco	white	0.4	QM
670	A	Wall	U Rgt		I	Stucco	white	0.5	QM
672	A	Window	Lft	Sill	I	Stucco	white	-0.2	QM
671	A	Window	Rgt	Sill	I	Stucco	white	-0.1	QM
675	A	Stairs	Lft	Railing	I	Metal	Lt. Gray	-0.2	QM
674	A	Stairs	Rgt	Railing	I	Metal	Lt. Gray	0.6	QM
676	B	Wall	U Rgt		I	Stucco	white	0.3	QM
677	B	Window	Rgt	Sill	I	Concrete	white	0.1	QM
678	B	Door	Ctr	Upper	I	Metal	white	-0.1	QM
679	B	Door	Ctr	Rgt jamb	I	Metal	white	-0.2	QM
680	B	Column	Lft		I	Stucco	white	0.3	QM
683	C	Pipe	Lft		I	Metal	white	1.0	QM
682	C	Wall	U Lft		I	Stucco	white	-0.1	QM
681	C	Wall	U Rgt		I	Stucco	white	0.2	QM
685	D	Wall	U Lft		I	Stucco	white	0.5	QM
684	D	Wall	U Rgt		I	Stucco	white	-0.1	QM

Calibration Readings

001								-0.1	Std
002								-0.1	Std
003								-0.2	Std
004								0.9	Std
005								0.8	Std
006								0.8	Std
487								1.1	Std
488								1.0	Std
489								1.0	Std
490								-0.1	Std
491								-0.2	Std

----- End of Readings -----

B117D. TXT

Appendix D
Cost Estimates

No lead-based paint components were determined to be in poor condition.

Appendix E
IHI Certifications

Jan 15 11 05:06a Robert Barclay 9705278546 P.5

CWD International, Inc. dba

Environmental Training Fund

39094.678CERT/PBIRE

900 N.W. 5TH Avenue, Fort Lauderdale, Florida 33311

(954) 524-7208 Processed By:

***This is to Certify that
Oulono Folau***



X X X - X X - 8 2 9 3

1729 W. 1000 N. , Salt Lake City, UT 84116

***has successfully completed an English
Lead 8 Hr. Building Inspector Refresher***

11-Jan-11

TO

11-Jan-11

Initial courses include an extensive hands-on component.

Complies with Sec. 402 TSCA 15 USC 2682 and Accredited by the IL-DPH, CT-DPH, MO-DOH, PA-DLI, TN-DOH, VA-DOH, WY-DOH, and the U.S. EPA.

Trainer(s): Robert Barclay

TEST SCORE: 96 Training Address: 640E. Wilmington Ave (700 E. 2200 S.), Salt Lake City, UT

Passed the hands-on assessment & completed the course exam on: 11-Jan-11

This Certificate Expires:

OSHA DATE: 11-Jan-12
SUNSET DATE: 10-Jan-14

10-Jan-14

GA-PreAudit

Seagull

To Authenticate Certificate
www.seagulltraining.com
1-800-966-9933

UNDER CIVIL AND CRIMINAL PENALTIES OF LAW FOR MAKING OR
PERMISSION OF FALSE OR FRAUDULENT STATEMENTS OR
RESERVATIONS (18 U.S.C. 1001 AND 1003), I
HEREBY CERTIFY THAT THIS TRAINING COURSE WITH APPLICABLE
REQUIREMENTS OF TITLE 40 CFR PART 171, "TOXIC SUBSTANCES
CONTROL ACT", 40 CFR PART 172, OR TOXIC SUBSTANCES
CONTROL ACT, FEDERAL, STATE OR LOCAL REQUIREMENTS, IS
APPROVED

James F. Stump, Training Manager

Certificate Number.....



1 4 6 6 4 8

Course Number UT1102

USEPA's actual expiration date will appear on individual's license. See individual state rules for actual state expiration date.