

### Building 31 – Community Living Center



Building No. 31 is the Community Living Center. The building is 31,328 ft<sup>2</sup> in size and was built in 1982. A total of two-hundred-two (202) samples were collected for Building 31, including layers. The construction materials sampled in Building 31 include:

- Drywall Systems
- Ceramic Tile Wall/Floor Systems
- Ceiling and Wall Plaster Systems
- Flooring Mastics, Sealants, Paints
- Exterior Stucco and Concrete Systems
- Exterior Window Glazing
- Interior & Exterior Caulking Systems and Various Sealants
- Roofing Penetration Mastics
- HVAC Mastics and Tapes

Note: There were no inaccessible areas of this building.

**Table 33. AHERA Risk Assessment Summary for Building 31.**

Homogenous Area(s)	Material Description	TSI (T)/Surfacing (S)/Misc.(M)	Condition (Good=1, Poor=7)	*Damage Assessment (1 - 7)	Potential For Future Damage (High, Mod., Low)	Friable Rating (Yes/No)
HA1	White window sealant	M	3	6	Low	No
HA2	Dark gray door sealant	M	3	6	Low	No
HA3	Gray door sealant	M	2	6	Low	No
HA4	Beige door sealant	M	2	6	Low	No
HA5	Gray window sealant	M	2	6	Low	No
HA6	Beige window sealant	M	2	6	Low	No

\*Damage Assessment Categories: Damaged or Significantly Damaged Friable TSI=1; Damaged Friable Surfacing Material=2; Significantly Damaged Friable Surfacing Material=3; Damaged or Significantly Damaged Friable Misc. Material=4; ACM w/ potential for significant damage=5; ACM w/ potential for damage=6; Any remaining friable ACM or assumed friable ACM=7.

‡Please refer to the drawings for the homogenous area (HA#) locations.

**Table 34. NESHAP Summary for Building 31.**

Material Description	Sample Location	Asbestos Type & Concentration	RACM/Cat. I*/Cat. II*	Quantity of ACM**
White exterior window sealant; Sample #s 12.9.19 527-529	Roof windows (N, SW & S)	8% Chrysotile	I	~486 ft <sup>2</sup>
Dark gray door sealant; Sample #s 12.9.20 548-550	Penthouse mechanical room (N), room 103 (S), NE hall @ room 102 entry	5% Chrysotile	I	~8 ft <sup>2</sup>
Gray door sealant; Sample # 12.9.20 551	Room 101 (NE)	4% Chrysotile	I	~4 ft <sup>2</sup>
Beige door sealant; Sample #s 12.9.20 552-554	Room 103 (NW), room 102 (NE), room 101 (E)	6% Chrysotile	I	~9 ft <sup>2</sup>
Gray window sealant; Sample #s 12.9.20 555-556	Room 172 (W), room 120 (N)	4% Chrysotile	I	~132 ft <sup>2</sup>
Beige window sealant; Sample # 12.9.20 557	Room 120 (N)	7% Chrysotile	I	~113 ft <sup>2</sup>

\*Indicates condition of material at the time of sampling. Category I and II Material may become friable and, thus, a Regulated Asbestos-Containing Material depending on the method of removal or potential for future damage. Material should be re-evaluated at the time of any project impacting these ACMs.

\*\*Quantities are approximate. These materials should be field verified prior to the start of any project impacted these ACMs.

Quantity Units: ft<sup>2</sup>=square feet, lf=linear feet, cf=cubic feet

**TABLE 1****Building Material Samples-ACM****VA FRESNO**

Sample No.	Sample Location	Material Type	Approx. Qty. (ft <sup>2</sup> )	Asbestos Content/Type	EPA Category <sup>1</sup>	Material Condition	See Figure
12.09.19- 501	Bldg. 31, Penthouse Mech. Rm. (NE)	Flooring Application	N/A	NAD	N/A	N/A	N/A
12.09.19- 501	Bldg. 31, Penthouse Mech. Rm. (NE)	Backing	N/A	NAD	N/A	N/A	N/A
12.09.19- 502	Bldg. 31, Penthouse Mech. Rm. (S)	Flooring Application	N/A	NAD	N/A	N/A	N/A
12.09.19- 502	Bldg. 31, Penthouse Mech. Rm. (S)	Backing	N/A	NAD	N/A	N/A	N/A
12.09.19- 503	Bldg. 31, Penthouse Mech. Rm. (W)	Flooring Application	N/A	NAD	N/A	N/A	N/A
12.09.19- 503	Bldg. 31, Penthouse Mech. Rm. (W)	Backing	N/A	NAD	N/A	N/A	N/A
12.09.19- 504	Bldg. 31, PH Mech. Rm. @ AC-1 Supply Door	HVAC Insulation	N/A	NAD	N/A	N/A	N/A

**TABLE 1****Building Material Samples-ACM****VA FRESNO**

Sample No.	Sample Location	Material Type	Approx. Qty. (ft <sup>2</sup> )	Asbestos Content/Type	EPA Category <sup>1</sup>	Material Condition	See Figure
12.09.19- 505	Bldg. 31, PH Mech. Rm. @ AC-2 Supply Door	HVAC Insulation	N/A	NAD	N/A	N/A	N/A
12.09.19- 506	Bldg. 31, PH Mech. Rm. @ AC-1 Return Duct	HVAC Tape	N/A	NAD	N/A	N/A	N/A
12.09.19- 507	Bldg. 31, PH Mech. Rm. @ AC-2 Return Duct	HVAC Tape	N/A	NAD	N/A	N/A	N/A
12.09.19- 508 A	Bldg. 31, PH Mech. Rm. @ AC-1 Return (N)	HVAC Tape	N/A	NAD	N/A	N/A	N/A
12.09.19- 508 A	Bldg. 31, PH Mech. Rm. @ AC-1 Return (N)	Texture	N/A	NAD	N/A	N/A	N/A
12.09.19- 508 B	Bldg. 31, PH Mech. Rm. @ AC-2 Return (N)	HVAC Tape	N/A	NAD	N/A	N/A	N/A
12.09.19- 508 B	Bldg. 31, PH Mech. Rm. @ AC-2 Return (N)	Texture	N/A	NAD	N/A	N/A	N/A

**TABLE 1****Building Material Samples-ACM****VA FRESNO**

<b>Sample No.</b>	<b>Sample Location</b>	<b>Material Type</b>	<b>Approx. Qty. (ft<sup>2</sup>)</b>	<b>Asbestos Content/Type</b>	<b>EPA Category<sup>1</sup></b>	<b>Material Condition</b>	<b>See Figure</b>
12.09.19- 509	Bldg. 31, PH Mech. Rm.	Gasket	N/A	NAD	N/A	N/A	N/A
12.09.19- 509	Bldg. 31, PH Mech. Rm.	Adhesive	N/A	NAD	N/A	N/A	N/A
12.09.19- 509	Bldg. 31, PH Mech. Rm.	Adhesive	N/A	NAD	N/A	N/A	N/A
12.09.19- 510	Bldg. 31, PH Mech. Rm.	Gasket	N/A	NAD	N/A	N/A	N/A
12.09.19- 510	Bldg. 31, PH Mech. Rm.	Adhesive	N/A	NAD	N/A	N/A	N/A
12.09.19- 510	Bldg. 31, PH Mech. Rm.	Adhesive	N/A	NAD	N/A	N/A	N/A
12.09.19- 511	Bldg. 31, PH Mech. Rm. (S)	Grout	N/A	NAD	N/A	N/A	N/A

**TABLE 1****Building Material Samples-ACM****VA FRESNO**

Sample No.	Sample Location	Material Type	Approx. Qty. (ft <sup>2</sup> )	Asbestos Content/Type	EPA Category <sup>1</sup>	Material Condition	See Figure
12.09.19- 512	Bldg. 31, PH Mech. Rm. (E)	Grout	N/A	NAD	N/A	N/A	N/A
12.09.19- 513	Bldg. 31, PH Mech. Rm. (W)	Grout	N/A	NAD	N/A	N/A	N/A
12.09.19- 514	Bldg. 31, PH Mech. Rm. (S. Side)	Sealant	N/A	NAD	N/A	N/A	N/A
12.09.19- 515	Bldg. 31, PH Mech. Rm. (E)	Sealant	N/A	NAD	N/A	N/A	N/A
12.09.19- 516	Bldg. 31, PH Mech. Rm. (W)	Sealant	N/A	NAD	N/A	N/A	N/A
12.09.19- 517	Bldg. 31, PH Mech. Rm. @ AC-2	Sealant	N/A	NAD	N/A	N/A	N/A
12.09.19- 518	Bldg. 31, PH Mech. Rm. @ AC-2	Sealant	N/A	NAD	N/A	N/A	N/A

**TABLE 1****Building Material Samples-ACM****VA FRESNO**

<b>Sample No.</b>	<b>Sample Location</b>	<b>Material Type</b>	<b>Approx. Qty. (ft<sup>2</sup>)</b>	<b>Asbestos Content/Type</b>	<b>EPA Category<sup>1</sup></b>	<b>Material Condition</b>	<b>See Figure</b>
12.09.19- 519	PH Mech. Rm. Entry on Interior, Bldg. 31	Sealant	N/A	NAD	N/A	N/A	N/A
12.09.19- 520	PH Mech. Rm. Entry on Exterior, Bldg. 31	Sealant	N/A	NAD	N/A	N/A	N/A
12.09.19- 521	Bldg. 31, Roof (N)	Flashing	N/A	NAD	N/A	N/A	N/A
12.09.19-522	Bldg. 31, Roof (E)	Flashing	N/A	NAD	N/A	N/A	N/A
12.09.19-523	Bldg. 31, Roof (W)	Flashing	N/A	NAD	N/A	N/A	N/A
12.09.19-524	Bldg. 31, Roof (S)	Sealant-1	N/A	NAD	N/A	N/A	N/A
12.09.19-524	Bldg. 31, Roof (S)	Sealant-2	N/A	NAD	N/A	N/A	N/A



**TABLE 1****Building Material Samples-ACM****VA FRESNO**

Sample No.	Sample Location	Material Type	Approx. Qty. (ft <sup>2</sup> )	Asbestos Content/Type	EPA Category <sup>1</sup>	Material Condition	See Figure
12.09.19-525	Bldg. 31, Roof (NW)	Sealant	N/A	NAD	N/A	N/A	N/A
12.09.19-526	Bldg. 31, Roof (E)	Sealant	N/A	NAD	N/A	N/A	N/A
12.09.19-527	Bldg. 31 (N)	Sealant	N/A	NAD	N/A	N/A	N/A
12.09.19-527	Bldg. 31 Roof (N)	Sealant (exterior white)	~486	8% Chrysotile	Cat I NF	Good	Fig. 1
12.09.19-528	Bldg. 31 (SW)	Sealant	N/A	NAD	N/A	N/A	N/A
12.09.19-528	Bldg. 31 (SW)	Sealant (exterior white)	~486	Not Analyzed/Stop Positive	N/A	N/A	Fig. 1
12.09.19-529	Bldg. 31 (S)	Sealant	N/A	NAD	N/A	N/A	N/A

**TABLE 1****Building Material Samples-ACM****VA FRESNO**

Sample No.	Sample Location	Material Type	Approx. Qty. (ft <sup>2</sup> )	Asbestos Content/Type	EPA Category <sup>1</sup>	Material Condition	See Figure
12.09.19-530	Bldg. 31 (E)	Sealant	N/A	NAD	N/A	N/A	N/A
12.09.19-530A	Bldg. 31 (W)	Sealant	N/A	NAD	N/A	N/A	N/A
12.09.19-531	Bldg. 31 (E)	Sealant	N/A	NAD	N/A	N/A	N/A
12.09.19-532	(NE)	Sealant	N/A	NAD	N/A	N/A	N/A
12.09.19-533	(W)	Sealant	N/A	NAD	N/A	N/A	N/A
12.09.19-534	(SE)	Sealant	N/A	NAD	N/A	N/A	N/A
12.09.19-535	Bldg. 31, Roof (Main Field, Mech./PH Upper Roof)	Asphalt Sheet Roof	N/A	NAD	N/A	N/A	N/A

**TABLE 1****Building Material Samples-ACM****VA FRESNO**

Sample No.	Sample Location	Material Type	Approx. Qty. (ft <sup>2</sup> )	Asbestos Content/Type	EPA Category <sup>1</sup>	Material Condition	See Figure
12.09.19-535	Bldg. 31, Roof (Main Field, Mech./PH Upper Roof)	Mastic	N/A	NAD	N/A	N/A	N/A
12.09.19-535	Bldg. 31, Roof (Main Field, Mech./PH Upper Roof)	Felt	N/A	NAD	N/A	N/A	N/A
12.09.19-536	Bldg. 31, Roof (Main Field, NW)	Asphalt Sheet Roof	N/A	NAD	N/A	N/A	N/A
12.09.19-536	Bldg. 31, Roof (Main Field, NW)	Mastic	N/A	NAD	N/A	N/A	N/A
12.09.19-536	Bldg. 31, Roof (Main Field, NW)	Felt	N/A	NAD	N/A	N/A	N/A
12.09.19-537	Bldg. 31, Roof (Main Field, W)	Asphalt Sheet Roof	N/A	NAD	N/A	N/A	N/A
12.09.19-537	Bldg. 31, Roof (Main Field, W)	Mastic	N/A	NAD	N/A	N/A	N/A

**TABLE 1****Building Material Samples-ACM****VA FRESNO**

Sample No.	Sample Location	Material Type	Approx. Qty. (ft <sup>2</sup> )	Asbestos Content/Type	EPA Category <sup>1</sup>	Material Condition	See Figure
12.09.19-537	Bldg. 31, Roof (Main Field, W)	Felt	N/A	NAD	N/A	N/A	N/A
12.09.19-538	Bldg. 31, Roof (Main Field, SE)	Asphalt Sheet Roof	N/A	NAD	N/A	N/A	N/A
12.09.19-538	Bldg. 31, Roof (Main Field, SE)	Mastic	N/A	NAD	N/A	N/A	N/A
12.09.19-538	Bldg. 31, Roof (Main Field, SE)	Felt	N/A	NAD	N/A	N/A	N/A
12.09.19-539	Bldg. 31, Roof (Main Field, E)	Asphalt Sheet Roof	N/A	NAD	N/A	N/A	N/A
12.09.19-539	Bldg. 31, Roof (Main Field, E)	Mastic	N/A	NAD	N/A	N/A	N/A
12.09.19-539	Bldg. 31, Roof (Main Field, E)	Felt	N/A	NAD	N/A	N/A	N/A

**TABLE 1****Building Material Samples-ACM****VA FRESNO**

<b>Sample No.</b>	<b>Sample Location</b>	<b>Material Type</b>	<b>Approx. Qty. (ft<sup>2</sup>)</b>	<b>Asbestos Content/Type</b>	<b>EPA Category<sup>1</sup></b>	<b>Material Condition</b>	<b>See Figure</b>
12.09.19-540	Bldg. 31, Roof (NW)	Stucco	N/A	NAD	N/A	N/A	N/A
12.09.19-541	Bldg. 31, Roof (N)	Stucco	N/A	NAD	N/A	N/A	N/A
12.09.19-542	Bldg. 31, Roof (E)	Stucco	N/A	NAD	N/A	N/A	N/A
12.09.19-543	Bldg. 31, Roof (S)	Stucco	N/A	NAD	N/A	N/A	N/A
12.09.19-544	Bldg. 31, Lower Wall (E)	Stucco	N/A	NAD	N/A	N/A	N/A
12.09.19-545	Bldg. 31, Lower Wall (SW)	Stucco	N/A	NAD	N/A	N/A	N/A
12.09.19-546	Bldg. 31, Lower Wall (SE)	Stucco	N/A	NAD	N/A	N/A	N/A

**TABLE 1****Building Material Samples-ACM****VA FRESNO**

Sample No.	Sample Location	Material Type	Approx. Qty. (ft <sup>2</sup> )	Asbestos Content/Type	EPA Category <sup>1</sup>	Material Condition	See Figure
12.09.19-547	Bldg. 31, PH Mech. Room (N)	Wallboard	N/A	NAD	N/A	N/A	N/A
12.09.19-547	Bldg. 31, PH Mech. Room (N)	Joint Compound	N/A	NAD	N/A	N/A	N/A
12.09.19-547	Bldg. 31, PH Mech. Room (N)	Composite (Wallboard/Joint Compound)	N/A	NAD	N/A	N/A	N/A
12.09.19-547	Bldg. 31, PH Mech. Room (N)	Paint	N/A	NAD	N/A	N/A	N/A
12.09.19-548	Bldg. 31, PH Mech. Room (N)	Sealant	N/A	NAD	N/A	N/A	N/A
12.09.19-549	Bldg. 31, Mec. Rm, NW Wing	Sealant	N/A	NAD	N/A	N/A	N/A
12.09.19-550	Bldg. 31, Mec. Rm, NW Wing	Sealant	N/A	NAD	N/A	N/A	N/A

**TABLE 1****Building Material Samples-ACM****VA FRESNO**

Sample No.	Sample Location	Material Type	Approx. Qty. (ft <sup>2</sup> )	Asbestos Content/Type	EPA Category <sup>1</sup>	Material Condition	See Figure
12.09.19-551	Bldg. 31, Mec. Rm, NW Wing	Base Cove	N/A	NAD	N/A	N/A	N/A
12.09.19-551	Bldg. 31, Mec. Rm, NW Wing	Mastic	N/A	NAD	N/A	N/A	N/A
12.09.19-552	Bldg. 31, NW Wing @ N. Door	Adhesive	N/A	NAD	N/A	N/A	N/A
12.09.19-553	Bldg. 31, Room 174	Grout	N/A	NAD	N/A	N/A	N/A
12.09.19-554	Bldg. 31, Room 174 (W)	Duct Tape	N/A	NAD	N/A	N/A	N/A
12.09.19-555	Bldg. 31, Room 174 (S)	Sealant	N/A	NAD	N/A	N/A	N/A
12.09.19-556	Bldg. 31, Room 174 (SE)	Adhesive	N/A	NAD	N/A	N/A	N/A

**TABLE 1****Building Material Samples-ACM****VA FRESNO**

Sample No.	Sample Location	Material Type	Approx. Qty. (ft <sup>2</sup> )	Asbestos Content/Type	EPA Category <sup>1</sup>	Material Condition	See Figure
12.09.19-557	Bldg. 31, Room 175C (N)	Grout	N/A	NAD	N/A	N/A	N/A
12.09.19-558	Bldg. 31, Room 175C (N)	Duct Tape	N/A	NAD	N/A	N/A	N/A
12.09.19-559	Bldg. 31, Room 175C (S)	Ceiling Tile	N/A	NAD	N/A	N/A	N/A
<b>09/20/2012</b>							
12.09.20-501	Bldg. 31, Dining Rm./Break Rm. (W)	Sheet Flooring	N/A	NAD	N/A	N/A	N/A
12.09.20-501	Bldg. 31, Dining Rm./Break Rm. (W)	Mastic	N/A	NAD	N/A	N/A	N/A
12.09.20-501	Bldg. 31, Dining Rm./Break Rm. (W)	Leveling Compound	N/A	NAD	N/A	N/A	N/A
12.09.20-502	Bldg. 31, Lobby (NE)	Sheet Flooring	N/A	NAD	N/A	N/A	N/A



**TABLE 1****Building Material Samples-ACM****VA FRESNO**

Sample No.	Sample Location	Material Type	Approx. Qty. (ft <sup>2</sup> )	Asbestos Content/Type	EPA Category <sup>1</sup>	Material Condition	See Figure
12.09.20-502	Bldg. 31, Lobby (NE)	Mastic	N/A	NAD	N/A	N/A	N/A
12.09.20-502	Bldg. 31, Lobby (NE)	Leveling Compound	N/A	NAD	N/A	N/A	N/A
12.09.20-503	Bldg. 31, East Wing Hall @ Nurse Desk	Sheet Flooring	N/A	NAD	N/A	N/A	N/A
12.09.20-503	Bldg. 31, East Wing Hall @ Nurse Desk	Mastic	N/A	NAD	N/A	N/A	N/A
12.09.20-504	Bldg. 31, South Wing, Adj. to Nurse Desk	Sheet Flooring	N/A	NAD	N/A	N/A	N/A
12.09.20-504	Bldg. 31, South Wing, Adj. to Nurse Desk	Mastic	N/A	NAD	N/A	N/A	N/A
12.09.20-504	Bldg. 31, South Wing, Adj. to Nurse Desk	Leveling Compound	N/A	NAD	N/A	N/A	N/A

**TABLE 1****Building Material Samples-ACM****VA FRESNO**

Sample No.	Sample Location	Material Type	Approx. Qty. (ft <sup>2</sup> )	Asbestos Content/Type	EPA Category <sup>1</sup>	Material Condition	See Figure
12.09.20-505	Bldg. 31, Room 179	VFT	N/A	NAD	N/A	N/A	N/A
12.09.20-505	Bldg. 31, Room 179	Adhesive	N/A	NAD	N/A	N/A	N/A
12.09.20-506	Bldg. 31, Room 172A (Locker Rm.) SW)	VFT	N/A	NAD	N/A	N/A	N/A
12.09.20-506	Bldg. 31, Room 172A (Locker Rm.) SW)	Mastic	N/A	NAD	N/A	N/A	N/A
12.09.20-507	Bldg. 31, Room 155 (NE)	VFT	N/A	NAD	N/A	N/A	N/A
12.09.20-507	Bldg. 31, Room 155 (NE)	Mastic	N/A	NAD	N/A	N/A	N/A
12.09.20-507	Bldg. 31, Room 155 (NE)	Compound	N/A	NAD	N/A	N/A	N/A

**TABLE 1****Building Material Samples-ACM****VA FRESNO**

Sample No.	Sample Location	Material Type	Approx. Qty. (ft <sup>2</sup> )	Asbestos Content/Type	EPA Category <sup>1</sup>	Material Condition	See Figure
12.09.20-508	Bldg. 31, Room 131 (W)	VFT	N/A	NAD	N/A	N/A	N/A
12.09.20-508	Bldg. 31, Room 131 (W)	Mastic	N/A	NAD	N/A	N/A	N/A
12.09.20-509	Bldg. 31, Room 120 (S)	VFT	N/A	NAD	N/A	N/A	N/A
12.09.20-509	Bldg. 31, Room 120 (S)	Mastic	N/A	NAD	N/A	N/A	N/A
12.09.20-510	Bldg. 31, Nurse Station (NE)	Ceiling Tile	N/A	NAD	N/A	N/A	N/A
12.09.20-510	Bldg. 31, Nurse Station (NE)	Mastic	N/A	NAD	N/A	N/A	N/A
12.09.20-510	Bldg. 31, Nurse Station (NE)	Wallboard	N/A	NAD	N/A	N/A	N/A

**TABLE 1****Building Material Samples-ACM****VA FRESNO**

Sample No.	Sample Location	Material Type	Approx. Qty. (ft <sup>2</sup> )	Asbestos Content/Type	EPA Category <sup>1</sup>	Material Condition	See Figure
12.09.20-511	Bldg. 31, Nurse Station (SW)	Ceiling Tile	N/A	NAD	N/A	N/A	N/A
12.09.20-511	Bldg. 31, Nurse Station (SW)	Joint Compound	N/A	NAD	N/A	N/A	N/A
12.09.20-511	Bldg. 31, Nurse Station (SW)	Wallboard	N/A	NAD	N/A	N/A	N/A
12.09.20-512	Bldg. 31, Nurse Station (Middle)	Ceiling Tile	N/A	NAD	N/A	N/A	N/A
12.09.20-512	Bldg. 31, Nurse Station (Middle)	Mastic	N/A	NAD	N/A	N/A	N/A
12.09.20-513	Bldg. 31, @ Custodial Door, Opposite of Room 165	Wallboard	N/A	NAD	N/A	N/A	N/A
12.09.20-513	Bldg. 31, @ Custodial Door, Opposite of Room 165	Joint Compound	N/A	NAD	N/A	N/A	N/A

**TABLE 1****Building Material Samples-ACM****VA FRESNO**

Sample No.	Sample Location	Material Type	Approx. Qty. (ft <sup>2</sup> )	Asbestos Content/Type	EPA Category <sup>1</sup>	Material Condition	See Figure
12.09.20-513	Bldg. 31, @ Custodial Door, Opposite of Room 165	Composite (Wallboard/Joint Compound)	N/A	NAD	N/A	N/A	N/A
12.09.20-514	Bldg. 31, Room 161 9S) @ R.R. Door	Wallboard	N/A	NAD	N/A	N/A	N/A
12.09.20-514	Bldg. 31, Room 161 9S) @ R.R. Door	Mastic	N/A	NAD	N/A	N/A	N/A
12.09.20-515	Bldg. 31, Room 143 Adj. to R.R. Door	Wallboard	N/A	NAD	N/A	N/A	N/A
12.09.20-515	Bldg. 31, Room 143 Adj. to R.R. Door	Mastic	N/A	NAD	N/A	N/A	N/A
12.09.20-515	Bldg. 31, Room 143 Adj. to R.R. Door	Adhesive	N/A	NAD	N/A	N/A	N/A
12.09.20-516	Bldg. 31, Room 146 Adj. to Sink	Wallboard	N/A	NAD	N/A	N/A	N/A

**TABLE 1****Building Material Samples-ACM****VA FRESNO**

Sample No.	Sample Location	Material Type	Approx. Qty. (ft <sup>2</sup> )	Asbestos Content/Type	EPA Category <sup>1</sup>	Material Condition	See Figure
12.09.20-516	Bldg. 31, Room 146 Adj. to Sink	Joint Compound	N/A	NAD	N/A	N/A	N/A
12.09.20-516	Bldg. 31, Room 146 Adj. to Sink	Composite (Wallboard/Joint Compound)	N/A	NAD	N/A	N/A	N/A
12.09.20-517	Bldg. 31, Room 121, E. Wing	Insulation	N/A	NAD	N/A	N/A	N/A
12.09.20-517	Bldg. 31, Room 121, E. Wing	Mastic	N/A	NAD	N/A	N/A	N/A
12.09.20-517	Bldg. 31, Room 121, E. Wing	Joint Compound	N/A	NAD	N/A	N/A	N/A
12.09.20-518	Bldg. 31, Room 120	Drywall	N/A	NAD	N/A	N/A	N/A
12.09.20-518	Bldg. 31, Room 120	Joint Compound	N/A	NAD	N/A	N/A	N/A

**TABLE 1****Building Material Samples-ACM****VA FRESNO**

<b>Sample No.</b>	<b>Sample Location</b>	<b>Material Type</b>	<b>Approx. Qty. (ft<sup>2</sup>)</b>	<b>Asbestos Content/Type</b>	<b>EPA Category<sup>1</sup></b>	<b>Material Condition</b>	<b>See Figure</b>
12.09.20-518	Bldg. 31, Room 120	DW/JC Composite	N/A	NAD	N/A	N/A	N/A
12.09.20-518	Bldg. 31, Room 120	Mastic	N/A	NAD	N/A	N/A	N/A
12.09.20-519	Bldg. 31, Dining Room (SE)	Drywall	N/A	NAD	N/A	N/A	N/A
12.09.20-519	Bldg. 31, Dining Room (SE)	Joint Compound	N/A	NAD	N/A	N/A	N/A
12.09.20-519	Bldg. 31, Dining Room (SE)	DW/JC Composite	N/A	NAD	N/A	N/A	N/A
12.09.20-519	Bldg. 31, Dining Room (SE)	Mastic-1	N/A	NAD	N/A	N/A	N/A
12.09.20-519	Bldg. 31, Dining Room (SE)	Mastic (2)	N/A	NAD	N/A	N/A	N/A

**TABLE 1****Building Material Samples-ACM****VA FRESNO**

<b>Sample No.</b>	<b>Sample Location</b>	<b>Material Type</b>	<b>Approx. Qty. (ft<sup>2</sup>)</b>	<b>Asbestos Content/Type</b>	<b>EPA Category<sup>1</sup></b>	<b>Material Condition</b>	<b>See Figure</b>
12.09.20-520	Bldg. 31, Room 178 (NW)	Base Cove	N/A	NAD	N/A	N/A	N/A
12.09.20-520	Bldg. 31, Room 178 (NW)	Mastic-1	N/A	NAD	N/A	N/A	N/A
12.09.20-520	Bldg. 31, Room 178 (NW)	Mastic-2	N/A	NAD	N/A	N/A	N/A
12.09.20-521	Bldg. 31, Din. Rm. (NW)	Base Cove	N/A	NAD	N/A	N/A	N/A
12.09.20-521	Bldg. 31, Din. Rm. (NW)	Adhesive	N/A	NAD	N/A	N/A	N/A
12.09.20-521	Bldg. 31, Din. Rm. (NW)	Joint Compound	N/A	NAD	N/A	N/A	N/A
12.09.20-522	Bldg. 31, Room 168 (E)	Base Cove	N/A	NAD	N/A	N/A	N/A



**TABLE 1****Building Material Samples-ACM****VA FRESNO**

<b>Sample No.</b>	<b>Sample Location</b>	<b>Material Type</b>	<b>Approx. Qty. (ft<sup>2</sup>)</b>	<b>Asbestos Content/Type</b>	<b>EPA Category<sup>1</sup></b>	<b>Material Condition</b>	<b>See Figure</b>
12.09.20-522	Bldg. 31, Room 168 (E)	Mastic-1	N/A	NAD	N/A	N/A	N/A
12.09.20-522	Bldg. 31, Room 168 (E)	Mastic-2	N/A	NAD	N/A	N/A	N/A
12.09.20-523	Bldg. 31, Room 165 (NW)	Base Cove	N/A	NAD	N/A	N/A	N/A
12.09.20-523	Bldg. 31, Room 165 (NW)	Mastic-1	N/A	NAD	N/A	N/A	N/A
12.09.20-523	Bldg. 31, Room 165 (NW)	Mastic-2	N/A	NAD	N/A	N/A	N/A
12.09.20-524	Bldg. 31, Room 164 (W)	Grout	N/A	NAD	N/A	N/A	N/A
12.09.20-525	Bldg. 31, S. Wing, Storage Room Adj. to Rm. 154	Base Cove	N/A	NAD	N/A	N/A	N/A

**TABLE 1****Building Material Samples-ACM****VA FRESNO**

<b>Sample No.</b>	<b>Sample Location</b>	<b>Material Type</b>	<b>Approx. Qty. (ft<sup>2</sup>)</b>	<b>Asbestos Content/Type</b>	<b>EPA Category<sup>1</sup></b>	<b>Material Condition</b>	<b>See Figure</b>
12.09.20-525	Bldg. 31, S. Wing, Storage Room Adj. to Rm. 154	Adhesive	N/A	NAD	N/A	N/A	N/A
12.09.20-526	Bldg. 31, Hall, S. Wing @ Room 150	Base Cove	N/A	NAD	N/A	N/A	N/A
12.09.20-526	Bldg. 31, Hall, S. Wing @ Room 150	Mastic-1	N/A	NAD	N/A	N/A	N/A
12.09.20-526	Bldg. 31, Hall, S. Wing @ Room 150	Mastic-2	N/A	NAD	N/A	N/A	N/A
12.09.20-527	Bldg. 31, Room 107 (W)	Base Cove	N/A	NAD	N/A	N/A	N/A
12.09.20-527	Bldg. 31, Room 107 (W)	Mastic-1	N/A	NAD	N/A	N/A	N/A
12.09.20-527	Bldg. 31, Room 107 (W)	Mastic-2	N/A	NAD	N/A	N/A	N/A

**TABLE 1****Building Material Samples-ACM****VA FRESNO**

Sample No.	Sample Location	Material Type	Approx. Qty. (ft <sup>2</sup> )	Asbestos Content/Type	EPA Category <sup>1</sup>	Material Condition	See Figure
12.09.20-527	Bldg. 31, Room 107 (W)	Mastic-3	N/A	NAD	N/A	N/A	N/A
12.09.20-528	Bldg. 31, Room 178 (S)	Wallboard	N/A	NAD	N/A	N/A	N/A
12.09.20-528	Bldg. 31, Room 178 (S)	Joint Compound	N/A	NAD	N/A	N/A	N/A
12.09.20-528	Bldg. 31, Room 178 (S)	Composite (Wallboard/Joint Compound)	N/A	NAD	N/A	N/A	N/A
12.09.20-529	Bldg. 31, Room 165 (W) @ Ceiling	Joint Compound	N/A	NAD	N/A	N/A	N/A
12.09.20-529	Bldg. 31, Room 165 (W) @ Ceiling	Paint	N/A	NAD	N/A	N/A	N/A
12.09.20-530	Bldg. 31, Room 107 (N)	Wall Canvas	N/A	NAD	N/A	N/A	N/A

**TABLE 1****Building Material Samples-ACM****VA FRESNO**

Sample No.	Sample Location	Material Type	Approx. Qty. (ft <sup>2</sup> )	Asbestos Content/Type	EPA Category <sup>1</sup>	Material Condition	See Figure
12.09.20-531	Bldg. 31, Room 121 (E. Wing)	Tape	N/A	NAD	N/A	N/A	N/A
12.09.20-532	Bldg. 31, Room 111	Tape	N/A	NAD	N/A	N/A	N/A
12.09.20-533	Bldg. 31, Kitchenette, S. of Rec. Rm. (SW)	Sink Insulation	N/A	NAD	N/A	N/A	N/A
12.09.20-534	Bldg. 31, Room 172 (SW))	Sink Insulation	N/A	NAD	N/A	N/A	N/A
12.09.20-535	Bldg. 31, Hall @ Room 169	Caulking	N/A	NAD	N/A	N/A	N/A
12.09.20-536	Bldg. 31, Office 177	Adhesive	N/A	NAD	N/A	N/A	N/A
12.09.20-537	Bldg. 31, Room 170	Adhesive	N/A	NAD	N/A	N/A	N/A

**TABLE 1****Building Material Samples-ACM****VA FRESNO**

Sample No.	Sample Location	Material Type	Approx. Qty. (ft <sup>2</sup> )	Asbestos Content/Type	EPA Category <sup>1</sup>	Material Condition	See Figure
12.09.20-538	Bldg. 31, Room 106B (S)	Adhesive	N/A	NAD	N/A	N/A	N/A
12.09.20-539	Bldg. 31, Room 114 (E. Wing)	Adhesive	N/A	NAD	N/A	N/A	N/A
12.09.20-540	Bldg. 31, Room 162	Sink Caulking	N/A	NAD	N/A	N/A	N/A
12.09.20-541	Bldg. 31, Men's R.R. (NE Corridor)	Sink Caulking	N/A	NAD	N/A	N/A	N/A
12.09.20-542	Bldg. 31, Women's R.R. (NE Corridor)	Sink Caulking	N/A	NAD	N/A	N/A	N/A
12.09.20-543	Bldg. 31, NE Corridor	Ceiling Tile	N/A	NAD	N/A	N/A	N/A
12.09.20-544	Bldg. 31, TV Room/Foyer (S)	Ceiling Tile	N/A	NAD	N/A	N/A	N/A

**TABLE 1****Building Material Samples-ACM****VA FRESNO**

Sample No.	Sample Location	Material Type	Approx. Qty. (ft <sup>2</sup> )	Asbestos Content/Type	EPA Category <sup>1</sup>	Material Condition	See Figure
12.09.20-545	Bldg. 31, NE Corridor	Ceiling Tile	N/A	NAD	N/A	N/A	N/A
12.09.20-546	Bldg. 31, Room (E)	Ceiling Tile	N/A	NAD	N/A	N/A	N/A
12.09.20-547	Bldg. 31, Room 111	Ceiling Tile	N/A	NAD	N/A	N/A	N/A
12.09.20-548	Bldg. 31, Recreation Room (SW)	Door sealant (dark gray)	~8	5% Chrysotile	Cat I NF	Good	Fig. 2
12.09.20-549	Bldg. 31, Break Rm./Dining Rm. (S)	Sealant	N/A	Not Analyzed/ Stop Positive	N/A	N/A	N/A
12.09.20-550	Bldg. 31, NE Corridor @ Din. Rm. Entry	Sealant	N/A	Not Analyzed/ Stop Positive	N/A	N/A	N/A
12.09.20-551	Bldg. 31, Kitchenette Rm. S. of Rec. Rm. (E)	Door sealant (gray)	~4	4% Chrysotile	Cat I NF	Good	Fig. 3

**TABLE 1****Building Material Samples-ACM****VA FRESNO**

Sample No.	Sample Location	Material Type	Approx. Qty. (ft <sup>2</sup> )	Asbestos Content/Type	EPA Category <sup>1</sup>	Material Condition	See Figure
12.09.20-552	Bldg. 31, Dining Rm./Break Rm. (NW)	Door sealant (beige)	~9	6% Chrysotile	Cat I NF	Good	Fig.4
12.09.20-553	Bldg. 31, Recreation Rm. (NE)	Sealant	N/A	Not Analyzed/ Stop Positive	N/A	N/A	N/A
12.09.20-554	Bldg. 31, Kitchenette Rm. S. of Rec. Rm. (E)	Sealant	N/A	Not Analyzed/ Stop Positive	N/A	N/A	N/A
12.09.20-555	Bldg. 31, Room 172 (W)	Window sealant (gray)	~132	4% Chrysotile	Cat I NF	Good	Fig. 5
12.09.20-556	Bldg. 31, Room 120 (N)	Sealant	N/A	Not Analyzed/ Stop Positive	N/A	N/A	N/A
12.09.20-557	Bldg. 31, Room 120 (N)	Window sealant (beige)	N/A	7% Chrysotile	Cat I NF	Good	Fig. 6
12.09.20-558	Bldg. 31, Room 172 (W)	Sealant	N/A	NAD	N/A	N/A	N/A

**TABLE 1****Building Material Samples-ACM****VA FRESNO**

Sample No.	Sample Location	Material Type	Approx. Qty. (ft <sup>2</sup> )	Asbestos Content/Type	EPA Category <sup>1</sup>	Material Condition	See Figure
12.09.20-559	Bldg. 31, Room 172A, R.R. (N)	Wall Tile	N/A	NAD	N/A	N/A	N/A
12.09.20-559	Bldg. 31, Room 172A, R.R. (N)	Grout	N/A	NAD	N/A	N/A	N/A
12.09.20-560	Bldg. 31, Room 172D, R.R. (E)	Grout	N/A	NAD	N/A	N/A	N/A
12.09.20-561	Bldg. 31, Custodial, Opposite of Rm. 165	Wall Tile	N/A	NAD	N/A	N/A	N/A
12.09.20-561	Bldg. 31, Custodial, Opposite of Rm. 165	Grout	N/A	NAD	N/A	N/A	N/A
12.09.20-562	Bldg. 31, Room 164 (NE)	Grout	N/A	NAD	N/A	N/A	N/A
12.09.20-562	Bldg. 31, Room 164 (NE)	Adhesive	N/A	NAD	N/A	N/A	N/A



**TABLE 1****Building Material Samples-ACM****VA FRESNO**

Sample No.	Sample Location	Material Type	Approx. Qty. (ft <sup>2</sup> )	Asbestos Content/Type	EPA Category <sup>1</sup>	Material Condition	See Figure
12.09.20-563	Bldg. 31, Room 164 (NW)	Grout	N/A	NAD	N/A	N/A	N/A
12.09.20-563	Bldg. 31, Room 164 (NW)	Adhesive	N/A	NAD	N/A	N/A	N/A
12.09.20-564	Bldg. 31, Storage Rm. Next to Room 154 (E)	Adhesive	N/A	NAD	N/A	N/A	N/A
12.09.20-564	Bldg. 31, Storage Rm. Next to Room 154 (E)	Paint	N/A	NAD	N/A	N/A	N/A
12.09.20-565	Bldg. 31, E. Wing, Rm. 120	Grout	N/A	NAD	N/A	N/A	N/A
120920-501	BLDG 3: HALLWAY RR FLOORING (NW)	Sheet Flooring	N/A	NAD	N/A	N/A	N/A
120920-502	BLDG 3: HALLWAY RR FLOORING (SW)	Sheet Flooring	N/A	NAD	N/A	N/A	N/A