

1 2 3 4 5 6 7 8 911 12 13 14 15 16 17 18 19

ALTERNATE 2 - REPAIR

Assume 475 S.F. Missing,
Broken and Cracked Slate

ALTERNATE 1 - REPAIR

Assume 475 S.F. Missing,
Broken and Cracked Slate

COURTYARD 2

58'-10 $\frac{1}{2}$ "

31'-6"


FLAT
ROOF

31'-6"

36'-6"

SHED

11'



Building 34
Roof Plan

FLAT
ROOF

A B C D E F G H I J K L

THREE INCHES EQUALS ONE FOOT
0 1 2 3 4 5

ONE AND ONE HALF INCHES EQUALS ONE INCH
0 1 2 3 4 5 6 7 8

THREE QUARTERS INCH EQUALS ONE FOOT
0 1 2 3 4 5 6 7 8

THREE EIGHTHS INCH EQUALS ONE FOOT
0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16

ONE QUARTER INCH EQUALS ONE FOOT
0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16

ONE EIGHTH INCH EQUALS ONE FOOT
0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16

LOCATION
CANANDAIGUA, NY 14424

NO.	DATE	DESCRIPTION
REVISIONS		
SHEET TITLE		
A4 - ALTERNATES 1 & 2		
PROJECT TITLE		
B34 ROOF REPAIR		
BLDG. NO.		
WCC		
CHECKED		
2-18-16		
DRAWING NUMBER		
5 of 5		
APPROVED		
CHIEF, ENGINEERING SERVICE		
15-507		
PROJECT NUMBER		
15-507		
APPROVED		
DIRECTOR, VAMC, CANANDAIGUA		
V.A. MEDICAL CENTER		

528A5-15-507