

REPAIR CLC COURTYARD

PRE-BID WALKTHROUGH QUESTIONS

08Feb2017

- 1) What was the basis of design for the pergola? Contractors would like to know so that they can research and provide cost to reflect a pergola that best fits into the intent of the project.

Walpole 10x10 Arch Top Freestanding Pergola

Walpole Woodworkers, Inc. 767 East Street

PO BOX 151

Walpole, MA 02081

Tel 508-668-2800

Toll-Free 800-343-6948

Fax 508-668-7301

Email: sales@walpolewoodworkers.com Website: www.walpolewoodworkers.com

Refer to sheet LS002; details 8, 9, & 10 for additional details.

- 2) What is the landscape block type?

AB Courtyard- Cut Stone Look

<http://www.allanblock.com/courtyard/courtyard-reference.aspx>

- 3) What is the actual style of the "Allan Block"?

AB Courtyard- Cut Stone Look

<http://www.allanblock.com/courtyard/courtyard-reference.aspx>

- 4) Would furnishing & planting new trees, of same type, be acceptable instead of relocating existing trees?

Yes, furnishing and planting new trees is acceptable.

- 5) Is there an existing underground ground ring at the facility as stated on drawing E101? If so, where?

Existing Underground Grounding Ring does exist. Exact locations are not known. It is known that grounding ring goes around entire building. Locations of lighting protection in CLC Courtyard are attached to grounding ring to assist in determining exact location.

- 6) Is there wall protection in this project?

No.