

ATTACHMENT 1
PICTURES

SHELTER 1



Figure 1: Side 1



Figure 2: Side 2, right



Figure 3: Side 2, left



Figure 4: Side 3



Figure 5: Side 4

SHELTER 2



Figure 6: Side 1



Figure 7: Side 2



Figure 8: Side 3, left



Figure 9: Side 3, bottom



Figure 10: Sides 3, bottom, & 4

SHELTER 3



Figure 11: Side 1, left



Figure 12: Side 1



Figure 13: Example of trim board, flashing and eave



Figure 14: Side 3



Figure 15: Side 4, left

SHELTER 4



Figure 16: Side 1



Figure 17: Side 2



Figure 18: Side 3



Figure 19: Side 4

SHELTER 5



Figure 20: Example of eave closure with debris



Figure 21: Side 1



Figure 22: Side 2



Figure 23: Side 3, left



Figure 24: Side 3, right



Figure 25: Side 4

FLAG STORAGE BUILDING



Figure 26



Figure 27



Figure 28

* Note: All pictures of Flag Storage Building were taken on the West side; the East side has similar damage.