

Current Rm Name/No.	Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT									Comment	
					Asbestos Present	Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc			
Basement	B03A	Ceiling	Acoustic Ceiling Panel	2x4		Not Detected	VALB-1c1.1 - c3.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Basement	B03A	Wall(s)	Wallboard w/Joint Compound		Beige	Not Detected	VALB-1c4.1-4.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Basement	B03A	Floor	Resilient Flooring Tile	12x12	Gray	Not Detected		Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Basement	B03A	Door/Door Frame	N/A						N/A	N/A								
Basement	B03A	Misc	Cove Base	4"	Off White	Not Detected	VALB-1m4.1 - m5.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Basement	B02A	Ceiling	Acoustic Ceiling Panel	2x4		Not Detected	VALB-1c1.1 - c3.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Basement	B02A	Wall(s)	Wallboard w/Joint Compound		Beige	Not Detected	VALB-1c4.1-4.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Basement	B02A	Floor	Resilient Flooring Tile	12x12	Gray	Not Detected	VALB-1f11.1-2	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Basement	B02A	Door/Door Frame	N/A						N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Material In Core
Basement	B02A	Misc	Cove Base	4"	Off White	Not Detected	VALB-1m4.1 - m5.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Basement	31A	Ceiling	Concrete			Not Suspect		N	N/A	N/A	N/A	N/A	N/A	N/S	N/A	N/A	N/A	
Basement	31A	Wall(s)	Plaster and Concrete		Off White	Not Suspect	VALB-1c5.1-5.2	Y	N/A	N/A	N/A	N/A	N/A	N/S	N/A	N/A	N/A	
Basement	31A	Floor	Concrete		Gray	Not Suspect		N	N/A	N/A	N/A	N/A	N/A	N/S	N/A	N/A	N/A	
Basement	31A	Door/Door Frame	Wood and Metal		Blue/Off White	Not Suspect		N	N/A	N/A	N/A	N/A	N/A	N/S	N/A	N/A	N/A	Possible Suspect Material In Core
Basement	31A	Misc	Fire Caulk		Red	Not Detected		N	N/A	N/A	N/A	N/A	N/A	Y/S	N/A	N/A	N/A	
Basement	31A	Misc	TSI at Hangar			ACM		Y	YES	Good	NONE	NONE	NONE	YES	YES	NO	NO	
Basement	31A	Misc	HVAC Sealant		Yellow	<1%Chrysotile	VALB-1-R3.1	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Basement	B17	Ceiling	Wallboard w/Joint Compound			Not Detected	VALB-1c4.1-4.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Basement	B17	Wall(s)	Plaster		Beige	Not Detected	VALB-1c5.1-5.2	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Basement	B17	Floor	Ceramic Tile	1x1	Green	Not suspect		N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Basement	B17	Door/Door Frame	Wood and Metal		White/Beige	Not Suspect		N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Material In Core
Basement	B17	Floor	Ceramic Tile	2x2	Green	Not suspect		N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Basement	B17	Wall(s)	Ceramic Tile	4x4	Off White	Not suspect		N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Basement	14	Ceiling	Fiberboard		Black/Yellow	Not suspect		N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Basement	14	Wall(s)	Concrete		Gray	Not Suspect		N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Basement	14	Floor	Concrete		Bare	Not Suspect		N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Basement	14	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect		N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Material In Core
Basement	B022	Ceiling	Acoustical Ceiling Panel	2x4		Not Detected	VALB-1c1.1 - c3.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Basement	B022	Wall(s)	Plaster		Beige	Not Detected	VALB-1c5.1-5.2	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Basement	B022	Floor	Resilient Flooring Tile	12x12	Gray	Not Detected	VALB-1f11.1-2	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Basement	B022	Door/Door Frame	Wood and Metal		White/Beige	Not Suspect		N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Material In Core
Basement	B022	Misc	Cove Base	4"	Off White	Not Detected	VALB-1m4.1 - m5.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Basement	15	Ceiling	Concrete		Beige	Not suspect		N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Basement	15	Wall(s)	Plaster		Beige	Not Detected	VALB-1c5.1-5.2	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Basement	15	Floor	Resilient Flooring Tile	9x9	Olive	ACM		Y	Non-Friable	Good	NONE	NONE	YES	NO	NO	YES		
Basement	15	Door/Door Frame	Metal and Metal		Gray	Not Suspect		N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Material In Core
Basement	15	Misc	Resilient Flooring Tile	12"	Gray	Not Detected	VALB-1F11.1-2	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Basement	15	Misc	Cove Base	4"	Gray	Not Detected	VALB-1m4.1 - m5.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Basement	16	Ceiling	Concrete		Beige	Not suspect		N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Basement	16	Wall(s)	Plaster		Beige	Not Detected	VALB-1c5.1-5.2	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Basement	16	Floor	Resilient Flooring Tile	9x9	Olive	ACM		Y	Non-Friable	Good	NONE	NONE	YES	NO	NO	YES		
Basement	16	Door/Door Frame	Metal and Metal		Gray	Not Suspect		N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Material In Core
Basement	16	Misc	Resilient Flooring Tile	12"	Gray	Not Detected	VALB-1F11.1-2	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Basement	16	Misc	Cove Base	4"	Gray	Not Detected	VALB-1m4.1 - m5.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	108	Ceiling	Acoustic Ceiling Tile Pinhole	2x4		Not Detected	VALB-1c1.1 - c3.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	108	Wall(s)	Wallboard w/ Joint Compound		Beige	Not Detected	VALB-1c4.1-4.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	108	Floor	Resilient Flooring Tile	12x12	Seafoam Dark Blue	Not Detected	VALB-1f3.1 - f3.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	108	Door/Door Frame	Wood and Metal		White/Beige	Not Suspect		N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Material In Core
1st Floor	108	Misc	Cove Base	4"	Off White	Not Detected	VALB-1m4.1 - m5.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	108	Misc	Window Putty		Gray	Not Detected		Y	Non-Friable		N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	109	Ceiling	Acoustic Ceiling Tile Pinhole	2x4		Not Detected	VALB-1c1.1 - c3.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	109	Wall(s)	Wallboard w/ Joint Compound		Beige	Not Detected	VALB-1c4.1-4.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	109	Floor	Resilient Flooring Tile	12x12	Seafoam Dark Blue	Not Detected	VALB-1f3.1 - f3.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	109	Door/Door Frame	Wood and Metal		White/Beige	Not Suspect		N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Material In Core
1st Floor	109	Misc	Cove Base	4"	Off White	Not Detected	VALB-1m4.1 - m5.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	109	Misc	Window Putty		Gray	Not Detected		Y	Non-Friable		N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	110	Ceiling	Acoustic Ceiling Tile Pinhole	2x4		Not Detected	VALB-1c1.1 - c3.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	110	Wall(s)	Wallboard w/ Joint Compound		Beige	Not Detected	VALB-1c4.1-4.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	110	Floor	Resilient Flooring Tile	12x12	Seafoam Dark Blue	Not Detected	VALB-1f3.1 - f3.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	110	Door/Door Frame	Wood and Metal		White/Beige	Not Suspect		N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Material In Core
1st Floor	110	Misc	Cove Base	4"	Off White	Not Detected	VALB-1m4.1 - m5.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	110	Misc	Window Putty		Gray	Not Detected		Y	Non-Friable		N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	114A	Ceiling	Acoustic Ceiling Tile Pinhole	2x4		Not Detected	VALB-1c1.1 - c3.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	114A	Wall(s)	Wallboard w/ Joint Compound		Beige	Not Detected	VALB-1c4.1-4.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	114A	Floor	Resilient Flooring Tile	12x12	Seafoam Dark Blue	Not Detected	VALB-1f3.1 - f3.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	114A	Door/Door Frame	Wood and Metal		White/Beige	Not Suspect		N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Material In Core
1st Floor	114A	Misc	Cove Base	4"	Off White	Not Detected	VALB-1m4.1 - m5.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	114A	Misc	Window Putty		Gray	Not Detected		Y	Non-Friable		N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	114	Ceiling	Acoustic Ceiling Tile Pinhole	2x4		Not Detected	VALB-1c1.1 - c3.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	114	Wall(s)	Wallboard w/ Joint Compound		Beige	Not Detected	VALB-1c4.1-4.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	114	Floor	Resilient Flooring Tile	12x12	Seafoam Dark Blue	Not Detected	VALB-1f3.1 - f3.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	114	Door/Door Frame	Wood and Metal		White/Beige	Not Suspect		N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Material In Core

Current Rm Name/No.	Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								Comment	
					Asbestos Present	Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc		
2nd Floor	200D	Floor	Carpet w/ mastic (presumed)		Brown	Not Detected	VALB-1-f13.2 - 13.4	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	200D	Door/Door Frame	Wood and Metal		White/Beige	Not Suspect		N			N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Material In Core
2nd Floor	200D	Misc	Cove Base	4"	Off White	Not Detected	VALB-1-m4.1 - m5.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	200K	Ceiling	Acoustic Ceiling Tile Pinhole	2x4		Not Detected	VALB-1c1.1 - c3.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	200K	Wall(s)	Wallboard w/ Joint Compound		Beige/Green	Not Detected	VALB-1c4.1-4.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	200K	Floor	Carpet w/ mastic (presumed)		Brown	Not Detected	VALB-1-f13.2 - 13.4	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	200K	Door/Door Frame	Wood and Metal		White/Beige	Not Suspect		N			N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Material In Core
2nd Floor	200K	Misc	Cove Base	4"	Off White	Not Detected	VALB-1-m4.1 - m5.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	200U	Ceiling	Acoustic Ceiling Tile Pinhole	2x4		Not Detected	VALB-1c1.1 - c3.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	200U	Wall(s)	Wallboard w/ Joint Compound		Beige/Green	Not Detected	VALB-1c4.1-4.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	200U	Floor	Carpet w/ mastic (presumed)		Brown	Not Detected	VALB-1-f13.2 - 13.4	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	200U	Door/Door Frame	Wood and Metal		White/Beige	Not Suspect		N			N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Material In Core
2nd Floor	200U	Misc	Cove Base	4"	Off White	Not Detected	VALB-1-m4.1 - m5.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	200F	Ceiling	Acoustic Ceiling Tile Pinhole	2x4		Not Detected	VALB-1c1.1 - c3.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	200F	Wall(s)	Wallboard w/ Joint Compound		Beige/Green	Not Detected	VALB-1c4.1-4.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	200F	Floor	Resilient Flooring Tile	12x12	Beige w/Brown	Not Detected	VALB-1-f2.1 - f2.2	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	200F	Door/Door Frame	Wood and Metal		White/Beige	Not Suspect		N			N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Material In Core
2nd Floor	200F	Misc	Cove Base	4"	Beige	Not Detected	VALB-1-m4.1 - m5.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	302C	Ceiling	Acoustical Ceiling Panel	2x4		Not Detected	VALB-1c1.1 - c3.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	302C	Wall(s)	Wallboard w/ Joint Compound		Off White	Not Detected	VALB-1c4.1-4.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	302C	Floor	Resilient Flooring Tile	12x12	Gray	Not Detected	VALB-1c4.1-4.3	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	302C	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect		N			N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Material In Core
3rd Floor	302C	Misc	Cove Base	4"	Gray	Not Detected	VALB-1-m4.1 - m5.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	301	Misc	TSI /F					Y	FRIABLE	GOOD	NONE	NONE	YES	YES	NO	NO	
3rd Floor	302D	Misc	TSI /F					Y									
3rd Floor	C3-1	Misc	TSI /F					Y									
3rd Floor	C3-2	Misc	TS/P					Y									
3rd Floor	C3-2	Misc	TS/F					Y									
3rd Floor	319B	Misc	TS/F					Y									
3rd Floor	C3-1	Ceiling	Acoustical Ceiling Panel	2x4	White	Not Detected	VALB-1c1.1 - c3.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	C3-1	Wall(s)	Wallboard w/ Joint Compound		Beige	Not Detected	VALB-1c4.1-4.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	C3-1	Floor	Resilient Flooring Tile	12x12	Seafoam Beige	Not Detected	VALB-1-f9.1 - f9.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	C3-1	Door/Door Frame	Metal and Metal		Beige/Beige	Not Suspect		N			N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Material In Core
3rd Floor	C3-1	Misc	Cove Base	4"	Off White	Not Detected	VALB-1-m4.1 - m5.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	310	Ceiling	Acoustical Ceiling Panel	2x4	Gray	Not Detected	VALB-1c1.1 - c3.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	310	Wall(s)	Wallboard w/ Joint Compound		Beige	Not Detected	VALB-1c4.1-4.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	310	Floor	Resilient Flooring Tile	12x12	Beige and Yellow	Not Detected	VALB-1c4.1-4.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	310	Door/Door Frame	Metal and Metal		Beige/Beige	Not Suspect		N			N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Material In Core
3rd Floor	310	Misc	Cove Base	4"	Off White	Not Detected	VALB-1-m4.1 - m5.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	310	Misc	Resilient Floor Tile Mastic(Hallway)		Black	YES		Y			N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	310B	Ceiling	Acoustical Ceiling Panel	2x4		Not Detected	VALB-1c1.1 - c3.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	310B	Wall(s)	Wallboard w/ Joint Compound		Beige	Not Detected	VALB-1c4.1-4.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	310B	Floor	Resilient Flooring Tile	12x12	Seafoam Beige	Not Detected	VALB-1-f9.1 - f9.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	310B	Door/Door Frame	Metal and Metal		Beige/Beige	Not Suspect		N			N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Material In Core
3rd Floor	310B	Misc	Cove Base	4"	Off White	Not Detected	VALB-1-m4.1 - m5.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	302D	Ceiling	Acoustical Ceiling Panel	2x4		Not Detected	VALB-1c1.1 - c3.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	302D	Wall(s)	Wallboard w/ Joint Compound		Beige	Not Detected	VALB-1c4.1-4.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	302D	Floor	Resilient Flooring Tile	12x12	Seafoam Beige	Not Detected	VALB-1-f9.1 - f9.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	302D	Door/Door Frame	Metal and Metal		Beige/Beige	Not Suspect		N			N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Material In Core
3rd Floor	302D	Misc	Cove Base	4"	Off White	Not Detected	VALB-1-m4.1 - m5.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	310A	Ceiling	Acoustical Ceiling Panel	2x4		Not Detected	VALB-1c1.1 - c3.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	310A	Wall(s)	Wallboard w/ Joint Compound		Beige	Not Detected	VALB-1c4.1-4.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	310A	Floor	Resilient Flooring Tile	12x12	Seafoam Beige	Not Detected	VALB-1-f9.1 - f9.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	310A	Door/Door Frame	Metal and Metal		Beige/Beige	Not Suspect		N			N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Material In Core
3rd Floor	310A	Misc	Cove Base	4"	Gray	Not Detected	VALB-1-m4.1 - m5.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	304	Ceiling	Acoustical Ceiling Panel	2x4		Not Detected	VALB-1c1.1 - c3.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	NN	N/A	
3rd Floor	304	Wall(s)	Wallboard w/ Joint Compound		Beige	Not Detected	VALB-1c4.1-4.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	304	Floor	Resilient Flooring Tile	12x12	Seafoam Beige	Not Detected	VALB-1-f9.1 - f9.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	304	Door/Door Frame	Metal and Metal		Beige/Beige	Not Suspect		N			N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Material In Core
3rd Floor	304	Misc	Cove Base	4"	Gray	Not Detected	VALB-1-m4.1 - m5.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	302	Ceiling	Acoustical Ceiling Panel	2x4		Not Detected	VALB-1c1.1 - c3.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	302	Wall(s)	Wallboard w/ Joint Compound		Beige	Not Detected	VALB-1c4.1-4.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	302	Floor	Resilient Flooring Tile and Mastic	12x12	Beige and Yellow	Not Detected	VALB-1-f11.1	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	302	Door/Door Frame	Metal and Metal		Beige/Beige	Not Suspect		N			N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Material In Core
3rd Floor	302	Misc	Cove Base	4"	Gray	Not Detected	VALB-1-m4.1 - m5.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	302	Misc	Resilient Floor Tile		Gray	Not Detected		Y			N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	311	Ceiling	Acoustical Ceiling Panel	2x4		Not Detected	VALB-1c1.1 - c3.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	311	Wall(s)	Wallboard w/ Joint Compound		Beige	Not Detected	VALB-1c4.1-4.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	311	Floor	Resilient Flooring Tile	12x12	Seafoam Beige	Not Detected	VALB-1-f9.1 - f9.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	311	Door/Door Frame	Metal and Metal		Beige/Beige	Not Suspect		N			N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Material In Core

Current Rm Name/No.	Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								Comment	
					Asbestos Present	Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc		
4th Floor	424	Floor	Carpet w/ mastic (presumed)		Brown	Not Detected	VALB-1-f13.2 - 13.4	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	424	Door/Door Frame	Wood and Metal		White/Beige	Not Suspect		N									Possible Suspect Material In Core
4th Floor	424	Misc	Cove Base	4"	Off White	Not Detected	VALB-1-m4.1 - m5.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	424	Misc	Window Putty		Gray	Not Detected		Y	Non-Friable		N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	425	Ceiling	Acoustic Ceiling Tile Pinhole	2x2		Not Detected		N			N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	425	Wall(s)	Wallboard w/ Joint Compound		Beige	Not Detected	VALB-1c4.1-4.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	425	Floor	Carpet w/ mastic (presumed)		Brown	Not Detected	VALB-1-f13.2 - 13.4	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	425	Door/Door Frame	Wood and Metal		White/Beige	Not Suspect		N									Possible Suspect Material In Core
4th Floor	425	Misc	Cove Base	4"	Off White	Not Detected	VALB-1-m4.1 - m5.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	425	Misc	Window Putty		Gray	Not Detected		Y	Non-Friable		N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	426	Ceiling	Acoustic Ceiling Tile Pinhole	2x2		Not Detected		N			N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	426	Wall(s)	Wallboard w/ Joint Compound		Beige	Not Detected	VALB-1c4.1-4.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	426	Floor	Carpet w/ mastic (presumed)		Brown	Not Detected	VALB-1-f13.2 - 13.4	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	426	Door/Door Frame	Wood and Metal		White/Beige	Not Suspect		N									Possible Suspect Material In Core
4th Floor	426	Misc	Cove Base	4"	Off White	Not Detected	VALB-1-m4.1 - m5.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	426	Misc	Window Putty		Gray	Not Detected		Y	Non-Friable		N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	427	Ceiling	Acoustic Ceiling Tile Pinhole	2x2		Not Detected		N			N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	427	Wall(s)	Wallboard w/ Joint Compound		Beige	Not Detected	VALB-1c4.1-4.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	427	Floor	Carpet w/ mastic (presumed)		Brown	Not Detected	VALB-1-f13.2 - 13.4	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	427	Door/Door Frame	Wood and Metal		White/Beige	Not Suspect		N									Possible Suspect Material In Core
4th Floor	427	Misc	Cove Base	4"	Off White	Not Detected	VALB-1-m4.1 - m5.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	427	Misc	Window Putty		Gray	Not Detected		Y	Non-Friable		N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	428	Ceiling	Acoustic Ceiling Tile Pinhole	2x2		Not Detected		N			N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	428	Wall(s)	Wallboard w/ Joint Compound		Beige	Not Detected	VALB-1c4.1-4.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	428	Floor	Carpet w/ mastic (presumed)		Brown	Not Detected	VALB-1-f13.2 - 13.4	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	428	Door/Door Frame	Wood and Metal		White/Beige	Not Suspect		N									Possible Suspect Material In Core
4th Floor	428	Misc	Cove Base	4"	Off White	Not Detected	VALB-1-m4.1 - m5.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	428	Misc	Window Putty		Gray	Not Detected		Y	Non-Friable		N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	428	Misc	Resilient Floor Tile and Mastic (Mastic-POS)	4000 sq.ft.		YES		Y			N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	429	Ceiling	Acoustic Ceiling Tile Pinhole	2x2		Not Detected		N			N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	429	Wall(s)	Wallboard w/ Joint Compound		Beige	Not Detected	VALB-1c4.1-4.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	429	Floor	Carpet w/ mastic (presumed)		Brown	Not Detected	VALB-1-f13.2 - 13.4	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	429	Door/Door Frame	Wood and Metal		White/Beige	Not Suspect		N									Possible Suspect Material In Core
4th Floor	429	Misc	Cove Base	4"	Off White	Not Detected	VALB-1-m4.1 - m5.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	429	Misc	Resilient Floor Tile (Mastic POS)	4000 sq.ft.		YES		Y									
4th Floor	434	Ceiling	Acoustic Ceiling Tile Pinhole	2x2		Not Detected		N			N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	434	Wall(s)	Wallboard w/ Joint Compound		Beige	Not Detected	VALB-1c4.1-4.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	434	Floor	Carpet w/ mastic (presumed)		Brown	Not Detected	VALB-1-f13.2 - 13.4	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	434	Door/Door Frame	Wood and Metal		White/Beige	Not Suspect		N									Possible Suspect Material In Core
4th Floor	434	Misc	Cove Base and Mastic	4"	Off White	Not Detected	VALB-1-m4.1 - m5.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	434	Misc	Window Putty		Gray	Not Detected		Y	Non-Friable		N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	433	Ceiling	Acoustic Ceiling Tile Pinhole	2x2		Not Detected		N			N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	433	Wall(s)	Wallboard w/ Joint Compound		Beige	Not Detected	VALB-1c4.1-4.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	433	Floor	Carpet w/ mastic (presumed)		Brown	Not Detected	VALB-1-f13.2 - 13.4	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	433	Door/Door Frame	Wood and Metal		White/Beige	Not Suspect		N									Possible Suspect Material In Core
4th Floor	433	Misc	Cove Base	4"	Off White	Not Detected	VALB-1-m4.1 - m5.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	438	Ceiling	Acoustic Ceiling Tile Pinhole	2x2		Not Detected		N			N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	438	Wall(s)	Wallboard w/ Joint Compound		Beige	Not Detected	VALB-1c4.1-4.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	438	Floor	Carpet w/ mastic (presumed)		Brown	Not Detected	VALB-1-f13.2 - 13.4	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	438	Door/Door Frame	Wood and Metal		White/Beige	Not Suspect		N									Possible Suspect Material In Core
4th Floor	438	Misc	Cove Base	4"	Off White	Not Detected	VALB-1-m4.1 - m5.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	437	Ceiling	Acoustic Ceiling Tile Pinhole	2x2		Not Detected		N			N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	437	Wall(s)	Wallboard w/ Joint Compound		Beige	Not Detected	VALB-1c4.1-4.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	437	Floor	Carpet w/ mastic (presumed)		Brown	Not Detected	VALB-1-f13.2 - 13.4	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	437	Door/Door Frame	Wood and Metal		White/Beige	Not Suspect		N									Possible Suspect Material In Core
4th Floor	437	Misc	Cove Base	4"	Off White	Not Detected	VALB-1-m4.1 - m5.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	436	Ceiling	Acoustic Ceiling Tile Pinhole	2x2		Not Detected		N			N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	436	Wall(s)	Wallboard w/ Joint Compound		Beige	Not Detected	VALB-1c4.1-4.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	436	Floor	Carpet w/ mastic (presumed)		Brown	Not Detected	VALB-1-f13.2 - 13.4	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	436	Door/Door Frame	Wood and Metal		White/Beige	Not Suspect		N									Possible Suspect Material In Core
4th Floor	436	Misc	Cove Base	4"	Off White	Not Detected	VALB-1-m4.1 - m5.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	435	Ceiling	Acoustic Ceiling Tile Pinhole	2x2		Not Detected		N			N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	435	Wall(s)	Wallboard w/ Joint Compound		Beige	Not Detected	VALB-1c4.1-4.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	435	Floor	Carpet w/ mastic (presumed)		Brown	Not Detected	VALB-1-f13.2 - 13.4	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	435	Door/Door Frame	Wood and Metal		White/Beige	Not Suspect		N									Possible Suspect Material In Core
4th Floor	435	Misc	Cove Base	4"	Off White	Not Detected	VALB-1-m4.1 - m5.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	432A	Ceiling	Acoustic Ceiling Tile Pinhole	2x2		Not Detected		N			N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	432A	Wall(s)	Wallboard w/ Joint Compound		Beige	Not Detected	VALB-1c4.1-4.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	432A	Floor	Resilient Flooring Tile	12x12	Beige w/Brown	Not Detected	VALB-1-f2.1 - f2.2	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
4th Floor	432A	Door/Door Frame	Wood and Metal		White/Beige	Not Suspect		N									Possible Suspect Material In Core

