

Current Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT			Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)						
1st Floor	166D	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
1st Floor	166D	Wall(s)	Plaster		Off White	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	166D	Floor	Mastic Exposed		Black	YES		Y	No	Poor		Yes	Yes			Yes	
1st Floor	166D	Door/Door Frame	Metal & Metal		Tan & Off White	Not Suspect											Possible suspect material in core
1st Floor	166D	Misc	Covebase Mastic	4"	Off White	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
1st Floor	166A	Ceiling	Plaster		Off White	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	166A	Wall(s)	Plaster		Off White	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	166A	Floor	Concrete		bare	Not suspect											
1st Floor	166A	Door/Door Frame	Metal & Metal		Blue & Off White	Not Suspect											Possible suspect material in core
1st Floor	166A	Misc	Covebase Mastic		Brown	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
1st Floor	166C	Ceiling	Plaster		Off White	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	166C	Wall(s)	Plaster		Off White	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	166C	Floor	Concrete		bare	Not suspect											
1st Floor	166C	Door/Door Frame	Metal & Metal		Blue & Off White	Not Suspect											Possible suspect material in core
1st Floor	166C	Misc	Covebase Mastic		Brown	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
1st Floor	166B	Ceiling	Plaster		Off White	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	166B	Wall(s)	Plaster		Off White	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	166B	Floor	Concrete		bare	Not suspect											
1st Floor	166B	Door/Door Frame	Metal & Metal		Blue & Off White	Not Suspect											Possible suspect material in core
1st Floor	166B	Wall(s)	Covebase Mastic		Brown	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
1st Floor	116	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
1st Floor	116	Wall(s)	Wallboard Joint Compound			Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A						
1st Floor	116	Floor	Resilient Floor Tile	12x12	Beige/Blue	Not Detected	VALB-2-F4.1	Y	N/A	N/A	N/A						
1st Floor	116	Door/Door Frame	Wood & Metal		Beige/Beige	Not Suspect											Possible suspect material in core
1st Floor	116	Misc	Covebase Mastic	4"	Blue	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
1st Floor	N104	Ceiling	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	N104	Wall(s)	Ceramic Tile	12x12	Beige	Not Suspect											
1st Floor	N104	Floor	Ceramic Tile	16x16	Tan	Not Suspect											
1st Floor	N102	Ceiling	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	N102	Wall(s)	Ceramic Tile	12x12	Beige	Not Suspect											
1st Floor	N102	Floor	Ceramic Tile	16x16	Tan	Not Suspect											
1st Floor	E102	Ceiling	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	E102	Wall(s)	Ceramic Tile	12x12	Beige	Not Suspect											
1st Floor	E102	Floor	Ceramic Tile	16x16	Tan	Not Suspect											
1st Floor	E102	Door/Door Frame	Wood & Metal	3"-1													
1st Floor	E103	Ceiling	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	E103	Wall(s)	Ceramic Tile	12x12	Beige	Not Suspect											
1st Floor	E103	Floor	Ceramic Tile	16x16	Tan	Not Suspect											
1st Floor	E103	Door/Door Frame	Wood & Metal	3"-1													
1st Floor	E107	Ceiling	Acoustic Ceiling Tile Pinhole	2x2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
1st Floor	E107	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	E107	Floor	Wood		White	Not Suspect											
1st Floor	E107	Door/Door Frame	Metal & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
1st Floor	E107	Misc	Covebase Mastic	6"	Off White	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
1st Floor	E107	Misc	Wainscot		Beige												
1st Floor	E107	Wall(s)	Ceramic Tile	4x4	Off White	Not Suspect											
1st Floor	E107	Ceiling	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	E107	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	E107	Floor	Wood		White	Not Detected											
1st Floor	E107	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
1st Floor	E107	Ceiling	Acoustic Ceiling Tile	2x2		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
1st Floor	E107	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	E107	Floor	Ceramic Tile	16x16	Tan	Not Suspect											
1st Floor	E107	Door/Door Frame	Metal & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
1st Floor	N115	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
1st Floor	N115	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	N115	Floor	Carpet (mastic)		Blue	Y	N/A	Y	No	Good	No	No	Yes			Yes	Possible ACM Flooring Underneath

Current Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT			Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)						
1st Floor	N115	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
1st Floor	N115	Misc	Covebase Mastic		Off White	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
1st Floor	N117	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
1st Floor	N117	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	N117	Floor	Carpet (mastic)		Blue	Y	N/A	Y	No	Good	No	No	Yes			Yes	Possible ACM Flooring Underneath
1st Floor	N117	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
1st Floor	N117	Misc	Covebase Mastic		Off White	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
1st Floor	N117	Ceiling	Acoustic Ceiling Tile	2x2		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
1st Floor	N117	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	N117	Floor	Resilient Floor Tile	12x12	White/Blue	<1%	VALB-2-F5.1	Y	No	Good	No	No	Yes			Yes	
1st Floor	N117	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
1st Floor	N117	Misc	Covebase Mastic	4"	Off White	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
1st Floor	N117	Ceiling	Acoustic Ceiling Tile	2x2		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
1st Floor	N117	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	N117	Floor	Resilient Floor Tile	12x12	White/Blue	<1%	VALB-2-F5.1	Y	No	Good	No	No	Yes			Yes	
1st Floor	N117	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
1st Floor	N117	Misc	Resilient Floor Tile	12x12	Seafoam Blue	<1%	VALB-2-F5.1	Y	No	Good	No	No	Yes			Yes	
1st Floor	N117	Misc	Covebase Mastic	4"	Off White	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
1st Floor	N117	Ceiling	Plaster	2x4		Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	N117	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	N117	Floor	Resilient Floor Tile		Blue	<1%	VALB-2-F5.1	Y	No	Good	No	No	Yes			Yes	
1st Floor	N117	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
1st Floor	N117	Misc	Covebase	4"	Off White	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
1st Floor	N118	Ceiling	Plaster	2x4		Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	N118	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	N118	Floor	Resilient Floor Tile		Blue	<1%	VALB-2-F5.1	Y	No	Good	No	No	Yes			Yes	
1st Floor	N118	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
1st Floor	N118	Misc	Covebase	4"	Off White	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
1st Floor	N119	Ceiling	Plaster	2x4		Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	N119	Wall(s)	Ceramic Tile	4x4	Off White	Not Suspect											
1st Floor	N119	Floor	Resilient Floor Tile		Blue	<1%	VALB-2-F5.1	Y	No	Good	No	No	Yes			Yes	
1st Floor	N119	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
1st Floor	N119	Misc	Covebase	4"	Off White	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
1st Floor	N106	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
1st Floor	N106	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	N106	Floor	Carpet (mastic)		Blue	Y	N/A	Y	No	Good	No	No	Yes			Yes	
1st Floor	N106	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
1st Floor	N106	Misc	Wallboard Joint Compound		Beige	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A						
1st Floor	N106	Misc	Covebase Mastic	4"	Off White	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
1st Floor	N107	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
1st Floor	N107	Wall(s)	Plaster		Beige & Green	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	N107	Floor	Resilient Floor Tile	12x12	White/Blue	<1%	VALB-2-F5.1	Y	No	Good	No	No	Yes			Yes	
1st Floor	N107	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
1st Floor	N107	Misc	Covebase Mastic	4"	Off White	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
1st Floor	N107	Wall(s)	Ceramic Tile	4x4	Off White	Not Suspect											
1st Floor	N108	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
1st Floor	N108	Wall(s)	Plaster		Beige & Green	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	N108	Floor	Resilient Floor Tile	12x12	White/Blue	<1%	VALB-2-F5.1	Y	No	Good	No	No	Yes			Yes	
1st Floor	N108	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
1st Floor	N108	Misc	Covebase Mastic	4"	Off White	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
1st Floor	N108	Wall(s)	Ceramic Tile	4x4	Off White	Not Suspect											
1st Floor	N109	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
1st Floor	N109	Wall(s)	Plaster		Beige & Green	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	N109	Floor	Resilient Floor Tile	12x12	White/Blue	<1%	VALB-2-F5.1	Y	No	Good	No	No	Yes			Yes	
1st Floor	N109	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
1st Floor	N109	Misc	Covebase Mastic	4"	Off White	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
1st Floor	N109	Wall(s)	Ceramic Tile	4x4	Off White	Not Suspect											

Current Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT			Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)						
1st Floor	N112	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
1st Floor	N112	Wall(s)	Plaster		Beige & Green	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	N112	Floor	Resilient Floor Tile	12x12	White/Blue	<1%	VALB-2-F5.1	Y	No	Good	No	No	Yes			Yes	
1st Floor	N112	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
1st Floor	N112	Wall(s)	Covebase Mastic	4"	Off White	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
1st Floor	N112	Wall(s)	Ceramic Tile	4x4	Off White	Not Suspect											
1st Floor	N113	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
1st Floor	N113	Wall(s)	Plaster		Beige & Green	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	N113	Floor	Resilient Floor Tile	12x12	White/Blue	<1%	VALB-2-F5.1	Y	No	Good	No	No	Yes			Yes	
1st Floor	N113	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
1st Floor	N113	Misc	Covebase Mastic	4"	Off White	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
1st Floor	N113	Wall(s)	Ceramic Tile	4x4	Off White	Not Suspect											
1st Floor	N114	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
1st Floor	N114	Wall(s)	Plaster		Beige & Green	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	N114	Floor	Resilient Floor Tile	12x12	White/Blue	<1%	VALB-2-F5.1	Y	No	Good	No	No	Yes			Yes	
1st Floor	N114	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
1st Floor	N114	Misc	Covebase Mastic	4"	Off White	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
1st Floor	N114	Wall(s)	Ceramic Tile	4x4	Off White	Not Suspect											
1st Floor	N122	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
1st Floor	N122	Wall(s)	Plaster		Beige & Green	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	N122	Floor	Resilient Floor Tile	12x12	White/Blue	<1%	VALB-2-F5.1	Y	No	Good	No	No	Yes			Yes	
1st Floor	N122	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
1st Floor	N122	Misc	Covebase Mastic	4"	Off White	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
1st Floor	N122	Wall(s)	Ceramic Tile	4x4	Off White	Not Suspect											
1st Floor	N111	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
1st Floor	N111	Wall(s)	Plaster		Beige & Green	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	N111	Floor	Resilient Floor Tile	12x12	White/Blue	<1%	VALB-2-F5.1	Y	No	Good	No	No	Yes			Yes	
1st Floor	N111	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
1st Floor	N111	Misc	Covebase Mastic	4"	Off White	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
1st Floor	N123	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
1st Floor	N123	Wall(s)	Plaster		Beige & Green	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	N123	Floor	Resilient Floor Tile	12x12	White/Blue	<1%	VALB-2-F5.1	Y	No	Good	No	No	Yes			Yes	
1st Floor	N123	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
1st Floor	N123	Misc	Covebase Mastic	6"	Off White	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
1st Floor	N123	Misc	Ceramic Tile	4x4	Off White	Not Suspect											
1st Floor	N124	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
1st Floor	N124	Wall(s)	Plaster		Beige & Green	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	N124	Floor	Resilient Floor Tile	12x12	White/Blue	<1%	VALB-2-F5.1	Y	No	Good	No	No	Yes			Yes	
1st Floor	N124	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
1st Floor	N124	Misc	Covebase Mastic	6"	Off White	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
1st Floor	N124	Misc	Ceramic Tile	4x4	Off White	Not Suspect											
1st Floor	N120	Ceiling	Plaster		Beige												
1st Floor	N120	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	N120	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
1st Floor	N120	Misc	Ceramic Tile	4x4	Beige	Not Suspect											
1st Floor	N11	Ceiling	Acoustic Ceiling Tile Pinhole	2x2		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
1st Floor	N11	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	N11	Floor	Wood		Wood	Not Suspect											
1st Floor	N11	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
1st Floor	N11	Misc	Covebase Mastic	6"	Off White	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
1st Floor	N11	Wall(s)	Wainscot		Beige												
1st Floor	121 F-2	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
1st Floor	121F-2	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A						
1st Floor	121F-2	Floor	Wood		Wood	Not Suspect											
1st Floor	121F-2	Door/Door Frame	Metal & Metal		Gray & Gray	Not Suspect											Possible suspect material in core
1st Floor	121F-2	Misc	Covebase Mastic	6"	Off White	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
1st Floor	N11	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						



Current Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT			SignificantlyDamaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)						
1st Floor	160C	Floor	Carpet (mastic)		Tan	Y	N/A	Y	No	Good	No	No	Yes			Yes	Possible ACM Flooring Underneath
1st Floor	160C	Door/Door Frame	Metal & Metal		Ble & Blue	Not Suspect											Possible suspect material in core
1st Floor	160A	Ceiling	Metal		Silver	Not Suspect											
1st Floor	160A	Wall(s)	Metal		Blue	Not Suspect											
1st Floor	160A	Floor	Carpet (mastic)		Tan	Y	N/A	Y	No	Good	No	No	Yes			Yes	Possible ACM Flooring Underneath
1st Floor	160A	Door/Door Frame	Metal & Metal		Ble & Blue	Not Suspect											Possible suspect material in core
1st Floor	151	Ceiling	Metal		Silver	Not Suspect											
1st Floor	151	Wall(s)	Metal		Blue	Not Suspect											
1st Floor	151	Floor	Carpet (mastic)		Tan	Y	N/A	Y	No	Good	No	No	Yes			Yes	Possible ACM Flooring Underneath
1st Floor	151	Door/Door Frame	Metal & Metal		Ble & Blue	Not Suspect											Possible suspect material in core
1st Floor	152	Ceiling	Metal		Silver	Not Suspect											
1st Floor	152	Wall(s)	Metal		Blue	Not Suspect											
1st Floor	152	Floor	Carpet (mastic)		Tan	Y	N/A	Y	No	Good	No	No	Yes			Yes	Possible ACM Flooring Underneath
1st Floor	152	Door/Door Frame	Metal & Metal		Ble & Blue	Not Suspect											Possible suspect material in core
1st Floor	158A-O	Ceiling	Metal		Silver	Not Suspect											
1st Floor	158A-O	Wall(s)	Metal		White & Dark Green	Not Suspect											
1st Floor	158A-O	Floor	Carpet (mastic)		Tan	Y	N/A	Y	No	Good	No	No	Yes			Yes	Possible ACM Flooring Underneath
1st Floor	158A-O	Door/Door Frame	Metal & Metal		Ble & Blue	Not Suspect											Possible suspect material in core
1st Floor	157A	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
1st Floor	157A	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A						
1st Floor	157A	Floor	Carpet (mastic)		Tan	Y	N/A	Y	No	Good	No	No	Yes			Yes	Possible ACM Flooring Underneath
1st Floor	157A	Door/Door Frame	Wood & Metal		White & Silver	Not Suspect											Possible suspect material in core
1st Floor	157A	Misc	Plaster		Off White	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	157A	Misc	Covebase Mastic	4"	Off White	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
1st Floor	157B	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
1st Floor	157B	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A						
1st Floor	157B	Floor	Carpet (mastic)		Tan	Y	N/A	Y	No	Good	No	No	Yes			Yes	Possible ACM Flooring Underneath
1st Floor	157B	Door/Door Frame	Wood & Metal		White & Silver	Not Suspect											Possible suspect material in core
1st Floor	157B	Misc	Plaster		Off White	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	157B	Misc	Covebase Mastic	4"	Off White	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
1st Floor	157C	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
1st Floor	157C	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A						
1st Floor	157C	Floor	Carpet (mastic)		Brown	Y	N/A	Y	No	Good	No	No	Yes			Yes	Possible ACM Flooring Underneath
1st Floor	157C	Door/Door Frame	Wood & Metal		White & Silver	Not Suspect											Possible suspect material in core
1st Floor	157C	Misc	Plaster		Off White	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	157C	Misc	Covebase Mastic	4"	Off White	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
1st Floor	N159	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
1st Floor	N159	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A						
1st Floor	N159	Floor	Resilient Floor Tile	12x12	Beige	Not Detected	VALB-2-F4.1	Y	N/A	N/A	N/A						
1st Floor	N159	Door/Door Frame	Wood & Metal		White & Silver	Not Suspect											Possible suspect material in core
1st Floor	N159	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	N159	Misc	Covebase Mastic	4"	Tan	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
1st Floor	N161	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
1st Floor	N161	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A						
1st Floor	N161	Floor	Carpet (mastic)		Tan	Y	N/A	Y	No	Good	No	No	Yes			Yes	Possible ACM Flooring Underneath
1st Floor	N161	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	N161	Misc	Covebase Mastic	4"	Off White	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
1st Floor	N163	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
1st Floor	N163	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A						
1st Floor	N163	Floor	Carpet (mastic)		Tan	Y	N/A	Y	N/A	Good	No	No	Yes			Yes	Possible ACM Flooring Underneath
1st Floor	N163	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	N163	Misc	Covebase Mastic	4"	Off White	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
1st Floor	N164	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
1st Floor	N164	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A						
1st Floor	N164	Floor	Carpet (mastic)		Tan	Y	N/A	Y	No	Good	No	No	Yes			Yes	Possible ACM Flooring Underneath
1st Floor	N164	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	N164	Misc	Covebase Mastic	4"	Off White	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						

Current Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT			Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)						
1st Floor	N157	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
1st Floor	N157	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A						
1st Floor	N157	Floor	Carpet (mastic)		Tan	Y	N/A	Y	No	Good	No	No	Yes			Yes	Possible ACM Flooring Underneath
1st Floor	N157	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	N157	Misc	Covebase Mastic	4"	Off White	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
1st Floor	N165	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
1st Floor	N165	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A						
1st Floor	N165	Floor	Carpet (mastic)		Tan	Y	N/A	Y	N/A	Good	No	No	Yes			Yes	Possible ACM Flooring Underneath
1st Floor	N165	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	N165	Misc	Covebase Mastic	4"	Off White	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
1st Floor	117	Ceiling	Acoustic Ceiling Tile	2x4	N	Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
1st Floor	117	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A						
1st Floor	117	Floor	Resilient Floor Tile	12x12	Gray/White	<1%	VALB-2-F5.1	Y	No	Good	No	No	Yes			Yes	
1st Floor	117	Door/Door Frame	Metal & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
1st Floor	117	Misc	Covebase Mastic	4"	Black	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
1st Floor	N114	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
1st Floor	N114	Wall(s)	Plaster		Green & Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	N114	Floor	Resilient Floor Tile	12x12	Beige/Brown	Not Detected	VALB-2-F4.1	Y	N/A	N/A	N/A						
1st Floor	N114	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
1st Floor	N114	Misc	Covebase Mastic	4"	Off White	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
1st Floor	N111	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
1st Floor	N111	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	N111	Floor	Carpet (mastic)		Brown	Y	N/A	Y	No	Good	No	No	Yes			Yes	Possible ACM Flooring Underneath
1st Floor	N111	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
1st Floor	N111	Misc	Wallboard Joint Compound		Beige & Green	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A						
1st Floor	N111	Misc	Covebase Mastic	4"	Off White	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
1st Floor	106	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
1st Floor	106	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	106	Floor	Carpet (mastic)		Brown	Y	N/A	Y	No	Good	No	No	Yes			Yes	Possible ACM Flooring Underneath
1st Floor	106	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
1st Floor	106	Misc	Wallboard Joint Compound		Beige & Green	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A						
1st Floor	106	Misc	Covebase Mastic	4"	Off White	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
1st Floor	166C	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
1st Floor	166C	Wall(s)	Plaster		Off White	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	166C	Floor	Concrete		bare	Not suspect											
1st Floor	166C	Door/Door Frame	Metal & Metal		Blue & Off White	Not Suspect											Possible suspect material in core
1st Floor	166C	Misc	Glue (Covebase Mastic Removed)		Brown & Yellow	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
1st Floor	166F	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
1st Floor	166F	Wall(s)	Plaster		Off White	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	166F	Floor	Concrete		bare	Not suspect											
1st Floor	166F	Door/Door Frame	Metal & Metal		Blue & Off White	Not Suspect											Possible suspect material in core
1st Floor	166F	Misc	Glue (Covebase Mastic Removed)		Brown & Yellow	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
1st Floor	57C	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
1st Floor	57C	Wall(s)	Plaster		Off White	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	57C	Floor	Resilient Floor Tile	12x12	Brown	Not Detected	VALB-2-F4.1	Y	N/A	N/A	N/A						
1st Floor	57C	Door/Door Frame	Glass & Metal		Glass & Black	Not Suspect											Possible suspect material in core
1st Floor	57C	Ceiling	Acoustic Ceiling Tile Pinhole	2x2		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
1st Floor	57C	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	57C	Floor	Resilient Floor Tile	12x12	Gray	Not Detected	VALB-2-F1.1 - F1.2	Y	N/A	N/A	N/A						
1st Floor	57C	Misc	Acoustic Ceiling Pinhole Big Worm	2x2		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
1st Floor	57C	Misc	Wainscot		Beige												
1st Floor	57C	Misc	Covebase Mastic	4"	Off White	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
1st Floor	N159A	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
1st Floor	N159A	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A						
1st Floor	N159A	Floor	Resilient Floor Tile	12x12	Beige	Not Detected	VALB-2-F4.1	Y	N/A	N/A	N/A						
1st Floor	N159A	Door/Door Frame	Wood & Metal		White & Silver	Not Suspect											Possible suspect material in core
1st Floor	N159A	Misc	Covebase Mastic	4"	Tan	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						

Current Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT			Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)						
1st Floor	Acoustic Ceiling Tile	Ceiling	Acoustice Ceiling Tile	2x2		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
1st Floor	Plaster	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	Carpet (mastic)	Floor	Carpet (mastic)		Green	Y	N/A	Y	No	Good	No	No	Yes			Yes	Possible ACM Flooring Underneath
1st Floor	Metal & Metal	Door/Door Frame	Metal & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
1st Floor	Wallboard Joint Compound	Misc	Wallboard Joint Compound		Beige	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A						
1st Floor	Covebase Mastic	Misc	Covebase Mastic	4"	Gray	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
1st Floor	Plaster	Ceiling	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	Plaster	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
1st Floor	Wood & Metal	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
1st Floor	Ceramic Tile	Misc	Ceramic Tile	4x4	Beige	Not Suspect											
2nd Floor	Plaster	Ceiling	Plaster		Off White	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
2nd Floor	Plaster	Wall(s)	Plaster		Off White	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
2nd Floor	Concrete	Floor	Concrete		Bare	Not suspect											
2nd Floor	Wood & Metal	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
2nd Floor	Fireplace	Misc	Fireplace		Gray												
2nd Floor	Plaster	Ceiling	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
2nd Floor	Ceramic Tile	Wall(s)	Ceramic Tile	12x12	Beige	Not Suspect											
2nd Floor	Ceramic Tile	Floor	Ceramic Tile	16x16	Tan	Not Suspect											
2nd Floor	Wood & Metal	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
2nd Floor	Sink Undercoat	Misc	Sink Undercoat		Gray												
2nd Floor	Acoustic Ceiling Tile Rough	Ceiling	Acoustic Ceiling Tile Rough	2x2		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
2nd Floor	Plaster	Wall(s)	Plaster			Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
2nd Floor	Resilient Floor Tile	Floor	Resilient Floor Tile	9x9	White/Olive	Y	N/A	Y	No	Good	No	No	Yes			Yes	
2nd Floor	Wood & Metal	Door/Door Frame	Wood & Metal		Beige & Yellow	Not Suspect											Possible suspect material in core
2nd Floor	Covebase Mastic	Misc	Covebase Mastic	4"	Brown	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
2nd Floor	Acoustic Ceiling Tile Pinhole	Ceiling	Acoustic Ceiling Tile Pinhole	2x2		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
2nd Floor	Plaster	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
2nd Floor	Resilient Floor Tile	Floor	Resilient Floor Tile	9x9	Beige/Brown	Y	N/A	Y	No	Good	No	No	Yes			Yes	
2nd Floor	Wood & Metal	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
2nd Floor	Covebase Mastic	Wall(s)	Covebase Mastic	4"	Off White	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
2nd Floor	Plaster	Ceiling	Plaster		Beige												
2nd Floor	Plaster	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
2nd Floor	Resilient Floor Tile	Floor	Resilient Floor Tile	9x9	White/Olive	Y	N/A	Y	No	Good	No	No	Yes			Yes	
2nd Floor	Wood & Metal	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
2nd Floor	Covebase Mastic	Misc	Covebase Mastic	4"	Brown	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
2nd Floor	Fireplace above Ceiling	Misc	Fireplace above Ceiling		Gray												
2nd Floor	Acoustic Ceiling Tile	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
2nd Floor	Wallboard Joint Compound	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A						
2nd Floor	Carpet (mastic)	Floor	Carpet (mastic)		Blue	Y	N/A	Y	No	Good	No	No	Yes			Yes	Possible ACM Flooring Underneath
2nd Floor	Wood & Metal	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
2nd Floor	Plaster	Misc	Plaster			Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
2nd Floor	Covebase Mastic	Misc	Covebase Mastic	4"	Tan	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
2nd Floor	Acoustic Ceiling Tile	Ceiling	Acoustic Ceiling Tile	1x2		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
2nd Floor	Wallboard Joint Compound	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A						
2nd Floor	Carpet (mastic)	Floor	Carpet (mastic)		Blue	Y	N/A	Y	No	Good	No	No	Yes			Yes	Possible ACM Flooring Underneath
2nd Floor	Wood & Metal	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
2nd Floor	Plaster	Misc	Plaster			Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
2nd Floor	Covebase Mastic	Misc	Covebase Mastic	4"	Off White	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
2nd Floor	Acoustic Ceiling Tile	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
2nd Floor	Wallboard Joint Compound	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A						
2nd Floor	Resilient Floor Tile	Floor	Resilient Floor Tile	9x9	White/Olive	Y	N/A	Y	No	Good	No	No	Yes			Yes	
2nd Floor	Wood & Metal	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
2nd Floor	Covebase Mastic	Wall(s)	Covebase Mastic	4"	Black	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
2nd Floor	Acoustic Ceiling Tile	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
2nd Floor	Wallboard Joint Compound	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A						
2nd Floor	Resilient Floor Tile	Floor	Resilient Floor Tile	9x9	White/Olive	Y	N/A	Y	No	Good	No	No	Yes			Yes	
2nd Floor	Wood & Metal	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect											Possible suspect material in core

Current Rm Name/No.	Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT			Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	Comment
					Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)						
2nd Floor	CC-2-2	Wall(s)	Covebase Mastic	4"	Black	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A					
2nd Floor	247A	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A					
2nd Floor	247A	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A					
2nd Floor	247A	Floor	Carpet (mastic)		Red	Y	N/A	Y	No	Good	No		No	Yes		Possible ACM Flooring Underneath
2nd Floor	247A	Door/Door Frame	Wood & Metal		White & Beige	Not Suspect										Possible suspect material in core
2nd Floor	247A	Misc	Covebase Mastic	4'	Off White	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A					
2nd Floor	247A	Misc	Carpet (mastic)		Brown	Y	N/A	Y	N/A	N/A	N/A					Possible ACM Flooring Underneath
2nd Floor	247A	Misc	Wallboard Joint Compound Over Plaster			Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A					
2nd Floor	2 stor 1	Ceiling	Plaster			Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A					
2nd Floor	2 stor 1	Wall(s)	Plaster		Off White	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A					
2nd Floor	2 stor 1	Floor	Resilient Floor Tile	9x9	Olive	Y	N/A	Y	No	Good	No		No	Yes		
2nd Floor	2 stor 1	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect										Possible suspect material in core
2nd Floor	2 stor 1	Misc	Covebase Mastic	4"	Black	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A					
2nd Floor	2 stor 1	Misc	Fire Caulk		Red	Not Detected	VALB-2-M1.1 - M1.3	Y	N/A	N/A	N/A					
2nd Floor	2 stor 1	Misc	TSI Elbow	1-6"												
2nd Floor	240 1	Ceiling	Plaster			Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A					
2nd Floor	2401	Wall(s)	Plaster		Off White	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A					
2nd Floor	2401	Floor	Resilient Floor Tile	9x9	Olive	Y	N/A	Y	No	Good	No		No	Yes		
2nd Floor	2401	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect										Possible suspect material in core
2nd Floor	2401	Misc	Covebase Mastic	4"	Black	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A					
2nd Floor	2401	Misc	Fire Caulk		Red	Not Detected	VALB-2-M1.1 - M1.3	Y	N/A	N/A	N/A					
2nd Floor	CC-2-2	Ceiling	Acoustic Ceiling Tile	2x2		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A					
2nd Floor	CC-2-2	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A					
2nd Floor	CC-2-2	Floor	Resilient Floor Tile	9x9	White/Olive	Y	N/A	Y	No	Good	No		No	Yes		
2nd Floor	CC-2-2	Door/Door Frame	Metal & Metal		Beige & Beige	Not Suspect										Possible suspect material in core
2nd Floor	CC-2-2	Misc	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A					
2nd Floor	CC-2-2	Misc	Covebase Mastic	4"	Off White	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A					
2nd Floor	CC-2-2	Misc	TSI/F	2'-6" & 1'-4"												
2nd Floor	CC-2-3	Ceiling	Acoustic Ceiling Tile	2x2		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A					
2nd Floor	CC-2-3	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A					
2nd Floor	CC-2-3	Floor	Resilient Floor Tile	9x9	White/Olive	Y	N/A	Y	No	Good	No		No	Yes		
2nd Floor	CC-2-3	Door/Door Frame	Metal & Metal		Beige & Beige	Not Suspect										Possible suspect material in core
2nd Floor	CC-2-3	Misc	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A					
2nd Floor	CC-2-3	Misc	Covebase Mastic	4"	Off White	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A					
2nd Floor	CC-2-3	Misc	TSI/F	2'-6" & 1'-4"												
2nd Floor	206P	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A					
2nd Floor	206P	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A					
2nd Floor	206P	Floor	Resilient Floor Tile		Gray	Not Detected	VALB-2-F1.1 - F1.2	Y	N/A	N/A	N/A					
2nd Floor	206P	Door/Door Frame	Wood & Metal		White & Gray	Not Suspect										Possible suspect material in core
2nd Floor	206P	Misc	Acoustic Ceiling Tile Pinhole	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A					
2nd Floor	206P	Misc	Covebase Mastic	6"	Gray	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A					
2nd Floor	207P	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A					
2nd Floor	207P	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A					
2nd Floor	207P	Floor	Resilient Floor Tile		Gray	Not Detected	VALB-2-F1.1 - F1.2	Y	N/A	N/A	N/A					
2nd Floor	207P	Door/Door Frame	Wood & Metal		White & Gray	Not Suspect										Possible suspect material in core
2nd Floor	207P	Misc	Acoustic Ceiling Tile Pinhole	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A					
2nd Floor	207P	Misc	Covebase Mastic	6"	Gray	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A					
2nd Floor	215P	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A					
2nd Floor	215P	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A					
2nd Floor	215P	Floor	Resilient Floor Tile		Gray	Not Detected	VALB-2-F1.1 - F1.2	Y	N/A	N/A	N/A					
2nd Floor	215P	Door/Door Frame	Wood & Metal		White & Gray	Not Suspect										Possible suspect material in core
2nd Floor	215P	Misc	Acoustic Ceiling Tile Pinhole	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A					
2nd Floor	215P	Misc	Covebase Mastic	6"	Gray	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A					
2nd Floor	204P	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A					
2nd Floor	204P	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A					
2nd Floor	204P	Floor	Resilient Floor Tile		Gray	Not Detected	VALB-2-F1.1 - F1.2	Y	N/A	N/A	N/A					
2nd Floor	204P	Door/Door Frame	Wood & Metal		White & Gray	Not Suspect										Possible suspect material in core



Current Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT			Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)						
2nd Floor	204P	Misc	Acoustic Ceiling Tile Pinhole	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
2nd Floor	204P	Misc	Covebase Mastic	6"	Gray	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
2nd Floor	205P	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
2nd Floor	205P	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A						
2nd Floor	205P	Floor	Resilient Floor Tile		Gray	Not Detected	VALB-2-F1.1 - F1.2	Y	N/A	N/A	N/A						
2nd Floor	205P	Door/Door Frame	Wood & Metal		White & Gray	Not Suspect											Possible suspect material in core
2nd Floor	205P	Misc	Acoustic Ceiling Tile Pinhole	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
2nd Floor	205P	Misc	Covebase Mastic	6"	Gray	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
2nd Floor	214P	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
2nd Floor	214P	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A						
2nd Floor	214P	Floor	Resilient Floor Tile		Gray	Not suspect	VALBA-2-F1.2	Y	N/A	N/A	N/A						
2nd Floor	214P	Door/Door Frame	Wood & Metal		White & Gray	Not Suspect											Possible suspect material in core
2nd Floor	214P	Misc	Acoustic Ceiling Tile Pinhole	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
2nd Floor	214P	Misc	Covebase Mastic	6"	Gray	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
2nd Floor	214P	Misc	Resilient Floor Tile	12x12	White	Y	VALB-2-F3.1	Y	No	Good	No	No	Yes			Yes	
2nd Floor	213P	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
2nd Floor	213P	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A						
2nd Floor	213P	Floor	Resilient Floor Tile		Gray	Not Detected	VALB-2-F1.1 - F1.2	Y	N/A	N/A	N/A						
2nd Floor	213P	Door/Door Frame	Wood & Metal		White & Gray	Not Suspect											Possible suspect material in core
2nd Floor	213P	Misc	Acoustic Ceiling Tile Pinhole	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
2nd Floor	213P	Misc	Covebase Mastic	6"	Gray	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
2nd Floor	210P	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
2nd Floor	210P	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A						
2nd Floor	210P	Floor	Resilient Floor Tile		Gray	Not suspect		Y	N/A	N/A	N/A						
2nd Floor	210P	Door/Door Frame	Wood & Metal		White & Gray	Not Suspect											Possible suspect material in core
2nd Floor	210P	Misc	Acoustic Ceiling Tile Pinhole	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
2nd Floor	210P	Misc	Covebase Mastic	6"	Gray	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
2nd Floor	209P	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
2nd Floor	209P	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A						
2nd Floor	209P	Floor	Resilient Floor Tile		Gray	Not Detected	VALB-2-F1.1 - F1.2	Y	N/A	N/A	N/A						
2nd Floor	209P	Door/Door Frame	Wood & Metal		White & Gray	Not Suspect											Possible suspect material in core
2nd Floor	209P	Misc	Acoustic Ceiling Tile Pinhole	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
2nd Floor	209P	Misc	Covebase Mastic	6"	Gray	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
2nd Floor	212P	Ceiling	Plaster		Beige												
2nd Floor	212P	Wall(s)	Plaster		Beige/Brown	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
2nd Floor	212P	Floor	Carpet (mastic)		White & Beige	Y	N/A	Y	No	Good	No	No	Yes			Yes	Possible ACM Flooring Underneath
2nd Floor	212P	Door/Door Frame	Metal & Metal		Off White	Not Suspect											Possible suspect material in core
2nd Floor	212P	Wall(s)	Covebase Mastic	4"	Red	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
2nd Floor	247	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
2nd Floor	247	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
2nd Floor	247	Floor	Resilient Floor Tile		Beige/Brown	Not Detected	VALB-2-F4.1	Y	N/A	N/A	N/A						
2nd Floor	247	Door/Door Frame	Wood & Metal		White & Beige	Not Suspect											Possible suspect material in core
2nd Floor	247	Misc	Covebase Mastic	4'	Off White	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
2nd Floor	247	Floor	Carpet (mastic)		Brown	Y	N/A	Y	No	Good	No	No	Yes			Yes	Possible ACM Flooring Underneath
2nd Floor	247	Wall(s)	Wallboard Joint Compound Over Plaster			Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A						
2nd Floor	236	Ceiling	Acoustic Ceiling Tile	1x2		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
2nd Floor	236	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A						
2nd Floor	236	Floor	Carpet (mastic)		Blue	Y	N/A	Y	No	Good	No	No	Yes			Yes	Possible ACM Flooring Underneath
2nd Floor	236	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
2nd Floor	236	Misc	Plaster			Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
2nd Floor	236	Misc	Covebase Mastic	4"	Tan	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
2nd Floor	237	Ceiling	Acoustic Ceiling Tile	1x2		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
2nd Floor	237	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A						
2nd Floor	237	Floor	Carpet (mastic)		Blue	Y	N/A	Y	No	Good	No	No	Yes			Yes	Possible ACM Flooring Underneath
2nd Floor	237	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
2nd Floor	237	Misc	Plaster			Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
2nd Floor	237	Misc	Covebase Mastic	4"	Tan	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						

Current Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT			Significantly Damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)						
2nd Floor	243	Ceiling	Acoustic Ceiling Tile	1x2		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
2nd Floor	243	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A						
2nd Floor	243	Floor	Carpet (mastic)		Blue	Y	N/A	Y	No	Good	No	No	Yes			Yes	Possible ACM Flooring Underneath
2nd Floor	243	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
2nd Floor	243	Misc	Plaster			Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
2nd Floor	243	Misc	Covebase Mastic	4"	Tan	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
2nd Floor	245	Ceiling	Acoustic Ceiling Tile	1x2		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
2nd Floor	245	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A						
2nd Floor	245	Floor	Carpet (mastic)		Blue	Y	N/A	Y	No	Good	No	No	Yes			Yes	Possible ACM Flooring Underneath
2nd Floor	245	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
2nd Floor	245	Misc	Plaster			Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
2nd Floor	245	Misc	Covebase Mastic	4"	Tan	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
2nd Floor	240	Ceiling	Acoustic Ceiling Tile	1x2		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
2nd Floor	240	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A						
2nd Floor	240	Floor	Carpet (mastic)		Blue	Y	N/A	Y	No	Good	No	No	Yes			Yes	Possible ACM Flooring Underneath
2nd Floor	240	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
2nd Floor	240	Wall(s)	Plaster			Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
2nd Floor	240	Misc	Covebase Mastic	4"	Tan	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
2nd Floor	240	Misc	TSI Elbow	2"													
2nd Floor	261	Ceiling	Plaster		Off White	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
2nd Floor	261	Wall(s)	Plaster		Off White	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
2nd Floor	261	Floor	Concrete		Bare	Not suspect											
2nd Floor	261	Wall(s)	Wallboard Joint Compund		Olive/White	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A						
2nd Floor	600-2	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
2nd Floor	600-2	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
2nd Floor	600-2	Floor	Resilient Floor Tile	9x9	White/Olive	Y	N/A	Y	No	Good	No	No	Yes			Yes	
2nd Floor	600-2	Door/Door Frame	Metal & Metal		Beige & Beige	Not Suspect											
2nd Floor	600-2		Resilient Floor Tile		Brown	Not Detected	VALB-2-F4.1	Y	N/A	N/A	N/A						
2nd Floor	600-2	Misc	Covebase Mastic	6"	Off White	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
2nd Floor	257	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
2nd Floor	257	Wall(s)	Plaster		Gray	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
2nd Floor	257	Floor	Carpet (mastic)		Gray	Y	N/A	Y	No	Good	No	No	Yes			Yes	Possible ACM Flooring Underneath
2nd Floor	257	Door/Door Frame	Wood & Metal		Off White & Gray	Not Suspect											Possible suspect material in core
2nd Floor	257	Misc	Covebase Mastic	4"	Gray	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
2nd Floor	255	Ceiling	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
2nd Floor	255	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
2nd Floor	255	Floor	Ceramic Tile	2x2	Beige	Not Suspect											
2nd Floor	255	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
2nd Floor	255	Misc	Ceramic Tile	4x4	Off White	Not Suspect											
2nd Floor	253A	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
2nd Floor	253A	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
2nd Floor	253A	Door/Door Frame	Metal & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
2nd Floor	253A	Misc	Covebase Mastic	6"	Off White	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
2nd Floor	353	Ceiling	Acoustic Ceiling Tile Textured	12x12		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
2nd Floor	353	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
2nd Floor	353	Floor	Wood V-shaped		Wood	Not suspect											
2nd Floor	353	Door/Door Frame	Metal & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
2nd Floor	353	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A						
2nd Floor	200-2	Ceiling	Plaster			Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
2nd Floor	200-2	Wall(s)	Plaster		Off White	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
2nd Floor	200-2	Floor	Concrete		Bare	Not suspect											
2nd Floor	200-2	Door/Door Frame	Wood & Metal		Off white & Off white	Not Suspect											Possible suspect material in core
2nd Floor	258	Ceiling	Plaster		Off White	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
2nd Floor	258	Wall(s)	Ceramic Tile		Geen	Not Suspect											
2nd Floor	258	Floor	Ceramic Tile	4x4	Gray & Dark Gray	Not Suspect											
2nd Floor	258	Door/Door Frame	Wood & Metal	1x2	Off white & Off white	Not Suspect											Possible suspect material in core
2nd Floor	263	Ceiling	Plaster		Off White	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						

Current Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT			Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)						
2nd Floor	263	Wall(s)	Plaster		Off White	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
2nd Floor	263	Floor	Ceramic Tile	1x1	Gray	Not Suspect											
2nd Floor	263	Door/Door Frame	Wood & Metal		On white & On white	Not Suspect											Possible suspect material in core
2nd Floor	263	Misc	Ceramic Tile	4x4	On white & On white	Not Suspect											
2nd Floor	260	Ceiling	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
2nd Floor	260	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
2nd Floor	260	Floor	Wood		Wood	Not suspect											
2nd Floor	260	Misc	Curtain Theater No tag		Blue & Black												
3rd Floor	260	Ceiling	Plaster		Red	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
3rd Floor	260	Wall(s)	Plaster		Red	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
3rd Floor	260	Floor	Resilient Floor Tile	9x9	White/Olive	Y	N/A	Y	No	Good	No	No	Yes			Yes	
3rd Floor	260	Door/Door Frame	Wood & Metal		Tan & Beige	Not Suspect											Possible suspect material in core
3rd Floor	260	Misc	Covebase Mastic	4"	Black	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
3rd Floor	357	Ceiling	Acoustic Ceiling Tile Tiny Pinhole	1x2		Not Detected	VALB-2-W1.1	Y	N/A	N/A	N/A						
3rd Floor	357	Wall(s)	Acoustic Ceiling Tile Tiny Pinhole	12x12		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
3rd Floor	357	Floor	Resilient Floor Tile	9x9	White/Olive	Y	N/A	Y	No	Good	No	No	Yes			Yes	
3rd Floor	357	Door/Door Frame	Metal & Metal		Gray & White	Not Suspect											Possible suspect material in core
3rd Floor	357	Misc	Covebase Mastic	4"	Black	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
3rd Floor	356	Ceiling	Acoustic Ceiling Tile Tiny Pinhole	1x2		Not Detected	VALB-2-C1.1 - C1.2	Y	N/A	N/A	N/A						
3rd Floor	356	Wall(s)	Acoustic Ceiling Tile Tiny Pinhole	12x12		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
3rd Floor	356	Floor	Resilient Floor Tile	9x9	White/Olive	Y	N/A	Y	No	Good	No	No	Yes			Yes	
3rd Floor	356	Door/Door Frame	Metal & Metal		Gray & White	Not Suspect											Possible suspect material in core
3rd Floor	356	Misc	Covebase Mastic	4"	Black	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
3rd Floor	355	Ceiling	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
3rd Floor	355	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
3rd Floor	355	Floor	Resilient Floor Tile	9x9	White/Olive	Y	N/A	Y	No	Good	No	No	Yes			Yes	
3rd Floor	355	Door/Door Frame	Wood & Metal		Gray & Beige	Not Suspect											Possible suspect material in core
3rd Floor	355	Misc	Covebase Mastic	4"	Black	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
3rd Floor	355C	Ceiling	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
3rd Floor	355C	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
3rd Floor	355C	Floor	Resilient Floor Tile	9x9	White/Olive	Y	N/A	Y	No	Good	No	No	Yes			Yes	
3rd Floor	355C	Door/Door Frame	Wood & Metal		Gray & Beige	Not Suspect											Possible suspect material in core
3rd Floor	355C	Misc	Covebase Mastic	4"	Black	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
3rd Floor	355B	Ceiling	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
3rd Floor	355B	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
3rd Floor	355B	Floor	Resilient Floor Tile	9x9	White/Olive	Y	N/A	Y	No	Good	No	No	Yes			Yes	
3rd Floor	355B	Door/Door Frame	Wood & Metal		Gray & Beige	Not Suspect											Possible suspect material in core
3rd Floor	355B	Misc	Covebase Mastic	4"	Black	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
3rd Floor	354	Ceiling	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
3rd Floor	354	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
3rd Floor	354	Floor	Resilient Floor Tile	9x9	White/Olive	Y	N/A	Y	No	Good	No	No	Yes			Yes	
3rd Floor	354	Door/Door Frame	Wood & Metal		Gray & Beige	Not Suspect											Possible suspect material in core
3rd Floor	354	Misc	Covebase Mastic	4"	Black	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
3rd Floor	355A	Ceiling	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
3rd Floor	355A	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
3rd Floor	355A	Floor	Ceramic Tile	1x1	Gray	Not Suspect											
3rd Floor	355A	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
3rd Floor	355A	Wall(s)	Ceramic Tile	4x4	Off White	Not Suspect											
3rd Floor	346A	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
3rd Floor	346A	Wall(s)	Wall board Joint Compound		Beige	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A						
3rd Floor	346A	Floor	Carpet (mastic)		Brown	Y	N/A	Y	N/A	N/A	N/A						
3rd Floor	346A	Door/Door Frame	Wood & Metal		White & Beige	Not Suspect											Possible suspect material in core
3rd Floor	346A	Wall(s)	Plaster		Beige & Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
3rd Floor	346A	Misc	Covebase Mastic	4"	Gray	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
3rd Floor	346A	Ceiling	Fire Caulk		Tan	Not Detected	VALB-2-M1.1 - M1.3	Y	N/A	N/A	N/A						
3rd Floor	305D	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
3rd Floor	305D	Wall(s)	Wall board Joint Compound		Beige	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A						

Current Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT			Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)						
3rd Floor	305D	Floor	Carpet (mastic)		Tan	Y	N/A	Y	No	Good	No	No	Yes			Yes	Possible ACM Flooring Underneath
3rd Floor	305D	Door/Door Frame	Wood & Metal		White & Beige	Not Suspect											Possible suspect material in core
3rd Floor	305D	Misc	Covebase Mastic	4"	Gray	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
3rd Floor	305D	Wall(s)	Plaster		Green	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
3rd Floor	348	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
3rd Floor	348	Wall(s)	Plaster		Off White	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
3rd Floor	348	Floor	Resilient Floor Tile	9x9	White/Olive	Y	N/A	Y	No	Good	No	No	Yes			Yes	
3rd Floor	348	Ceiling	Plaster		Off White												
3rd Floor	349	Ceiling	Plaster			Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
3rd Floor	349	Wall(s)	Plaster		Off White	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
3rd Floor	349	Floor	Ceramic Tile	1x1	Gray	Not Suspect											
3rd Floor	349	Door/Door Frame	Wood & Metal		White & Off White	Not Suspect											Possible suspect material in core
3rd Floor	349	Wall(s)	Ceramic Tile	4x4	Off White	Not Suspect											
3rd Floor	351	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
3rd Floor	351	Wall(s)	Plaster		Off White	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
3rd Floor	351	Floor	Resilient Floor Tile	9x9	White/Olive	Y	N/A	Y	No	Good	No	No	Yes			Yes	
3rd Floor	351	Misc	Plaster		Off White												
3rd Floor	304A	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
3rd Floor	304A	Wall(s)	Wall board Joint Compound		Beige & Gray	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A						
3rd Floor	304A	Floor	Carpet (mastic)		Brown	Y	N/A	Y	No	Good	No	No	Yes			Yes	Possible ACM Flooring Underneath
3rd Floor	304A	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
3rd Floor	304A	Misc	Covebase Mastic	4"	Beige	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
3rd Floor	304B	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
3rd Floor	304B	Wall(s)	Wall board Joint Compound		Beige & Gray	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A						
3rd Floor	304B	Floor	Carpet (mastic)		Brown	Y	N/A	Y	No	Good	No	No	Yes			Yes	Possible ACM Flooring Underneath
3rd Floor	304B	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
3rd Floor	304B	Misc	Covebase Mastic	4"	Beige	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
3rd Floor	304C	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
3rd Floor	304C	Wall(s)	Wall board Joint Compound		Beige & Gray	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A						
3rd Floor	304C	Floor	Carpet (mastic)		Brown	Y	N/A	Y	No	Good	No	No	Yes			Yes	Possible ACM Flooring Underneath
3rd Floor	304C	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
3rd Floor	304C	Misc	Covebase Mastic	4"	Beige	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
3rd Floor	304D	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
3rd Floor	304D	Wall(s)	Wall board Joint Compound		Beige & Gray	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A						
3rd Floor	304D	Floor	Carpet (mastic)		Brown	Y	N/A	Y	No	Good	No	No	Yes			Yes	Possible ACM Flooring Underneath
3rd Floor	304D	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
3rd Floor	304D	Misc	Covebase Mastic	4"	Beige	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
3rd Floor	304E	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
3rd Floor	304E	Wall(s)	Wall board Joint Compound		Beige & Gray	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A						
3rd Floor	304E	Floor	Carpet (mastic)		Brown	Y	N/A	Y	No	Good	No	No	Yes			Yes	Possible ACM Flooring Underneath
3rd Floor	304E	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
3rd Floor	304E	Misc	Covebase Mastic	4"	Beige	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
3rd Floor	304F	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
3rd Floor	304F	Wall(s)	Wall board Joint Compound		Beige & Gray	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A						
3rd Floor	304F	Floor	Carpet (mastic)		Brown	Y	N/A	Y	No	Good	No	No	Yes			Yes	Possible ACM Flooring Underneath
3rd Floor	304F	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
3rd Floor	304F	Misc	Covebase Mastic	4"	Beige	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
3rd Floor	304G	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
3rd Floor	304G	Wall(s)	Wall board Joint Compound		Beige & Gray	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A						
3rd Floor	304G	Floor	Carpet (mastic)		Brown	Y	N/A	Y	No	Good	No	No	Yes			Yes	Possible ACM Flooring Underneath
3rd Floor	304G	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
3rd Floor	304G	Misc	Covebase Mastic	4"	Beige	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
3rd Floor	304H	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
3rd Floor	304H	Wall(s)	Wall board Joint Compound		Beige & Gray	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A						
3rd Floor	304H	Floor	Carpet (mastic)		Brown	Y	N/A	Y	No	Good	No	No	Yes			Yes	Possible ACM Flooring Underneath
3rd Floor	304H	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
3rd Floor	304H	Misc	Covebase Mastic	4"	Beige	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						

Current Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT			Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)						
3rd Floor	304J	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
3rd Floor	304J	Wall(s)	Wall board Joint Compound		Beige & Gray	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A						
3rd Floor	304J	Floor	Carpet (mastic)		Brown	Y	N/A	Y	No	Good	No	No	Yes			Yes	Possible ACM Flooring Underneath
3rd Floor	304J	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
3rd Floor	304J	Misc	Covebase Mastic	4"	Beige	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
3rd Floor	304K	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
3rd Floor	304K	Wall(s)	Wall board Joint Compound		Beige & Gray	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A						
3rd Floor	304K	Floor	Carpet (mastic)		Brown	Y	N/A	Y	No	Good	No	No	Yes			Yes	Possible ACM Flooring Underneath
3rd Floor	304K	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
3rd Floor	304K	Misc	Covebase Mastic	4"	Beige	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
3rd Floor	305A	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
3rd Floor	305A	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
3rd Floor	305A	Floor	Carpet (mastic)		Tan	Y	N/A	Y	No	Good	No	No	Yes			Yes	Possible ACM Flooring Underneath
3rd Floor	305A	Wall(s)	Wall board Joint Compound		Beige	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A						
3rd Floor	305A	Misc	Covebase Mastic	4"	Blue	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
3rd Floor	346B	Ceiling	Plaster		Red	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
3rd Floor	346B	Wall(s)	Plaster		Red	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
3rd Floor	346B	Floor	Carpet (mastic)		Tan	Y	N/A	Y	No	Good	No	No	Yes			Yes	Possible ACM Flooring Underneath
3rd Floor	346B	Misc	Wall board Joint Compound		Red	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A						
3rd Floor	346B	Misc	Covebase Mastic & Grout	4"	Gray & Brown	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
3rd Floor	346B	Ceiling	Acoustic Ceiling Tile - Whole Brg			Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
3rd Floor	346B	Wall(s)	Wall board Joint Compound		Beige	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A						
3rd Floor	346B	Floor	Carpet (mastic)		Blue	Y	N/A	Y	No	Good	No	No	Yes			Yes	Possible ACM Flooring Underneath
3rd Floor	346B	Door/Door Frame	Wood & Metal		Wood	Not Suspect											Possible suspect material in core
3rd Floor	346B	Misc	Plaster		Beige & Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
3rd Floor	346B	Misc	Covebase Mastic & Grout		Tan	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
3rd Floor	346B	Misc	Above Ceiling HVAC Wrap		Green	Y	N/A	Y	Y	Fair	No	No	Yes	Yes			
Basement	48	Ceiling	Concrete		White	Not suspect											
Basement	48	Wall(s)	Plaster on Carpet (mastic) Mastic		White & Gray	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						Possible ACM Flooring Underneath
Basement	48	Floor	Concrete		Gray	Not suspect											
Basement	48	Door/Door Frame	Metal		Blue	Not Suspect											Possible suspect material in core
Basement	48	Misc	HVAC Wrap		Tan												
Basement	48	Misc	TSI at Fitting (elbow etc.)	2" x 4" x 1/2"													
Basement	48	Misc	Reselient Floor Tile	12x12	Gray												
Basement	48	Ceiling	Corrugated Metal														
Basement	48	Wall(s)	Concrete with Vapor			Not suspect											
Basement	48	Floor	Concrete			Not suspect											
Basement	48	Door/Door Frame	Metal & Metal		Beige	Not Suspect											Possible suspect material in core
Basement	38	Ceiling	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
Basement	38	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
Basement	38	Floor	Ceramic Tile	2x2	Beige	Not Suspect											
Basement	38	Door/Door Frame	Wood & Metal		Gray & Beige	Not Suspect											Possible suspect material in core
Basement	38	Wall(s)	Ceramic Tile	4x4	Off White	Not Suspect											
Basement	38	Ceiling	Plaster		Off White	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
Basement	38	Wall(s)	Plaster		Beige & Gray	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
Basement	38	Floor	Reselient Floor Tile	12x12	Seafoam Blue	<1%	VALB-2-F5.1	Y	No	Good	No	No	Yes			Yes	
Basement	38	Door/Door Frame	Wood & Metal		Green & Beige	Not Suspect											Possible suspect material in core
Basement	38	Wall(s)	Reselient Floor Tile	12x12	Beige												
Basement	38	Misc	Covebase Mastic	4"	Brown	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
Basement	38	Misc	Covebase Mastic	6"	Brown	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
Basement	40	Ceiling	Plaster		Beige & Purple	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
Basement	40	Wall(s)	Plaster		Pink	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
Basement	40	Floor	Ceramic Tile	1x1	Gray	Not Suspect											
Basement	40	Door/Door Frame	Wood & Metal		Green & Pink	Not Suspect											Possible suspect material in core
Basement	40	Misc	Ceramic Tile	4x4	Off White	Not Suspect											
Basement	39	Ceiling	Plaster		Beige & Purple	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
Basement	39	Wall(s)	Plaster		Pink	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						

Current Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT			Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)						
Basement	39	Floor	Ceramic Tile	1x1	Gray	Not Suspect											
Basement	39	Door/Door Frame	Wood & Metal		Green & Pink	Not Suspect											Possible suspect material in core
Basement	39	Misc	Ceramic Tile	4x4	Off White	Not Suspect											
Basement	35	Ceiling	Plaster		Beige & Purple	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
Basement	35	Wall(s)	Plaster		Pink	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
Basement	35	Floor	Ceramic Tile	1x1	Gray	Not Suspect											
Basement	35	Door/Door Frame	Wood & Metal		Green & Pink	Not Suspect											Possible suspect material in core
Basement	35	Wall(s)	Ceramic Tile	4x4	Off White	Not Suspect											
Basement	46A	Ceiling	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
Basement	46A	Wall(s)	Plaster on Carpet (mastic) Mastic		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						Possible ACM Flooring Underneath
Basement	46A	Floor	Reselient Floor Tile	12x12	Gray												
Basement	46A	Door/Door Frame	Wood & Metal		Green & Off White	Not Suspect											Possible suspect material in core
Basement	46A	Wall(s)	Covebase Mastic	6"	Brown	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
Basement	46	Ceiling	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
Basement	46	Wall(s)	Plaster on Carpet (mastic) Mastic		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						Possible ACM Flooring Underneath
Basement	46	Floor	Reselient Floor Tile	12x12	Gray												
Basement	46	Door/Door Frame	Wood & Metal		Green & Off White	Not Suspect											Possible suspect material in core
Basement	46	Wall(s)	Covebase Mastic	6"	Brown	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
Basement	46	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
Basement	46	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
Basement	46	Floor	Concrete		Gray	Not suspect											
Basement	46	Door/Door Frame	Metal & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
Basement	58	Ceiling	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
Basement	58	Wall(s)	Plaster		Beige & Blue	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
Basement	58	Floor	Metal Exposed		Black	Not suspect											
Basement	58	Door/Door Frame	Metal & Metal		Beige & Blue	Not Suspect											Possible suspect material in core
Basement	58	Misc	Covebase Mastic & Grout		Brown & Brown	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
Basement	37A	Ceiling	Wallboard Joint Compound		Beige	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A						
Basement	37A	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A						
Basement	37A	Floor	Reselient Floor Tile	12x12	Seafoam Blue	<1%	VALB-2-F5.1	Y	No	Good	No	No	Yes			Yes	
Basement	37A	Door/Door Frame	Metal & Metal		Green & Beige	Not Suspect											Possible suspect material in core
Basement	37A	Misc	Reselient Floor Tile	12x12	Beige	Not suspect	VALB-2-F4.1	Y									
Basement	37A	Misc	Covebase Mastic	6"	Brown	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
Basement	45	Ceiling	Plaster		Off White	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
Basement	45	Wall(s)	Ceramic Tile	4x4	Off White	Not Suspect											
Basement	45	Floor	Ceramic Tile	1x1	Gray & White	Not Suspect											
Basement	45	Door/Door Frame	Wood & Metal		Gray & Beige	Not Suspect											Possible suspect material in core
Basement	44	Ceiling	Plaster		Off White	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
Basement	44	Wall(s)	Ceramic Tile	4x4	Off White	Not Suspect											
Basement	44	Floor	Ceramic Tile	1x1	Gray & White	Not Suspect											
Basement	44	Door/Door Frame	Wood & Metal		Gray & Beige	Not Suspect											Possible suspect material in core
Basement	43	Ceiling	Plaster		Off White	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
Basement	43	Wall(s)	Ceramic Tile	4x4	Off White	Not Suspect											
Basement	43	Floor	Ceramic Tile	1x1	Gray & White	Not Suspect											
Basement	43	Door/Door Frame	Wood & Metal		Gray & Beige	Not Suspect											Possible suspect material in core
Basement	Refrige	Ceiling	Metal			Not suspect											
Basement	Refrige	Wall(s)	Metal			Not suspect											
Basement	Refrige	Floor	Ceramic Tile	1"	Gray	Not Suspect											
Basement	Refrige	Door/Door Frame	Metal & Metal		Silver & Siver	Not Suspect											Possible suspect material in core
Basement	Refrige	Misc	TSI at Fitting (elbow etc.)	1+8" & 3"		Y	N/A	Y	Y	Good	No	No	Yes	Yes			
Basement	50B	Ceiling	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
Basement	50B	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	No	Good	No	No	Yes			Yes	

Current Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT			Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)						
Basement	50B	Floor	Reselient Floor Tile	12x12	Seafoam Blue	<1%	VALB-2-F5.1	Y									
Basement	50B	Door/Door Frame	Metal & Metal		Blue & Beige	Not Suspect											Possible suspect material in core
Basement	50B	Misc	Covebase Mastic	4"	Gray	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
Basement	50M	Ceiling	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
Basement	50M	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
Basement	50M	Floor	Concrete		Gray	Not suspect											
Basement	50M	Door/Door Frame	Wood & Metal		Blue & Beige	Not Suspect											Possible suspect material in core
Basement	50L	Ceiling	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
Basement	50L	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
Basement	50L	Floor	Concrete		Gray	Not suspect											
Basement	50L	Door/Door Frame	Wood & Metal		Blue & Beige	Not Suspect											Possible suspect material in core
Basement	50C	Ceiling	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
Basement	50C	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
Basement	50C	Floor	Reselient Floor Tile	12x12	Gray												
Basement	50C	Door/Door Frame	Wood & Metal		Blue & Beige	Not Suspect											Possible suspect material in core
Basement	50C	Misc	Covebase Mastic	4"	Gray	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
Basement	57	Ceiling	Plaster		Beige												
Basement	57	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
Basement	57	Floor	Concrete		Gray	Not suspect											
Basement	57	Door/Door Frame	Wood & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
Basement	57	Misc	Ceramic Tile	4x4	Off White	Not Suspect											
Basement	50A	Ceiling	Plaster		Off White	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
Basement	50A	Wall(s)	Plaster		Off White	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
Basement	50A	Floor	Concrete		Gray	Not suspect											
Basement	50A	Door/Door Frame	Metal & Metal		Blue & Beige	Not Suspect											Possible suspect material in core
Basement	50A	Misc	Fire Caulk		Red	Not Detected	VALB-2-M1.1 - M1.3	Y	N/A	N/A	N/A						
Basement	50A	Misc	Pipe Logging		Beige	Y	N/A	Y	Y	Good	No	No	Yes	Yes			
Basement	55	Ceiling	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
Basement	55	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
Basement	55	Floor	Concrete Gloss with Black Mastic		Beige	Not suspect											
Basement	55	Door/Door Frame	Metal & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
Basement	55	Misc	Wallboard Joint Compound		Beige	Not Detected	VALB-2-C5.6 - 5.7	Y	N/A	N/A	N/A						
Basement	55	Misc	Covebase Mastic	4"	Off White	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
Basement	55	Misc	Fire Caulk		Red	Not Detected	VALB-2-M1.1 - M1.3	Y	N/A	N/A	N/A						
Basement	55	Misc	Pipe Logging		Beige	Y	N/A	Y	Y	Good	No	No	Yes	Yes			
Basement	55	Misc	Fire Caulk		Blue & Beige	Not Detected	VALB-2-M2.1	Y	N/A	N/A	N/A						
Basement	50C	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
Basement	50C	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
Basement	50C	Floor	Reselient Floor Tile	12x12	Gray												
Basement	50C	Door/Door Frame	Metal & Metal		Blue & Beige	Not Suspect											Possible suspect material in core
Basement	50C	Wall(s)	Covebase Mastic	4"	Gray	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
Basement	50 CC	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
Basement	50 CC	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
Basement	50 CC	Floor	Ceramic Tile	1x2	Gray & Dark Gray	Not Suspect											
Basement	50 CC	Door/Door Frame	Metal & Metal		Blue & Beige	Not Suspect											Possible suspect material in core
Basement	50 CC	Misc	Covebase Mastic	4"	Gray	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
Basement	50 BB	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
Basement	50 BB	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
Basement	50 BB	Floor	Ceramic Tile	1x2	Gray & Dark Gray	Not Suspect											
Basement	50 BB	Door/Door Frame	Metal & Metal		Blue & Beige	Not Suspect											Possible suspect material in core
Basement	50 BB	Misc	Covebase Mastic	4"	Gray	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
Basement	50D	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
Basement	50D	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						

Current Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT			Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)						
Basement	50D	Floor	Concrete		Gray	Not suspect											
Basement	50D	Door/Door Frame	Metal & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
Basement	50J	Ceiling	Plaster		Off White	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
Basement	50J	Wall(s)	Plaster		Off White	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
Basement	50J	Floor	Concrete		Bare	Not suspect											
Basement	50J	Door/Door Frame	Metal & Metal		Off White	Not Suspect											Possible suspect material in core
Basement	50J	Misc	Covebase Mastic	4"	Brown	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
Basement	50I	Ceiling	Plaster		Off White	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
Basement	50I	Wall(s)	Plaster		Off White	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
Basement	50I	Floor	Concrete		Bare	Not suspect											
Basement	50I	Door/Door Frame	Metal & Metal		Off White	Not Suspect											Possible suspect material in core
Basement	50I	Misc	Covebase Mastic	4"	Brown	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
Basement	50E	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
Basement	50E	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
Basement	50E	Floor	Reselient Floor Tile	12x12	Gray												
Basement	50E	Door/Door Frame	Metal & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
Basement	50E	Misc	Covebase Mastic	4"	Brown	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
Basement	50G	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
Basement	50G	Wall(s)	Plaster			Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
Basement	50G	Floor	Carpet (mastic)		Blue & Beige	Y	N/A	Y	N/A	N/A	N/A						Possible ACM Flooring Underneath
Basement	50G	Door/Door Frame	Metal & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
Basement	50G	Misc	Covebase Mastic	4"	Brown	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
Basement	50G	Misc	Reselient Floor Tile / Mastic	12x12	White	Y	VALB-2-F6.1	Y									
Basement	50F	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
Basement	50F	Wall(s)	Plaster			Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
Basement	50F	Floor	Carpet (mastic)		Blue & Beige	Y	N/A	Y	No	Good	No	No	Yes			Yes	Possible ACM Flooring Underneath
Basement	50F	Door/Door Frame	Metal & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
Basement	50F	Wall(s)	Covebase Mastic	4"	Off White	Not Detected	VALB-2-M3.1 - M3.2	Y	N/A	N/A	N/A						
Basement	50F	Misc	Reselient Floor Tile / Mastic	12x12	White	Y	VALB-2-F6.2	Y									
Basement	50Z-	Ceiling	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
Basement	50Z-	Wall(s)	Plaster & Concrete		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
Basement	50Z-	Floor	Concrete		Bare	Not suspect											
Basement	50Z-	Door/Door Frame	Metal & Metal		Blue & Beige	Not Suspect											Possible suspect material in core
Basement	50Z-	Ceiling	Acoustic Ceiling Tile	2x4		Not Detected	VALB-2-C1.1 - C5.7	Y	N/A	N/A	N/A						
Basement	50Z-	Wall(s)	Concrete & Block		Beige	Not suspect											
Basement	50Z-	Floor	Concrete		Bare	Not suspect											
Basement	50Z-	Door/Door Frame	Metal & Metal		Silver & Black	Not Suspect											Possible suspect material in core
Basement	54	Ceiling	Concrete		Beige	Not suspect											
Basement	54	Wall(s)	Concrete		Beige	Not suspect											
Basement	54	Floor	Concrete		bare	Not suspect											
Basement	54	Door/Door Frame	Metal & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
Basement	54	Misc	Fire Caulk		Red	Not Detected	VALB-2-M1.1 - M1.3	Y	N/A	N/A	N/A						
Basement	54	Misc	HVAC Tape		Off White	Y	VALB-2-M4.1	Y	No	Good	No	No	Yes			Yes	
Basement	54	Misc	TSI at Fitting (elbow etc.)	4"-2+		Y	N/A	Y	Y	Good	No	No	Yes	Yes			
Basement	2FEC1	Ceiling	Plaster		Red	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
Basement	2FEC1	Wall(s)	Plaster			Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
Basement	2FEC1	Floor	Concrete		Bare	Not suspect											
Basement	50Z-	Ceiling	Plaster		Tan	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
Basement	50Z-	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
Basement	50Z-	Floor	Concrete		Bare	Not suspect											
Basement	50Z-	Door/Door Frame	Metal & Metal		Beige & Beige	Not Suspect											Possible suspect material in core
Basement	50	Ceiling	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
Basement	50	Wall(s)	Plaster		Beige	Not Detected	VALB-2-C5.1 - 5.5	Y	N/A	N/A	N/A						
Basement	50	Floor	Concrete		Bare	Not suspect											
Basement	50	Door/Door Frame	Metal & Metal		Blue & Off White	Not Suspect											Possible suspect material in core
Basement	50	Misc	TSI at Fitting (elbow etc.)	4"-2+													
Basement	50	Misc	Fire Caulk		Red	Not Detected	VALB-2-M1.1 - M1.3	Y	N/A	N/A	N/A						



[illegible]