

[illegible]

[illegible]

Rm Name/No.		Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	HA #	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	SignificantlyDamaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
Basement	18A	Ceiling	Acoustic Ceiling Tile Pinhole Worm	2 x 4	White	C1.1-C1.3	N	C1	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Basement	18A	Wall(s)	Concrete Wallboard with Joint Compound	950 SF	Beige	N	W1.1-W1.3	N	W1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Basement	18A	Floor	Resilient Floor Tile	12 x 12/450 SF	Brown	N	F8.1-F8.3	N	F8	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Basement	18A	Door/Door Frame	Wood and Metal		Blue/White	Not Suspect	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Basement	18A	Misc	Covebase & Glue	4"	Brown & Tan	N	N	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Basement	18A	Misc	Ceramic Tile & Grout	4 x 4	White & White	N/A-Would have required destructive sampling.	N/A	N/a	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Basement	18B	Ceiling	Acoustic Ceiling Tile Pinhole Worm	2 x 4	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Basement	18B	Wall(s)	Concrete Wallboard with Joint Compound		Beige	N	W1.1-W1.3	N	W1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Basement	18B	Floor	Resilient Floor Tile	12 x 12	Brown	N	F8.1-F8.3	N	F8	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Basement	18B	Door/Door Frame	Wood and Metal		Blue/White	Not Suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Basement	18B	Misc	Covebase & Glue	4"	Brown & Tan	N	M4.1-M4.3	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Basement	18B	Misc	Ceramic Tile & Grout	4 x 4	White & White	N/A-Would have required destructive sampling.	N/A	N/a	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Basement	18C	Ceiling															
Basement	18C	Wall(s)	Wallboard & Joint Compound/ Plaster			N	C2.1-C2.3	N	C2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Basement	18C	Floor															
Basement	Exterior	Wall(s)	Concrete		Beige	Not Suspect	NA	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Basement	Exterior	Wall(s)	Windows (Old) & Window Putty		Beige	N	N	Y	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Basement	Exterior	Floor	Windows (New) & Window Sealant- First Floor		Silver	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Basement	Exterior	Wall(s)	Stucco 1st Floor		Beige	N	N	Y	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100T	Ceiling	Acoustic Ceiling Tile Pinhole Worm	2 x 4	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100T	Wall(s)	Wallboard with Joint Compound		Green/Beige	N	N	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100T	Floor	Carpet		Brown	Not Suspect	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100T	Door/Door Frame	Wood and Metal		Bare/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100T	Misc	Covebase & Glue	4"	Beige & Tan	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100S	Ceiling	Acoustic Ceiling Tile Pinhole Worm	2 x 4	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100S	Wall(s)	Wallboard with Joint Compound		Green/Beige	N	N	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100S	Floor	Carpet		Brown	Not Suspect	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100S	Door/Door Frame	Wood and Metal		Bare/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Rm Name/No.		Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	HA #	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	SignificantlyDamaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
1st Floor	100S	Misc	Covebase & Glue	4"	Beige & Tan	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100A	Ceiling	Acoustic Ceiling Tile Pinhole Worm	2 x 4	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100A	Wall(s)	Wallboard with Joint Compound		Green/Beige	N	N	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100A	Floor	Carpet		Brown	Not Suspect	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100A	Door/Door Frame	Wood and Metal		Bare/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100A	Misc	Covebase & Glue	4"	Beige & Tan	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100Q	Ceiling	Acoustic Ceiling Tile Pinhole Worm	2 x 4	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100Q	Wall(s)	Wallboard with Joint Compound		Green/Beige	N	N	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100Q	Floor	Carpet		Brown	Not Suspect	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100Q	Door/Door Frame	Wood and Metal		Bare/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100Q	Misc	Covebase & Glue	4"	Beige & Tan	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Rm Name/No.		Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	HA #	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	SignificantlyDamaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
1st Floor	100D	Ceiling	Acoustic Ceiling Tile Pinhole Worm	2 x 4	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100D	Wall(s)	Wallboard with Joint Compound		Green/Beige	N	N	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100D	Floor	Carpet		Brown	Not Suspect	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100D	Door/Door Frame	Wood and Metal		Bare/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100D	Misc	Covebase & Glue	4"	Beige & Tan	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100C	Ceiling	Acoustic Ceiling Tile Pinhole Worm	2 x 4	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100C	Wall(s)	Wallboard with Joint Compound		Green/Beige	N	N	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100C	Floor	Carpet		Brown	Not Suspect	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100C	Door/Door Frame	Wood and Metal		Bare/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100C	Misc	Covebase & Glue	4"	Beige & Tan	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100M	Ceiling	Acoustic Ceiling Tile Pinhole Worm	2 x 4	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100M	Wall(s)	Wallboard with Joint Compound		Green/Beige	N	N	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100M	Floor	Carpet		Brown	Not Suspect	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100M	Door/Door Frame	Wood and Metal		Bare/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100M	Misc	Covebase & Glue	4"	Beige & Tan	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100U	Ceiling	Acoustic Ceiling Tile Pinhole Worm	2 x 4	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100U	Wall(s)	Wallboard with Joint Compound		Green/Beige	N		N		N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100U	Floor	Carpet		Brown	Not Suspect	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100U	Door/Door Frame	Wood and Metal		Bare/Beige	Not Suspect	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100U	Misc	Covebase & Glue	4"	Beige & Tan	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100K	Ceiling	Acoustic Ceiling Tile Pinhole Worm	2 x 4	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100K	Wall(s)	Wallboard with Joint Compound		Green/Beige	N	N	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100K	Floor	Carpet		Brown	Not Suspect	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100K	Door/Door Frame	Wood and Metal		Bare/Beige	Not Suspect	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100K	Misc	Covebase & Glue	4"	Beige & Tan	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100P	Ceiling	Acoustic Ceiling Tile Pinhole Worm	2 x 4	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100P	Wall(s)	Wallboard with Joint Compound		White	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100P	Floor	Resilient Floor Tile	12 x 12	Lt Blue	N	F6.1-F6.3	Y	F6	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100P	Door/Door Frame	Wood and Metal		Bare/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100P	Misc	Covebase & Glue	4"	Lt Brown & Off-White	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Rm Name/No.		Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	HA #	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	SignificantlyDamaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
1st Floor	100R	Ceiling	Acoustic Ceiling Tile Pinhole Worm	2 x 4	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100R	Wall(s)	Wallboard with Joint Compound		Off-White	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100R	Floor	Ceramic Tile & Grout	2 x 2	Blue & Off-White	N/A-Would have required destructive sampling.	N/A	N/a	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100R	Door/Door Frame	Wood and Metal		Bare/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100R	Wall(s)	Ceramic Tile & Grout	4 x 4	White & White	N/A-Would have required destructive sampling.	N/A	N/a	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100R	Wall(s)	Ceramic Tile & Grout	4 x 4	Blue & White	N/A-Would have required destructive sampling.	N/A	N/a	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100Y	Ceiling	Acoustic Ceiling Tile Pinhole Worm	2 x 4	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100Y	Wall(s)	Wallboard with Joint Compound		Tan												
1st Floor	100Y	Floor	Carpet		Blue	Y (Mastic-5%)	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100Y	Door/Door Frame	Wood/Metal		Bare/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100Y	Misc	Covebase & Glue	4"	Lt Brown & Off-white	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Rm Name/No.		Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	HA #	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	SignificantlyDamaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
1st Floor	100N	Ceiling	Acoustic Ceiling Tile Pinhole Worm	2 x 4		N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100N	Wall(s)	Wallboard with Joint Compound		Off-White	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100N	Floor	Carpet		Blue	Y (Mastic-5%)	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100N	Door/Door Frame	Wood/Metal		Bare/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100N	Misc	Covebase & Glue		Lt Brown & Off-White	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC-100-	Ceiling	Acoustic Ceiling Tile Pinhole Worm	2 x 4		N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC-100-	Wall(s)	Wallboard with Joint Compound		Off-White	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC-100-	Floor	Carpet		Blue	Y (Mastic-5%)	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC-100-	Door/Door Frame	Wood and Metal		Bare/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC-100-	Misc	Covebase & Glue	4"	Lt Brown & Off-White	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC-100-	Ceiling	Acoustic Ceiling Tile Pinhole Worm	2 x 4	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC-100-	Wall(s)	Wallboard with Joint Compound		Off-White	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC-100-	Floor	Carpet		Blue	Y (Mastic-5%)	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC-100-	Door/Door Frame	Wood and Metal		Bare/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC-100-	Misc	Covebase & Glue	4"	Lt Brown & Off-White	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100F	Ceiling	Acoustic Ceiling Tile Pinhole Worm	2 x 4	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100F	Wall(s)	Wallboard with Joint Compound		Off-White	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100F	Floor	Carpet		Blue	Y (Mastic-5%)	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100F	Door/Door Frame	Wood and Metal		Bare/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100F	Misc	Covebase & Glue	4"	Lt Brown & Off-White	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100U	Ceiling	Acoustic Ceiling Tile Pinhole Worm	2 x 4	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100U	Wall(s)	Wallboard with Joint Compound		Off-White	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100U	Floor	Carpet		Blue	Y (Mastic-5%)	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100U	Door/Door Frame	Wood and Metal		Bare/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100U	Misc	Covebase & Glue	4"	Lt Brown & Off-White	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100W	Ceiling	Acoustic Ceiling Tile Pinhole Worm	2 x 4	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100W	Wall(s)	Wallboard with Joint Compound		Off-white	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100W	Floor	Carpet		Blue	Y (Mastic-5%)	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100W	Door/Door Frame	Wood and Metal		Bare/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100W	Misc	Covebase & Glue	4"	Lt Brown & Off-white	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Rm Name/No.		Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	HA #	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	SignificantlyDamaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
1st Floor	100X	Ceiling	Acoustic Ceiling Tile Pinhole Worm	2 x 4	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100X	Wall(s)	Wallboard with Joint Compound		Off-White	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100X	Floor	Carpet		Blue	Y (Mastic-5%)	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100X	Door/Door Frame	Wood and Metal		Bare/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100X	Misc	Covebase & Glue	4"	Lt Brown & Off-White	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100X	Misc															
1st Floor	100B	Ceiling	Acoustic Ceiling Tile Pinhole Worm	2 x 4	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100B	Wall(s)	Wallboard with Joint Compound		Off-White	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100B	Floor	Carpet		Blue	Y (Mastic-5%)	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100B	Door/Door Frame	Wood and Metal		Bare/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100B	Misc	Covebase & Glue	4"	Lt Brown & Off-White	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A



Rm Name/No.		Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	HA #	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	SignificantlyDamaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
1st Floor	CC-100-	Ceiling	Acoustic Ceiling Tile Pinhole Worm	2 x 4	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC-100-	Wall(s)	Wallboard with Joint Compound		Beige/Green	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC-100-	Floor	Resilient Floor Tile & Mastic	12 x 12	Lt Blue	N	F6.1-F6.3	N	F6	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC-100-	Door/Door Frame	Metal and Metal		Silver/Silver	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC-100-	Misc	Covebase & Glue	4"	Beige/Tan	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC-100-	Ceiling	Acoustic Ceiling Tile Pinhole Worm	2 x 4	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC-100-	Wall(s)	Wallboard with Joint Compound		Beige/Green	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC-100-	Floor	Resilient Floor Tile	12 x 12	Lt Blue	N	F6.1-F6.3	N	F6	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC-100-	Door/Door Frame	Metal and Metal		Silver/Silver	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC-100-	Misc	Covebase & Glue	4"	Beige/Tan	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100-5	Ceiling	Acoustic Ceiling Tile Pinhole	2x4	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100-5	Wall(s)	Wallboard with Joint Compound		Beige	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100-5	Floor	Resilient Floor Tile	12 x 12	Lt Blue	N	F6.1-F6.3	N	F6	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100-5	Door/Door Frame	Wood and Metal		Bare/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100-5	Misc	Covebase & Glue	4"	Lt Brown/Off-White	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100H	Ceiling	Acoustic Ceiling Tile Pinhole Worm	2 x 4	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100H	Wall(s)	Wallboard with Joint Compound		Beige	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100H	Floor	Ceramic Tile & Grout	6 x 6	Gray & Gray	N/A-Would have required destructive	N/A	N/a	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100H	Door/Door Frame	Wood and Metal		Bare/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100H	Wall(s)	Ceramic Tile & Grout	6 x 6	Gray & Gray	N/A-Would have required destructive	N/A	N/a	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100G	Ceiling	Acoustic Ceiling Tile Pinhole Worm	2 x 4	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100G	Wall(s)	Wallboard with Joint Compound		Beige	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100G	Floor	Ceramic Tile & Grout	6 x 6	Gray & Gray	N/A-Would have required destructive	N/A	N/a	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100G	Door/Door Frame	Wood and Metal		Bare/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100G	Wall(s)	Ceramic Tile & Grout		Lt Pink & Gray	N/A-Would have required destructive	N/A	N/a	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	100G	Floor	Ceramic Tile & Grout		Lt Pink & Gray	N/A-Would have required destructive	N/A	N/a	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M100-A	Ceiling	Acoustic Ceiling Tile Pinhole Worm	2 x 4	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M100-A	Wall(s)	Wallboard with Joint Compound		Beige/Tan	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M100-A	Floor	Carpet		Brown	Not Suspect	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M100-A	Door/Door Frame	Wood and Metal		Bare/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Rm Name/No.		Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	HA #	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	SignificantlyDamaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
1st Floor	M100-A	Misc	Covebase & Glue	4"	Beige & Off-white	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M100-A	Misc	Fire Stop		Red	N	M1.1-M1.3	N	M1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M100-B	Ceiling	Acoustic Ceiling Tile Pinhole Worm	2 x 4	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M100-B	Wall(s)	Wallboard with Joint Compound		Beige/Tan	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M100-B	Floor	Carpet		Brown	Not Suspect	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M100-B	Door/Door Frame	Wood and Metal		Bare/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M100-B	Misc	Covebase & Glue	4"	Beige & Off-white	N	M3.1-M3.3	N	M3	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M100-B	Misc	Fire Stop		Red	N	M1.1-M1.3	N	M1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M100-C	Ceiling	Acoustic Ceiling Tile Pinhole Worm	2 x 4	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M100-C	Wall(s)	Wallboard with Joint Compound		Beige/Tan	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M100-C	Floor	Carpet		Brown	Not Suspect	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M100-C	Door/Door Frame	Wood and Metal		Bare/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M100-C	Misc	Covebase & Glue	4"	Beige & Off-White	N	M3.1-M3.3	N	M3	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M100-C	Misc	Fire Stop		Red	N	M1.1-M1.3	N	M1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Rm Name/No.		Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	HA #	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	SignificantlyDamaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
1st Floor	M100-D	Ceiling	Acoustic Ceiling Tile Pinhole Worm	2 x 4	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M100-D	Wall(s)	Wallboard with Joint Compound		Beige/Tan	N	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M100-D	Floor	Carpet		Brown	Not Suspect	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M100-D	Door/Door Frame	Wood and Metal		Bare/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M100-D	Misc	Covebase & Glue	4"	Beige & Off-White	N	M3.1-M3.3	N	M3	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M100-D	Misc	Fire Stop		Red	N	M1.1-M1.3	N	M1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M100-E	Ceiling	Acoustic Ceiling Tile Pinhole Worm	2 x 4	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M100-E	Wall(s)	Wallboard with Joint Compound		Beige/Tan	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M100-E	Floor	Carpet		Brown	Not Suspect	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M100-E	Door/Door Frame	Wood and Metal		Bare/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M100-E	Misc	Covebase & Glue	4"	Beige & Off-White	N	M3.1-M3.3	N	M3	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M100-E	Misc	Fire Stop		Red	N	M1.1-M1.3	N	M1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M100-F	Ceiling	Acoustic Ceiling Tile Pinhole Worm	2 x 4	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M100-F	Wall(s)	Wallboard with Joint Compound		Beige/Tan	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M100-F	Floor	Carpet		Brown	Not Suspect	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M100-F	Door/Door Frame	Wood and Metal		Bare/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M100-F	Misc	Covebase & Glue	4"	Beige & Off-white	N	M3.1-M3.3	N	M3	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M100-F	Misc	Fire Stop		Red	N	M1.1-M1.3	N	M1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M100-G	Ceiling	Acoustic Ceiling Tile Pinhole Worm	2 x 4	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M100-G	Wall(s)	Wallboard with Joint Compound		Beige/Tan	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M100-G	Floor	Carpet		Brown	Not Suspect	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M100-G	Door/Door Frame	Wood and Metal		Bare/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M100-G	Misc	Covebase & Glue	4"	Beige & Off-white	N	M3.1-M3.3	N	M3	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M100-G	Misc	Fire Stop		Red	N	M1.1-M1.3	N	M1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	124	Ceiling	Concrete		Off-white	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	124	Wall(s)	Concrete		Off-white	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	124	Floor	Concrete		Bare	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	124	Door/Door Frame	Wood and Metal		Brown & Brown	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	124	Misc	Covebase & Glue	4"	Lt Brown & Tan	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	124A	Ceiling	Acoustic Ceiling Tile Pinhole Worm	2 x 4	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Rm Name/No.		Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	HA #	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	SignificantlyDamaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
1st Floor	124A	Wall(s)	Wallboard with Joint Compound		Lt Blue	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	124A	Floor	Resilient Floor Tile	12 x 12	Beige with Gray	N	N	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	124A	Door/Door Frame	Wood and Metal		Bare/Off-white	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	124A	Misc	Covebase & Glue	4"	Lt Brown & Tan	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	124F	Ceiling	Wood		Bare	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	124F	Wall(s)	Wood		Bare	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	124F	Floor	Concrete		Bare	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	124F	Door/Door Frame	Wood and Metal		Green/Green	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	124G	Ceiling	Wood		Bare	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	124G	Wall(s)	Wood		Bare	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	124G	Floor	Concrete		Bare	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	124G	Door/Door Frame	Wood and Metal		Green/Green	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Rm Name/No.		Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	HA #	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	SignificantlyDamaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
1st Floor	124 Ves	Ceiling	Wallboard with Joint Compound		Beige	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	121 Ves	Wall(s)	Wallboard with Joint Compound		Beige	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	121 Ves	Floor	Resilient Floor Tile	12 x 12	Tan	N	F8.1-F8.3	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	121 Ves	Door/Door Frame	Metal and Metal		Beige/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	121 Ves	Misc	Covebase & Glue		Beige & Gray	N	N	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	124C	Ceiling	Wallboard with Joint Compound		Beige	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	124C	Wall(s)	Wallboard with Joint Compound		Beige	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	124C	Floor	Resilient Floor Tile	12 x 12	Tan	N	F6.1-F6.3	N	F6	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	124C	Door/Door Frame	Metal and Metal		Beige/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	124C	Misc	Covebase & Glue		Beige & Gray	N	N	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	125C	Ceiling	Concrete		Green	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	125C	Wall(s)	Wallboard with Joint Compound		Mauve & Off-white	N	W2.1-W2.6	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	125C	Floor	Resilient Floor Tile	12 x 12	White with Gray	Y( 5%)	F7.1-F7.3	N	F7	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	125C	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	125C	Wall(s)	Ceramic Tile & Grout	6 x 6	White & White	N/A-Would have required destructive	N/A	N/a	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	125C	Wall(s)	Ceramic Tile & Grout	6 x 6	Blue & White	N/A-Would have required destructive	N/A	N/a	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	124E	Ceiling	Wallboard		Beige	N	C2.1-C2.3	N	C2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	124E	Wall(s)	Wallboard with Joint Compound		Beige	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	124E	Floor	Vinyl Floor Tile	16 x 16/300 SF	Beige	N	F2.1-F2.3	N	F2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	124E	Door/Door Frame	Wood and Metal		Bare/White	Not Suspect	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	124E	Misc	Covebase & Glue	6"	Beige & gray	N	M5.1-M5.3	N	M5	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	124E	Misc	Vinyl Floor Tile	16 x 16/ 70SF	Tan	N	F4.1	N	F4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	124E	Misc	Vinyl Floor Tile	16 x 16/ 70SF	Dark Brown	N	F5.1	N	F5	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	124 A-1	Ceiling	Wallboard		White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A		N/A	N/A
1st Floor	124 A-1	Wall(s)	Concrete		White/Blue	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	124 A-1	Floor	Concrete		Bare	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	124 A-1	Misc	No TSI Suspect														
1st Floor	125	Ceiling	Concrete/Plywood		Off-White	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	125	Wall(s)	Concrete/Plywood		Off-White/Brown	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	125	Floor	Concrete/Plywood		Bare	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A

[illegible]

Rm Name/No.		Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	HA #	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	SignificantlyDamaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
1st Floor	118	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2 x 4	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	118	Wall(s)	Concrete		Off-White	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	118	Floor	Resilient Floor Tile	12 x 12	White with Gray	Y (Mastic 4%)	F7.1-F7.3	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	118	Door/Door Frame	Wood and Metal		Brown and Brown	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	118	Wall(s)	Wallboard with Joint Compound		Off-White	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	118	Wall(s)	Covebase & Glue	4"	Brown and Brown	Brown and Tan	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	118	Misc															
1st Floor	120	Ceiling	Concrete Plywood		Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	120	Wall(s)	Concrete Wallboard with Joint Compound		Beige	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	120	Floor	Concrete Wallboard with Joint Compound		Gray	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	120	Door/Door Frame	Wood and Metal		Brown/Brown	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	120	Misc	Covebase & Glue	4"	Brown and Tan	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	120	Misc	No Suspect TSI														
1st Floor	128D	Ceiling	Concrete Plywood		Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	128D	Wall(s)	Concrete Wallboard with Joint Compound		Beige	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	128D	Floor	Concrete Wallboard with Joint Compound		Gray	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	128D	Door/Door Frame	Wood and Metal		Brown/Brown	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	128D	Wall(s)	Covebase & Glue	4"	Brown and Tan	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	128D	Misc	No Suspect TSI														
1st Floor	118A	Ceiling	Acoustic Ceiling Tile Pinhole	1 x 1	N	N	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	118A	Wall(s)	Concrete Wallboard with Joint Compound		White	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	118A	Floor	Concrete Wallboard with Joint Compound		Gray	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	118A	Door/Door Frame	Wood and Metal		Purple/Purple	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	118A	Ceiling	Acoustic Ceiling Tile Mastic			N	N	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	128C	Ceiling															
1st Floor	128C	Wall(s)	Wallboard with Joint Compound			N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	128C	Door/Door Frame	Wood and Metal		Blue/Black	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	128 D-1	Ceiling	Concrete Plywood		Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	128 D-1	Wall(s)	Concrete Wallboard with Joint Compound		Beige	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	128 D-1	Floor	Resilient Floor Tile	12 x 12	White with Gray	Y (Mastic 4%)	N	F7	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Rm Name/No.		Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	HA #	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	SignificantlyDamaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
1st Floor	128 D-1	Door/Door Frame	Wood and Metal		Brown/Brown	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	128 D-1	Wall(s)	Covebase & Glue	4"	Brown and Tan	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	128 D-1	Misc	No Suspect TSI														
1st Floor	130	Ceiling	Acoustic Ceiling Tile Pinworm,	2 x 4 x 8/20,000 SF	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	130	Wall(s)	Wallboard with Joint Compound		Beige/Green	N	W2.1-W2.6	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	130	Floor	Resilient Floor Tile	12 x 12	White with Gray	Y (5 %)	F7.1-F7.3	F7	N/A	N/A	N/A						
1st Floor	130	Door/Door Frame	Wood and Metal		Brown/Brown	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	130	Wall(s)	Covebase & Glue	4"	Beige and Gray	N	M3.1-M3.3	N	M3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	132	Ceiling	Acoustic Ceiling Tile Pinworm,	2 x 4	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	132	Wall(s)	Wallboard with Joint Compound		Beige/Green	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	132	Floor	Carpet		Brown	Not Suspect	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	132	Wall(s)	Covebase & Glue	4"	Beige and Off-white	N	M3.1-M3.3	N	M3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A



[illegible]

Rm Name/No.		Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	HA #	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	SignificantlyDamaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
1st Floor	131	Door/Door Frame	Wood and Metal		Bare/Off-white	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	131	Misc	Covebase & Glue	4"	Lt Brown and Brown	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	131	Misc	Fire Caulk		Red	N	M1.1-M1.3	N	M1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	131	Misc	Note: East Wall 2 x 2 Door with Asbestos Warning Sign														
1st Floor	131B	Ceiling	Acoustic Ceiling Tile Pinworm	2 x 4	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	131B	Wall(s)	Wallboard with Joint Compound		Beige	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	131B	Floor	Resilient Floor Tile	12 x 12	Lt Blue	N	F6.1-6.3	N	F6	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	131B	Door/Door Frame	Wood and Metal		Bare/Off-white	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	131B	Misc	Covebase & Glue	4"	Lt Brown and Brown	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	131C	Ceiling	Acoustic Ceiling Tile Pinworm	2 x 4	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	131C	Wall(s)	Wallboard with Joint Compound		Beige	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	131C	Floor	Resilient Floor Tile	12 x 12	White with Gray	Y( 5%)	F7.1-F7.3	N	F7	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	131C	Door/Door Frame	Wood and Metal		Bare/Off-white	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	131C	Misc	Covebase & Glue	4"	Lt Brown and Brown	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Rm Name/No.		Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	HA #	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	SignificantlyDamaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
1st Floor	131E	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2 x 4	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	131E	Wall(s)	Wallboard with Joint Compound		Off-white/Tan	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	131E	Floor	Resilient Floor Tile	12 x 12	White with Gray	Y( 5%)	F7.1-F7.3	N	F7	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	131E	Door/Door Frame	Wood and Metal		Bare/Off-White	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	131E	Misc	Covebase & Glue	4"	Brown and Brown	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	Elec. Sh	Ceiling	Wallboard with Joint Compound		Beige	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	Elec. Sh	Wall(s)	Wallboard with Joint Compound		Beige	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	Elec. Sh	Floor	Resilient Floor Tile	12 x 12	Pinkish Brown Spot	Y (Mastic-10%)	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	Elec. Sh	Door/Door Frame	Metal and Metal		Beige/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	Elec. Sh	Misc	Covebase & Glue	4"	Beige and Tan	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	Biomed	Ceiling	Wallboard with Joint Compound		Beige	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	Biomed	Wall(s)	Wallboard with Joint Compound		Beige	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	Biomed	Floor	Resilient Floor Tile & Mastic	12 x 12	Pinkish Brown Spot	Y (Mastic-10%)	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	Biomed	Door/Door Frame	Metal and Metal		Beige/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	Biomed	Misc	Covebase & Glue	4"	Beige and Tan	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	148	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2 x 4	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	148	Wall(s)	Wallboard with Joint Compound		Beige	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	148	Floor	Resilient Floor Tile	12 x 12	Tan	N	F8.1-F8.3	N	F8	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	148	Door/Door Frame	Wood and Metal		Bare/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	148	Misc	Covebase & Glue	4"	Beige and Brown	N	M3.1-M3.3	N	M3	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	148	Wall(s)	Ceramic Tile & Grout	4 x 4	Beige and White	N/A-Would have required destructive	N/A	N/a	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	146	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2 x 4	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	146	Wall(s)	Wallboard with Joint Compound		Beige/Green	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	146	Floor	Carpet		Brown	Not Suspect	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	146	Door/Door Frame	Wood and Metal		Bare/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	146	Misc	Covebase & Glue	4"	Beige and Tan	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	142	Ceiling	Acoustic Ceiling Tile Pinworm	2 x 4	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	142	Wall(s)	Wallboard with Joint Compound		Off-White	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	142	Floor	Resilient Floor Tile	12 x 12	Pinkish Brown Spot	Y (Mastic-10%)	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	142	Door/Door Frame	Wood and Metal		Bare/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Rm Name/No.		Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	HA #	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	SignificantlyDamaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
1st Floor	142	Misc	Covebase & Glue		Lt Brown and Brown	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	142	Wall(s)	Ceramic Tile & Grout	4 x 4	White and White	N/A	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	142	Misc	Fire Stop														
1st Floor	140	Ceiling	Acoustic Ceiling Tile Pinworm	2 x 4	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	140	Wall(s)	Wallboard with Joint Compound		Off-White	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	140	Floor	Resilient Floor Tile	12 x 12	Pinkish Brown Spot	Y (Mastic-10%)	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	140	Door/Door Frame	Wood and Metal		Bare/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	140	Misc	Covebase & Glue		Lt Brown and Brown	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	140	Wall(s)	Ceramic Tile & Grout	4 x 4	White and White	N/A	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	140	Misc	Fire Stop		Red	N	M1.1-M1.3	N	M1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Rm Name/No.		Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	HA #	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	SignificantlyDamaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
1st Floor	141	Ceiling	Acoustic Ceiling Tile Pinworm	2 x 4	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	141	Wall(s)	Wallboard with Joint Compound		Off-White	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	141	Floor	Resilient Floor Tile	12 x 12	Pinkish Brown Spot	Y (Mastic-10%)	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	141	Door/Door Frame	Wood and Metal		Bare/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	141	Misc	Covebase & Glue		Lt Brown and Brown	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	141	Wall(s)	Ceramic Tile & Grout	4 x 4	White and White	N/A	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	141	Misc	Fire Stop		Red	N	M1.1-M1.3	N	M1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	142A	Ceiling	Acoustic Ceiling Tile Pinworm	2 x 4	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	142A	Wall(s)	Wallboard with Joint Compound		Off-White	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	142A	Floor	Resilient Floor Tile	12 x 12	Pinkish Brown Spot	Y (Mastic-10%)	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	142A	Door/Door Frame	Wood and Metal		Bare/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	142A	Misc	Covebase & Glue		Lt Brown and Brown	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	142A	Wall(s)	Ceramic Tile & Grout	4 x 4	White and White	N/A	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	142A	Misc	Fire Stop		Red	N	M1.1-M1.3	N	M1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	144	Ceiling	Acoustic Ceiling Tile Pinworm	2 x 4	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	144	Wall(s)	Wallboard with Joint Compound		Off-White	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	144	Floor	Resilient Floor Tile	12 x 12	Pinkish Brown Spot	Y (Mastic-10%)	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	144	Door/Door Frame	Wood and Metal		Bare/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	144	Misc	Covebase & Glue		Lt Brown and Brown	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	144	Wall(s)	Ceramic Tile & Grout	4 x 4	White and White	N/A	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	144	Misc	Fire Stop		Red	N	M1.1-M1.3	N	M1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	139A	Ceiling	Acoustic Ceiling Tile Pinworm	2 x 4	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	139A	Wall(s)	Wallboard with Joint Compound		Off-White	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	139A	Floor	Resilient Floor Tile	12 x 12	Pinkish Brown Spot	Y (Mastic-10%)	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	139A	Door/Door Frame	Wood and Metal		Bare/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	139A	Misc	Covebase & Glue		Lt Brown and Brown	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	139A	Wall(s)	Ceramic Tile & Grout	4 x 4	White and White	N/A	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	139A	Misc	Fire Stop		Red	N	M1.1-M1.3	N	M1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	144A	Ceiling	Acoustic Ceiling Tile Pinworm	2 x 4	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	144A	Wall(s)	Wallboard with Joint Compound		Off-White	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Rm Name/No.		Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	HA #	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	SignificantlyDamaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
1st Floor	144A	Floor	Resilient Floor Tile	12 x 12	Pinkish Brown Spot	Y (Mastic-10%)	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	144A	Door/Door Frame	Wood and Metal		Bare/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	144A	Misc	Covebase & Glue		Lt Brown and Brown	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	144A	Wall(s)	Ceramic Tile & Grout	4 x 4	White and White	N/A	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	144A	Misc	Fire Stop		Red	N	M1.1-M1.3	N	M1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	136	Ceiling	Acoustic Ceiling Tile Pinworm	2 x 4	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	136	Wall(s)	Wallboard with Joint Compound		Off-White	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	136	Floor	Resilient Floor Tile	12 x 12	Pinkish Brown Spot	Y (Mastic-10%)	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	136	Door/Door Frame	Wood and Metal		Bare/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	136	Misc	Covebase & Glue		Lt Brown and Brown	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	136	Wall(s)	Ceramic Tile & Grout	4 x 4	White and White	N/A	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	136	Misc	Fire Stop		Red	N	M1.1-M1.3	N	M1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Rm Name/No.		Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	HA #	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	SignificantlyDamaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
1st Floor	136A	Ceiling	Acoustic Ceiling Tile Pinworm	2 x 4	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	136A	Wall(s)	Wallboard with Joint Compound		Off-White	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	136A	Floor	Resilient Floor Tile	12 x 12	Pinkish Brown Spot	Y (Mastic-10%)	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	136A	Door/Door Frame	Wood and Metal		Bare/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	136A	Misc	Covebase & Glue		Lt Brown and Brown	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	136A	Wall(s)	Ceramic Tile & Grout	4 x 4	White and White	N/A	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	136A	Misc	Fire Stop		Red	N	M1.1-M1.3	N	M1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	135	Ceiling	Acoustic Ceiling Tile Pinworm	2 x 4	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	135	Wall(s)	Wallboard with Joint Compound		Off-White	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	135	Floor	Resilient Floor Tile	12 x 12	Pinkish Brown Spot	Y (Mastic-10%)	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	135	Door/Door Frame	Wood and Metal		Bare/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	135	Misc	Covebase & Glue		Lt Brown and Brown	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	135	Wall(s)	Ceramic Tile & Grout	4 x 4	White and White	N/A-Would have required destructive	N/A	N/a	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	135	Misc	Fire Stop		Red	N	M1.1-M1.3	N	M1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	139	Ceiling	Acoustic Ceiling Tile Pinworm	2 x 4	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	139	Wall(s)	Wallboard with Joint Compound		Off-White	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	139	Floor	Resilient Floor Tile	12 x 12	Pinkish Brown Spot	Y (Mastic-10%)	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	139	Door/Door Frame	Wood and Metal		Bare/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	139	Misc	Covebase & Glue		Lt Brown and Brown	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	139	Wall(s)	Ceramic Tile & Grout	4 x 4	White and White	N/A	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	139	Misc	Fire Stop		Red	N	M1.1-M1.3	N	M1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC-5-1	Ceiling	Wallboard	2 x 4	Off-White	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC-5-1	Wall(s)	Wallboard with Joint Compound		Off-White	N	W2.1-W2.6	N	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC-5-1	Floor	Resilient Floor Tile	12 x 12	Pinkish Brown Spot	Y (Mastic-10%)	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC-5-1	Door/Door Frame	Wood and Metal		Bare/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC-5-1	Misc	Covebase & Glue		Lt Brown and Brown	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC-5-1	Misc	Ceramic Tile & Grout	4 x 4	White and White	N/A	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC-5-1	Misc	Fire Stop		Red	N	M1.1-M1.3	N	M1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	138	Ceiling	Acoustic Ceiling Tile Pinworm	2 x 4	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	138	Wall(s)	Wallboard with Joint Compound		Off-White	N	W2.1-W2.6	N	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Rm Name/No.		Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	HA #	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	SignificantlyDamaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
1st Floor	138	Floor	Carpet with Resilient Floor Tile Under with Mastic	12 x 12	Blue	N	F6.1-6.3	N	F6	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	138	Door/Door Frame	Wood and Metal		Bare/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	138	Misc	Covebase & Glue		Lt Brown and Brown	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	138	Misc	Ceramic Tile & Grout	4 x 4	White and White	N/A-Would have required destructive	N/A	N/a	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	138	Misc	Fire Stop		Red	N	M1.1-M1.3	N	M1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	139C	Ceiling	Wallboard		Beige	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	139C	Wall(s)	Wallboard with Joint Compound		Beige	N	W2.1-W2.6	N	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	139C	Floor	Resilient Floor Tile	12 x 12	White with Brown	Y (Mastic-2%)	F1.1	N	F1	N/A	N/A	Yes/No	N/A	High/Needs Immediate Attention	N/A	N/A	N/A
1st Floor	139C	Door/Door Frame	Wood and Metal		Bare/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	139C	Misc	Covebase & Glue	4"	Brown and Brown	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A



Rm Name/No.		Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	HA #	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	SignificantlyDamaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
1st Floor	139B	Ceiling	Acoustic Ceiling Tile Pinworm	2 x 4	Beige	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	139B	Wall(s)	Wallboard with Joint Compound	20000 SF	Off-White	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	139B	Floor	Resilient Floor Tile	12 x 12	Pinkish Brown Spot	Y (Mastic-10%)	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	139B	Door/Door Frame	Wood and Metal		Bare/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	139B	Misc	Covebase & Glue		Lt Brown and Brown	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	139B	Misc	Ceramic Tile & Grout	4 x 4	White and White	N/A-Would have required destructive	N/A	N/a	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	139B	Floor	Resilient Floor Tile	12 x 12/12 x 12	300sf White with Brown/ 80sf	Y (Mastic-2%)	F1.1	N	F1	N/A	N/A	Yes/No	N/A	High/Needs Immediate Attention	N/A	N/A	N/A
1st Floor	137	Ceiling	Acoustic Ceiling Tile Pinworm	2 x 4	Beige	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	137	Wall(s)	Wallboard with Joint Compound		Beige/Green	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	137	Floor	Resilient Floor Tile		Pink	Y (Mastic-10%)	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	137	Door/Door Frame	Wood and Metal		Bare/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	137	Misc	Covebase & Glue	4"	Lt Brown and Tan	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	134	Ceiling	Wood Open	2 x 4		Not Suspect	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	134	Wall(s)	Open Wood		Beige/Green	Not Suspect	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	134	Floor	Resilient Floor Tile		Pinkish Brown Spot	Y (Mastic-10%)	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	134	Door/Door Frame	Wood and Metal		Bare/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	134	Misc	Covebase & Glue	4"	Lt Brown and Tan	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	134	Misc	Vapor Barrier			N	M2.1-M2.3	N	M2	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	134	Misc	Note: No Suspect TSI														
1st Floor	133	Ceiling	Wood Open	2 x 4		Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	133	Wall(s)	Open Wood		Beige/Green	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	133	Floor	Resilient Floor Tile		Pinkish Brown Spot	Y (Mastic-10%)	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	133	Door/Door Frame	Wood and Metal		Bare/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	133	Misc	Covebase & Glue	4"	Lt Brown and Tan	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	133	Misc	Note: No Suspect TSI														
1st Floor	150	Ceiling	Acoustic Ceiling Tile Pinworm	2 x 4	White	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	150	Wall(s)	Wallboard with Joint Compound		Beige	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	150	Floor	Resilient Floor Tile	12 x 12	Brown	N	F8.1-F8.3	N	F8	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	150	Door/Door Frame	Wood and Metal		Bare/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	150	Misc	Covebase & Glue	4"	Beige and Tan	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Rm Name/No.		Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	HA #	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	SignificantlyDamaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
1st Floor	150	Wall(s)	Ceramic Tile & Grout	4 x 4	White and White	N/A-Would have required destructive	N/A	N/a	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	131A	Ceiling	Wallboard		Off-white	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	131A	Wall(s)	Concrete Wallboard with Joint Compound		Off-white	N	W2.1-W2.6	N	W2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	131A	Floor	Concrete Wallboard with Joint Compound		Bare	N	W2.1-W2.7	N	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	131A	Door/Door Frame	Metal and Metal		Off-white/Off-white	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	131A	Wall(s)	Ceramic Tile & Grout	6 x 12	Yellow and Off-white	N/A-Would have required destructive	N/A	N/a	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	131A	Misc	Fire Caulk		Red	N	M1.1-M1.3	N	M1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	131	Ceiling	No Wallboard and Robinson Deck		Beige	Not Suspect	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	131	Wall(s)	Concrete Wallboard with Joint Compound		Off-white	N	W2.1-W2.7	N	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	131	Floor	Concrete Wallboard with Joint Compound		Bare	N	W2.1-W2.7	N	W3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	131	Door/Door Frame	Metal and Metal		Off-white/Off-white	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	131	Misc	Ceramic Tile & Grout	6 x 12	Yellow and Off-white	N/A-Would have required destructive	N/A	N/a	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	131	Misc	Fire Caulk		Red	N	M1.1-M1.3	N	M1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Rm Name/No.		Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	HA #	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	SignificantlyDamaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
1st Floor	18 - Boil	Ceiling	Robinson Decking		Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	18 - Boil	Wall(s)	Concrete		Off-white	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	18 - Boil	Floor	Concrete		Bare	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	18 - Boil	Door/Door Frame	Metal and Metal		Off-white/Off-white	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	18 - Boil	Misc	TSI Possible. Construction Area														
1st Floor	18D - Office	Floor	Resilient Floor Tile	12 x 12	Blue	N	F6.2	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	10 F	Ceiling	Above Ceiling- Acoustic Ceiling Tiles	1x1	White/Brown	N	N	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	10 F	Ceiling	Acoustic Ceiling Tile Pinhole	1x1	White/Brown	N	N	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	10 F	Door/Door Frame	Acoustis Ceiling Tile Mastic	Only Room 1008 A		N	N	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	10 F	Misc	NO TSI														
1st Floor	CC-100-3	Ceiling	Above Ceiling- Acoustic Ceiling Tiles	1x1	White/Brown	N	N	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC-100-3	Wall(s)	Acoustic Ceiling Tile Pinhole	1x1	White/Brown	N	N	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC-100-3	Door/Door Frame				N	N	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC-100-3	Misc		100 IF & Corr													
2nd Floor	Corridor	Ceiling	Acoustic Ceiling Tile Pinhole	2x4	N	C1.1-C1.3	N	C1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	Corridor	Wall(s)	Wallboard with Joint Compound		White	N	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	Corridor	Floor	Carpet		Blue	Y (Mastic-5%)	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	Corridor	Door/Door Frame	Wood and Metal		Bare/Beige	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	Corridor	Misc	Covebase & Glue	4"	Light Brown/Tan/Brow	N	M4.1-M4.3	N	M4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	Corridor	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	1x1	White	N	N	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	Corridor	Ceiling	Acoustical Tile Mastic		Brown	N	N	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	204	Ceiling	Wallboard	1500 SF	White	N	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	204	Wall(s)	Wallboard with Joint Compound		White	N	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	204	Floor	Resilient Floor Tile	12x12	Pinkish	Y (Mastic-10%)	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	204	Door/Door Frame	Wood and Wood		White/White	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	204	Floor	Resilient Floor Tile 12sq ft	12x12	White and Gray	Y (Mastic-5%)	F7.1-7.3	N	F7	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	204A	Ceiling	Wallboard		White	N	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	204A	Wall(s)	Wallboard with Joint Compound		White	N	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	204A	Door/Door Frame	Wood and Wood		White/White	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	204A	Floor	Resilient Floor Tile and Mastic	12x12/ 12 SF	White and Grey	Y (Mastic-5%)	F7.1-7.3	N	F7	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Rm Name/No.		Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	HA #	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	SignificantlyDamaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
2nd Floor	203	Ceiling	Wallboard		White	N	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	203	Wall(s)	Wallboard with Joint Compound		White	N	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	203	Floor	Resilient Flooring Tile	9x9	Tan	Y(Mastic-10%, Tile-2%)	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	203	Door/Door Frame	Wood and Wood		White/White	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	203	Misc	Cove Base / Glue	4"	Brown/Brown	N	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	202	Ceiling	Wallboard		White	N	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	202	Wall(s)	Wallboard with Joint Compound		White	N	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	202	Floor	Resilient Flooring Tile	9x9	Tan	Y(Mastic-10%, Tile-2%)	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	202	Door/Door Frame	Wood and Wood		White/White	Not Suspect	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	202	Misc	Cove Base / Glue	4"	Brown/Brown	N	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	201	Ceiling	Wallboard w/Joint Compound		White	N	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	201	Wall(s)	Wallboard with Joint Compound		White	N	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	201	Floor	Carpet		Blue	Y (Mastic-5%)	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	201	Misc	Cove Base / Glue	4"	Light Brown	N	M4.1-M4.3	N	M4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Rm Name/No.		Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	HA #	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	SignificantlyDamaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
2nd Floor	206	Ceiling	Acoustic Ceiling Tile Pinhole	2x4	White	N	C1.1-C1.3	N	C1	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	206	Wall(s)	Wallboard with Joint Compound		White	N	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	206	Floor	Carpet		Blue	Y (Mastic-5%)	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	206	Misc	Cove Base / Glue		Light Brown/Tan	N	M4.1-M4.3	N	M4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	206	Misc	Acoustic Ceiling Tile Pinhole Big Worm	1x1	White	N	N	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	206	Misc	Acoustical Tile Mastic		Brown	N	N	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	210	Ceiling	Acoustic Ceiling Tile Pinhole	2x4	White	N	C1.1-C1.3	N	C1	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	210	Wall(s)	Wallboard with Joint Compound		White	N	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	210	Floor	Carpet		Blue	Y (Mastic-5%)	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	210	Door/Door Frame															
2nd Floor	210	Misc	Cove Base / Glue		Light Brown/Tan	N	M4.1-M4.3	N	M4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	210	Misc	Acoustic Ceiling Tile Pinhole Big Worm	1x1	White	N	N	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	210	Misc	Acoustical Tile Mastic		Brown	N	N	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	209	Ceiling	Acoustic Ceiling Tile Pinhole	2x4	White	N	C1.1-C1.3	N	C1	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	209	Wall(s)	Wallboard with Joint Compound		White	N	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	209	Floor	Carpet		Blue	Y (Mastic-5%)	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	209	Misc	Cove Base & Glue		Light Brown/Tan	N	M4.1-M4.3	N	M4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	209	Misc	Acoustic Ceiling Tile Pinhole Big Worm	1x1	White	N	N	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	209	Misc	Acoustical Tile Mastic		Brown	N	N	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	207	Ceiling	Acoustic Ceiling Tile Pinhole	2x4	White	N	C1.1-C1.3	N	C1	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	207	Wall(s)	Wallboard with Joint Compound		White	N	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	207	Floor	Carpet		Blue	Y (Mastic-5%)	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	207	Misc	Cove Base & Glue		Light Brown/Tan	N	M4.1-M4.3	N	M4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	207	Misc	Acoustic Ceiling Tile Pinhole Big Worm	1x1	White	N	N	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	207	Misc	Acoustical Tile Mastic		Brown	N	N	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	208	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	1x1	White	N	N	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	208	Wall(s)	Wallboard /Wallboard with Joint Compound		White/Bare	N	W5.1-W5.3	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	208	Floor	Carpet		Blue	Y (Mastic-5%)	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	208	Door/Door Frame	Wood and Wood		Bare/White	Not Suspect	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	208	Misc	Cove Base / Glue	4"	Light Brown/Tan	N	M4.1-M4.3	N	M4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Rm Name/No.		Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	HA #	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	SignificantlyDamaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
2nd Floor	208	Ceiling	Acoustical Tile Mastic		Brown	N	N	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	208A	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	1x1	White	N	N	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	208A	Wall(s)	Wallboard /Wallboard with Joint Compound		White/Bare	N	W5.1-W5.3	N	W5	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	208A	Floor	Carpet		Blue	Y (Mastic-5%)	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	208A	Door/Door Frame	Wood and Wood		Bare/White	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	208A	Misc	Cove Base / Glue	4"	Light Brown/Tan	N	M4.1-M4.3	N	M4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	208A	Misc	Acoustical Tile Mastic		Brown	N	N	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	205	Ceiling	Acoustic Ceiling Tile Pinhole	2x4	White	N	C1.1-C1.3	N	C1	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	205	Wall(s)	Wallboard Wallboard w/Joint Compound		White/Brown	N	W5.1-W5.3	N	W5	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	205	Floor	Carpet		Brown	Not Suspect	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	205	Door/Door Frame	Wood and Wood		White/White	Not Suspect	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	205	Misc	Cove Base / Glue	4"	Brown/Tan	N	N	Y	N								

[illegible]

[illegible]