

[illegible]

Current Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	SignificantlyDamaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
1st Floor	26	Ceiling	Open to Rafters		Beige		N/A										
1st Floor	26	Wall(s)	Wallboard with Joint Compound		White	Not Detected	N/A	Y									
1st Floor	26	Floor	Concrete		Bare	Not Suspect	N/A	Y									
1st Floor	26	Door/Door Frame	Gate Metal		Beige	Not Suspect	N/A	Y									Possible suspect material in core
1st Floor	26	Wall(s)	Wood		Beige	Not Suspect	N/A	Y									
1st Floor	26	Wall(s)	Plywood		Beige		N/A										
1st Floor	43	Ceiling	Acoustic Ceiling Tile Pinhole Bigworm	2x4		Not Detected	N/A	Y									
1st Floor	43	Wall(s)	Wallboard with Joint Compound		Blue and Off White	Not Detected	N/A	Y									
1st Floor	43	Floor	Resilient Floor Tile and BLK Mastic	12x12	Pink	5% Chrsotile	N/A	Y	No	Good			No			Yes	ACM is in mastic
1st Floor	43	Door/Door Frame	Metal and Metal		Brown and Brown	Not Suspect	N/A	Y									Possible suspect material in core
1st Floor	43	Misc	Coverbase and Glue	4"	Black and Brown	Not Detected	N/A	Y									
1st Floor	44	Ceiling	Hardlid		Off White		N/A										
1st Floor	44	Wall(s)	Wallboard with Joint Compound		Off White	Not Detected	N/A	Y									
1st Floor	44	Floor	Concrete		Bare	Not Suspect	N/A	Y									
1st Floor	44	Door/Door Frame	Wood and Metal		Off white and Off	Not Suspect	N/A	Y									Possible suspect material in core

[illegible]

[illegible]

[illegible]