

| Current Rm Name/No. | | Surface | Material | Size | Color | Sample Info | | | HAZARD ASSESSMENT | | | | | | | | Comment |
|---------------------|---------|-----------------|---|------|----------------|------------------|-----------------------|--------------------------|-------------------|------------------|--|---|---|-----|-----------|------|---------------------------|
| | | | | | | Asbestos Present | Contractor Sample No. | Previously Sampled (Y/N) | Friable | Good - No Damage | Damaged (10% overall or 25% localized) | Significantly Damaged >10% overall OR >25% localized) | Potential for Damage (vibration, Access, Erosion) | TSI | Surfacing | Misc | |
| Basement | 11A | Door/Door Frame | Metal and Metal | | Blue/Blue | Not Suspect | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | Core may contain asbestos |
| Basement | 11A | Misc | | | | | | | | | | | | | | | |
| Basement | 11A | Misc | | | | | | | | | | | | | | | |
| Basement | 11A | Misc | | | | | | | | | | | | | | | |
| Basement | 11B | Ceiling | Concrete | | | Not Suspect | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| Basement | 11B | Wall(s) | Wallboard with Joint Compound /Concrete | | | ND | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| Basement | 11B | Floor | Concrete | | Blue | Not Suspect | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| Basement | 11B | Door/Door Frame | Wood and Metal | | Blue/Off White | Not Suspect | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | Core may contain asbestos |
| Basement | 11B | Misc | Fire Caulk | | Red | ND | M1.1-M1.5 | N/A | M1 | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| Basement | 11B | Misc | | | | | | | | | | | | | | | |
| Basement | 11B | Misc | | | | | | | | | | | | | | | |
| Basement | FEC B-1 | Ceiling | Wallboard with Joint Compound | | | ND | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| Basement | FEC B-1 | Wall(s) | Wallboard with Joint Compound | | | ND | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| Basement | FEC B-1 | Floor | Concrete | | Bare | Not Suspect | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| Basement | FEC B-1 | Door/Door Frame | Wood and Metal | | Blue/Blue | Not Suspect | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | Core may contain asbestos |

[illegible]

[illegible]

| Current Rm Name/No. | | Surface | Material | Size | Color | Sample Info | | | HAZARD ASSESSMENT | | | | | | | | Comment |
|---------------------|--------|-----------------|---|-------|-----------------|------------------|-----------------------|--------------------------|-------------------|------------------|--|---|---|-----|-----------|------|--|
| | | | | | | Asbestos Present | Contractor Sample No. | Previously Sampled (Y/N) | Friable | Good - No Damage | Damaged (10% overall or 25% localized) | Significantly Damaged >10% overall OR >25% localized) | Potential for Damage (vibration, Access, Erosion) | TSI | Surfacing | Misc | |
| 1st Floor | 104 | Ceiling | Acoustic Ceiling Tile Pinhole | 2x4 | N | ND | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 1st Floor | 104 | Wall(s) | Wallboard with Joint Compound | | Beige | ND | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 1st Floor | 104 | Floor | Carpet | | Brown | | | | | | | | | | | | Mastic underneath may contain asbestos |
| 1st Floor | 104 | Door/Door Frame | Wood and Metal | | Beige/Off White | | | | | | | | | | | | Core may contain asbestos |
| 1st Floor | 104 | Misc | Cove Base | 6" | Beige | | | | | | | | | | | | |
| 1st Floor | 104 | Misc | | | | | | | | | | | | | | | |
| 1st Floor | 104 | Misc | | | | | | | | | | | | | | | |
| 1st Floor | 101HAC | Ceiling | No Access | | | | | | | | | | | | | | |
| 1st Floor | 101HAC | Wall(s) | | | | | | | | | | | | | | | |
| 1st Floor | 101HAC | Floor | | | | | | | | | | | | | | | |
| 1st Floor | 101HAC | Door/Door Frame | | | | | | | | | | | | | | | |
| 1st Floor | 101HAC | Misc | | | | | | | | | | | | | | | |
| 1st Floor | 101HAC | Misc | | | | | | | | | | | | | | | |
| 1st Floor | 101HAC | Misc | | | | | | | | | | | | | | | |
| 1st Floor | 100A | Ceiling | | | | | | | | | | | | | | | |
| 1st Floor | 100A | Wall(s) | | | | | | | | | | | | | | | |
| 1st Floor | 100A | Floor | | | | | | | | | | | | | | | |
| 1st Floor | 100A | Door/Door Frame | | | | | | | | | | | | | | | |
| 1st Floor | 100A | Misc | Cove Base / Mastic | 4" | Gray | Y | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 1st Floor | 100A | Misc | | | | | | | | | | | | | | | |
| 1st Floor | 100A | Misc | | | | | | | | | | | | | | | |
| 1st Floor | 100B | Ceiling | No Access | | | | | | | | | | | | | | |
| 1st Floor | 100B | Wall(s) | | | | | | | | | | | | | | | |
| 1st Floor | 100B | Floor | | | | | | | | | | | | | | | |
| 1st Floor | 100B | Door/Door Frame | | | | | | | | | | | | | | | |
| 1st Floor | 100B | Misc | | | | | | | | | | | | | | | |
| 1st Floor | 100B | Misc | | | | | | | | | | | | | | | |
| 1st Floor | 100B | Misc | | | | | | | | | | | | | | | |
| 1st Floor | 100C | Ceiling | Acoustic Ceiling Tile Pinhole Big Worm | 2x4 | N | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 1st Floor | 100C | Wall(s) | Concrete/ Wallboard with Joint Compound | | Green/Beige | | | | | | | | | | | | |
| 1st Floor | 100C | Floor | Resilient Flooring Tile | 12x12 | Gray | N | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 1st Floor | 100C | Door/Door Frame | Resilient Flooring Tile | 12x12 | Beige | N | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 1st Floor | 100C | Misc | | 12x12 | Tan | N | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 1st Floor | 100C | Misc | Resilient Flooring Tile | 12x12 | | | | | | | | | | | | | |
| 2nd Floor | 223 | Ceiling | Acoustic Ceiling Tile Pinhole Big Worm | 2x4 | N | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 2nd Floor | 223 | Wall(s) | Wallboard with Joint Compound | | Beige/Green | N | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 2nd Floor | 223 | Floor | Resilient Flooring Tile | 12x12 | Beige | Yes* | N/A | Y | N/A | Y | N/A | N/A | N/A | N/A | N/A | Y | *Mastic is ACM |
| 2nd Floor | 223 | Door/Door Frame | Wood and Metal | | Beige/Beige | | | | | | | | | | | | Core may contain asbestos |
| 2nd Floor | 223 | Misc | Cove Base | 4" | Beige | | | | | | | | | | | | |
| 2nd Floor | 223 | Misc | Cove Base - Terraza | 6" | Green | N | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 2nd Floor | 223 | Misc | | | | | | | | | | | | | | | |
| 2nd Floor | 214C | Ceiling | Acoustic Ceiling Tile Pinhole Big Worm | 2x4 | N | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 2nd Floor | 214C | Wall(s) | Wallboard with Joint Compound | | Beige | N | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 2nd Floor | 214C | Floor | Resilient Flooring Tile | 12x12 | Beige | Yes* | N/A | Y | N/A | Y | N/A | N/A | N/A | N/A | N/A | Y | *Mastic is ACM |

[illegible]

| Current Rm Name/No. | | Surface | Material | Size | Color | Sample Info | | | HAZARD ASSESSMENT | | | | | | | Comment | | |
|---------------------|------|-----------------|---|-------|------------------|------------------|-----------------------|--------------------------|-------------------|------------------|--|---|---|-----|-----------|---------|---------------------------|--|
| | | | | | | Asbestos Present | Contractor Sample No. | Previously Sampled (Y/N) | Friable | Good - No Damage | Damaged (10% overall or 25% localized) | Significantly Damaged >10% overall OR >25% localized) | Potential for Damage (vibration, Access, Erosion) | TSI | Surfacing | | Misc | |
| 2nd Floor | 217 | Ceiling | Acoustic Ceiling Tile Pinhole Worm | 2x4 | N | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | |
| 2nd Floor | 217 | Wall(s) | Wallboard with Joint Compound | | Beige | N | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | |
| 2nd Floor | 217 | Floor | Carpet | | Brown | | | | | | | | | | | | | |
| 2nd Floor | 217 | Door/Door Frame | | | | | | | | | | | | | | | | |
| 2nd Floor | 217 | Misc | Cove Base | 4" | Beige | | | | | | | | | | | | | |
| 2nd Floor | 217 | Wall(s) | Wainscot | 4" | Beige | | | | | | | | | | | | | |
| 2nd Floor | 217 | Misc | | | | | | | | | | | | | | | | |
| 2nd Floor | 215 | Ceiling | Acoustic Ceiling Tile Pinhole Worm | 2x4 | N | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | |
| 2nd Floor | 215 | Wall(s) | | | | | | | | | | | | | | | | |
| 2nd Floor | 215 | Floor | Resilient Flooring Tile | 12x12 | Beige | Yes* | N/A | Y | N/A | Y | N/A | N/A | N/A | N/A | N/A | Y | *Mastic is ACM | |
| 2nd Floor | 215 | Door/Door Frame | Wood and Metal | 4" | Beige/Beige | | | | | | | | | | | | Core may contain asbestos | |
| 2nd Floor | 215 | Misc | Cove Base | 6" | Beige | | | | | | | | | | | | | |
| 2nd Floor | 215 | Misc | Cove Base - Terrazo | | Green | N | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | |
| 2nd Floor | 215 | Misc | | | | | | | | | | | | | | | | |
| 2nd Floor | 214 | Ceiling | No Access | | | | | | | | | | | | | | | |
| 2nd Floor | 214 | Wall(s) | | | | | | | | | | | | | | | | |
| 2nd Floor | 214 | Floor | | | | | | | | | | | | | | | | |
| 2nd Floor | 214 | Door/Door Frame | | | | | | | | | | | | | | | | |
| 2nd Floor | 214 | Misc | | | | | | | | | | | | | | | | |
| 2nd Floor | 214 | Misc | | | | | | | | | | | | | | | | |
| 2nd Floor | 214 | Misc | | | | | | | | | | | | | | | | |
| 2nd Floor | 209 | Ceiling | Acoustic Ceiling Tile Pinhole Worm | 2x4 | N | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | |
| 2nd Floor | 209 | Wall(s) | Wallboard with Joint Compound /Concrete | | Beige/Green | | | | | | | | | | | | | |
| 2nd Floor | 209 | Floor | Carpet | | Blue/Purple | | | | | | | | | | | | | |
| 2nd Floor | 209 | Door/Door Frame | Wood and Metal | | Beige/Beige | | | | | | | | | | | | Core may contain asbestos | |
| 2nd Floor | 209 | Misc | | | | | | | | | | | | | | | | |
| 2nd Floor | 209A | Ceiling | Hard Lid Plaster | | Beige | | | | | | | | | | | | | |
| 2nd Floor | 209A | Wall(s) | Plaster | | Beige | Yes* | N/A | Y | N/A | Y | N/A | N/A | N/A | N/A | N/A | Y | *Mastic is ACM | |
| 2nd Floor | 209A | Floor | Ceramic Tile and Grout | 1x2 | Black/Grey/White | | | | | | | | | | | | | |
| 2nd Floor | 209A | Door/Door Frame | Wood and Metal | | Brown/Beige | | | | | | | | | | | | Core may contain asbestos | |
| 2nd Floor | 209A | Wall(s) | Ceramic Tile and Grout | 3x6 | Green/White | | | | | | | | | | | | | |
| 2nd Floor | 209A | Misc | | | | | | | | | | | | | | | | |
| 2nd Floor | 209A | Misc | | | | | | | | | | | | | | | | |
| 2nd Floor | 209B | Ceiling | No Access | | | | | | | | | | | | | | | |
| 2nd Floor | 209B | Wall(s) | | | | | | | | | | | | | | | | |
| 2nd Floor | 209B | Floor | | | | | | | | | | | | | | | | |
| 2nd Floor | 209B | Door/Door Frame | | | | | | | | | | | | | | | | |
| 2nd Floor | 209B | Misc | | | | | | | | | | | | | | | | |
| 2nd Floor | 209B | Misc | | | | | | | | | | | | | | | | |
| 2nd Floor | 209B | Misc | | | | | | | | | | | | | | | | |
| 2nd Floor | 214M | Ceiling | Acoustic Ceiling Tile Pinhole Big Worm | 2x4 | | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | |
| 2nd Floor | 214M | Wall(s) | Wallboard with Joint Compound | | Beige | N | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | |
| 2nd Floor | 214M | Floor | Resilient Flooring Tile | 12x12 | Beige | Yes* | N/A | Y | N/A | Y | N/A | N/A | N/A | N/A | N/A | Y | *Mastic is ACM | |
| 2nd Floor | 214M | Door/Door Frame | Wood | | Beige | | | | | | | | | | | | Core may contain asbestos | |
| 2nd Floor | 214M | Misc | Cove Base | 4" | Beige | | | | | | | | | | | | | |

[illegible]

| Current Rm Name/No. | | Surface | Material | Size | Color | Sample Info | | | HAZARD ASSESSMENT | | | | | | | | Comment |
|---------------------|--------------------|-----------------|------------------------------------|-------|-------------------|------------------|-----------------------|--------------------------|-------------------|------------------|--|---|---|-----|-----------|------|---------------------------|
| | | | | | | Asbestos Present | Contractor Sample No. | Previously Sampled (Y/N) | Friable | Good - No Damage | Damaged (10% overall or 25% localized) | Significantly Damaged >10% overall OR >25% localized) | Potential for Damage (vibration, Access, Erosion) | TSI | Surfacing | Misc | |
| 2nd Floor | 213A | Ceiling | Acoustic Ceiling Tile Pinhole Worm | 2x4 | | ND | Y | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 2nd Floor | 213A | Wall(s) | Wallboard with Joint Compound | | Beige | ND | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 2nd Floor | 213A | Floor | Carpet | | Brown | | | | | | | | | | | | |
| 2nd Floor | 213A | Door/Door Frame | Wood and Metal | | Beige/Beige | | | | | | | | | | | | Core may contain asbestos |
| 2nd Floor | 213A | Wall(s) | Plaster | | Green | ND | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 2nd Floor | 213A | Misc | Cove Base | 4" | Beige | | | | | | | | | | | | |
| 2nd Floor | 213A | Misc | | | | | | | | | | | | | | | |
| 2nd Floor | 210 | Ceiling | Acoustic Ceiling Tile Pinhole Worm | 2x4 | | ND | Y | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 2nd Floor | 210 | Wall(s) | Wallboard with Joint Compound | | | ND | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 2nd Floor | 210 | Floor | Carpet | 12x12 | Beige | Yes* | N/A | Y | N/A | Y | N/A | N/A | N/A | N/A | N/A | Y | *Mastic is ACM |
| 2nd Floor | 210 | Door/Door Frame | Wood and Metal | | Beige/Beige | | | | | | | | | | | | Core may contain asbestos |
| 2nd Floor | 210 | Misc | Cove Base | 4" | Beige | | | | | | | | | | | | |
| 2nd Floor | 210 | Wall(s) | Ceramic Tile and Grout | 4x4 | On white/On white | | | | | | | | | | | | |
| 2nd Floor | 210 | Misc | | | | | | | | | | | | | | | |
| 2nd Floor | 211 | Ceiling | Acoustic Ceiling Tile Pinhole Worm | 2x4 | N | ND | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 2nd Floor | 211 | Wall(s) | Wallboard with Joint Compound | | Beige | N | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 2nd Floor | 211 | Floor | Carpet | | Blue/Purple | | | | | | | | | | | | |
| 2nd Floor | 211 | Door/Door Frame | Wood and Metal | | Beige/Beige | | | | | | | | | | | | Core may contain asbestos |
| 2nd Floor | 211 | Misc | Cove Base | 4" | Tan | | | | | | | | | | | | |
| 2nd Floor | 211 | Misc | | | | | | | | | | | | | | | |
| 2nd Floor | 211 | Misc | | | | | | | | | | | | | | | |
| 2nd Floor | 213 Utility Closet | Ceiling | No Access | | | | | | | | | | | | | | |
| 2nd Floor | 213 Utility Closet | Wall(s) | | | | | | | | | | | | | | | |
| 2nd Floor | 213 Utility Closet | Floor | | | | | | | | | | | | | | | |
| 2nd Floor | 213 Utility Closet | Door/Door Frame | | | | | | | | | | | | | | | |
| 2nd Floor | 213 Utility Closet | Misc | | | | | | | | | | | | | | | |
| 2nd Floor | 213 Utility Closet | Misc | | | | | | | | | | | | | | | |
| 2nd Floor | 213 Utility Closet | Misc | | | | | | | | | | | | | | | |
| 2nd Floor | 212 Utility | Ceiling | No Access | | | | | | | | | | | | | | |
| 2nd Floor | 212 Utility | Wall(s) | | | | | | | | | | | | | | | |
| 2nd Floor | 212 Utility | Floor | | | | | | | | | | | | | | | |
| 2nd Floor | 212 Utility | Door/Door Frame | | | | | | | | | | | | | | | |
| 2nd Floor | 212 Utility | Misc | | | | | | | | | | | | | | | |
| 2nd Floor | 212 Utility | Misc | | | | | | | | | | | | | | | |
| 2nd Floor | 212 Utility | Misc | | | | | | | | | | | | | | | |
| 2nd Floor | 209B TELE | Ceiling | No Access | | | | | | | | | | | | | | |
| 2nd Floor | 209B TELE | Wall(s) | | | | | | | | | | | | | | | |
| 2nd Floor | 209B TELE | Floor | | | | | | | | | | | | | | | |
| 2nd Floor | 209B TELE | Door/Door Frame | | | | | | | | | | | | | | | |
| 2nd Floor | 209B TELE | Misc | | | | | | | | | | | | | | | |
| 2nd Floor | 209B TELE | Misc | | | | | | | | | | | | | | | |
| 2nd Floor | 209B TELE | Misc | | | | | | | | | | | | | | | |
| 2nd Floor | 206 | Ceiling | No Access | | | | | | | | | | | | | | |
| 2nd Floor | 206 | Wall(s) | | | | | | | | | | | | | | | |
| 2nd Floor | 206 | Floor | | | | | | | | | | | | | | | |
| 2nd Floor | 206 | Door/Door Frame | | | | | | | | | | | | | | | |
| 2nd Floor | 206 | Misc | | | | | | | | | | | | | | | |
| 2nd Floor | 206 | Misc | | | | | | | | | | | | | | | |

| Current Rm Name/No. | | Surface | Material | Size | Color | Sample Info | | | HAZARD ASSESSMENT | | | | | | | Comment | | |
|---------------------|---------------|-----------------|------------------------------------|-------|-------------|------------------|-----------------------|--------------------------|-------------------|------------------|--|---|---|-----|-----------|---------|---------------------------|-----|
| | | | | | | Asbestos Present | Contractor Sample No. | Previously Sampled (Y/N) | Friable | Good - No Damage | Damaged (10% overall or 25% localized) | Significantly Damaged >10% overall OR >25% localized) | Potential for Damage (vibration, Access, Erosion) | TSI | Surfacing | | Misc | |
| 2nd Floor | 202 Dark Room | Ceiling | No Access | | | | | | | | | | | | | | | |
| 2nd Floor | 202 Dark Room | Wall(s) | | | | | | | | | | | | | | | | |
| 2nd Floor | 202 Dark Room | Floor | | | | | | | | | | | | | | | | |
| 2nd Floor | 202 Dark Room | Door/Door Frame | | | | | | | | | | | | | | | | |
| 2nd Floor | 202 Dark Room | Misc | | | | | | | | | | | | | | | | |
| 2nd Floor | 202 Dark Room | Misc | | | | | | | | | | | | | | | | |
| 2nd Floor | 202 Dark Room | Misc | | | | | | | | | | | | | | | | |
| 2nd Floor | 200E | Ceiling | No Access | | | | | | | | | | | | | | | |
| 2nd Floor | 200E | Wall(s) | | | | | | | | | | | | | | | | |
| 2nd Floor | 200E | Floor | | | | | | | | | | | | | | | | |
| 2nd Floor | 200E | Door/Door Frame | | | | | | | | | | | | | | | | |
| 2nd Floor | 200E | Misc | | | | | | | | | | | | | | | | |
| 2nd Floor | 200E | Misc | | | | | | | | | | | | | | | | |
| 2nd Floor | 200E | Misc | | | | | | | | | | | | | | | | |
| 2nd Floor | 200D | Ceiling | Acoustic Ceiling Tile Pinhole Worm | 2x4 | N | ND | Y | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 2nd Floor | 200D | Wall(s) | Wallboard with Joint Compound | | Beige | ND | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 2nd Floor | 200D | Floor | Resilient Flooring Tile | 12x12 | Beige | Yes* | N/A | Y | N/A | Y | N/A | N/A | N/A | N/A | N/A | Y | *Mastic is ACM | |
| 2nd Floor | 200D | Door/Door Frame | Wood and Metal | | Beige/Beige | | | | | | | | | | | | Core may contain asbestos | |
| 2nd Floor | 200D | Wall(s) | Plaster | | Beige | N | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 2nd Floor | 200D | Misc | Cove Base | 4" | Beige | | | | | | | | | | | | | |
| 2nd Floor | 200D | Misc | Sink undercoat | | Black | | | | | | | | | | | | | |
| 2nd Floor | 200C | Ceiling | No Access | | | | | | | | | | | | | | | |
| 2nd Floor | 200C | Wall(s) | | | | | | | | | | | | | | | | |
| 2nd Floor | 200C | Floor | | | | | | | | | | | | | | | | |
| 2nd Floor | 200C | Door/Door Frame | | | | | | | | | | | | | | | | |
| 2nd Floor | 200C | Misc | | | | | | | | | | | | | | | | |
| 2nd Floor | 200C | Misc | | | | | | | | | | | | | | | | |
| 2nd Floor | 200C | Misc | | | | | | | | | | | | | | | | |
| 2nd Floor | 200BA | Ceiling | No Access | | | | | | | | | | | | | | | |
| 2nd Floor | 200BA | Wall(s) | | | | | | | | | | | | | | | | |
| 2nd Floor | 200BA | Floor | | | | | | | | | | | | | | | | |
| 2nd Floor | 200BA | Door/Door Frame | | | | | | | | | | | | | | | | |
| 2nd Floor | 200BA | Misc | | | | | | | | | | | | | | | | |
| 2nd Floor | 200BA | Misc | | | | | | | | | | | | | | | | |
| 2nd Floor | 200BA | Misc | | | | | | | | | | | | | | | | |
| 2nd Floor | 200A | Ceiling | Acoustic Ceiling Tile Pinhole Worm | 2x4 | N | ND | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 2nd Floor | 200A | Wall(s) | Wallboard with Joint Compound | | Beige/Green | ND | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 2nd Floor | 200A | Floor | Resilient Flooring Tile | 12x12 | Beige | Yes* | N/A | Y | N/A | Y | N/A | N/A | N/A | N/A | N/A | Y | *Mastic is ACM | |
| 2nd Floor | 200A | Door/Door Frame | Wood and Metal | | White/Beige | | | | | | | | | | | | Core may contain asbestos | |
| 2nd Floor | 200A | Wall(s) | Plaster | | Green | N | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 2nd Floor | 200A | Misc | Sink undercoat | | Black | | | | | | | | | | | | | |
| 2nd Floor | 200A | Misc | | | | | | | | | | | | | | | | |
| 2nd Floor | 200B | Ceiling | Acoustic Ceiling Tile Pinhole Worm | 2x4 | N | ND | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 2nd Floor | 200B | Wall(s) | Wallboard with Joint Compound | | Beige/Green | ND | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 2nd Floor | 200B | Floor | Resilient Flooring Tile | 12x12 | Beige | Yes* | N/A | Y | N/A | Y | N/A | N/A | N/A | N/A | N/A | Y | *Mastic is ACM | |
| 2nd Floor | 200B | Door/Door Frame | Wood and Metal | | White/Beige | | | | | | | | | | | | Core may contain asbestos | |

[illegible]

[illegible]

[illegible]

| Current Rm Name/No. | | Surface | Material | Size | Color | Sample Info | | | HAZARD ASSESSMENT | | | | | | | | Comment |
|---------------------|--------------|-----------------|-------------------------------|-------|-------------------|------------------|-----------------------|--------------------------|-------------------|------------------|--|---|---|-----|-----------|------|---------------------------|
| | | | | | | Asbestos Present | Contractor Sample No. | Previously Sampled (Y/N) | Friable | Good - No Damage | Damaged (10% overall or 25% localized) | Significantly Damaged >10% overall OR >25% localized) | Potential for Damage (vibration, Access, Erosion) | TSI | Surfacing | Misc | |
| 3rd Floor | 306 | Ceiling | Acoustic Ceiling Tile Pinhole | 2x4 | N | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 306 | Wall(s) | Wallboard with Joint Compound | | Beige | N | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 306 | Floor | Resilient Flooring Tile | 12x12 | Gray | Yes* | N/A | Y | N/A | Y | N/A | N/A | N/A | N/A | N/A | Y | *Mastic is ACM |
| 3rd Floor | 306 | Door/Door Frame | Wood and Metal | | Beige/Beige | | | | | | | | | | | | Core may contain asbestos |
| 3rd Floor | 306 | Wall(s) | Plaster | | Beige | N | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 306 | Wall(s) | Ceramic Tile and Grout | 4x4 | On white/On White | | | | | | | | | | | | |
| 3rd Floor | 306 | Misc | Cove Base | 4" | Beige | | | | | | | | | | | | |
| 3rd Floor | 306 | Misc | Cove Base - Terrazao | 6" | | | | | | | | | | | | | |
| 3rd Floor | 303C | Ceiling | Acoustic Ceiling Tile Pinhole | 2x4 | N | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 303C | Wall(s) | Wallboard with Joint Compound | | Beige | N | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 303C | Floor | Resilient Flooring Tile | 12x12 | Gray | Yes* | N/A | Y | N/A | Y | N/A | N/A | N/A | N/A | N/A | Y | *Mastic is ACM |
| 3rd Floor | 303C | Door/Door Frame | Wood and Metal | | Beige/Beige | | | | | | | | | | | | Core may contain asbestos |
| 3rd Floor | 303C | Wall(s) | Plaster | | Beige | N | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 303C | Wall(s) | Ceramic Tile and Grout | 4x4 | On white/On White | | | | | | | | | | | | |
| 3rd Floor | 303C | Misc | Cove Base | 4" | Beige | | | | | | | | | | | | |
| 3rd Floor | 303C | Misc | Cove Base - Terrazao | 6" | | | | | | | | | | | | | |
| 3rd Floor | 303B | Ceiling | No Access | | | | | | | | | | | | | | |
| 3rd Floor | 303B | Wall(s) | | | | | | | | | | | | | | | |
| 3rd Floor | 303B | Floor | | | | | | | | | | | | | | | |
| 3rd Floor | 303B | Door/Door Frame | | | | | | | | | | | | | | | |
| 3rd Floor | 303B | Misc | | | | | | | | | | | | | | | |
| 3rd Floor | 303B | Misc | | | | | | | | | | | | | | | |
| 3rd Floor | 303B | Misc | | | | | | | | | | | | | | | |
| 3rd Floor | 303A | Ceiling | Acoustic Ceiling Tile Pinhole | 2x4 | N | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 303A | Wall(s) | Wallboard with Joint Compound | | Beige | N | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 303A | Floor | Resilient Flooring Tile | 12x12 | Gray | Yes* | N/A | Y | N/A | Y | N/A | N/A | N/A | N/A | N/A | Y | *Mastic is ACM |
| 3rd Floor | 303A | Door/Door Frame | Wood and Metal | | Beige/Beige | | | | | | | | | | | | |
| 3rd Floor | 303A | Wall(s) | Plaster | | Beige | N | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 303A | Wall(s) | Ceramic Tile and Grout | 4x4 | On white/On White | | | | | | | | | | | | |
| 3rd Floor | 303A | Misc | Cove Base | 4" | Beige | | | | | | | | | | | | |
| 3rd Floor | 303A | Misc | Cove Base - Terrazao | 6" | | | | | | | | | | | | | |
| 3rd Floor | 302 Storage | Ceiling | No Access | | | | | | | | | | | | | | |
| 3rd Floor | 302 Storage | Wall(s) | | | | | | | | | | | | | | | |
| 3rd Floor | 302 Storage | Floor | | | | | | | | | | | | | | | |
| 3rd Floor | 302 Storage | Door/Door Frame | | | | | | | | | | | | | | | |
| 3rd Floor | 302 Storage | Misc | | | | | | | | | | | | | | | |
| 3rd Floor | 302 Storage | Misc | No Access | | | | | | | | | | | | | | |
| 3rd Floor | 302 Storage | Misc | | | | | | | | | | | | | | | |
| 3rd Floor | 307 Stoarage | Ceiling | | | | | | | | | | | | | | | |
| 3rd Floor | 307 Stoarage | Wall(s) | | | | | | | | | | | | | | | |
| 3rd Floor | 307 Stoarage | Floor | | | | | | | | | | | | | | | |
| 3rd Floor | 307 Stoarage | Door/Door Frame | | | | | | | | | | | | | | | |
| 3rd Floor | 307 Stoarage | Misc | | | | | | | | | | | | | | | |
| 3rd Floor | 307 Stoarage | Misc | No Access | | | | | | | | | | | | | | |
| 3rd Floor | 307 Stoarage | Misc | | | | | | | | | | | | | | | |
| 3rd Floor | 307 Stoarage | Misc | | | | | | | | | | | | | | | |
| 3rd Floor | 307 | Ceiling | Acoustic Ceiling Tile Pinhole | 2x4 | N | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 307 | Wall(s) | Wallboard with Joint Compound | | Beige/Green | N | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 307 | Floor | Resilient Flooring Tile | 9x9 | Yellow with Mar | Y | N/A | Y | N/A | Y | N/A | N/A | N/A | N/A | N/A | Y | N/A |

[illegible]

[illegible]

[illegible]

| Current Rm Name/No. | | Surface | Material | Size | Color | Sample Info | | | HAZARD ASSESSMENT | | | | | | | | Comment |
|---------------------|-----|-----------------|--|-------|-------------------|------------------|-----------------------|--------------------------|-------------------|------------------|--|---|---|-----|-----------|------|---------------------------|
| | | | | | | Asbestos Present | Contractor Sample No. | Previously Sampled (Y/N) | Friable | Good - No Damage | Damaged (10% overall or 25% localized) | Significantly Damaged >10% overall OR >25% localized) | Potential for Damage (vibration, Access, Erosion) | TSI | Surfacing | Misc | |
| 3rd Floor | 313 | Ceiling | Acoustic Ceiling Tile Pinhole | 2x4 | N | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 313 | Wall(s) | Wallboard with Joint Compound | | Beige | N | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 313 | Floor | Resilient Flooring Tile | 12x12 | Gray | Yes* | N/A | Y | N/A | Y | N/A | N/A | N/A | N/A | N/A | Y | *Mastic is ACM |
| 3rd Floor | 313 | Door/Door Frame | Wood and Metal | | Beige/Beige | Not Suspect | | | | | | | | | | | Core may contain asbestos |
| 3rd Floor | 313 | Wall(s) | Plaster | | Beige | ND | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 313 | Wall(s) | Ceramic Tile and Grout | 4x4 | On white/On White | Not Suspect | | | | | | | | | | | |
| 3rd Floor | 313 | Misc | Cove Base | 4" | Beige | ND | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 313 | Misc | Cove Base - Terrazao | 6" | Green | ND | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 311 | Ceiling | Acoustic Ceiling Tile Pinhole Big Worm | 2x4 | N | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 311 | Wall(s) | Wallboard with Joint Compound | | Beige | ND | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 311 | Floor | Resilient Flooring Tile | 12x12 | withDark Brown | Yes* | N/A | Y | N/A | Y | N/A | N/A | N/A | N/A | N/A | Y | *Mastic is ACM |
| 3rd Floor | 311 | Door/Door Frame | Metal and Metal | | Beige/Beige | Not Suspect | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | Core may contain asbestos |
| 3rd Floor | 311 | Misc | Plaster | | Beige | ND | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 311 | Misc | Cove Base | 4" | Off White | | | | | | | | | | | | |
| 3rd Floor | 311 | Misc | | | | | | | | | | | | | | | |
| 3rd Floor | 308 | Ceiling | No Access | | | | | | | | | | | | | | |
| 3rd Floor | 308 | Wall(s) | | | | | | | | | | | | | | | |
| 3rd Floor | 308 | Floor | | | | | | | | | | | | | | | |
| 3rd Floor | 308 | Door/Door Frame | | | | | | | | | | | | | | | |
| 3rd Floor | 308 | Misc | | | | | | | | | | | | | | | |
| 3rd Floor | 308 | Misc | | | | | | | | | | | | | | | |
| 3rd Floor | 308 | Misc | | | | | | | | | | | | | | | |
| 3rd Floor | 320 | Ceiling | Acoustic Ceiling Tile Pinhole | 2x4 | N | ND | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 320 | Wall(s) | Wallboard with Joint Compound | | Beige | ND | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 320 | Floor | Resilient Flooring Tile | 12x12 | Gray | Yes* | N/A | Y | N/A | Y | N/A | N/A | N/A | N/A | N/A | Y | *Mastic is ACM |
| 3rd Floor | 320 | Door/Door Frame | Wood and Metal | | Beige/Beige | Not Suspect | | | | | | | | | | | Core may contain asbestos |
| 3rd Floor | 320 | Wall(s) | Plaster | | Beige | ND | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 320 | Wall(s) | Ceramic Tile and Grout | 4x4 | On white/On White | Not Suspect | | | | | | | | | | | |
| 3rd Floor | 320 | Misc | Cove Base | 4" | Beige | ND | N/A | Y | | | | | | | | | |
| 3rd Floor | 320 | Misc | Cove Base - Terrazao | 6" | Green | ND | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 317 | Ceiling | Acoustic Ceiling Tile Pinhole | 2x4 | N | ND | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 317 | Wall(s) | Wallboard with Joint Compound | | Beige | ND | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 317 | Floor | Resilient Flooring Tile | 12x12 | Gray | Yes* | N/A | Y | N/A | Y | N/A | N/A | N/A | N/A | N/A | Y | *Mastic is ACM |
| 3rd Floor | 317 | Door/Door Frame | Wood and Metal | | Beige/Beige | | | | | | | | | | | | Core may contain asbestos |
| 3rd Floor | 317 | Wall(s) | Plaster | | Beige | ND | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 317 | Wall(s) | Ceramic Tile and Grout | 4x4 | On white/On White | | | | | | | | | | | | |
| 3rd Floor | 317 | Misc | Cove Base | 4" | Beige | | | | | | | | | | | | |
| 3rd Floor | 317 | Misc | Cove Base - Terrazao | 6" | | | | | | | | | | | | | |
| 3rd Floor | 315 | Ceiling | Acoustic Ceiling Tile Pinhole | 2x4 | N | ND | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 315 | Wall(s) | Wallboard with Joint Compound | | Beige | ND | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 315 | Floor | Resilient Flooring Tile | 12x12 | Gray | Yes* | N/A | Y | N/A | Y | N/A | N/A | N/A | N/A | N/A | Y | *Mastic is ACM |

[illegible]

| Current Rm Name/No. | | Surface | Material | Size | Color | Sample Info | | | HAZARD ASSESSMENT | | | | | | | | Comment |
|---------------------|-----|-----------------|-------------------------------|-------|-------------------|------------------|-----------------------|--------------------------|-------------------|------------------|--|---|---|-----|-----------|------|---------------------------|
| | | | | | | Asbestos Present | Contractor Sample No. | Previously Sampled (Y/N) | Friable | Good - No Damage | Damaged (10% overall or 25% localized) | Significantly Damaged >10% overall OR >25% localized) | Potential for Damage (vibration, Access, Erosion) | TSI | Surfacing | Misc | |
| 3rd Floor | 324 | Ceiling | Plaster | | Beige | ND | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 324 | Wall(s) | Plaster | | Beige | ND | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 324 | Floor | Resilient Flooring Tile | 12x12 | Gray | Yes* | N/A | Y | N/A | Y | N/A | N/A | N/A | N/A | N/A | Y | *Mastic is ACM |
| 3rd Floor | 324 | Door/Door Frame | Wood and Metal | | Beige/Beige | | | | | | | | | | | | Core may contain asbestos |
| 3rd Floor | 324 | Misc | Cove Base | 4" | Beige | | | | | | | | | | | | |
| 3rd Floor | 324 | Misc | | | | | | | | | | | | | | | |
| 3rd Floor | 324 | Misc | | | | | | | | | | | | | | | |
| 3rd Floor | 321 | Ceiling | Acoustic Ceiling Tile Pinhole | 2x4 | N | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 321 | Wall(s) | Wallboard with Joint Compound | | Beige | N | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 321 | Floor | Resilient Flooring Tile | 12x12 | Gray | Yes* | N/A | Y | N/A | Y | N/A | N/A | N/A | N/A | N/A | Y | *Mastic is ACM |
| 3rd Floor | 321 | Door/Door Frame | Wood and Metal | | Beige/Beige | | | | | | | | | | | | Core may contain asbestos |
| 3rd Floor | 321 | Wall(s) | Plaster | | Beige | ND | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 321 | Wall(s) | Ceramic Tile and Grout | 4x4 | On white/On white | | | | | | | | | | | | |
| 3rd Floor | 321 | Misc | Cove Base | 4" | Beige | | | | | | | | | | | | |
| 3rd Floor | 321 | Misc | Cove Base - Terrazao | 6" | | | | | | | | | | | | | |
| 3rd Floor | 322 | Ceiling | Plaster | | Beige | ND | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 322 | Wall(s) | Wallboard with Joint Compound | | Beige | ND | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 322 | Floor | Ceramic Tile and Grout | 1x1 | Tan/Brown | Not Suspect | | | | | | | | | | | |
| 3rd Floor | 322 | Door/Door Frame | Wood and Metal | | Beige | | | | | | | | | | | | Core may contain asbestos |
| 3rd Floor | 322 | Wall(s) | Ceramic Tile and Grout | 4x4 | Beige | | | | | | | | | | | | |
| 3rd Floor | 322 | Misc | | | Beige/Brown | | | | | | | | | | | | |
| 3rd Floor | 322 | Misc | | | | | | | | | | | | | | | |
| 3rd Floor | 323 | Ceiling | Plaster | | Beige | N | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 323 | Wall(s) | Ceramic Tile and Grout | 4x4 | On white/On white | Not Suspect | | | | | | | | | | | |
| 3rd Floor | 323 | Floor | Ceramic Tile and Grout | 1x1 | Gray/Gray | Not Suspect | | | | | | | | | | | |
| 3rd Floor | 323 | Door/Door Frame | Wood and Metal | | Beige/Beige | | | | | | | | | | | | Core may contain asbestos |
| 3rd Floor | 323 | Misc | | | | | | | | | | | | | | | |
| 3rd Floor | 323 | Misc | | | | | | | | | | | | | | | |
| 3rd Floor | 323 | Misc | | | | | | | | | | | | | | | |
| 3rd Floor | 327 | Ceiling | Acoustic Ceiling Tile Pinhole | 2x4 | N | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 327 | Wall(s) | Wallboard with Joint Compound | | Beige | ND | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 327 | Floor | Resilient Flooring Tile | 12x12 | Gray | Yes* | N/A | Y | N/A | Y | N/A | N/A | N/A | N/A | N/A | Y | *Mastic is ACM |
| 3rd Floor | 327 | Door/Door Frame | Wood and Metal | | Beige/Beige | | | | | | | | | | | | Core may contain asbestos |
| 3rd Floor | 327 | Wall(s) | Plaster | | Beige | N | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 327 | Wall(s) | Ceramic Tile and Grout | 4x4 | On white/On white | | | | | | | | | | | | |
| 3rd Floor | 327 | Misc | Cove Base | 4" | Beige | | | | | | | | | | | | |
| 3rd Floor | 327 | Misc | Cove Base - Terrazao | 6" | | | | | | | | | | | | | |
| 3rd Floor | 325 | Ceiling | Acoustic Ceiling Tile Pinhole | 2x4 | N | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 325 | Wall(s) | Wallboard with Joint Compound | | Beige | N | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 325 | Floor | Resilient Flooring Tile | 12x12 | Gray | Yes* | N/A | Y | N/A | Y | N/A | N/A | N/A | N/A | N/A | Y | *Mastic is ACM |

[illegible]

| Current Rm Name/No. | | Surface | Material | Size | Color | Sample Info | | | HAZARD ASSESSMENT | | | | | | | Comment | |
|---------------------|----------|-----------------|--|-------|-------------|------------------|-----------------------|--------------------------|-------------------|------------------|--|--|---|-----|-----------|---------|---------------------------|
| | | | | | | Asbestos Present | Contractor Sample No. | Previously Sampled (Y/N) | Friable | Good - No Damage | Damaged (10% overall or 25% localized) | Significantly Damaged >10% overall OR >25% localized | Potential for Damage (vibration, Access, Erosion) | TSI | Surfacing | | Misc |
| 3rd Floor | 326 ELEC | Ceiling | | | | | | | | | | | | | | | |
| 3rd Floor | 326 ELEC | Wall(s) | | | | | | | | | | | | | | | |
| 3rd Floor | 326 ELEC | Floor | | | | | | | | | | | | | | | |
| 3rd Floor | 326 ELEC | Door/Door Frame | No Acces | | | | | | | | | | | | | | |
| 3rd Floor | 326 ELEC | Misc | | | | | | | | | | | | | | | |
| 3rd Floor | 326 ELEC | Misc | | | | | | | | | | | | | | | |
| 3rd Floor | 326 ELEC | Misc | | | | | | | | | | | | | | | |
| 3rd Floor | 329 | Ceiling | Acoustic Ceiling Tile Pinhole Big Worm | 2x4 | N | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 329 | Wall(s) | Wallboard with Joint Compound | | Beige | N | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 329 | Floor | Carpet | | Brown | | | | | | | | | | | | |
| 3rd Floor | 329 | Door/Door Frame | Metal and Metal | | Beige/Beige | Not Suspect | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | Core may contain asbestos |
| 3rd Floor | 329 | Misc | Plaster | | Beige | N | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 329 | Misc | Cove Base | 4" | Beige | | | | | | | | | | | | |
| 3rd Floor | 329 | Misc | Cove Base - Terrazo | 6" | Green | | | | | | | | | | | | |
| 3rd Floor | 328 | Ceiling | Acoustic Ceiling Tile Pinhole Big Worm | 2x4 | N | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 328 | Wall(s) | Wallboard with Joint Compound | | Beige | ND | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 328 | Floor | Carpet | | Brown | Y | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | |
| 3rd Floor | 328 | Door/Door Frame | Metal and Metal | | Beige/Beige | Not Suspect | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | Core may contain asbestos |
| 3rd Floor | 328 | Misc | Plaster | | Beige | ND | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 328 | Misc | Cove Base | 4" | Beige | Y | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 328 | Misc | Cove Base - Terrazo | 6" | Green | | | | | | | | | | | | |
| 3rd Floor | 328D | Ceiling | Acoustic Ceiling Tile Pinhole Big Worm | 2x4 | N | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 328D | Wall(s) | Wallboard with Joint Compound | | Beige | ND | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 328D | Floor | Resilient Flooring Tile | 12x12 | Gray | Yes* | N/A | Y | N/A | Y | N/A | N/A | N/A | N/A | N/A | Y | *Mastic is ACM |
| 3rd Floor | 328D | Door/Door Frame | Wood and Metal | | Beige/Beige | | | | | | | | | | | | Core may contain asbestos |
| 3rd Floor | 328D | Misc | Cove Base | 4" | Beige | ND | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 328D | Misc | Cove Base - Terraza | 6" | Green | ND | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 328D | Misc | | | | | | | | | | | | | | | |
| 3rd Floor | 328C | Ceiling | Acoustic Ceiling Tile Pinhole | 2x4 | N | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 328C | Wall(s) | Wallboard with Joint Compound | | Beige | N | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 328C | Floor | Resilient Flooring Tile | 12x12 | Gray | Yes* | N/A | Y | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 328C | Door/Door Frame | Wood and Metal | | Beige/Beige | | | | | | | | | | | | Core may contain asbestos |
| 3rd Floor | 328C | Misc | Plaster | | Beige | ND | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 328C | Misc | Cove Base | 4" | Beige | ND | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 328C | Misc | | | | | | | | | | | | | | | |
| 3rd Floor | 328B | Ceiling | Acoustic Ceiling Tile Pinhole | 2x4 | N | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 328B | Wall(s) | Wallboard with Joint Compound | | Beige | N | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 328B | Floor | Resilient Flooring Tile | 12x12 | Gray | Yes* | N/A | Y | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | *Mastic is ACM |
| 3rd Floor | 328B | Door/Door Frame | Wood and Metal | | Beige/Beige | | | | | | | | | | | | Core may contain asbestos |
| 3rd Floor | 328B | Misc | Plaster | | Beige | ND | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 328B | Misc | Cove Base | 4" | Beige | ND | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| 3rd Floor | 328B | Misc | | | | | | | | | | | | | | | |
| 3rd Floor | 328A | Ceiling | Acoustic Ceiling Tile Pinhole | 2x4 | N | N/A | Y | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |

