

[illegible]



Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								NOTES
						Asbestos Present?	Previously Sampled (Y/N)	Contractor Sample No.	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
1st Floor	109	Ceiling	Acoustic Ceiling Tile Pinhole Only	2X4	Beige	None Detected	N	VALB-8-c1.1-c2.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	109	Floor	Carpet		Blue	Not suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Mastic, if present, may contain ACM
1st Floor	109	Misc	Covebase Mastic Terrzzo	6"	Off White	None Detected	N	VALB-8-m1.1-3.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	109	Wall(s)	Plaster		Off White	None Detected	N	VALB-8-w1.7-1.9	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	109	Misc	Window 3x		Beige	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	109	Door/Door Frame	Wood/Metal		Beige	Not suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Core may contain ACM
1st Floor	111	Ceiling	NOT ACCESSIBLE														
1st Floor	111	Floor															
1st Floor	111	Wall(s)															
1st Floor	114	Ceiling	Acoustic Ceiling Tile Pinhole Only	2X4	White	None Detected	N	VALB-8-c1.1-c2.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	114	Floor	Carpet		Blue	Not suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Mastic, if present, may contain ACM
1st Floor	114	Misc	Covebase Mastic	6"	Off White	None Detected	N	VALB-8-m1.1-3.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	114	Wall(s)	Plaster		Off White	None Detected	N	VALB-8-w1.7-1.9	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	114	Misc	Window 1x		Off White	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	114	Door/Door Frame	Wood/Metal		Beige	Not suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Core may contain ACM
1st Floor	115	Misc	Covebase Mastic	4"	Off White	None Detected	N	VALB-8-m1.1-3.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	115	Wall(s)	Drywall		Off White	Non Detected	N	VALB-8-w1.2-1.6	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	115	Ceiling	Expose Acoustical tile Mastic		Brown	None Noted	Y	VALB-8-f5.1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	115	Misc	Firestop		Red	None Detected	Y	VALB-8-m4.1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	115	Misc	Mastic		Yellow	None Detected	Y	VALB-8-f5.1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	115	Floor	Resilient Floor Tile	12x12	Seafoam Blue	None Detected	Y	VALB-8-f5.1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	115	Door/Door Frame	Wood/Metal		Beige	Not suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Core may contain ACM
1st Floor	116	Ceiling	NOT ACCESSIBLE														
1st Floor	116	Floor															
1st Floor	116	Wall(s)															
1st Floor	117	Ceiling	Acoustic Ceiling Tile Only	2X4	White	None Detected	N	VALB-8-c1.1-c2.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	117	Floor	Carpet		Blue	Not suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Mastic, if present, may contain ACM
1st Floor	117	Misc	Covebase Mastic	6"	off White	None Detected	N	VALB-8-m1.1-3.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	117	Wall(s)	Drywall		off White	Non Detected	N	VALB-8-w1.2-1.6	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	117	Misc	Window 2x Metal		Beige	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	117	Door/Door Frame	Wood/Metal		Beige	Not suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Core may contain ACM
1st Floor	118	Ceiling	Acoustic Ceiling Tile Pinhole Only	2X4	Beige	None Detected	N	VALB-8-c1.1-c2.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	118	Floor	Carpet		Blue	Not suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Mastic, if present, may contain ACM
1st Floor	118	Floor	Carpet		Blue	Not suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Mastic, if present, may contain ACM
1st Floor	118	Misc	Covebase Mastic Terrazzo	6"	Off White	None Detected	N	VALB-8-m1.1-3.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	118	Misc	HVAC Seal,TSI and Pipe Insulation	5000 sq.ft.	White and Yellow	None Detected	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	118	Wall(s)	Plaster		Off White	None Detected	N	VALB-8-w1.7-1.9	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	118	Misc	Window 3x		Beige	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	118	Door/Door Frame	Wood/Metal		Beige	Not suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Core may contain ACM
1st Floor	119	Ceiling	Acoustic Ceiling Tile Both	2X4	White	None Detected	N	VALB-8-c1.1-c2.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	119	Floor	Carpet		Blue	Not suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NA	Mastic, if present, may contain ACM
1st Floor	119	Misc	Covebase Mastic	6"	Off White	None Detected	N	VALB-8-m1.1-3.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	119	Wall(s)	Drywall/Plaster		off White	Non Detected	N	VALB-8-w1.2-1.9	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	119	Misc	Window 4x Metal		Beige	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	119	Door/Door Frame	Wood/Metal		Beige	Not suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Core may contain ACM
1st Floor	121	Ceiling	Acoustic Ceiling Tile Only	2X4	White	None Noted			N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	121	Ceiling	Acoustic Ceiling Tile Pinhole Only	2X4	Beige	None Detected	N	VALB-8-c1.1-c2.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
1st Floor	121	Floor	Carpet		Blue	Not suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Mastic, if present, may contain ACM
1st Floor	121	Floor	Carpet		Blue	Not suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Mastic, if present, may contain ACM





[illegible]

Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								NOTES
						Asbestos Present?	Previously Sampled (Y/N)	Contractor Sample No.	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
2nd Floor	205	Ceiling	Acoustic Ceiling Tile Pinhole Only	2X4	White	None Detected	Y	VALB-8-c1.1-c2.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Mastic, if present, may contain ACM
2nd Floor	205	Floor	Carpet Tile with Mastic	16X16	Blue/Black	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	205	Misc	Covebase Mastic		Brown	None Detected	N	VALB-8-m1.1-3.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	205	Wall(s)	Plaster/Drywall		Off White/Tan	None Detected	N	VALB-8-w1.2-1.9	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	205	Misc	Window 1x		Green	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	205	Door/Door Frame	Wood/Metal		Off White	Not suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Core may contain ACM
2nd Floor	206	Ceiling	Acoustice Ceiling Tile Pinhole Only	2X4	White	None Detected	Y	VALB-8-c1.1-c2.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	206	Wall(s)	Drywall/Plaster		Off White/Tan	Non Detected	N	VALB-8-w1.2-1.9	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	206	Floor	Resilient Floor Tile	12X12	Beige	<1% Chrysotile	N	VALB-8-f2.1	Non Friable	N/A	N/A	N/A	N/A	N/A	N/A	N/A	mastic is <1%
2nd Floor	206	Door/Door Frame	Wood/Metal		Off White	Not suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Core may contain ACM
2nd Floor	207	Ceiling	Acoustic Ceiling Tile Pinhole Only	2X4	White	None Detected	Y	VALB-8-c1.1-c2.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	207	Floor	Carpet Tile with Mastic	16X16	Blue/Black	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Mastic, if present, may contain ACM
2nd Floor	207	Misc	Exposed Covebase Mastic		Brown	None Detected	N	VALB-8-m1.1-3.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	207	Wall(s)	Plaster/Drywall		Off White/Tan	None Detected	N	VALB-8-w1.2-1.9	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	207	Misc	Window 1x		Tan	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	207	Door/Door Frame	Wood/Metal			Not suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	208	Misc	Exposed Covebase Mastic		Brown	None Detected	N	VALB-8-m1.1-3.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	209	Ceiling	Acoustic Ceiling Tile Pinhole Only	2X4	White	None Detected	Y	VALB-8-c1.1-c2.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	209	Floor	Carpet Tile with Mastic	16X16	Blue/Black	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Mastic, if present, may contain ACM
2nd Floor	209	Misc	Exposed Covebase Mastic		Brown	None Detected	N	VALB-8-m1.1-3.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	209	Wall(s)	Plaster/Drywall		Off White/Tan	None Detected	N	VALB-8-w1.2-1.9	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	209	Misc	Window 1x		Tan	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	209	Door/Door Frame	Wood/Metal			Not suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	210	Ceiling	Acoustic Ceiling Tile Pinhole Only	2X4	White	None Detected	Y	VALB-8-c1.1-c2.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	210	Floor	Carpet Tile with Mastic	16X16	Blue/Black	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Mastic, if present, may contain ACM
2nd Floor	210	Misc	Exposed Covebase Mastic		Brown	None Detected	N	VALB-8-m1.1-3.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	210	Wall(s)	Plaster/Drywall		Off White/Tan	None Detected	N	VALB-8-w1.2-1.9	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	210	Misc	Window 1x		Tan	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	210	Door/Door Frame	Wood/Metal			Not suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	211	Ceiling	Acoustic Ceiling Tile Pinhole Only	2X4	White	None Detected	Y	VALB-8-c1.1-c2.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	211	Floor	Carpet Tile with Mastic	16X16	Blue/Black	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Mastic, if present, may contain ACM
2nd Floor	211	Misc	Exposed Covebase Mastic		Brown	None Detected	N	VALB-8-m1.1-3.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	211	Wall(s)	Plaster/Drywall		Off White/Tan	None Detected	N	VALB-8-w1.2-1.9	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	211	Misc	Window 1x		Tan	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
2nd Floor	211	Door/Door Frame	Wood/Metal			Not suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	212	Ceiling	Acoustic Ceiling Tile Pinhole Only	2X4	White	None Detected	Y	VALB-8-c1.1-c2.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	

[illegible]





Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								NOTES
						Asbestos Present?	Previously Sampled (Y/N)	Contractor Sample No.	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	SignificantlyDamaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
2nd Floor	221	Ceiling	Acoustic Ceiling Tile Pinhole Only	2X4	White	None Detected	Y	VALB-8-c1.1-c2.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	221	Floor	Carpet Tile with Mastic	16X16	Blue/Black	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Mastic, if present, may contain ACM
2nd Floor	221	Misc	Exposed Covebase Mastic		Brown	None Detected	N	VALB-8-m1.1-3.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	221	Wall(s)	Plaster/Drywall		Off White/Tan	None Detected	N	VALB-8-w1.2-1.9	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	221	Misc	Window 1x		Tan	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	221	Door/Door Frame	Wood/Metal			Not suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Core may contain ACM
2nd Floor	222	Ceiling	Acoustic Ceiling Tile Pinhole Only	2X4	White	None Detected	Y	VALB-8-c1.1-c2.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	222	Floor	Carpet Tile with Mastic	16X16	Blue/Black	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Mastic, if present, may contain ACM
2nd Floor	222	Misc	Exposed Covebase Mastic		Brown	None Detected	N	VALB-8-m1.1-3.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	222	Wall(s)	Plaster/Drywall		Off White/Tan	None Detected	N	VALB-8-w1.2-1.9	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	222	Misc	Window 1x		Tan	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	222	Door/Door Frame	Wood/Metal			Not suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Core may contain ACM
2nd Floor	223	Ceiling	Acoustic Ceiling Tile Pinhole Only	2X4	White	None Detected	Y	VALB-8-c1.1-c2.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	223	Floor	Carpet Tile with Mastic	16X16	Blue/Black	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Mastic, if present, may contain ACM
2nd Floor	223	Misc	Exposed Covebase Mastic		Brown	None Detected	N	VALB-8-m1.1-3.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	223	Wall(s)	Plaster/Drywall		Off White/Tan	None Detected	N	VALB-8-w1.2-1.9	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	223	Misc	Window 1x		Tan	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	223	Door/Door Frame	Wood/Metal			Not suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Core may contain ACM
2nd Floor	224	Ceiling	Acoustic Ceiling Tile Pinhole Only	2X4	White	None Detected	Y	VALB-8-c1.1-c2.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	224	Floor	Carpet Tile with Mastic	16X16	Blue/Black	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Mastic, if present, may contain ACM
2nd Floor	224	Misc	Exposed Covebase Mastic		Brown	None Detected	N	VALB-8-m1.1-3.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	224	Wall(s)	Plaster/Drywall		Off White/Tan	None Detected	N	VALB-8-w1.2-1.9	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	224	Misc	Window 1x		Tan	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	224	Door/Door Frame	Wood/Metal			Not suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Core may contain ACM
2nd Floor	225	Ceiling	Acoustic Ceiling Tile Both Pinhole & Pinworm	2X4	White	None Detected	Y	VALB-8-c1.1-c2.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	225	Floor	Carpet Tiles With Mastic	16X16	Blue/Black	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Mastic, if present, may contain ACM
2nd Floor	225	Wall(s)	Wood Panels (Over Plaster)		Off White and Tan	None Noted	N		N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	225	Door/Door Frame	Wood/Metal		Off White	Not suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Core may contain ACM
2nd Floor	200A	Misc	(Exterior at Room 200 A) Window Puttv		White	None Detected	Y	VALB-8-ext1.1	N/A	N/A	N/A	N	N/A	N/A	N/A	N/A	
2nd Floor	200A	Ceiling	Acoustice Ceiling Tile Small Pinholes	1X2	White	None Detected	Y	VALB-8-c1.1-c2.3	N/A	N/A	N/A	N	N/A	N/A	N/A	N/A	
2nd Floor	200A	Wall(s)	Plaster		Beige/Pink Streaks	None Detected	N	VALB-8-w1.7-1.9	N/A	N/A	N/A	N	N/A	N/A	N/A	NA	
2nd Floor	200A	Floor	Resilient Floor Tile	9x9/12x12	Off White	Yes	N	VALB-8-f1.1-3.1	Non Friable	N/A	N/A	N	N/A	N/A	N/A	Yes	
2nd Floor	200A	Misc	Window Double Glass	6X6		Not Suspect	N/A	N/A	N/A	N/A	N/A	N	N/A	N/A	N/A	N/A	
2nd Floor	200A	Door/Door Frame	Wood/Metal		Off White/Bare	Not suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Core may contain ACM
2nd Floor	200B	Ceiling	Acoustic Ceiling Tile Small Pinholes	1X2	Yellow	None Detected	Y	VALB-8-c1.1-c2.3	N/A	N/A	N/A	N	N/A	N/A	N/A	N/A	
2nd Floor	200B	Floor	Carpet Tiles		Brown	Not suspect	N		N/A	N/A	N/A	N	N/A	N/A	N/A	N/A	Mastic, if present, may contain ACM

Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								NOTES
						Asbestos Present?	Previously Sampled (Y/N)	Contractor Sample No.	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
2nd Floor	200B	Misc	Covebase and Mastic		Beigeand White	None Detected	N	VALB-8-m1.1-3.3	N/A	N/A	N/A	N	N/A	N/A	N/A	N/A	
2nd Floor	200B	Wall(s)	Partition		Off White & Tan	Not Suspect	N	N/A	N/A	N/A	N/A	N	N/A	N/A	N/A	N/A	
2nd Floor	200B	Wall(s)	Plaster/Drywall		Off White	None Detected	N	VALB-8-w1.2-1.9	N/A	N/A	N/A	N	N/A	N/A	N/A	N/A	
2nd Floor	200B	Misc	Window 6 Pane		Beige	Not Suspect	N/A	N/A	N/A	N/A	N/A	Yes	High	N/A	N/A	N/A	
2nd Floor	200B	Door/Door Frame	Wood/Metal		Off White/Bare	Not suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Core may contain ACM
2nd Floor	200C	Ceiling	Acoustic Ceiling Tile Pinworm/Small Pinhole	2X4/1X2	Yellow	None Detected	Y	VALB-8-c1.1-c2.3	N/A	N/A	N/A	N	N/A	N/A	N/A	N/A	
2nd Floor	200C	Floor	Carpet with Tarazzo Under	2X2	Brown/Green Tarazzo	Not suspect	N	N/A	N/A	N/A	N/A	N	N/A	N/A	N/A	N/A	Mastic, if present, may contain ACM
2nd Floor	200C	Misc	Covebase Mastic	4"	Beige	None Detected	N	VALB-8-m1.1-3.3	N/A	N/A	N/A	N	N/A	N/A	N/A	N/A	
2nd Floor	200C	Wall(s)	Partition Wall		Beige	Not Suspect	N	N/A	N/A	N/A	N/A	N	N/A	N/A	N/A	N/A	
2nd Floor	200C	Wall(s)	Plaster/Drywall		Green	None Detected	N	VALB-8-w1.2-1.9	N/A	N/A	N/A	N	N/A	N/A	N/A	N/A	
2nd Floor	200C	Misc	Window 6 Pane		Green	Not Suspect	N/A	N/A	N/A	N/A	N/A	N	N/A	N/A	N/A	N/A	
2nd Floor	200C	Door/Door Frame	Wood/Metal		Beige/Bare	Not suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Core may contain ACM
2nd Floor	200D	Ceiling	Acoustice Ceiling Tile Pinhole Bigwrom & Tinv Pinhole	2x4 & 1x2		None Detected	Y	VALB-8-c1.1-c2.3	N/A	N/A	N/A	N	N/A	N/A	N/A	N A	
2nd Floor	200D	Floor	Carpet with Tarazzo Under	2x2	Brown/Green Tarazzo	Not suspect	N	N/A	N/A	N/A	N/A	N	N/A	N/A	N/A	N/A	Mastic, if present, may contain ACM
2nd Floor	200D	Misc	Covebase and Mastic	4"	Tan and Tan	None Detected	N	VALB-8-m1.1-3.3	N/A	N/A	N/A	N	N/A	N/A	N/A	N/A	
2nd Floor	200D	Wall(s)	Partition Wall			Not Suspect	N	N/A	N/A	N/A	N/A	N	N/A	N/A	N/A	N/A	
2nd Floor	200D	Wall(s)	Plaster/Drywall		Greed	None Detected	N	VALB-8-w1.2-1.9	N/A	N/A	N/A	N	N/A	N/A	N/A	N/A	
2nd Floor	200D	Misc	Window 6 Pane		Green	Not Suspect	N/A	N/A	N/A	N/A	N/A	N	N/A	N/A	N/A	N/A	
2nd Floor	200D	Door/Door Frame	Wood/Metal		Beige/Bare	Not suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Core may contain ACM
2nd Floor	200E	Ceiling	Acoustice Ceiling Tile Pinhole Bigwrom & Tinv Pinhole	2x4 & 1x2		None Detected	Y	VALB-8-c1.1-c2.3	N/A	N/A	N/A	N	N/A	N/A	N/A	N/A	
2nd Floor	200E	Floor	Carpet with Tarazzo Under	2x2	Brown/Green Tarazzo	Not suspect	N	N/A	N/A	N/A	NN	N	N/A	N/A	N/A	N/A	Mastic, if present, may contain ACM
2nd Floor	200E	Misc	Covebase Mastic	4"	Beige	None Detected	N	VALB-8-m1.1-3.3	N/A	N/A	N/A	N	N/A	N/A	N/A	N/A	
2nd Floor	200E	Misc	Partition Wall			Not Suspect	N	N/A	N/A	N/A	N/A	N	N/A	N/A	N/A	N/A	
2nd Floor	200E	Wall(s)	Plaster/Drywall		Green	None Detected	N	VALB-8-w1.2-1.9	N/A	N/A	N/A	N	N/A	N/A	N/A	NA	
2nd Floor	200E	Misc	Window 6 Pane		Green	Not Suspect	N/A	N/A	N/A	N/A	N/A	N	N/A	N/A	N/A	N/A	
2nd Floor	200E	Door/Door Frame	Wood/Metal		Beige/Bare	Not suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Core may contain ACM
2nd Floor	208	Ceiling	Acoustic Ceiling Tile Pinhole Only	2X4	White	None Detected	Y	VALB-8-c1.1-c2.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	208	Floor	Carpet Tile with Mastic	16X16	Blue/Black	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Mastic, if present, may contain ACM
2nd Floor	208	Wall(s)	Plaster/Drywall		Off White/Tan	None Detected	N	VALB-8-w1.2-1.9	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	208	Misc	Window 1x		Tan	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	208	Door/Door Frame	Wood/Metal			Not suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Core may contain ACM
2nd Floor	212 -NA	Floor	NOT ACCESSIBLE														
2nd Floor	212 -NA	Ceiling															
2nd Floor	212 -NA	Door/Door Frame												N/A			
2nd Floor	212 -NA	Wall(s)															
2nd Floor	223A	Ceiling	Acoustic Ceiling Tile Pinhole Only	2X4	White	None Detected	Y	VALB-8-c1.1-c2.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								NOTES
						Asbestos Present?	Previously Sampled (Y/N)	Contractor Sample No.	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	SignificantlyDamaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
2nd Floor	223A	Misc	Mastic		Black	4% Chrysotile	Y	VALB-8-f2.1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	223A	Misc	Mastic		Yellow	None Detected	Y	VALB-8-f2.1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	223A	Wall(s)	Plaster/Drywall		Off White/Off White	None Detected	N	VALB-8-w1.2-1.9	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	223A	Floor	Resilient Floor Tile /mastic	12X12	Beige	<1% Chrysotile	N	VALB-8-f2.1	Non Friable	N/A	N/A	N/A	N/A	N/A	N/A	Yes	mastic is <1%
2nd Floor	223A	Door/Door Frame	Wood/Metal		Off White	Not suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Core may contain ACM
2nd Floor	C8-3	Ceiling	Hardlid Plaster		White	None Detected	N	VALB-W-1.7-1.9	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	C8-3	Misc	Mastic		Yellow	None Detected	Y	VALB-8-f3.1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	C8-3	Floor	Resilient Floor Tile /mastic	12X12	Tan	<1% Chrysotile	Y	VALB-8-f3.1	Non Friable	N/A	N/A	N/A	N/A	N/A	N/A	Yes	mastic is <1%
2nd Floor	C8-3	Wall(s)	Concrete & Plaster		Off White & Tan	None Noted	N		N/A	N/A	N/A	N	N/A	N/A	N/A	N/A	
2nd Floor	C8-3 Corridor	Ceiling	Acoustic Ceiling Tile Pinhole & Bigworm	1x1	White w/ Exposed brown mastic	None Detected	Y	VALB-8-c1.1-c2.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	C8-3 Corridor	Ceiling	Acoustic Ceiling Tile Pinhole & Pinworm	2x4	White	None Detected	N	VALB-8-c1.3	N/A	N/A	N/A	N	N/A	N/A	N/A	N/A	
2nd Floor	C8-3 Corridor	Wall(s)	Concrete & Plaster		Off White & Tan	None Noted	N		N/A	N/A	N/A	N	N/A	N/A	N/A	N/A	
2nd Floor	C8-3 Corridor	Door/Door Frame	Covebase Mastic Terrazzo		Green	Not suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Core may contain ACM
2nd Floor	C8-3 Corridor	Misc	Exposed Covebase Mastic		Gray & Brown	None Detected	N	VALB-8-m1.1-3.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	C8-3 Corridor	Floor	Resilient Floor Tile /mastic	9x9/12x12	Beige with Pink Streaks/Mauve	3-5% Chrysotile	N	VALB-8-f3.1	Non Friable	N/A	N/A	N	N/A	N/A	N/A	Yes	ACM is in the mastic & 9"
2nd Floor	C8-3 Corridor	Misc	Window 6 Pane			Not Suspect	N/A	N/A	N/A	N/A	N/A	Yes	High	N/A	N/A	N/A	

Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								NOTES
						Asbestos Present?	Previously Sampled (Y/N)	Contractor Sample No.	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
2nd Floor	C8-3 East	Ceiling	Hardlid Plaster		White	None Detected	N	VALB-W-1.7-1.9	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	C8-3 East	Misc	Mastic		Yellow	None Detected	Y	VALB-8-f1.2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	C8-3 East	Floor	Resilient Floor Tile /mastic	12X12	Beige	<1% Chrysotile	Y	VALB-8-f1.2	Non Friable	N/A	N/A	N/A	N/A	N/A	N/A	Yes	mastic is <1%
2nd Floor	C8-3 East	Wall(s)	Concrete & Plaster		Off White & Tan	None Noted	N		N/A	N/A	N/A	N	N/A	N/A	N/A	N/A	
2nd Floor	C8-3A	Ceiling	Hardlid Plaster		White	None Detected	N	VALB-W-1.7-1.9	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	C8-3A	Misc	Mastic		Black	2% Chrysotile	Y	VALB-8-F1.1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	C8-3A	Misc	Mastic		Brown	None Detected	Y	VALB-8-F1.1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	C8-3A	Floor	Resilient Floor Tile /mastic	12X12	Tan	<1% Chrysotile	Y	VALB-8-F1.1	Non Friable	N/A	N/A	N/A	N/A	N/A	N/A	Yes	mastic is <1%
2nd Floor	C8-3A	Wall(s)	Concrete & Plaster		Off White & Tan	None Noted	N		N/A	N/A	N/A	N	N/A	N/A	N/A	N/A	
2nd Floor	C8-3A North	Ceiling	Acoustic Ceiling Tile Pinhole & Pinworm	2X4	White	None Detected	Y	VALB-8-c1.1-c2.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	C8-3A North	Wall(s)	Drywall		Off White	Non Detected	N	VALB-8-w1.2-1.6	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	C8-3A North	Misc	Exposed Covebase Mastic		Brown	None Detected	N	VALB-8-m1.1-3.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	C8-3A North	Floor	Resilient Floor Tile / Mastic	12X12	Tan & Mauve	<1% Chrysotile	N	VALB-8-f3.1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	mastic is <1%
2nd Floor	C8-3A North	Door/Door Frame	Wood/Metal		Off White	Not suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Core may contain ACM
2nd Floor	C8-3A South	Ceiling	Acoustic Ceiling Tile Pinhole only	2X4	White Exposed Hockey Puck & Tile	None Detected	Y	VALB-8-c1.1-c2.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	C8-3A South	Floor	Carpet with Mastic		Blue/Black Mastic	<1% Chrysotile	N	VALB-8-f6.2	Non Friable	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Black mastic is <1%, probable remnant from FT mastic
2nd Floor	C8-3A South	Wall(s)	Drywall/Ceramic Tile	4X4	Off White/White	Non Detected	N	VALB-8-w1.2-1.6	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	C8-3A South	Misc	Exposed Covebase Mastic		Brown	None Detected	N	VALB-8-m1.1-3.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	C8-3A South	Door/Door Frame	Wood/Metal		Off White	Not suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Core may contain ACM
2nd Floor	C8-3A1 and C8-3A1 East	Misc	Covebase (C8-3A1 East)	4"	Tan	None Detected	N	VALB-8-m1.1-3.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	C8-3A1 and C8-3A1 East	Ceiling	Hardlid Plaster		White	None Detected	N	VALB-W-1.7-1.9	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	C8-3A1 and C8-3A1 East	Misc	Mastic		Yellow	None Detected	Y	VALB-8-f3.2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	C8-3A1 and C8-3A1 East	Floor	Resilient Floor Tile /mastic	12X12	Tan	<1% Chrysotile	Y	VALB-8-f3.2	Non Friable	N/A	N/A	N/A	N/A	N/A	N/A	Yes	mastic is <1%
2nd Floor	C8-3A1 and C8-3A1 East	Wall(s)	Drywall/Ceramic Tile	4X4	Off White/White	Non Detected	N	VALB-8-w1.2-1.6	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	Corridor C8-3B	Ceiling	Acoustic Ceiling Tile Pinhole only	2X4	White Exposed Hockey Puck & Tile	None Detected	Y	VALB-8-c1.1-c2.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	Corridor C8-3B	Floor	Carpet with Mastic		Blue/Black Mastic	<1% Chrysotile	N	VALB-8-f6.2	Non Friable	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Black mastic is <1%, probable remnant from FT mastic
2nd Floor	Corridor C8-3B	Wall(s)	Drywall/Ceramic Tile	4X4	Off White/White	Non Detected	N	VALB-8-w1.2-1.6	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	Corridor C8-3B	Misc	Exposed Covebase Mastic		Brown	None Detected	N	VALB-8-m1.1-3.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	Corridor C8-3B	Door/Door Frame	Wood/Metal		Off White	Not suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Core may contain ACM
2nd Floor	Electrical Panel 218A - NA	Floor	Carpet Tile		Blue	Not suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	Electrical Panel 218A - NA	Wall(s)	Drywall		Off White	Non Detected	N	VALB-8-w1.2-1.6	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	Electrical Panel 218A - NA	Ceiling	Expose Acoustical tile Mastic		Brown	None Noted	Y	VALB-8-f5.1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	Electrical Panel 218A - NA	Door/Door Frame	Wood/Metal		Off White	Not suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Core may contain ACM
2nd Floor	RR 216 Womans	Misc	1 Window		Off White	Not Suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	RR 216 Womans	Floor	Ceramic Tile	1X1	White	Not Suspect	N	VALB-8-c1.1-c2.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	RR 216 Womans	Wall(s)	Ceramic Tile/Drywall		Blue/Off White	None Noted	N		N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	RR 216 Womans	Ceiling	Hardlid Plaster		Off White	None Detected	N	VALB-W-1.7-1.9	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	RR 216 Womans	Door/Door Frame	Wood/Metal		Off White	Not suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Core may contain ACM

[illegible]

Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								NOTES
						Asbestos Present?	Previously Sampled (Y/N)	Contractor Sample No.	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
2nd Floor	Tel HB - 2A	Ceiling	Acoustic Ceiling Tile Exposed Hockey Puck		Brown	None Detected	Y	VALB-8-c1.1-c2.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	Tel HB - 2A	Wall(s)	Drywall All		Off White	Non Detected	N	VALB-8-w1.2-1.6	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	Tel HB - 2A	Misc	Exposed Covebase Mastic		Brown	None Detected	N	VALB-8-m1.1-3.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	Tel HB - 2A	Floor	Resilient Floor Tile /mastic	12X12	Beige/Black	<1% Chrysotile	N	VALB-8-f3.1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	mastic is <1%
2nd Floor	Tel HB - 2A	Door/Door Frame	Wood/Metal		Off White	Not suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Core may contain ACM
2nd Floor	Stair 2 2nd Floor	Ceiling	Hard Concrete		White	Not Suspect			N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	Stair 2 2nd Floor	Floor	Concrete			Not suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	Stair 2 2nd Floor	Wall(s)	Concrete		Off White	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	Stair 2 2nd Floor	Misc	Covebase Mastic		Off White	None Detected	N	VALB-8-m1.1-3.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
2nd Floor	Stair 2 2nd Floor	Door/Door Frame	Metal/Metal		Beige	Not suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Core may contain ACM
2nd Floor	Stair 2 2nd Floor	Misc	Window 1x Putty		White & Blue	None Detected	N/A	VALB-8-ext1.1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	303	Floor	Ceramic Tile	2X2	White	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	303	Ceiling	Hardlid Plaster		White	None Detected	N	VALB-W-1.7-1.9	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	303	Door/Door Frame	Metal/Metal		Off White/Off White	Not suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Core may contain ACM
3rd Floor	303	Wall(s)	Plaster		White	None Detected	N	VALB-8-w1.7-1.9	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	304	Ceiling	Acoustic Ceiling Tile Both	2X4	White	None Detected	Y	VALB-8-c1.1-c2.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	304	Floor	Carpet		Green	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Mastic, if present, may contain ACM
3rd Floor	304	Misc	Covebase Mastic	6"	Beige	None Detected	N	VALB-8-m1.1-3.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	304	Wall(s)	Plaster/Drywall		Tan/Beige	None Detected	N	VALB-8-w1.2-1.9	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	304	Misc	Window 1x		Tan	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	304	Door/Door Frame	Wood/Metal		Off White/Off White	Not suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Core may contain ACM
3rd Floor	305	Ceiling	Acoustic Ceiling Tile Both	2X4	White	None Detected	Y	VALB-8-c1.1-c2.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	305	Floor	Carpet		Green	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Mastic, if present, may contain ACM
3rd Floor	305	Misc	Covebase Mastic	6"	Beige	None Detected	N	VALB-8-m1.1-3.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	305	Wall(s)	Plaster/Drywall		Tan/Beige	None Detected	N	VALB-8-w1.2-1.9	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	305	Misc	Window 1x		Tan	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	305	Door/Door Frame	Wood/Metal		Off White/Off White	Not suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Core may contain ACM
3rd Floor	306	Ceiling	Acoustic Ceiling Tile Both	2X4	White	None Detected	Y	VALB-8-c1.1-c2.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	306	Floor	Carpet		Green	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Mastic, if present, may contain ACM
3rd Floor	306	Misc	Carpet Glue		Yellow	None Detected	Y	VALB-8-f6.1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	306	Misc	Covebase Mastic	6"	Beige	None Detected	N	VALB-8-m1.1-3.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	306	Wall(s)	Plaster/Drywall		Tan/Beige	None Detected	N	VALB-8-w1.2-1.9	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	306	Door/Door Frame	Wood/Metal		Off White/Off White	Not suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Core may contain ACM
3rd Floor	310	Ceiling	Acoustic Ceiling Tile Both	2X4	White	None Detected	Y	VALB-8-c1.1-c2.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	310	Floor	Carpet		Green	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Mastic, if present, may contain ACM
3rd Floor	310	Misc	Covebase Mastic	6"	Beige	None Detected	N	VALB-8-m1.1-3.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	310	Wall(s)	Plaster/Drywall		Tan/Beige	None Detected	N	VALB-8-w1.2-1.9	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	310	Misc	Window 1x		Tan	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	310	Door/Door Frame	Wood/Metal		Off White/Off White	Not suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Core may contain ACM
3rd Floor	312	Ceiling	Acoustic Ceiling Tile Both	2X4	White	None Detected	Y	VALB-8-c1.1-c2.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	312	Floor	Carpet		Green	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Mastic, if present, may contain ACM
3rd Floor	312	Misc	Covebase Mastic	6"	Beige	None Detected	N	VALB-8-m1.1-3.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	312	Wall(s)	Plaster/Drywall		Tan/Beige	None Detected	N	VALB-8-w1.2-1.9	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	312	Misc	Window 1x		Tan	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	312	Door/Door Frame	Wood/Metal		Off White/Off White	Not suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Core may contain ACM
3rd Floor	316	Floor	Carpet		Green	Not Suspect	N		N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Mastic, if present, may contain ACM
3rd Floor	316	Misc	Covebase Mastic		Beige	None Detected	N	VALB-8-m1.1-3.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	316	Ceiling	Plaster			None Detected	Y	VALB-8-c1.1-c2.3	N/A	N/A	N/A	N/A	N/A	TSI Elbows	N/A	N/A	
3rd Floor	316	Wall(s)	Plaster/Drywall		Off White	None Detected	N	VALB-8-w1.2-1.9	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	





[illegible]

[illegible]

Rm Name/No.	Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								NOTES
					Asbestos Present?	Previously Sampled (Y/N)	Contractor Sample No.	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	SignificantlyDamaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
3rd Floor	300E	Wall(s)														
3rd Floor	301 NA	Ceiling	NOT ACCESSIBLE													
3rd Floor	301 NA	Door/Door Frame														
3rd Floor	301 NA	Floor														
3rd Floor	301 NA	Wall(s)														
3rd Floor	302 NA	Floor	Ceramic Tile	2X2	White	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	302 NA	Ceiling	Hardlid Plaster		White	None Detected	N	VALB-W-1.7-1.9	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	302 NA	Wall(s)														
3rd Floor	309 and 309 North	Ceiling	Acoustic Ceiling Tile Both	2X4	White	None Detected	Y	VALB-8-c1.1-c2.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	309 and 309 North	Floor	Carpet		Green	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Mastic, if present, may contain ACM
3rd Floor	309 and 309 North	Misc	Covebase Mastic	6"	Beige	None Detected	N	VALB-8-m1.1-3.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	309 and 309 North	Wall(s)	Plaster/Drywall		Tan/Beige	None Detected	N	VALB-8-w1.2-1.9	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	309 and 309 North	Misc	Wallboard with Joint Compound (309 North)		White	None Detected	Y		N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	309 and 309 North	Misc	Window 1x		Tan	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	309 and 309 North	Door/Door Frame	Wood/Metal		Off White/Off White	Not suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Core may contain ACM
3rd Floor	321 NA	Door/Door Frame	NOT ACCESSIBLE													
3rd Floor	321 NA	Ceiling														
3rd Floor	321 NA	Floor														
3rd Floor	321 NA	Wall(s)														
3rd Floor	c*-3B3	Ceiling	Acoustic Ceiling Tile Both	2X4	White	None Detected	Y	VALB-8-c1.1-c2.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	c*-3B3	Floor	Carpet with Terazzo Under		Green	Not Suspect	N		N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	c*-3B3	Misc	Covebase Mastic		Beige	None Detected	N	VALB-8-m1.1-3.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	c*-3B3	Wall(s)	Plaster/Drywall		Green/Off White	None Detected	N	VALB-8-w1.2-1.9	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	c*-3B3	Door/Door Frame	Wood/Metal		Off White/Off White	Not suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Core may contain ACM
3rd Floor	c8-3A1	Ceiling	Acoustic Ceiling Tile	2X4	White	None Detected	N	VALB-8-c1.1-c2.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	c8-3A1	Misc	Covebase Mastic/Terazzo	4"	Beige/Green	None Detected	N	VALB-8-m1.1-3.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	c8-3A1	Door/Door Frame	Frame		Off White	Not suspect	N		N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	c8-3A1	Misc	Joint Compound			2%Chrysotile	N	VALB-8--w1.1	N/A	N/A	N/A	N/A	N/A	N/A	Yes	
3rd Floor	c8-3A1	Wall(s)	Plaster		Off White/Green	None Detected	N	VALB-8-w1.7-1.9	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	c8-3A1	Floor	Resilient Floor Tile	9X9/12X12	White with Pink Streaks/Mauve	3-5% Chrysotile	N	VALB-8-f3.1	Non Friable	N/A	N/A	N/A	N/A	N/A	Yes	ACM is in the mastic & 9"
3rd Floor	c8-3A1	Misc	Wallboard		Brown	None Noted	N		N/A	N/A	NN	N/A	N/A	N/A	N/A	
3rd Floor	C8-3A2	Ceiling	Acoustic Ceiling Tile	2X4	White	None Detected	N	VALB-8-c1.1-c2.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	C8-3A2	Misc	Covebase Mastic/Terazzo	4"	Beige/Green	None Detected	N	VALB-8-m1.1-3.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	C8-3A2	Door/Door Frame	Frame		Off White	Not suspect	N		N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	C8-3A2	Misc	Joint Compound		White	None Detected	N	VALB-8--w1.2-1.6	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	C8-3A2	Wall(s)	Plaster		Off White/Green	None Detected	N	VALB-8-w1.7-1.9	N/A	N/A	N/A	N/A	N/A	N/A	B/A	
3rd Floor	C8-3A2	Floor	Resilient Floor Tile	9X9/12X12	White with Pink Streaks/Mauve	3-5% Chrysotile	N	VALB-8-f3.1	Non Friable	N/A	N/A	N/A	N/A	N/A	Yes	ACM is in the mastic & 9"
3rd Floor	C8-3A2	Misc	Walboard		Brown	None Noted	N		N/A	N/A	NN	N/A	N/A	N/A	N/A	
3rd Floor	c8-3B2	Ceiling	Acoustic Ceiling Tile Both	2X4	White	None Detected	Y	VALB-8-c1.1-c2.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	c8-3B2	Floor	Carpet with Terazzo Under		Green	Not Suspect	N		N/A	N/A	N/A	N/A	N/A	NA	N/A	
3rd Floor	c8-3B2	Misc	Covebase Mastic		Beige	None Detected	N	VALB-8-m1.1-3.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	c8-3B2	Wall(s)	Plaster/Drywall		Green & Off White	None Detected	N	VALB-8-w1.2-1.9	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	c8-3B2	Door/Door Frame	Wood/Metal		Off White/Off White	Not suspect	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Core may contain ACM
3rd Floor	RR 317A Mens	Ceiling	Acoustic Ceiling Tile Pinworm	2X4	White	None Detected	Y	VALB-8-c1.1-c2.3	N/A	N/A	N/A	N/A	NN	N/A	N/A	
3rd Floor	RR 317A Mens	Misc	Covebase Mastic		Beige	None Detected	N	VALB-8-m1.1-3.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	RR 317A Mens	Wall(s)	Drywall		Off White	Non Detected	N	VALB-8-w1.2-1.6	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
3rd Floor	RR 317A Mens	Floor	Resilient Floor Tile	12X12	Gray with Gray Spots	Not Suspect	N		N/A	N/A	N/A	NA	N/A	N/A	N/A	

[illegible]



[illegible]

Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								NOTES
						Asbestos Present?	Previously Sampled (Y/N)	Contractor Sample No.	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	SignificantlyDamaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
Roof	Main Roof - North East	Misc	Flashing Mastic		Black	Non Detected	N	VALB-8-r1.1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Roof	Main Roof - North West	Misc	Flashing Mastic		black	4% Chrysotile	N	VALB-8-r1.2	Non Friable	N/A	NO	NO	Yes	N/A	N/A	Yes	
Roof	Corridor Roof - North West	Roof	Flashing Mastic		Black	None Detected	N	VALB-8-r1.3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Roof	Corridor Roof - South Center	Roof	Flashing Mastic		Silver/Black	3% Chrysotile	N	VALB-8-r2.1	Non Friable	N/A	NO	NO	Yes	N/A	N/A	Yes	
Roof	Kickout Roof - South	Roof	Flashing Mastic		Silver/Black	3% Chrysotile	N	VALB-8-r2.2	Non Friable	N/A	NO	NO	Yes	N/A	N/A	Yes	
Roof	Corridor Roof - North East	Roof	Flashing Mastic		Silver/Black	2% Chrysotile	N	VALB-8-r2.3	Non Friable	N/A	NO	NO	Yes	N/A	N/A	Yes	
Roof	Main Roof-South, North & East Center	Roof	Flashing Caulk		Gray/White	None Detected	N	VALB-8-r3.1-3.3	N/A	N/A	NO	NO	Yes	N/A	N/A	Yes	
Roof	Main Roof-West & East	Roof	Flashing Core		Gray	3-6% Chrysotile	N	VALB-8-r3.1-3.3	N/A	N/A	NO	NO	Yes	N/A	N/A	Yes	
Roof	Main Roof-Northeast	Misc	Roof Core		Gray	6-8% Chrysotile	N	VALB-8-r5.1-5.3	N/A	N/A	NO	NO	Yes	N/A	N/A	Yes	