

[illegible]

Current Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
					Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	HA #	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	SignificantlyDam aged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
13	Childcare	Ceiling	Wall Board		N	N	Y	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
		Wall(s)	Wallboard with Joint Compound	Black	N	N	Y	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
		Floor	Resilient Floor Sheetting	Black	N	N	Y	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
		Door/Door Frame	Metal and Metal	Black and Black	Not Suspect	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
		Misc	Cove Base with Mastic	6"	Black	N	Y	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
		Misc														
14	Childcare	Ceiling	Acoustic Ceiling Tile Pinhole	2x4	N	N	Y	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
		Wall(s)	Wallboard with Joint Compound	Black	N	N	Y	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
		Floor	Resilient Floor Sheetting	Black	N	N	Y	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
		Door/Door Frame	Wood and Metal	White and Black	Not Suspect	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
		Misc	Cove Base with Mastic	6"	Black	N	Y	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
		Misc														
15	Childcare	Ceiling	Acoustic Ceiling Tile Pinhole	2x4	N	N	Y	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
		Wall(s)	Wallboard with Joint Compound	Black	N	N	Y	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
		Floor	Resilient Floor Sheetting	Black	N	N	Y	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
		Door/Door Frame	Wood and Metal	White and Black	Not Suspect	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
		Misc	Cove Base with Mastic	6"	Black	N	Y	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
		Misc														
EXT.	Childcare	Ceiling	Corragated Metal		Not suspect	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
		Wall(s)	Stucco	Black	N	N	Y	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
		Floor	Concrete	Bare	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
		Door/Door Frame	Glass and Metal	Clear and Silver	Not suspect	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
		Misc	Seam Caulking (on Concrete)	Gray	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
		Misc	Seam Caulking (on Windows)	Black	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
		Misc	Penetration Mastic	Black	Y (8%)	N	Y	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
		Roof 1	Rolled Roofing	Grey	N	N	Y	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Mechanical Systems		Ceiling														
		Wall(s)														
		Floor														
		Door/Door Frame														
		Pipe Insulation	HVAC Seal	White	N	N	Y	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
		Pipe Insulation	HVAC Seal	Black	N	N	Y	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
		Misc														
115	aring Storage	Ceiling	Wood	Bare	Not Suspect	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
		Wall(s)	Stucco	Grey	Not Suspect	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
		Floor	Resilient Floor Sheetting	Blue/White	N	N	Y	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
		Floor	Concrete	Bare	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
		Door/Door Frame	Metal /Metal Roll up	Beige/Beige	Not Suspect	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

