

Curent Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
1st Floor	108A	Ceiling	Acoustic Ceiling Tile	2x4	White	Not Detected	N/A	Y	N/A	N/A							
1st Floor	108A	Wall(s)	Drywall		White	Not Detected	N/A	Y	N/A	N/A							
1st Floor	108A	Floor	Resilient Floor Tile with Mastic	12x12	Blue	Not Detected	N/A	Y	N/A	N/A							
1st Floor	108A	Door/Door Frame	Metal/Metal			Not Suspect	N/A	Y	N/A	N/A							Possible suspect material in core
1st Floor	108A	Misc	Cove Base with Mastic	4"	Tan	Not Detected	N/A	Y	N/A	N/A							
1st Floor	108B	Ceiling	Acoustic Ceiling Tile	2x4	White	Not Detected	VALB-50-W1.1 -	Y	N/A	N/A							
1st Floor	108B	Wall(s)	Drywall	-	White	Not Detected	N/A	Y	N/A	N/A							
1st Floor	108B	Floor	Carpet/Glue	-	Blue & Yellow	Not Detected	N/A	Y	N/A	N/A							Possible ACM flooring underneath
1st Floor	108B	Door/Door Frame	Metal/Metal	-	Beige	Not Suspect	N/A	Y	N/A	N/A							Possible suspect material in core
1st Floor	108B	Misc	Cove Base & Mastic	4"	Tan	Not Detected	N/A	Y	N/A	N/A							
1st Floor	108B	Misc	Window 1x Metal	-		Not Suspect	N/A		N/A	N/A							
1st Floor	108C	Ceiling	Acoustic Ceiling Tile	2x4	White	Not Detected	VALB-50-W1.1 -	Y	N/A	N/A							
1st Floor	108C	Wall(s)	Drywall		Beige	Not Detected	N/A	Y	N/A	N/A							
1st Floor	108C	Floor	Carpet/Glue		Blue	Not Detected	N/A	Y	N/A	N/A							Possible ACM flooring underneath
1st Floor	108C	Door/Door Frame	Metal/Metal		Beige	Not Suspect	N/A		N/A	N/A							Possible suspect material in core
1st Floor	108C	Misc	Cove Base & Mastic	4"	Beige	Not Detected	N/A	Y	N/A	N/A							
1st Floor	108L	Ceiling	Acoustic Ceiling Tile	2x4	White	Not Detected	VALB-50-W1.1 -	Y	N/A	N/A							
1st Floor	108L	Wall(s)	Drywall		Beige	Not Detected	N/A	Y	N/A	N/A							
1st Floor	108L	Floor	Resilient Floor Tile & Mastic	12x12	Blue	Not Detected	N/A	Y	N/A	N/A							
1st Floor	108L	Door/Door Frame	Metal/Metal 2x		Beige	Not Suspect	N/A		N/A	N/A							Possible suspect material in core
1st Floor	108L	Misc	Cove Base & Mastic	4"	Beige	Not Detected	N/A	Y	N/A	N/A							
1st Floor	108K	Ceiling	Insulation			Yes	N/A	Y	N/A	N/A	N	N	Y	Y			
1st Floor	108K	Wall(s)	Drywall		White	Not Detected	N/A	Y	N/A	N/A							
1st Floor	108K	Floor	Concrete			Not Suspect	N/A		N/A	N/A							
1st Floor	108K	Door/Door Frame	Metal/Metal Double		Beige	Not Suspect	N/A		N/A	N/A							Possible suspect material in core
1st Floor	108D	Ceiling	Insulation			Yes	N/A	Y	N/A	N/A	N	N	Y	Y			
1st Floor	108D	Wall(s)	Drywall		White	Not Detected	N/A	Y	N/A	N/A							
1st Floor	108D	Floor	Bare				N/A		N/A	N/A							
1st Floor	108D	Door/Door Frame	Metal/Metal		Beige	Not Suspect	N/A		N/A	N/A							Possible suspect material in core
1st Floor	108D	Misc	Window 1x Metal			Not Suspect	N/A		N/A	N/A							
1st Floor	108D	Misc	Sink				N/A		N/A	N/A							
1st Floor	108E	Ceiling	Insulation			Yes	N/A	Y	N/A	N/A	N	N	Y	Y			
1st Floor	108E	Wall(s)	Drywall		White	Not Detected	N/A	Y	N/A	N/A							
1st Floor	108E	Floor	Concrete			Not Suspect	N/A		N/A	N/A							
1st Floor	108E	Door/Door Frame	Metal/Metal		Blue/White	Not Suspect	N/A		N/A	N/A							Possible suspect material in core
1st Floor	108F	Ceiling	N/A				N/A		N/A	N/A							
1st Floor	108F	Wall(s)	Concrete			Not Suspect	N/A		N/A	N/A							
1st Floor	108F	Floor	Concrete			Not Suspect	N/A		N/A	N/A							
1st Floor	108F	Door/Door Frame	Metal/Metal		Beige	Not Suspect	N/A		N/A	N/A							Possible suspect material in core
1st Floor	108F	Misc	Cove Base & Mastic	8"	Black	Not Detected	N/A	Y	N/A	N/A							
1st Floor	108G	Ceiling	Drywall		White	Not Detected	N/A	Y	N/A	N/A							
1st Floor	108G	Wall(s)	Drywall / Ceramic Tile with Grout	4x4	White/Beige/Beige	Not Detected	N/A	Y	N/A	N/A							
1st Floor	108G	Floor	Ceramic Tile with Grout	2x2	Blue/Black		N/A		N/A	N/A							
1st Floor	108G	Door/Door Frame	Metal/Metal		Beige	Not Suspect	N/A		N/A	N/A							Possible suspect material in core
1st Floor	108G	Misc	Sink				N/A		N/A	N/A							
1st Floor	108J	Ceiling	Acoustic Ceiling Tile	2x4	White	Not Detected	VALB-50-W1.1 -	Y	N/A	N/A							
1st Floor	108J	Wall(s)	Drywall		White	Not Detected	N/A	Y	N/A	N/A							
1st Floor	108J	Floor	Resilient Floor Tile & Mastic	12x12	Blue	Not Detected	N/A	Y	N/A	N/A							
1st Floor	108J	Door/Door Frame	Metal/Metal		Beige	Not Suspect	N/A		N/A	N/A							Possible suspect material in core
1st Floor	108J	Misc	Cove Base & Mastic	4"	Tan	Not Detected	N/A	Y	N/A	N/A							
1st Floor	108H	Ceiling	Drywall		White	Not Detected	N/A	Y	N/A	N/A							
1st Floor	108H	Wall(s)	Drywall /Ceramic Tile with Grout	4x4	White/Beige/Beige	Not Detected	N/A	Y	N/A	N/A							
1st Floor	108H	Floor	Ceramic Tile with Grout	2x2	Blue/Black		N/A		N/A	N/A							
1st Floor	108H	Door/Door Frame	Metal/Metal		Beige	Not Suspect	N/A		N/A	N/A							Possible suspect material in core
1st Floor	108H	Misc	Sink				N/A		N/A	N/A							
1st Floor	108H	Misc	Window 1x Metal			Not Suspect	N/A		N/A	N/A							

Curent Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	SignificantlyDamaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
1st Floor	101A Closet No Access	Ceiling	Exposed Insulation			Yes	N/A	Y	N/A	N/A	N	N	Y	Y			
1st Floor	101A Closet No Access	Wall(s)	N/A Wallboard & Joint Compound		White	Not Detected	N/A	Y	N/A	N/A							
1st Floor	101A Closet No Access	Floor	Resilient Floor Tile & Mastic & Glue	12x12	Blue/Yellow	Not Detected	N/A	Y	N/A	N/A							
1st Floor	101A Closet No Access	Door/Door Frame	Wood/Metal		Blue/White	Not Suspect	N/A		N/A	N/A							Possible suspect material in core

Curent Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT							Comment	
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing		Misc
1st Floor	101 Main	Ceiling	Acoustic Ceiling Tile	2x4	White	Not Detected	VALB-50-W1.1 -	Y	N/A	N/A							
1st Floor	101 Main	Wall(s)	Drywall		White	Not Detected	N/A	Y	N/A	N/A							
1st Floor	101 Main	Floor	Resilient Floor Tile & Mastic	12x12	Blue	Y	N/A	Y	N/A	N/A							
1st Floor	101 Main	Door/Door Frame	Metal/Metal		Tan	Not Suspect	N/A		N/A	N/A							Possible suspect material in core
1st Floor	101 Main	Misc	Cove Base & Mastic	4"	Tan	Not Detected	N/A	Y	N/A	N/A							
1st Floor	101 Main	Misc	Window 2x Metal			Not Suspect	N/A		N/A	N/A							
1st Floor	101 A	Ceiling	Acoustic Ceiling Tile	2x4	White	Not Detected	VALB-50-W1.1 -	Y	N/A	N/A			N/A	N			
1st Floor	101 A	Wall(s)	Wood Panels			Not Suspect	N/A	N	N/A	N/A			N/A	N			
1st Floor	101 A	Floor	Carpet & Mastic		Blue	Not Detected	N/A	Y	N/A	N/A			N/A	N			Possible ACM flooring underneath
1st Floor	101 A	Door/Door Frame	Metal/Metal		Blue/White	Not Suspect	N/A	N	N/A	N/A			N/A	N			Possible suspect material in core
1st Floor	101 A	Misc	5x Windows/Bare		Wood		N/A	N	N/A	N/A			N/A	N			
1st Floor	101B No Access	Ceiling	Acoustic Ceiling Tile	2x4	White	Not Detected	VALB-50-W1.1 -	Y	N/A	N/A							
1st Floor	101B No Access	Wall(s)	Drywall/Wood Panels		Beige/White	Not Detected	N/A	Y	N/A	N/A							
1st Floor	101B No Access	Floor	Resilient Floor Tile & Mastic	12x12	White withBlack	Not Detected	N/A	Y	N/A	N/A							
1st Floor	101B No Access	Door/Door Frame	Wood/Metal		White	Not Suspect	N/A		N/A	N/A							Possible suspect material in core
1st Floor	101B No Access	Misc	Cove Base & Mastic	4"	Gray	Not Detected	N/A	Y	N/A	N/A							
1st Floor	101B No Access	Misc	TSI/F Removed		Yes	N/A	N/A	Y	N/A	N/A	N	N	Y	Y			
1st Floor	101 Helpdesk	Ceiling	Acoustic Ceiling Tile	2x4	White	Not Detected	VALB-50-W1.1 -	Y	N/A	N/A							
1st Floor	101 Helpdesk	Wall(s)	Drywall		White	Not Detected	N/A	Y	N/A	N/A							
1st Floor	101 Helpdesk	Floor	Carpet Mastic		Blue	Not Detected	N/A	Y	N/A	N/A							Possible ACM flooring underneath
1st Floor	101 Helpdesk	Door/Door Frame	Metal/Metal		Gray/Gray	Not Suspect	N/A		N/A	N/A							Possible suspect material in core
1st Floor	101 Helpdesk	Misc	Cove Base & Mastic	4"	Tan	Not Detected	N/A	Y	N/A	N/A							
1st Floor	102	Ceiling	Acoustic Ceiling Tile	2x4	White	Not Detected	VALB-50-W1.1 -	Y	N/A	N/A							
1st Floor	102	Wall(s)	Drywall		White	Not Detected	N/A	Y	N/A	N/A							
1st Floor	102	Floor	Carpet and Mastic		Blue	Not Detected	N/A	Y	N/A	N/A							
1st Floor	102	Door/Door Frame	Wood/Metal		White	Not Suspect	N/A		N/A	N/A							Possible suspect material in core
1st Floor	102	Misc	Cove Base & Mastic	4"	Tan	Not Detected	N/A	Y	N/A	N/A							
1st Floor	102	Misc	Windows 4x				N/A		N/A	N/A							
1st Floor	113 101 Storage	Ceiling	Bare Insulation			Yes	N/A	Y	N/A	N/A	N	N	Y	Y			
1st Floor	113 101 Storage	Wall(s)	Drywall		White	Not Detected	N/A	Y	N/A	N/A							
1st Floor	113 101 Storage	Floor	Concrete			Not Suspect	N/A		N/A	N/A							
1st Floor	113 101 Storage	Door/Door Frame	Metal/Metal		Blue/White	Not Suspect	N/A		N/A	N/A							Possible suspect material in core
1st Floor	103	Ceiling	Acoustic Ceiling Tile	2x4	White	Not Detected	VALB-50-W1.1 -	Y	N/A	N/A							
1st Floor	103	Wall(s)	Plaster / Drywall		Beige/Gold	Not Detected	N/A	Y	N/A	N/A							
1st Floor	103	Floor	Resilient Floor Tile & Mastic	12x12		Not Detected	N/A	Y	N/A	N/A							
1st Floor	103	Door/Door Frame	Metal/Metal		Beige	Not Suspect	N/A		N/A	N/A							Possible suspect material in core
1st Floor	103	Misc	Cove Base & Mastic	4"	Beige	Not Detected	N/A	Y	N/A	N/A							
1st Floor	104 RR	Ceiling	Wallboard		White	Not Detected	N/A	Y	N/A	N/A							
1st Floor	104 RR	Wall(s)	Drywall		Beige	Not Detected	N/A	Y	N/A	N/A							
1st Floor	104 RR	Floor	Resilient Floor Tile & Mastic	12x12		Not Detected	N/A	Y	N/A	N/A							
1st Floor	104 RR	Door/Door Frame	Wood/Metal		Beige	Not Suspect	N/A		N/A	N/A							Possible suspect material in core
1st Floor	104 RR	Misc	Cove Base & Mastic	4"	Beige	Not Detected	N/A	Y	N/A	N/A							
1st Floor	104 RR	Misc	Window 1x Wood Frame		Beige		N/A		N/A	N/A							
1st Floor	104 RR	Misc	Sink 1x				N/A		N/A	N/A							
1st Floor	105	Ceiling	Acoustic Ceiling Tile	2x4	White	Not Detected	VALB-50-W1.1 -	Y	N/A	N/A							
1st Floor	105	Wall(s)	Drywall		Beige/Gold	Not Detected	N/A	Y	N/A	N/A							
1st Floor	105	Floor	Resilient Floor Tile & Mastic	12x12		Not Detected	N/A	Y	N/A	N/A							
1st Floor	105	Door/Door Frame	Wood/Metal		Beige	Not Suspect	N/A		N/A	N/A							Possible suspect material in core
1st Floor	105	Misc	Cove Base & Mastic	4"	Beige	Not Detected	N/A	Y	N/A	N/A							
1st Floor	105	Misc	Sink 1x				N/A		N/A	N/A							
1st Floor	107 RR Sink Pipe	Ceiling	Wallboard		Beige	Not Detected	N/A	Y	N/A	N/A							
1st Floor	107 RR Sink Pipe	Wall(s)	Drywall		Beige	Not Detected	N/A	Y	N/A	N/A							
1st Floor	107 RR Sink Pipe	Floor	Resilient Floor Tile & Mastic		Tan	Not Detected	N/A	Y	N/A	N/A							
1st Floor	107 RR Sink Pipe	Door/Door Frame	Wood/Metal	12x12	Beige	Not Suspect	N/A	Y	N/A	N/A							Possible suspect material in core
1st Floor	107 RR Sink Pipe	Misc	Cove Base & Mastic/	4"	Beige	Not Detected	N/A	Y	N/A	N/A							

Curent Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT							Comment	
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	SignificantlyDamaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing		Misc
1st Floor	107 RR Sink Pipe	Misc	Windows 2x withwood frame		Beige		N/A		N/A	N/A							
1st Floor	107 RR Sink Pipe	Misc	sink 2x				N/A		N/A	N/A							
1st Floor	100D	Ceiling	Wallboard		Beige	Not Detected	N/A	Y	N/A	N/A							
1st Floor	100D	Wall(s)	Drywall		Beige	Not Detected	N/A	Y	N/A	N/A							
1st Floor	100D	Floor	Concrete			Not Suspect	N/A	N	N/A	N/A							
1st Floor	100D	Door/Door Frame	Wood/Metal		White/Beige	Not Suspect	N/A		N/A	N/A							Possible suspect material in core
1st Floor	100D	Misc	Sink 1x				N/A		N/A	N/A							
1st Floor	100C Closet	Ceiling	Drywall		White	Not Detected	N/A	Y	N/A	N/A							
1st Floor	100C Closet	Wall(s)	Drywall		White	Not Detected	N/A	Y	N/A	N/A							
1st Floor	100C Closet	Floor	Resilient Floor Tile & Mastic	12x12		Not Detected	N/A	Y	N/A	N/A							
1st Floor	100C Closet	Door/Door Frame	Wood/Metal		Beige	Not Suspect	N/A		N/A	N/A							Possible suspect material in core
1st Floor	100C Closet	Misc	Cove Base & Mastic	4"	Beige	Not Detected	N/A	Y	N/A	N/A							

Curent Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
1st Floor	100B Vault	Ceiling	Hard Wood		Green	Not Suspect	N/A		N/A	N/A							
1st Floor	100B Vault	Wall(s)	Concrete		Green	Not Suspect	N/A		N/A	N/A							
1st Floor	100B Vault	Floor	Resilient Floor Tile & Mastic	12x12	White withGreen & Brown Streaks	Not Detected	N/A	Y	N/A	N/A							
1st Floor	100B Vault	Door/Door Frame	Metal/Wood		Beige	Not Suspect	N/A		N/A	N/A							Possible suspect material in core
1st Floor	TEL	Ceiling	Acoustic Ceiling Tile	2x2	White	Not Detected	VALB-50-W1.1 -	Y	N/A	N/A			L				
1st Floor	TEL	Wall(s)	Drywall		Yellow	Not Detected	N/A	Y	N/A	N/A							
1st Floor	TEL	Floor	Resilient Floor Tile & Mastic /exposed mastic	9x9	Gray/Black	Y	N/A	Y	N/A	N/A			L				X
1st Floor	TEL	Door/Door Frame	Metal/Wood		Beige	Not Suspect	N/A		N/A	N/A							Possible suspect material in core
1st Floor	100E	Ceiling	Acoustic Ceiling Tile	2x2	White	Not Detected	VALB-50-W1.1 -	Y	N/A	N/A							
1st Floor	100E	Wall(s)	Drywall		Beige/Green	Not Detected	N/A	Y	N/A	N/A							
1st Floor	100E	Floor	Resilient Floor Tile & Mastic	12x12		Not Detected	N/A	Y	N/A	N/A							
1st Floor	100E	Door/Door Frame	Cove Base & Mastic/	4"	White	Not Suspect	N/A	Y	N/A	N/A							Possible suspect material in core
1st Floor	100E	Misc	Window 2x Metal		Beige	Not Suspect	N/A		N/A	N/A							
1st Floor	100E	Misc	Window 2x				N/A		N/A	N/A							
1st Floor	100 withReception	Ceiling	Acoustic Ceiling Tile	2x4	White	Not Detected	VALB-50-W1.1 -	Y	N/A	N/A							
1st Floor	100 withReception	Wall(s)	Drywall		Beige	Not Detected	N/A	Y	N/A	N/A							
1st Floor	100 withReception	Floor	Resilient Floor Tile & Mastic & Carpet (Reception)	12x12	Tan/Brown	Not Detected	N/A	Y	N/A	N/A							Possible ACM flooring underneath
1st Floor	100 withReception	Door/Door Frame	Wood/Metal		Beige	Not Suspect	N/A		N/A	N/A							Possible suspect material in core
1st Floor	100 withReception	Misc	Cove Base & Mastic	4"	Beige	Not Detected	N/A	Y	N/A	N/A							
1st Floor	100 withReception	Misc	Windows 1x				N/A		N/A	N/A							
1st Floor	100F	Ceiling	Acoustic Ceiling Tile	2x4	White	Not Detected	VALB-50-W1.1 -	Y	N/A	N/A							
1st Floor	100F	Wall(s)	Drywall		Beige/Green	Not Detected	N/A	Y	N/A	N/A							
1st Floor	100F	Floor	Carpet no Resilient Floor Tile & Mastic under glue		Brown/Yellow	Not Detected	N/A	Y	N/A	N/A							
1st Floor	100F	Door/Door Frame	Wood/Metal		Beige	Not Suspect	N/A		N/A	N/A							Possible suspect material in core
1st Floor	100F	Misc	Cove Base & Mastic	4"	Beige	Not Detected	N/A	Y	N/A	N/A							
1st Floor	100F	Misc	Window 1x				N/A		N/A	N/A							
1st Floor	100G	Ceiling	Acoustic Ceiling Tile	2x4	White	Not Detected	VALB-50-W1.1 -	Y	N/A	N/A							
1st Floor	100G	Wall(s)	Drywall		Beige	Not Detected	N/A	Y	N/A	N/A							
1st Floor	100G	Floor	Carpet Glue		Brown/Yellow	Not Detected	N/A	Y	N/A	N/A							Possible ACM flooring underneath
1st Floor	100G	Door/Door Frame	Wood/Metal		Beige	Not Suspect	N/A		N/A	N/A							Possible suspect material in core
1st Floor	100G	Misc	Cove Base & Mastic	4"	Beige	Not Detected	N/A	Y	N/A	N/A							
1st Floor	100G	Misc	Windows 2x				N/A		N/A	N/A							
1st Floor	100H	Ceiling	Acoustic Ceiling Tile	2x4	White	Not Detected	VALB-50-W1.1 -	Y	N/A	N/A							
1st Floor	100H	Wall(s)	Drywall		Tan	Not Detected	N/A	Y	N/A	N/A							
1st Floor	100H	Floor	Carpet		Brown/YellowwithBlk	Not Detected	N/A	Y	N/A	N/A							
1st Floor	100H	Door/Door Frame	Wood/Metal		Beige	Not Suspect	N/A		N/A	N/A							Possible suspect material in core
1st Floor	100H	Misc	Cove Base & Mastic	4"	Beige		N/A	Y	N/A	N/A					F		
1st Floor	100H	Misc	Window 2x		White Frame		N/A		N/A	N/A							
1st Floor	100I	Ceiling	Acoustic Ceiling Tile	2x4	White	Not Detected	VALB-50-W1.1 -	Y	N/A	N/A							
1st Floor	100I	Wall(s)	Drywall		Tan	Not Detected	N/A	Y	N/A	N/A							
1st Floor	100I	Floor	Carpet Glue & Mastic		Brwn/YellowwithBrwn	Not Detected	N/A	Y	N/A	N/A							
1st Floor	100I	Door/Door Frame	Wood/Metal		Metal	Not Suspect	N/A		N/A	N/A					F		Possible suspect material in core
1st Floor	100I	Misc	Cove Base & Mastic	6"	Beige	Not Detected	N/A	Y	N/A	N/A							
1st Floor	100I	Misc	Window 2x Wood all		White		N/A		N/A	N/A							
1st Floor	109B	Ceiling	Acoustic Ceiling Tile	2x4	White	Not Detected	VALB-50-W1.1 -	Y	N/A	N/A							
1st Floor	109B	Wall(s)	Wallboard with Joint Compound		White	Not Detected	N/A	Y	N/A	N/A							
1st Floor	109B	Floor	Carpet & Glue		Blue/Yellow	Not Detected	N/A	Y	N/A	N/A							Possible ACM flooring underneath
1st Floor	109B	Door/Door Frame	Metal/Wood		White/Beige	Not Suspect	N/A		N/A	N/A							Possible suspect material in core
1st Floor	109B	Misc	Cove Base & Mastic & Glue		Tan/Off White	Not Detected	N/A	Y	N/A	N/A							
1st Floor	109B	Misc	No Access TSI			Yes	N/A	Y	N/A	N/A	N	N	Y	Y	N		
1st Floor	109	Ceiling	Acoustic Ceiling Tile	2x4	White	Not Detected	VALB-50-W1.1 -	Y	N/A	N/A							

Curent Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	SignificantlyDamaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
1st Floor	109	Wall(s)	Wallboard with Joint Compound		White	Not Detected	N/A	Y	N/A	N/A							
1st Floor	109	Floor	Carpet & Glue		Blue/Yellow	Not Detected	N/A	Y	N/A	N/A							Possible ACM flooring underneath
1st Floor	109	Door/Door Frame	Metal/Wood		White/Blue	Not Suspect	N/A		N/A	N/A							Possible suspect material in core
1st Floor	109	Misc	Cove Base & Mastic & Glue		Tan/ Off White	Not Detected	N/A	Y	N/A	N/A							
1st Floor	109	Misc	No Access TSI			Yes	N/A	Y	N/A	N/A	N	N	Y	Y	N		
1st Floor	109A	Ceiling	Acoustic Ceiling Tile	2x4	White	Not Detected	VALB-50-W1.1 -	Y	N/A	N/A							
1st Floor	109A	Wall(s)	Wallboard with Joint Compound		White	Not Detected	N/A	Y	N/A	N/A							
1st Floor	109A	Floor	Carpet & Glue		Blue/Yellow	Not Detected	N/A	Y	N/A	N/A							Possible ACM flooring underneath
1st Floor	109A	Door/Door Frame	Metal/Wood		White/Blue	Not Suspect	N/A		N/A	N/A							Possible suspect material in core
1st Floor	109A	Misc	Cove Base & Mastic & Glue		Tan/Off White	Not Detected	N/A	Y	N/A	N/A							
1st Floor	109A	Misc	No Access TSI			Yes	N/A	Y	N/A	N/A	N	N	Y	Y	N		

Curent Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
1st Floor	Vest 115 108	Ceiling	Acoustic Ceiling Tile	2x4	White	Not Detected	VALB-50-W1.1 -	Y	N/A	N/A							
1st Floor	Vest 115 108	Wall(s)	Plaster /Drywall		Green/Beige	Not Detected	N/A	Y	N/A	N/A							
1st Floor	Vest 115 108	Floor	Resilient Floor Tile & Mastic	12x12	Blue	Not Detected	N/A	Y	N/A	N/A							
1st Floor	Vest 115 108	Door/Door Frame	Metal/Metal		Beige	Not Suspect	N/A		N/A	N/A							Possible suspect material in core
1st Floor	Vest 115 108	Misc	Cove Base & Mastic	4"	Beige	Not Detected	N/A	Y	N/A	N/A							
1st Floor	#4 115 P	Ceiling	Acoustic Ceiling Tile	2x4	White	Not Detected	VALB-50-W1.1 -	Y	N/A	N/A							
1st Floor	#4 115 P	Wall(s)	Plaster /Drywall		Green/Beige	Not Detected	N/A	Y	N/A	N/A							
1st Floor	#4 115 P	Floor	Resilient Floor Tile & Mastic	12x12	Blue	Not Detected	N/A	Y	N/A	N/A							
1st Floor	#4 115 P	Door/Door Frame	Metal/Metal		Beige	Not Suspect	N/A		N/A	N/A							Possible suspect material in core
1st Floor	#4 115 P	Misc	Cove Base & Mastic	4"	Beige	Not Detected	N/A	Y	N/A	N/A							
1st Floor	#3 115 O	Ceiling	Acoustic Ceiling Tile	2x4	White	Not Detected	VALB-50-W1.1 -	Y	N/A	N/A							
1st Floor	#3 115 O	Wall(s)	Plaster /Drywall		Green/Beige	Not Detected	N/A	Y	N/A	N/A							
1st Floor	#3 115 O	Floor	Resilient Floor Tile & Mastic	12x12	Blue	Not Detected	N/A	Y	N/A	N/A							
1st Floor	#3 115 O	Door/Door Frame	Metal/Metal		Beige	Not Suspect	N/A		N/A	N/A							Possible suspect material in core
1st Floor	#3 115 O	Misc	Cove Base & Mastic	4"	Beige	Not Detected	N/A	Y	N/A	N/A							
1st Floor	#2 115 N	Ceiling	Acoustic Ceiling Tile	2x4	White	Not Detected	VALB-50-W1.1 -	Y	N/A	N/A							
1st Floor	#2 115 N	Wall(s)	Plaster /Drywall		Green/Beige	Not Detected	N/A	Y	N/A	N/A							
1st Floor	#2 115 N	Floor	Resilient Floor Tile & Mastic	12x12	Blue	Not Detected	N/A	Y	N/A	N/A							
1st Floor	#2 115 N	Door/Door Frame	Metal/Metal		Beige	Not Suspect	N/A		N/A	N/A							Possible suspect material in core
1st Floor	#2 115 N	Misc	Cove Base & Mastic	4"	Beige	Not Detected	N/A	Y	N/A	N/A							
1st Floor	#1 115 M	Ceiling	Acoustic Ceiling Tile	2x4	White	Not Detected	VALB-50-W1.1 -	Y	N/A	N/A							
1st Floor	#1 115 M	Wall(s)	Plaster /Drywall		Green/Beige	Not Detected	N/A	Y	N/A	N/A							
1st Floor	#1 115 M	Floor	Resilient Floor Tile & Mastic	12x12	Blue	Not Detected	N/A	Y	N/A	N/A							
1st Floor	#1 115 M	Door/Door Frame	Metal/Metal		Beige	Not Suspect	N/A		N/A	N/A							Possible suspect material in core
1st Floor	#1 115 M	Misc	Cove Base & Mastic	4"	Beige	Not Detected	N/A	Y	N/A	N/A							
1st Floor	#1 115 M	Wall(s)	Stucco		Yellow	Not Detected	N/A	Y	N/A	N/A							
1st Floor	102 A Freds Office	Ceiling	Acoustic Ceiling Tile	2x4	White	Not Detected	VALB-50-W1.1 - W1.3	Y	N/A	N/A							
1st Floor	102 A Freds Office	Wall(s)	Drywall & Wood Panel		White	Not Detected	N/A	Y	N/A	N/A							
1st Floor	102 A Freds Office	Floor	Carpet & Mastic & Glue		Blue/Yellow w/Blk	Not Detected	N/A	Y	N/A	N/A							Possible ACM flooring underneath
1st Floor	102 A Freds Office	Door/Door Frame	Metal/Wood		White/Blue	Not Suspect	N/A		N/A	N/A							Possible suspect material in core
1st Floor	102 A Freds Office	Misc	Windows 3x				N/A		N/A	N/A							
Exterior		Wall(s)	Stucco		Tan	Not Detected	N/A	Y	N/A	N/A							
Exterior		Wall(s)	Vapor Barrier		Black/Tan	Not Detected	N/A	Y	N/A	N/A							
Exterior		Roof	Roof Mastic		Black	Not Detected	N/A	Y	N/A	N/A							
Exterior		Roof	Rolled Roof		Gray	Not Detected	N/A	Y	N/A	N/A							
Exterior		Roof	Roof Felt		Black	Not Detected	N/A	Y	N/A	N/A							