

Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
Basement	OP41	Ceiling	Acoustic Ceiling Panel	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP41	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP41	Floor	Carpet & Glue		Tan & Yell/Black	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP41	Door/Door Frame	Wood/Metal		Beige & Beige	Not Suspect											Possible Suspect Material In Core
Basement	OP41	Misc	Covebase Mastic & Glue	4"	Tan & Beige & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP41	Misc	Resilient Floor Tile Under Carpet & Glue		Tan & Black	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP40	Ceiling	Acoustic Ceiling Panel	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP40	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP40	Floor	Carpet & Glue		Tan & Yell/Black	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP40	Door/Door Frame	Wood/Metal		Beige & Beige	Not Suspect											Possible Suspect Material In Core
Basement	OP40	Roof	Covebase Mastic & Glue	4"	Tan & Beige & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP40	Misc	Resilient Floor Tile Under Carpet & Glue		Tan & Black	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP18	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP18	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP18	Floor	Resilient Floor Tile	12X12	Beige/White/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP18	Door/Door Frame	Wood/Metal		Blue & Off White	Not Suspect											Possible Suspect Material In Core
Basement	OP18	Misc	Covebase Mastic	6"	Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP19	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP19	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP19	Floor	Resilient Floor Tile	12X12	Beige/White/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP19	Door/Door Frame	Wood/Metal		Blue & Off White	Not Suspect											Possible Suspect Material In Core
Basement	OP19	Misc	Covebase Mastic	6"	Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP20	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP20	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP20	Floor	Resilient Floor Tile	12X12	Beige/White/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP20	Door/Door Frame	Wood/Metal		Blue & Off White	Not Suspect											Possible Suspect Material In Core
Basement	OP20	Misc	Covebase Mastic	6"	Off White	Not Detected	N/A	Y	N/A	N/A	N/A						

Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
Basement	OP43	Ceiling	Acoustic Ceiling Panel	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP43	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP43	Floor	Carpet & Glue		Tan & Yell/Black	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP43	Door/Door Frame	Wood/Metal		Beige & Beige	Not Suspect											Possible Suspect Material In Core
Basement	OP43	Misc	Covebase Mastic & Glue	4"	Tan & Beige & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP43	Misc	Resilient Floor Tile Under Carpet & Glue		Tan & Black	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP45	Ceiling	Acoustic Ceiling Panel	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP45	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP45	Floor	Carpet & Glue		Tan & Yell/Black	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP45	Door/Door Frame	Wood/Metal		Beige & Beige	Not Suspect											Possible Suspect Material In Core
Basement	OP45	Misc	Covebase Mastic & Glue	4"	Tan & Beige & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP45	Misc	Resilient Floor Tile Under Carpet & Glue		Tan & Black	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP47	Ceiling	Acoustic Ceiling Panel	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP47	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP47	Floor	Carpet & Glue		Tan & Yell/Black	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP47	Door/Door Frame	Wood/Metal		Beige & Beige	Not Suspect											Possible Suspect Material In Core
Basement	OP47	Misc	Covebase Mastic & Glue	4"	Tan & Beige & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP47	Misc	Resilient Floor Tile Under Carpet & Glue		Tan & Black	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP46	Ceiling	Acoustic Ceiling Panel	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP46	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP46	Floor	Carpet & Glue		Tan & Yell/Black	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP46	Door/Door Frame	Wood/Metal		Beige & Beige	Not Suspect											Possible Suspect Material In Core
Basement	OP46	Misc	Covebase Mastic & Glue	4"	Tan & Beige & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP46	Misc	Resilient Floor Tile Under Carpet & Glue		Tan & Black	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP44	Ceiling	Acoustic Ceiling Panel	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP44	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP44	Floor	Carpet & Glue		Tan & Yell/Black	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP44	Door/Door Frame	Wood/Metal		Beige & Beige	Not Suspect											Possible Suspect Material In Core
Basement	OP44	Misc	Covebase Mastic & Glue	4"	Tan & Beige & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP44	Misc	Resilient Floor Tile Under Carpet & Glue		Tan & Black	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP18A	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP18A	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP18A	Floor	Resilient Floor Tile	12X12	Beige/White/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP18A	Door/Door Frame	Wood/Metal		Blue & Off White	Not Suspect											Possible Suspect Material In Core
Basement	OP18A	Misc	Covebase Mastic	6"	Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP42	Ceiling	Acoustic Ceiling Panel	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						

Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
Basement	OP42	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP42	Floor	Carpet & Glue		Tan & Yell/Black	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP42	Door/Door Frame	Wood/Metal		Beige & Beige	Not Suspect											Possible Suspect Material In Core
Basement	OP42	Misc	Covebase Mastic & Glue	4"	Tan & Beige & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP42	Misc	Resilient Floor Tile Under Carpet & Glue		Tan & Black	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP10	Ceiling	Acoustic Ceiling Panel Pinhole	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP10	Wall(s)	Wallboard Joint Compound		off White	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP10	Floor	Carpet		Blue	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP10	Door/Door Frame	Wood/Metal		Blue & Off White	Not Suspect											Possible Suspect Material In Core
Basement	OP10	Misc	Covebase Mastic	4"	Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP33	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP33	Wall(s)	Wallboard Joint Compound		Green & Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP33	Floor	Carpet		Purple & Blue	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP33	Door/Door Frame	Metal/Metal		Beige & Off White	Not Suspect											Possible Suspect Material In Core
Basement	OP33	Misc	Covebase Mastic	4"	Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP00	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP00	Wall(s)	Plaster		Yellow	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP00	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP00	Door/Door Frame	Metal/Metal		Beige & Silver	Not Suspect											Possible Suspect Material In Core
Basement	OP00	Misc	Covebase Mastic	4"	Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP00	Misc	Ceramic Tile & Grout	4X4	Off White & Off White	Not Suspect											
Basement	OP40A	Ceiling	Acoustic Ceiling Panel	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP40A	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP40A	Floor	Carpet & Glue		Tan & Yell/Black	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP40A	Door/Door Frame	Wood/Metal		Beige & Beige	Not Suspect											Possible Suspect Material In Core
Basement	OP40A	Misc	Covebase Mastic & Glue	4"	Tan & Beige & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP40A	Misc	Resilient Floor Tile Under Carpet & Glue		Tan & Black	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP-CIA	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2x4		Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP-CIA	Wall(s)	Plaster Wallboard oint Compound		Beige/Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP-CIA	Floor	Resilient Floor Tile	12X12	Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP-CIA	Misc	Ceramic Tile & Grout	4X4	White & Off White	Not Suspect											
Basement	OP-CIA	Misc	Covebase Mastic & Glue	4"	Beige & Tan/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	CC-OP-126-2	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2x4		Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	CC-OP-126-2	Wall(s)	Plaster Wallboard oint Compound		Beige/Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	CC-OP-126-2	Floor	Resilient Floor Tile	12X12	Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	CC-OP-126-2	Misc	Ceramic Tile & Grout	4X4	White & Off White	Not Suspect											
Basement	CC-OP-126-2	Misc	Covebase Mastic & Glue	4"	Beige & Tan/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						

Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
Basement	CC-OP-126-4	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2x4		Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	CC-OP-126-4	Wall(s)	Plaster Wallboard oint Compound		Beige/Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	CC-OP-126-4	Floor	Resilient Floor Tile	12X12	Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	CC-OP-126-4	Misc	Ceramic Tile & Grout	4X4	White & Off White	Not Suspect											
Basement	CC-OP-126-4	Misc	Covebase Mastic & Glue	4"	Beige & Tan/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	CC-OP-126-3	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2x4		Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	CC-OP-126-3	Wall(s)	Plaster Wallboard oint Compound		Beige/Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	CC-OP-126-3	Floor	Resilient Floor Tile	12X12	Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	CC-OP-126-3	Misc	Ceramic Tile & Grout	4X4	White & Off White	Not Suspect											
Basement	CC-OP-126-3	Misc	Covebase Mastic & Glue	4"	Beige & Tan/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	CC-OP-126-5	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2x4		Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	CC-OP-126-5	Wall(s)	Plaster Wallboard oint Compound		Beige/Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	CC-OP-126-5	Floor	Resilient Floor Tile	12X12	Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	CC-OP-126-5	Misc	Ceramic Tile & Grout	4X4	White & Off White	Not Suspect											
Basement	CC-OP-126-5	Misc	Covebase Mastic & Glue	4"	Beige & Tan/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	CC-OP-126-6	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2x4		Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	CC-OP-126-6	Wall(s)	Plaster Wallboard oint Compound		Beige/Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	CC-OP-126-6	Floor	Resilient Floor Tile	12X12	Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	CC-OP-126-6	Misc	Ceramic Tile & Grout	4X4	White & Off White	Not Suspect											
Basement	CC-OP-126-6	Misc	Covebase Mastic & Glue	4"	Beige & Tan/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	CC-OP-126-10	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	CC-OP-126-10	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	CC-OP-126-10	Floor	Carpet		Blue /Purple	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	CC-OP-126-10	Door/Door Frame	Metal/Metal		B/B	Not Suspect											Possible Suspect Material In Core
Basement	CC-OP-126-10	Misc	Covebase Mastic & Glue	4"	Light Brown & Tan/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	CC-OP-126-10	Misc	Resilient Floor Tile	12X12	Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP-01	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP-01	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP-01	Floor	Carpet		Blue /Purple	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP-01	Door/Door Frame	Metal/Metal		B/B	Not Suspect											Possible Suspect Material In Core
Basement	OP-01	Misc	Covebase Mastic & Glue	4"	Light Brown & Tan/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP-02	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP-02	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP-02	Floor	Carpet		Blue /Purple	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP-02	Door/Door Frame	Metal/Metal		B/B	Not Suspect											Possible Suspect Material In Core

Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
Basement	OP-02	Misc	Covebase Mastic & Glue	4"	Light Brown & Tan/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP-03	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP-03	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP-03	Floor	Carpet		Blue /Purple	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP-03	Door/Door Frame	Metal/Metal		B/B	Not Suspect											Possible Suspect Material In Core
Basement	OP-03	Misc	Covebase Mastic & Glue	4"	Light Brown & Tan/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP-06	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP-06	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP-06	Floor	Carpet		Blue /Purple	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP-06	Door/Door Frame	Metal/Metal		B/B	Not Suspect											Possible Suspect Material In Core
Basement	OP-06	Misc	Covebase Mastic & Glue	4"	Light Brown & Tan/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP-05	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP-05	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP-05	Floor	Carpet		Blue /Purple	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP-05	Door/Door Frame	Metal/Metal		B/B	Not Suspect											Possible Suspect Material In Core
Basement	OP-05	Misc	Covebase Mastic & Glue	4"	Light Brown & Tan/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP-06B	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP-06B	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP-06B	Floor	Carpet		Blue /Purple	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP-06B	Door/Door Frame	Metal/Metal		B/B	Not Suspect											Possible Suspect Material In Core
Basement	OP-06B	Misc	Covebase Mastic & Glue	4"	Light Brown & Tan/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP-17	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4	White	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP-17	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP-17	Floor	Resilient Floor Tile	12X12	Light Blue	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP-17	Door/Door Frame	Carpet		Blue & White	Not Detected	N/A	Y	N/A	N/A	N/A						Possible Suspect Material In Core
Basement	OP-17	Roof	Wood/Metal	4"	Light Brown & Tan/Brown	Not Suspect											
Basement	OP-17	Misc	Covebase Mastic & Glue			Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP-16	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP-16	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP-16	Floor	Resilient Floor Tile		Blue/Purple	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP-16	Door/Door Frame	Carpet		Blue/White	Not Detected	N/A	Y	N/A	N/A	N/A						Possible Suspect Material In Core
Basement	OP-16	Misc	Wood/Metal		Light Brown & Tan/Brown	Not Suspect											
Basement	OP-16	Misc	Covebase Mastic & Glue			Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP-25A	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						

Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
Basement	OP-25A	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP-25A	Floor	Resilient Floor Tile		Blue/Purple	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP-25A	Door/Door Frame	Carpet		Blue/White	Not Detected	N/A	Y	N/A	N/A	N/A						Possible Suspect Material In Core
Basement	OP-25A	Misc	Wood/Metal		Light Brown & Tan/Brown	Not Suspect											
Basement	OP-25A	Misc	Covebase Mastic & Glue			Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP-13	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP-13	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP-13	Floor	Resilient Floor Tile		Blue/Purple	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP-13	Door/Door Frame	Carpet		Blue/White	Not Detected	N/A	Y	N/A	N/A	N/A						Possible Suspect Material In Core
Basement	OP-13	Roof	Wood/Metal		Light Brown & Tan/Brown	Not Suspect											
Basement	OP-13	Misc	Covebase Mastic & Glue			Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP-12	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP-12	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP-12	Floor	Resilient Floor Tile		Blue/Purple	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP-12	Door/Door Frame	Carpet		Blue/White	Not Detected	N/A	Y	N/A	N/A	N/A						Possible Suspect Material In Core
Basement	OP-12	Misc	Wood/Metal		Light Brown & Tan/Brown	Not Suspect											
Basement	OP-12	Misc	Covebase Mastic & Glue			Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP-11	Ceiling	Acoustic Ceiling Tile Pinhole			Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP-11	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP-11	Floor	Resilient Floor Tile	12X12	White with Gray	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP-11	Door/Door Frame	Wood/Metal		Bare/Off White	Not Suspect											Possible Suspect Material In Core
Basement	OP-11	Misc	Covebase Mastic & Glue	4"	Gray & Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP28	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP28	Wall(s)	Wallboard Joint Compound Concrete		Beige/Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP28	Floor	Carpet		Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP28	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
Basement	OP28	Roof	Covebase Mastic & Glue	4"	Beige & Tan/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP29	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP29	Wall(s)	Wallboard Joint Compound Concrete		Beige/Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP29	Floor	Carpet		Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP29	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
Basement	OP29	Misc	Covebase Mastic & Glue	4"	Beige & Tan/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP30	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP30	Wall(s)	Wallboard Joint Compound Concrete		Beige/Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP30	Floor	Carpet		Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP30	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core

Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
Basement	OP30	Misc	Covebase Mastic & Glue	4"	Beige & Tan/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP31	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP31	Wall(s)	Wallboard Joint Compound Concrete		Beige/Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP31	Floor	Carpet		Brwon	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP31	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
Basement	OP31	Roof	Covebase Mastic & Glue	4"	Beige & Tan/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP32	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP32	Wall(s)	Wallboard Joint Compound Concrete		Beige/Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP32	Floor	Carpet		Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP32	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
Basement	OP32	Roof	Covebase Mastic & Glue	4"	Beige & Tan/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP34	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP34	Wall(s)	Wallboard Joint Compound Concrete		Beige/Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP34	Floor	Carpet		Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP34	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
Basement	OP34	Misc	Covebase Mastic & Glue	4"	Beige & Tan/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP35	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP35	Wall(s)	Wallboard Joint Compound Concrete		Beige/Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP35	Floor	Carpet		Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP35	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
Basement	OP35	Misc	Covebase Mastic & Glue	4"	Beige & Tan/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP36	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP36	Wall(s)	Wallboard Joint Compound Concrete		Beige/Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP36	Floor	Carpet		Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP36	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
Basement	OP36	Roof	Covebase Mastic & Glue	4"	Beige & Tan/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP37	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP37	Wall(s)	Wallboard Joint Compound		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP37	Floor	Carpet Resilient Floor Tile 12X12 under		Blue/Purple	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP26	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm			Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP26	Wall(s)	Wallboard Joint Compound		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP26	Floor	Resilient Floor Tile	12X12	Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP26	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
Basement	OP26	Misc	Covebase Mastic & Glue	4"	Beige & Gray/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP27	Ceilin g	Acoustic Ceiling Tile Pinhole Big Worm			Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP27	Wall(s)	Wallboard Joint Compound		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP27	Floor	Resilient Floor Tile	12X12	Tan	Not Detected	N/A	Y	N/A	N/A	N/A						

Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
Basement	OP27	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
Basement	OP27	Misc	Covebase Mastic & Glue	4"	Beige & Gray/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP24	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm			Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP24	Wall(s)	Wallboard Joint Compound		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP24	Floor	Resilient Floor Tile	12X12	Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP24	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
Basement	OP24	Roof	Covebase Mastic & Glue	4"	Beige & Gray/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP25	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP25	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP25	Floor	Carpet		Blue/Purple	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP25	Door/Door Frame	Metal/Metal		Blue & Off White	Not Suspect											Possible Suspect Material In Core
Basement	OP25	Roof	Covebase Mastic	4"	Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP21	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP21	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP21	Floor	Resilient Floor Tile	12X12	Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP21	Door/Door Frame	Wood/Metal		Blue & Beige	Not Suspect											Possible Suspect Material In Core
Basement	OP21	Misc	Covebase Mastic	4"	Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	BFAC1	Ceiling	Wallboard Joint Compound		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	BFAC1	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	BFAC1	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	BFAC1	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
Basement	BFAC1	Misc	Covebase Mastic & Glue	4"	Black & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP14	Ceiling	Concrete		White	Not Suspect											
Basement	OP14	Wall(s)	Wallboard Joint Compound		Bare	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP14	Floor	Concrete		Bare	Not Suspect											
Basement	OP14	Door/Door Frame	Metal/Metal		Beige/Beige	Not Suspect											Possible Suspect Material In Core
Basement	OP14	Roof	Plaster		Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP14	Misc	Fire Caulk		Red												
Basement	OP15	Ceiling	Concrete		White	Not Suspect											
Basement	OP15	Wall(s)	Wallboard Joint Compound		Bare	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP15	Floor	Concrete		Bare	Not Suspect											
Basement	OP15	Door/Door Frame	Metal/Metal		Beige/Beige	Not Suspect											Possible Suspect Material In Core
Basement	OP15	Roof	Plaster		Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP15	Misc	Fire Caulk		Red												
Basement	OP14A	Ceiling	Concrete		White	Not Suspect											
Basement	OP14A	Wall(s)	Wallboard Joint Compound		Bare	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP14A	Floor	Concrete		Bare	Not Suspect											

Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
Basement	OP14A	Door/Door Frame	Metal/Metal		Beige/Beige	Not Suspect											Possible Suspect Material In Core
Basement	OP14A	Roof	Plaster		Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP14A	Misc	Fire Caulk		Red												
Basement	OP14B	Ceiling	Concrete		White	Not Suspect											
Basement	OP14B	Wall(s)	Wallboard Joint Compound		Bare	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP14B	Floor	Concrete		Bare	Not Suspect											
Basement	OP14B	Door/Door Frame	Metal/Metal		Beige/Beige	Not Suspect											Possible Suspect Material In Core
Basement	OP14B	Misc	Plaster		Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP14B	Misc	Fire Caulk		Red												
Basement	OP28A	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP28A	Wall(s)	Wallboard Joint Compound Concrete		Beige/Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP28A	Floor	Resilient Floor Tile	12X12	Olive	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP28A	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
Basement	OP28A	Misc	Covebase Mastic & Glue	4"	Beige & Tan/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP52	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP52	Wall(s)	Wallboard Joint Compound Concrete		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP52	Floor	Resilient Floor Tile	12X12	Seafoam/Dark Blue	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP52	Door/Door Frame	Wood/Metal		Beige & Beige	Not Suspect											Possible Suspect Material In Core
Basement	OP52	Misc	Covebase Mastic	4"	Blue	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP52B	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP52B	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP52B	Floor	Resilient Floor Tile	12X12	Seafoam/Dark Blue	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP52B	Misc	Resilient Floor Tile	12X12	Off White with Blue	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP52B	Misc	Covebase Mastic	4"	Blue	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP51	Ceiling	Concrete		Beige	Not Suspect											
Basement	OP51	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP51	Floor	Concrete		Bare	Not Suspect											
Basement	OP51	Door/Door Frame	Wood/Metal		Beige & Beige	Not Suspect											Possible Suspect Material In Core
Basement	OP51	Misc	Covebase Mastic & Glue		Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP50	Ceiling	Concrete		Beige	Not Suspect											
Basement	OP50	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP50	Floor	Concrete		Bare	Not Suspect											
Basement	OP50	Door/Door Frame	Wood/Metal		Beige & Beige	Not Suspect											Possible Suspect Material In Core
Basement	OP50	Misc	Covebase Mastic & Glue		Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	BFAC2	Ceiling	Wallboard Joint Compound		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	BFAC2	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	BFAC2	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						

Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
Basement	BFAC2	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
Basement	BFAC2	Misc	Covebase Mastic & Glue	4"	Black & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP09	Ceiling	Wallboard Joint Compound		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP09	Wall(s)	Wallboard Joint Compound			Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP09	Floor	Resilient Floor Tile	12X12	Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP09	Door/Door Frame	Wood/Metal		Beige & Beige	Not Suspect											Possible Suspect Material In Core
Basement	OP09	Wall(s)	Covebas Mastic	4"	Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP09	Misc	Fire Caulk		Red												
Basement	OP08	Ceiling	Acoustic Ceiling Tile Pinhole Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP08	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP08	Floor	Ceramic Tile & Grout	1X1	Gray & Gray	Not Suspect											
Basement	OP08	Door/Door Frame	Metal/Metal		Beige & Beige	Not Suspect											Possible Suspect Material In Core
Basement	OP08	Wall(s)	Ceramic Tile & Grout	4X4	Off White & Off White	Not Suspect											
Basement	OP05	Ceiling	Acoustic Ceiling Tile Pinhole Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP05	Wall(s)	Plaster Wallboard Joint Compound		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP05	Floor	Ceramic Tile & Grout	1X1	Blue & Black	Not Suspect											
Basement	OP05	Door/Door Frame	Wood/Metal		Beige/Beige	Not Suspect											Possible Suspect Material In Core
Basement	OP05	Wall(s)	Ceramic Tile & Grout	4X4	White & White	Not Suspect											
Basement	OP07	Ceiling	Acoustic Ceiling Tile Pinhole Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP07	Wall(s)	Plaster Wallboard Joint Compound		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
Basement	OP07	Floor	Ceramic Tile & Grout	1X1	Pink & Black	Not Suspect											
Basement	OP07	Door/Door Frame	Wood/Metal		Beige/Beige	Not Suspect											Possible Suspect Material In Core
Basement	OP07	Misc	Ceramic Tile & Grout	4X4	White & White	Not Suspect											
1st Floor	OP132	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4	White	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP132	Wall(s)	Wallboard Joint Compound		Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP132	Floor	Resilient Tile Floor	12X12	Tan & Brown with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP132	Door/Door Frame	Resilient Tile Floor			Not Detected	N/A	Y	N/A	N/A	N/A						Possible Suspect Material In Core
1st Floor	OP132	Misc	Covebase Mastic & Glue	4"	Beige & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP132 Clinic Area	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4	White	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP132 Clinic Area	Wall(s)	Wallboard Joint Compound		Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP132 Clinic Area	Floor	Resilient Tile Floor	12X12	Tan & Brown with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP132 Clinic Area	Door/Door Frame	Resilient Tile Floor			Not Detected	N/A	Y	N/A	N/A	N/A						Possible Suspect Material In Core
1st Floor	OP132 Clinic Area	Roof	Covebase Mastic & Glue	4"	Beige & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	CC-126-OP-3	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4	Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	CC-126-OP-3	Wall(s)	Wallboard Joint Compound		Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	CC-126-OP-3	Floor	Resilient Tile Floor	12X12	Multi rust	Y	N/A	Y	No	Good	no	no	yes			yes	

Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
1st Floor	CC-126-OP-3	Door/Door Frame	Metal/Metal		B/B	Not Suspect											Possible Suspect Material In Core
1st Floor	CC-126-OP-3	Misc	Covebase Mastic & Glue	4"	Beige & Brown	Y	N/A	Y	No	Good	no	no	yes			yes	
1st Floor	CC-126-OP-4	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4	Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	CC-126-OP-4	Wall(s)	Wallboard Joint Compound		Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	CC-126-OP-4	Floor	Resilient Tile Floor	12X12	Multi rust	Y	N/A	Y	No	Good	no	no	yes			yes	
1st Floor	CC-126-OP-4	Door/Door Frame	Metal/Metal		B/B	Not Suspect											Possible Suspect Material In Core
1st Floor	CC-126-OP-4	Misc	Covebase Mastic & Glue	4"	Beige & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	CC-126-OP-5	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4	Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	CC-126-OP-5	Wall(s)	Wallboard Joint Compound		Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	CC-126-OP-5	Floor	Resilient Tile Floor	12X12	Multi rust	Y	N/A	Y	No	Good	no	no	yes			yes	
1st Floor	CC-126-OP-5	Door/Door Frame	Metal/Metal		B/B	Not Suspect											Possible Suspect Material In Core
1st Floor	CC-126-OP-5	Misc	Covebase Mastic & Glue	4"	Beige & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-00	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4	Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-00	Wall(s)	Wallboard Joint Compound Plaster Concrete		Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-00	Floor	Resilient Tile Floor	12X12	Seafoam Blue & Seafoam Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-00	Door/Door Frame	Resilient Tile Floor			Not Detected	N/A	Y	N/A	N/A	N/A						Possible Suspect Material In Core
1st Floor	OP-00	Misc	Covebase Mastic & Glue	4"	Beige & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	CC-126-OP-6	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4	Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	CC-126-OP-6	Wall(s)	Wallboard Joint Compound Plaster Concrete		Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	CC-126-OP-6	Floor	Resilient Tile Floor	12X12	Seafoam Blue & Seafoam Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	CC-126-OP-6	Door/Door Frame	Resilient Tile Floor			Not Detected	N/A	Y	N/A	N/A	N/A						Possible Suspect Material In Core
1st Floor	CC-126-OP-6	Misc	Covebase Mastic & Glue	4"	Beige & Brown	Y	N/A	Y	No	Good	no	no	yes			yes	
1st Floor	OP-189F	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4	Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-189F	Wall(s)	Wallboard Joint Compound Plaster Concrete		Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-189F	Floor	Resilient Tile Floor	12X12	Seafoam Blue & Seafoam Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-189F	Door/Door Frame	Resilient Tile Floor			Not Detected	N/A	Y	N/A	N/A	N/A						Possible Suspect Material In Core
1st Floor	OP-189F	Misc	Covebase Mastic & Glue	4"	Beige & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-104 A	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4	Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-104 A	Wall(s)	Wallboard Joint Compound Plaster Concrete		Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-104 A	Floor	Resilient Tile Floor	12X12	Seafoam Blue & Seafoam Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-104 A	Door/Door Frame	Resilient Tile Floor			Not Detected	N/A	Y	N/A	N/A	N/A						Possible Suspect Material In Core
1st Floor	OP-104 A	Misc	Covebase Mastic & Glue	4"	Beige & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	CC-126-OP-12	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4	Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	CC-126-OP-12	Wall(s)	Wallboard Joint Compound Plaster Concrete		Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	CC-126-OP-12	Floor	Resilient Tile Floor	12X12	Seafoam Blue & Seafoam Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	CC-126-OP-12	Door/Door Frame	Resilient Tile Floor			Not Detected	N/A	Y	N/A	N/A	N/A						Possible Suspect Material In Core

Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	SignificantlyDamaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
1st Floor	CC-126-OP-12	Misc	Covebase Mastic & Glue	4"	Beige & Brown	Y	N/A	Y	No	Good	no	no	yes			yes	
1st Floor	CC-126-OP-8	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	CC-126-OP-8	Wall(s)	Wallboard Joint Compound		Beige & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	CC-126-OP-8	Floor	Resilient Tile Floor x2	12X12	Seafoam Blue & Seafoam Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	CC-126-OP-8	Door/Door Frame	Wood/Metal		Beige/Beige	Not Suspect											Possible Suspect Material In Core
1st Floor	CC-126-OP-8	Misc	Covebase Mastic & Glue	4"	Beige & Gray/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	CC-126-OP-11	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	CC-126-OP-11	Wall(s)	Wallboard Joint Compound		Beige & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	CC-126-OP-11	Floor	Resilient Tile Floor x2	12X12	Seafoam Blue & Seafoam Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	CC-126-OP-11	Door/Door Frame	Wood/Metal		Beige/Beige	Not Suspect											Possible Suspect Material In Core
1st Floor	CC-126-OP-11	Misc	Covebase Mastic & Glue	4"	Beige & Gray/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	CC-126-OP-10	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	CC-126-OP-10	Wall(s)	Wallboard Joint Compound		Beige & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	CC-126-OP-10	Floor	Resilient Tile Floor x2	12X12	Seafoam Blue & Seafoam Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	CC-126-OP-10	Door/Door Frame	Wood/Metal		Beige/Beige	Not Suspect											Possible Suspect Material In Core
1st Floor	CC-126-OP-10	Misc	Covebase Mastic & Glue	4"	Beige & Gray/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	CC-126-OP-9	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	CC-126-OP-9	Wall(s)	Wallboard Joint Compound		Beige & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	CC-126-OP-9	Floor	Resilient Tile Floor x2	12X12	Seafoam Blue & Seafoam Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	CC-126-OP-9	Door/Door Frame	Wood/Metal		Beige/Beige	Not Suspect											Possible Suspect Material In Core
1st Floor	CC-126-OP-9	Misc	Covebase Mastic & Glue	4"	Beige & Gray/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	CC-126-OP-12	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	CC-126-OP-12	Wall(s)	Wallboard Joint Compound		Beige & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	CC-126-OP-12	Floor	Resilient Tile Floor x2	12X12	Seafoam Blue & Seafoam Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	CC-126-OP-12	Door/Door Frame	Wood/Metal		Beige/Beige	Not Suspect											Possible Suspect Material In Core
1st Floor	CC-126-OP-12	Misc	Covebase Mastic & Glue	4"	Beige & Gray/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	CC-126-OP-7	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	CC-126-OP-7	Wall(s)	Wallboard Joint Compound		Beige & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	CC-126-OP-7	Floor	Resilient Tile Floor x2	12X12	Seafoam Blue & Seafoam Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	CC-126-OP-7	Door/Door Frame	Wood/Metal		Beige/Beige	Not Suspect											Possible Suspect Material In Core
1st Floor	CC-126-OP-7	Misc	Covebase Mastic & Glue	4"	Beige & Gray/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	CC-126-OP-11	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	CC-126-OP-11	Wall(s)	Wallboard Joint Compound		Beige & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	CC-126-OP-11	Floor	Resilient Tile Floor x2	12X12	Seafoam Blue & Seafoam Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	CC-126-OP-11	Door/Door Frame	Wood/Metal		Beige/Beige	Not Suspect											Possible Suspect Material In Core
1st Floor	CC-126-OP-11	Misc	Covebase Mastic & Glue	4"	Beige & Gray/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP184C	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP184C	Wall(s)	Wallboard Joint Compound		Beige & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP184C	Floor	Resilient Tile Floor x2	12X12	Seafoam Blue & Seafoam Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP184C	Door/Door Frame	Wood/Metal		Beige/Beige	Not Suspect											Possible Suspect Material In Core
1st Floor	OP184C	Misc	Covebase Mastic & Glue	4"	Beige & Gray/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP184D	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP184D	Wall(s)	Wallboard Joint Compound		Beige & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP184D	Floor	Resilient Tile Floor x2	12X12	Seafoam Blue & Seafoam Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP184D	Door/Door Frame	Wood/Metal		Beige/Beige	Not Suspect											Possible Suspect Material In Core
1st Floor	OP184D	Misc	Covebase Mastic & Glue	4"	Beige & Gray/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP184E	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						

Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
1st Floor	OP184E	Wall(s)	Wallboard Joint Compound		Beige & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP184E	Floor	Resilient Tile Floor x2	12X12	Seafoam Blue & Seafoam Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP184E	Door/Door Frame	Wood/Metal		Beige/Beige	Not Suspect											Possible Suspect Material In Core
1st Floor	OP184E	Misc	Covebase Mastic & Glue	4"	Beige & Gray/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP184	Door/Door Frame	Under Construction														Possible Suspect Material In Core
1st Floor	OP184B	Door/Door Frame	Under Construction														Possible Suspect Material In Core
1st Floor	OP184A	Door/Door Frame	Under Construction														Possible Suspect Material In Core
1st Floor	CC-126-OP-13	Door/Door Frame	Under Construction														Possible Suspect Material In Core
1st Floor	OP114	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP114	Wall(s)	Wallboard Joint Compound		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP114	Floor	Resilient Tile Floor x2	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP114	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
1st Floor	OP114	Misc	Covebase Mastic & Glue	4"	Beige & Gray/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP114	Misc	Ceramic Tile & Grout	4X4	White & White	Not Suspect											
1st Floor	OP118	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP118	Wall(s)	Wallboard Joint Compound		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP118	Floor	Resilient Tile Floor x2	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP118	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
1st Floor	OP118	Misc	Covebase Mastic & Glue	4"	Beige & Gray/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP118	Misc	Ceramic Tile & Grout	4X4	White & White	Not Suspect											
1st Floor	OP119	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP119	Wall(s)	Wallboard Joint Compound		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP119	Floor	Resilient Tile Floor x2	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP119	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
1st Floor	OP119	Misc	Covebase Mastic & Glue	4"	Beige & Gray/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP119	Misc	Ceramic Tile & Grout	4X4	White & White	Not Suspect											
1st Floor	OP120	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP120	Wall(s)	Wallboard Joint Compound		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP120	Floor	Resilient Tile Floor x2	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP120	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
1st Floor	OP120	Misc	Covebase Mastic & Glue	4"	Beige & Gray/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP120	Misc	Ceramic Tile & Grout	4X4	White & White	Not Suspect											
1st Floor	OP142	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP142	Wall(s)	Wallboard Joint Compound		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP142	Floor	Resilient Tile Floor x2	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP142	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
1st Floor	OP142	Misc	Covebase Mastic & Glue	4"	Beige & Gray/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP142	Misc	Ceramic Tile & Grout	4X4	White & White	Not Suspect											
1st Floor	OP141	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP141	Wall(s)	Wallboard Joint Compound		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP141	Floor	Resilient Tile Floor x2	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP141	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
1st Floor	OP141	Misc	Covebase Mastic & Glue	4"	Beige & Gray/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP141	Misc	Ceramic Tile & Grout	4X4	White & White	Not Suspect											
1st Floor	OP137	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP137	Wall(s)	Wallboard Joint Compound		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP137	Floor	Resilient Tile Floor x2	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP137	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
1st Floor	OP137	Misc	Covebase Mastic & Glue	4"	Beige & Gray/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP137	Misc	Ceramic Tile & Grout	4X4	White & White	Not Suspect											
1st Floor	OP136	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP136	Wall(s)	Wallboard Joint Compound		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP136	Floor	Resilient Tile Floor x2	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP136	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
1st Floor	OP136	Misc	Covebase Mastic & Glue	4"	Beige & Gray/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP136	Misc	Ceramic Tile & Grout	4X4	White & White	Not Suspect											

Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
1st Floor	OP135	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP135	Wall(s)	Wallboard Joint Compound		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP135	Floor	Resilient Tile Floor x2	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP135	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
1st Floor	OP135	Misc	Covebase Mastic & Glue	4"	Beige & Gray/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP135	Misc	Ceramic Tile & Grout	4X4	White & White	Not Suspect											
1st Floor	OP125	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP125	Wall(s)	Wallboard Joint Compound		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP125	Floor	Resilient Tile Floor x2	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP125	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
1st Floor	OP125	Misc	Covebase Mastic & Glue	4"	Beige & Gray/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP125	Misc	Ceramic Tile & Grout	4X4	White & White	Not Suspect											
1st Floor	OP124	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP124	Wall(s)	Wallboard Joint Compound		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP124	Floor	Resilient Tile Floor x2	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP124	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
1st Floor	OP124	Misc	Covebase Mastic & Glue	4"	Beige & Gray/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP124	Misc	Ceramic Tile & Grout	4X4	White & White	Not Suspect											
1st Floor	OP113	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP113	Wall(s)	Wallboard Joint Compound		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP113	Floor	Resilient Tile Floor x2	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP113	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
1st Floor	OP113	Misc	Covebase Mastic & Glue	4"	Beige & Gray/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP113	Misc	Ceramic Tile & Grout	4X4	White & White	Not Suspect											
1st Floor	OP114	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP114	Wall(s)	Wallboard Joint Compound		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP114	Floor	Resilient Tile Floor x2	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP114	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
1st Floor	OP114	Misc	Covebase Mastic & Glue	4"	Beige & Gray/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP114	Misc	Ceramic Tile & Grout	4X4	White & White	Not Suspect											
1st Floor	OP115	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP115	Wall(s)	Wallboard Joint Compound		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP115	Floor	Resilient Tile Floor x2	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP115	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
1st Floor	OP115	Misc	Covebase Mastic & Glue	4"	Beige & Gray/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP115	Misc	Ceramic Tile & Grout	4X4	White & White	Not Suspect											
1st Floor	OP116	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP116	Wall(s)	Wallboard Joint Compound		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP116	Floor	Resilient Tile Floor x2	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP116	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
1st Floor	OP116	Misc	Covebase Mastic & Glue	4"	Beige & Gray/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP116	Misc	Ceramic Tile & Grout	4X4	White & White	Not Suspect											
1st Floor	OP134	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP134	Wall(s)	Wallboard Joint Compound		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP134	Floor	Resilient Tile Floor x2	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP134	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
1st Floor	OP134	Misc	Covebase Mastic & Glue	4"	Beige & Gray/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP134	Misc	Ceramic Tile & Grout	4X4	White & White	Not Suspect											
1st Floor	OP133	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP133	Wall(s)	Wallboard Joint Compound		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP133	Floor	Resilient Tile Floor x2	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP133	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
1st Floor	OP133	Misc	Covebase Mastic & Glue	4"	Beige & Gray/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP133	Misc	Ceramic Tile & Grout	4X4	White & White	Not Suspect											
1st Floor	OP130	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP130	Wall(s)	Wallboard Joint Compound		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP130	Floor	Resilient Tile Floor x2	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						

Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
1st Floor	OP130	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
1st Floor	OP130	Misc	Covebase Mastic & Glue	4"	Beige & Gray/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP130	Misc	Ceramic Tile & Grout	4X4	White & White	Not Suspect											
1st Floor	OP131	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP131	Wall(s)	Wallboard Joint Compound		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP131	Floor	Resilient Tile Floor x2	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP131	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
1st Floor	OP131	Misc	Covebase Mastic & Glue	4"	Beige & Gray/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP131	Misc	Ceramic Tile & Grout	4X4	White & White	Not Suspect											
1st Floor	OP129	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP129	Wall(s)	Wallboard Joint Compound		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP129	Floor	Resilient Tile Floor x2	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP129	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
1st Floor	OP129	Misc	Covebase Mastic & Glue	4"	Beige & Gray/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP129	Misc	Ceramic Tile & Grout	4X4	White & White	Not Suspect											
1st Floor	OP126	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP126	Wall(s)	Wallboard Joint Compound		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP126	Floor	Resilient Tile Floor x2	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP126	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
1st Floor	OP126	Misc	Covebase Mastic & Glue	4"	Beige & Gray/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP126	Misc	Ceramic Tile & Grout	4X4	White & White	Not Suspect											
1st Floor	OP127	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP127	Wall(s)	Wallboard Joint Compound		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP127	Floor	Resilient Tile Floor x2	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP127	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
1st Floor	OP127	Misc	Covebase Mastic & Glue	4"	Beige & Gray/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP127	Misc	Ceramic Tile & Grout	4X4	White & White	Not Suspect											
1st Floor	OP139	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP139	Wall(s)	Wallboard Joint Compound		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP139	Floor	Resilient Tile Floor x2	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP139	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
1st Floor	OP139	Misc	Covebase Mastic & Glue	4"	Beige & Gray/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP139	Misc	Ceramic Tile & Grout	4X4	White & White	Not Suspect											
1st Floor	OP138	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP138	Wall(s)	Wallboard Joint Compound		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP138	Floor	Resilient Tile Floor x2	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP138	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
1st Floor	OP138	Misc	Covebase Mastic & Glue	4"	Beige & Gray/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP138	Misc	Ceramic Tile & Grout	4X4	White & White	Not Suspect											
1st Floor	OP128	Ceiling	Wallboard Joint Compound		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP128	Wall(s)	Resilient Tile Floor x2	12X12	Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP128	Floor	Wood/Metal		Beige & Beige	Not Suspect											
1st Floor	OP128	Door/Door Frame	Covebase Mastic	4"	Brown	Not Detected	N/A	Y	N/A	N/A	N/A						Possible Suspect Material In Core
1st Floor	OP128	Misc	Fire Caulk		Red												
1st Floor	1 FAC 2	Ceiling	Wallboard Joint Compund		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	1 FAC 2	Wall(s)	Wallboard Joint Compund		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	1 FAC 2	Floor	Resilient Floor Tile	12X12	Multi Rust	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	1 FAC 2	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
1st Floor	1 FAC 2	Misc	Covebase Mastic & Glue	4"	Brown & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	1 FAC 1	Ceiling	Wallboard Joint Compound		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	1 FAC 1	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	1 FAC 1	Floor	Resilient Floor Tile	12X12	Multi Rust	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	1 FAC 1	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
1st Floor	1 FAC 1	Misc	Covebase Mastic & Glue	4"	Brown & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP123	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP123	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP123	Floor	Resilient Floor Tile	12X12	Beige	Not Detected	N/A	Y	N/A	N/A	N/A						

Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
1st Floor	OP123	Door/Door Frame	Wood/Metal		Beige & Beige	Not Suspect											Possible Suspect Material In Core
1st Floor	OP123	Misc	Covebase Mastic	4"	Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP112A	Wall(s)	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP112A	Floor	Wallboard Joint Compound		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP112A	Door/Door Frame	Carpet		Blue/Purple	Not Detected	N/A	Y	N/A	N/A	N/A						Possible Suspect Material In Core
1st Floor	OP112A	Misc	Covebase Mastic & Glue	4"		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP112A	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP112A	Wall(s)	Wallboard Joint Compound		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP112A	Floor	Carpet		Green	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP112A	Misc	Covebase Mastic & Glue	4"		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-152	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-152	Wall(s)	Wallboard Joint Compound		White	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-152	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-152	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
1st Floor	OP-152	Misc	Covebase Mastic & Glue	4"	Light Brown & Tan Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-152	Misc	Ceramic Tile & Grout	4X4	Off White & Off White	Not Suspect											
1st Floor	OP-154	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-154	Wall(s)	Wallboard Joint Compound		White	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-154	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-154	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
1st Floor	OP-154	Misc	Covebase Mastic & Glue	4"	Light Brown & Tan Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-154	Misc	Ceramic Tile & Grout	4X4	Off White & Off White	Not Suspect											
1st Floor	OP-156	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-156	Wall(s)	Wallboard Joint Compound		White	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-156	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-156	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
1st Floor	OP-156	Misc	Covebase Mastic & Glue	4"	Light Brown & Tan Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-156	Misc	Ceramic Tile & Grout	4X4	Off White & Off White	Not Suspect											
1st Floor	OP-158	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-158	Wall(s)	Wallboard Joint Compound		White	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-158	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-158	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
1st Floor	OP-158	Misc	Covebase Mastic & Glue	4"	Light Brown & Tan Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-158	Misc	Ceramic Tile & Grout	4X4	Off White & Off White	Not Suspect											
1st Floor	OP-160	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-160	Wall(s)	Wallboard Joint Compound		White	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-160	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-160	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
1st Floor	OP-160	Misc	Covebase Mastic & Glue	4"	Light Brown & Tan Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-160	Misc	Ceramic Tile & Grout	4X4	Off White & Off White	Not Suspect											
1st Floor	OP-161	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-161	Wall(s)	Wallboard Joint Compound		White	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-161	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-161	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
1st Floor	OP-161	Misc	Covebase Mastic & Glue	4"	Light Brown & Tan Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-161	Misc	Ceramic Tile & Grout	4X4	Off White & Off White	Not Suspect											
1st Floor	OP-159	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-159	Wall(s)	Wallboard Joint Compound		White	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-159	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-159	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core

Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
1st Floor	OP-159	Misc	Covebase Mastic & Glue	4"	Light Brown & Tan Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-159	Misc	Ceramic Tile & Grout	4X4	Off White & Off White	Not Suspect											
1st Floor	OP-157	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-157	Wall(s)	Wallboard Joint Compund		White	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-157	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-157	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
1st Floor	OP-157	Misc	Covebase Mastic & Glue	4"	Light Brown & Tan Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-157	Misc	Ceramic Tile & Grout	4X4	Off White & Off White	Not Suspect											
1st Floor	OP-165	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-165	Wall(s)	Wallboard Joint Compund		White	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-165	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-165	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
1st Floor	OP-165	Misc	Covebase Mastic & Glue	4"	Light Brown & Tan Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-165	Misc	Ceramic Tile & Grout	4X4	Off White & Off White	Not Suspect											
1st Floor	OP-163	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-163	Wall(s)	Wallboard Joint Compund		White	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-163	Floor	Resilient Floor Tile	12X12	Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-163	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
1st Floor	OP-163	Misc	Covebase Mastic & Glue	4"	Light Brown & Tan Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-163	Misc	Ceramic Tile & Grout	4X4	Off White & Off White	Not Suspect											
1st Floor	OP-153	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-153	Wall(s)	Wallboard Joint Compund		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-153	Floor	Carpet		Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-153	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
1st Floor	OP-153	Misc	Covebase Mastic & Glue	4"	Beige & Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-151	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-151	Wall(s)	Wallboard Joint Compund		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-151	Floor	Carpet		Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP-151	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
1st Floor	OP-151	Misc	Covebase Mastic & Glue	4"	Beige & Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP145	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP145	Wall(s)	Wallboard Joint Compund		White	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP145	Floor	Carpet		Blue Purple	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP145	Door/Door Frame	Wood/Metal		Off White/ Off White	Not Suspect											Possible Suspect Material In Core
1st Floor	OP145	Misc	Covebase Mastic & Glue	4"	Beige & Gray	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP145D	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP145D	Wall(s)	Wallboard Joint Compund		White	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP145D	Floor	Carpet		Blue Purple	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP145D	Door/Door Frame	Wood/Metal		Off White/ Off White	Not Suspect											Possible Suspect Material In Core
1st Floor	OP145D	Misc	Covebase Mastic & Glue	4"	Beige & Gray	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP145E	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4	White	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP145E	Wall(s)	Wallboard Joint Compund		Blue Purple	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP145E	Floor	Carpet		Off White/ Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP145E	Door/Door Frame	Wood/Metal		Beige & Gray	Not Suspect											Possible Suspect Material In Core
1st Floor	OP145E	Misc	Covebase Mastic & Glue	4"		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP145A	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP145A	Wall(s)	Wallboard Joint Compund		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP145A	Floor	Resilient Floor Tile	12X12	Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP145A	Door/Door Frame	Wood/Metal		Off White/ Off White	Not Suspect											Possible Suspect Material In Core
1st Floor	OP145A	Misc	Covebase Mastic & Glue	4"	Beige & Tan/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP145B	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP145B	Wall(s)	Wallboard Joint Compund		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP145B	Floor	Resilient Floor Tile	12X12	Tan	Not Detected	N/A	Y	N/A	N/A	N/A						

Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
1st Floor	OP145B	Door/Door Frame	Wood/Metal		Off White/ Off White	Not Suspect											Possible Suspect Material In Core
1st Floor	OP145B	Misc	Covebase Mastic & Glue	4"	Beige & Tan/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP145C	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP145C	Wall(s)	Wallboard Joint Compund		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP145C	Floor	Resilient Floor Tile	12X12	Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP145C	Door/Door Frame	Wood/Metal		Off White/ Off White	Not Suspect											Possible Suspect Material In Core
1st Floor	OP145C	Misc	Covebase Mastic & Glue	4"	Beige & Tan/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP182	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP182	Wall(s)	Wallboard Joint Compund		Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP182	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP182	Door/Door Frame	Wood/Metal		Beige & Off White	Not Suspect											Possible Suspect Material In Core
1st Floor	OP181	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP181	Wall(s)	Wallboard Joint Compund		Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP181	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP181	Door/Door Frame	Wood/Metal		Beige & Off White	Not Suspect											Possible Suspect Material In Core
1st Floor	OP180	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP180	Wall(s)	Wallboard Joint Compund		Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP180	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP180	Door/Door Frame	Wood/Metal		Beige & Off White	Not Suspect											Possible Suspect Material In Core
1st Floor	OP179	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP179	Wall(s)	Wallboard Joint Compund		Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP179	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP179	Door/Door Frame	Wood/Metal		Beige & Off White	Not Suspect											Possible Suspect Material In Core
1st Floor	OP178	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP178	Wall(s)	Wallboard Joint Compund		Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP178	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP178	Door/Door Frame	Wood/Metal		Beige & Off White	Not Suspect											Possible Suspect Material In Core
1st Floor	OP177	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP177	Wall(s)	Wallboard Joint Compund		Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP177	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP177	Door/Door Frame	Wood/Metal		Beige & Off White	Not Suspect											Possible Suspect Material In Core
1st Floor	OP176	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP176	Wall(s)	Wallboard Joint Compund		Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP176	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						

Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
1st Floor	OP183	Ceiling	Acoustic Ceiling Panel No Holes	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP183	Wall(s)	Wallboard Joint Compund		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP183	Floor	Carpet		Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP183	Door/Door Frame	Wood/Metal		White & Beige	Not Suspect											Possible Suspect Material In Core
1st Floor	OP183	Misc	Covebase Mastic	4"	Silver	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP162	Ceiling	Acoustic Tile Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP162	Wall(s)	Wallboard Joint Compund		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP162	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP162	Door/Door Frame	Wood/Metal		Beige/Beige	Not Suspect											Possible Suspect Material In Core
1st Floor	OP162	Misc	Covebase Mastic & Glue	4"	Light Brown & Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP164	Ceiling	Acoustic Tile Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP164	Wall(s)	Wallboard Joint Compund		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP164	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP164	Door/Door Frame	Wood/Metal		Beige/Beige	Not Suspect											Possible Suspect Material In Core
1st Floor	OP164	Misc	Covebase Mastic & Glue	4"	Light Brown & Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP105	Ceiling	Acoustic Tile Panel Pinhole Big Worm	2X2		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP105	Wall(s)	Wallboard Joint Compund Ceramic tile & Grout	12X12	Beige & Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP105	Floor	Ceramic Tile & Grout	16X16	Beige Swirl	Not Suspect											
1st Floor	OP105	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
1st Floor	OP105	Misc	Ceramic Tile & Grout Accent	1X1X8	Multi Beige & Beige	Not Suspect											
1st Floor	OP104	Ceiling	Acoustic Tile Panel Pinhole Big Worm	2X2		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP104	Wall(s)	Wallboard Joint Compund Ceramic tile & Grout	12X12	Beige & Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP104	Floor	Ceramic Tile & Grout	16X16	Beige Swirl	Not Suspect											
1st Floor	OP104	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
1st Floor	OP104	Misc	Ceramic Tile & Grout Accent	1X1X8	Multi Beige & Beige	Not Suspect											
1st Floor	OP106	Ceiling	Acoustic Tile Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP106	Wall(s)	Wallboard Joint Compound Concrete		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP106	Floor	Carpet		Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP106	Misc	Covebase Mastic & Glue	4"	Beige & Gray	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP1060	Ceiling	Acoustic Tile Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP1060	Wall(s)	Wallboard Joint Compound Concrete		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP1060	Floor	Carpet		Blue Purple	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP1060	Door/Door Frame	Wood/Metal		Bare/Beige	Not Suspect											Possible Suspect Material In Core
1st Floor	OP1060	Misc	Covebase Mastic & Glue	4"	Gray & Light Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP106	Ceiling	Acoustic Tile Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP106	Wall(s)	Wallboard Joint Compound Concrete		White	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP106	Floor	Carpet		Blue Purple	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP106	Door/Door Frame	Wood/Metal		Bare/Beige	Not Suspect											Possible Suspect Material In Core
1st Floor	OP106	Misc	Covebase Mastic & Glue	4"	Light Brown & Gray	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP111	Ceiling	Acoustic Tile Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP111	Wall(s)	Wallboard Joint Compound Concrete		White	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP111	Floor	Carpet		Blue Purple	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP111	Door/Door Frame	Wood/Metal		Bare/Beige	Not Suspect											Possible Suspect Material In Core
1st Floor	OP111	Misc	Covebase Mastic & Glue	4"	Light Brown & Gray	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP106B	Ceiling	Acoustic Tile Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP106B	Wall(s)	Wallboard Joint Compound Concrete		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP106B	Floor	Carpet		Blue Purple	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP106B	Door/Door Frame	Wood/Metal		Bare/Beige	Not Suspect											Possible Suspect Material In Core
1st Floor	OP106B	Misc	Covebase Mastic & Glue	4"	Beige & Gray	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP106K	Ceiling	Acoustic Tile Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP106K	Wall(s)	Wallboard Joint Compound Concrete		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP106K	Floor	Carpet		Blue Purple	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP106K	Door/Door Frame	Wood/Metal		Bare/Beige	Not Suspect											Possible Suspect Material In Core
1st Floor	OP106K	Misc	Covebase Mastic & Glue	4"	Beige & Gray	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP106D	Ceiling	Acoustic Tile Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP106D	Wall(s)	Wallboard Joint Compound Concrete		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP106D	Floor	Carpet		Blue Purple	Not Detected	N/A	Y	N/A	N/A	N/A						

Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
1st Floor	OP106D	Door/Door Frame	Wood/Metal		Bare/Beige	Not Suspect											Possible Suspect Material In Core
1st Floor	OP106D	Misc	Covebase Mastic & Glue	4"	Beige & Gray	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP106E	Ceiling	Acoustic Tile Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP106E	Wall(s)	Wallboard Joint Compound Concrete		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP106E	Floor	Carpet		Blue Purple	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP106E	Door/Door Frame	Wood/Metal		Bare/Beige	Not Suspect											Possible Suspect Material In Core
1st Floor	OP106E	Misc	Covebase Mastic & Glue	4"	Beige & Gray	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP106F	Ceiling	Acoustic Tile Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP106F	Wall(s)	Wallboard Joint Compound Concrete		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP106F	Floor	Carpet		Blue Purple	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP106F	Door/Door Frame	Wood/Metal		Bare/Beige	Not Suspect											Possible Suspect Material In Core
1st Floor	OP106F	Misc	Covebase Mastic & Glue	4"	Beige & Gray	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP106G	Ceiling	Acoustic Tile Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP106G	Wall(s)	Wallboard Joint Compound Concrete		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP106G	Floor	Carpet		Blue Purple	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP106G	Door/Door Frame	Wood/Metal		Bare/Beige	Not Suspect											Possible Suspect Material In Core
1st Floor	OP106G	Misc	Covebase Mastic & Glue	4"	Beige & Gray	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP106H	Ceiling	Acoustic Tile Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP106H	Wall(s)	Wallboard Joint Compound Concrete		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP106H	Floor	Carpet		Blue Purple	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP106H	Door/Door Frame	Wood/Metal		Bare/Beige	Not Suspect											Possible Suspect Material In Core
1st Floor	OP106H	Misc	Covebase Mastic & Glue	4"	Beige & Gray	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP106M	Ceiling	Acoustic Tile Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP106M	Wall(s)	Wallboard Joint Compound Concrete		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP106M	Floor	Carpet		Blue Purple	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP106M	Door/Door Frame	Wood/Metal		Bare/Beige	Not Suspect											Possible Suspect Material In Core
1st Floor	OP106M	Misc	Covebase Mastic & Glue	4"	Beige & Gray	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP106J	Ceiling	Acoustic Tile Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP106J	Wall(s)	Wallboard Joint Compound Concrete		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP106J	Floor	Carpet		Blue Purple	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP106J	Door/Door Frame	Wood/Metal		Bare/Beige	Not Suspect											Possible Suspect Material In Core
1st Floor	OP106J	Misc	Covebase Mastic & Glue	4"	Beige & Gray	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP106N	Ceiling	Acoustic Tile Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP106N	Wall(s)	Wallboard Joint Compound Concrete		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP106N	Floor	Carpet		Blue Purple	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP106N	Door/Door Frame	Wood/Metal		Bare/Beige	Not Suspect											Possible Suspect Material In Core
1st Floor	OP106N	Misc	Covebase Mastic & Glue	4"	Beige & Gray	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP106C	Ceiling	Acoustic Tile Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP106C	Wall(s)	Wallboard Joint Compound Concrete		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP106C	Floor	Carpet		Blue Purple	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP106C	Door/Door Frame	Wood/Metal		Bare/Beige	Not Suspect											Possible Suspect Material In Core
1st Floor	OP106C	Misc	Covebase Mastic & Glue	4"	Beige & Gray	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP108	Ceiling	Acoustic Tile Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP108	Wall(s)	Wallboard Joint Compound Concrete		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP108	Floor	Resilient Floor Tile	12x12	Beige & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP108	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
1st Floor	OP108	Misc	Covebase Mastic & Glue	4"	Beige & Gray	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP111	Ceiling	Acoustic Tile Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP111	Wall(s)	Wallboard Joint Compound Concrete		Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP111	Floor	Carpet		Blue	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP111	Door/Door Frame	Wood/Metal		Off White/Off White	Not Suspect											Possible Suspect Material In Core
1st Floor	OP111	Misc	Covebase Mastic & Glue	4"	Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP110	Ceiling	Acoustic Tile Panel Pinhole	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP110	Wall(s)	Wallboard Joint Compound Concrete		Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP110	Floor	Carpet		Blue	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP110	Door/Door Frame	Wood/Metal		Off White/Off White	Not Suspect											Possible Suspect Material In Core

Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
1st Floor	OP110	Misc	Covebase Mastic & Glue	4"	Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP109	Ceiling	Acoustic Tile Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP109	Wall(s)	Wallboard Joint Compound Concrete		Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP109	Floor	Carpet		Blue /Purple	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP109	Door/Door Frame	Wood/Metal		Beige/Off White	Not Suspect											Possible Suspect Material In Core
1st Floor	OP109	Misc	Covebase Mastic & Glue	4"	Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP167	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP167	Wall(s)	Ceramic Tile	4X4	Off White	Not Suspect											
1st Floor	OP167	Floor	Resilient Floor Tile	12X12	Beige with Brown B/B	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP167	Door/Door Frame	Wood/Metal			Not Suspect											Possible Suspect Material In Core
1st Floor	OP167	Wall(s)	Covebase Mastic & Glue	4"	Light Brown & Tan Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP167	Misc	Ceramic Tile & Grout	4X4	Off White & Off White	Not Suspect											
1st Floor	OP165	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP165	Wall(s)	Ceramic Tile	4X4	Off White	Not Suspect											
1st Floor	OP165	Floor	Resilient Floor Tile	12X12	Beige with Brown B/B	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP165	Door/Door Frame	Wood/Metal			Not Suspect											Possible Suspect Material In Core
1st Floor	OP165	Misc	Covebase Mastic & Glue	4"	Light Brown & Tan Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP165	Misc	Ceramic Tile & Grout	4X4	Off White & Off White	Not Suspect											
1st Floor	OP168	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP168	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP168	Floor	Resilient Floor Tile	12X12	Tan with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP168	Door/Door Frame	Wood/Metal		Beige & Off White	Not Suspect											Possible Suspect Material In Core
1st Floor	OP168	Misc	Covebase Mastic	4"	Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP168	Wall(s)	Ceramic Tile	4X4	Off White	Not Suspect											
1st Floor	OP170	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP170	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP170	Floor	Resilient Floor Tile	12X12	Tan with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP170	Door/Door Frame	Wood/Metal		Beige & Off White	Not Suspect											Possible Suspect Material In Core
1st Floor	OP170	Misc	Covebase Mastic	4"	Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP170	Wall(s)	Ceramic Tile	4X4	Off White	Not Suspect											
1st Floor	OP172	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP172	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP172	Floor	Resilient Floor Tile	12X12	Tan with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP172	Door/Door Frame	Wood/Metal		Beige & Off White	Not Suspect											Possible Suspect Material In Core
1st Floor	OP172	Misc	Covebase Mastic	4"	Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP172	Wall(s)	Ceramic Tile	4X4	Off White	Not Suspect											
1st Floor	OP174	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP174	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP174	Floor	Resilient Floor Tile	12X12	Tan with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP174	Door/Door Frame	Wood/Metal		Beige & Off White	Not Suspect											Possible Suspect Material In Core
1st Floor	OP174	Misc	Covebase Mastic	4"	Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP174	Wall(s)	Ceramic Tile	4X4	Off White	Not Suspect											
1st Floor	OP181	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP181	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP181	Floor	Resilient Floor Tile	12X12	Tan with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP181	Door/Door Frame	Wood/Metal		Beige & Off White	Not Suspect											Possible Suspect Material In Core
1st Floor	OP181	Misc	Covebase Mastic	4"	Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP181	Wall(s)	Ceramic Tile	4X4	Off White	Not Suspect											
1st Floor	OP179	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP179	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP179	Floor	Resilient Floor Tile	12X12	Tan with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP179	Door/Door Frame	Wood/Metal		Beige & Off White	Not Suspect											Possible Suspect Material In Core
1st Floor	OP179	Misc	Covebase Mastic	4"	Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP179	Wall(s)	Ceramic Tile	4X4	Off White	Not Suspect											
1st Floor	OP178	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						

Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
1st Floor	OP178	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP178	Floor	Resilient Floor Tile	12X12	Tan with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP178	Door/Door Frame	Wood/Metal		Beige & Off White	Not Suspect											Possible Suspect Material In Core
1st Floor	OP178	Misc	Covebase Mastic	4"	Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP178	Wall(s)	Ceramic Tile	4X4	Off White	Not Suspect											
1st Floor	OP176	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP176	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP176	Floor	Resilient Floor Tile	12X12	Tan with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP176	Door/Door Frame	Wood/Metal		Beige & Off White	Not Suspect											Possible Suspect Material In Core
1st Floor	OP176	Misc	Covebase Mastic	4"	Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP176	Wall(s)	Ceramic Tile	4X4	Off White	Not Suspect											
1st Floor	OP177	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP177	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP177	Floor	Resilient Floor Tile	12X12	Tan with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP177	Door/Door Frame	Wood/Metal		Beige & Off White	Not Suspect											Possible Suspect Material In Core
1st Floor	OP177	Misc	Covebase Mastic	4"	Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP177	Wall(s)	Ceramic Tile	4X4	Off White	Not Suspect											
1st Floor	OP180	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP180	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP180	Floor	Resilient Floor Tile	12X12	Tan with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP180	Door/Door Frame	Wood/Metal		Beige & Off White	Not Suspect											Possible Suspect Material In Core
1st Floor	OP180	Misc	Covebase Mastic	4"	Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP180	Wall(s)	Ceramic Tile	4X4	Off White	Not Suspect											
1st Floor	OP182	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP182	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP182	Floor	Resilient Floor Tile	12X12	Tan with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP182	Door/Door Frame	Wood/Metal		Beige & Off White	Not Suspect											Possible Suspect Material In Core
1st Floor	OP182	Misc	Covebase Mastic	4"	Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP182	Wall(s)	Ceramic Tile	4X4	Off White	Not Suspect											
1st Floor	OP169	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP169	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP169	Floor	Resilient Floor Tile	12X12	Tan with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP169	Door/Door Frame	Wood/Metal		Beige & Off White	Not Suspect											Possible Suspect Material In Core
1st Floor	OP169	Misc	Covebase Mastic	4"	Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP169	Misc	Ceramic Tile	4X4	Off White	Not Suspect											
1st Floor	OP171	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP171	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP171	Floor	Resilient Floor Tile	12X12	Tan with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP171	Door/Door Frame	Wood/Metal		Beige & Off White	Not Suspect											Possible Suspect Material In Core
1st Floor	OP171	Misc	Covebase Mastic	4"	Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP171	Misc	Ceramic Tile	4X4	Off White	Not Suspect											
1st Floor	OP173	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP173	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP173	Floor	Resilient Floor Tile	12X12	Tan with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP173	Door/Door Frame	Wood/Metal		Beige & Off White	Not Suspect											Possible Suspect Material In Core
1st Floor	OP173	Misc	Covebase Mastic	4"	Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
1st Floor	OP173	Misc	Ceramic Tile	4X4	Off White	Not Suspect											
2nd Floor	OP216	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm			Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP216	Wall(s)	Wallboard Joint Compound		Green & Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP216	Floor	Resilient Floor Tile	12X12	Beige with Brown												
2nd Floor	OP216	Door/Door Frame	Wood/Metal		Beige & Beige	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP216	Misc	Covebase Mastic	4"	Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP216	Misc	Ceramic Tile	4X4	Off White & Off White	Not Suspect											
2nd Floor	OP218	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm			Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP218	Wall(s)	Wallboard Joint Compound		Green & Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP218	Floor	Resilient Floor Tile	12X12	Beige with Brown												
2nd Floor	OP218	Door/Door Frame	Wood/Metal		Beige & Beige	Not Suspect											Possible Suspect Material In Core

Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
2nd Floor	OP218	Roof	Covebase Mastic	4"	Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP218	Misc	Ceramic Tile	4X4	Off White & Off White	Not Suspect											
2nd Floor	OP210	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm			Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP210	Wall(s)	Wallboard Joint Compound		Green & Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP210	Floor	Rselient Floor Tile	12X12	Beige with Brown												
2nd Floor	OP210	Door/Door Frame	Wood/Metal		Beige & Beige	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP210	Misc	Covebase Mastic	4"	Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP210	Misc	Ceramic Tile	4X4	Off White & Off White	Not Suspect											
2nd Floor	OP227	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm			Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP227	Wall(s)	Wallboard Joint Compound		Green & Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP227	Floor	Rselient Floor Tile	12X12	Beige with Brown												
2nd Floor	OP227	Door/Door Frame	Wood/Metal		Beige & Beige	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP227	Misc	Covebase Mastic	4"	Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP227	Misc	Ceramic Tile	4X4	Off White & Off White	Not Suspect											
2nd Floor	OP225	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm			Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP225	Wall(s)	Wallboard Joint Compound		Green & Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP225	Floor	Rselient Floor Tile	12X12	Beige with Brown												
2nd Floor	OP225	Door/Door Frame	Wood/Metal		Beige & Beige	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP225	Misc	Covebase Mastic	4"	Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP225	Misc	Ceramic Tile	4X4	Off White & Off White	Not Suspect											
2nd Floor	OP211	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm			Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP211	Wall(s)	Wallboard Joint Compound		Green & Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP211	Floor	Rselient Floor Tile	12X12	Beige with Brown												
2nd Floor	OP211	Door/Door Frame	Wood/Metal		Beige & Beige	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP211	Misc	Covebase Mastic	4"	Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP211	Misc	Ceramic Tile	4X4	Off White & Off White	Not Suspect											
2nd Floor	OP204	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP204	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP204	Floor	Resilient Floor Tile	12X12	Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP204	Misc	Resilient Floor Tile	12X12	Seafoam Blue	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP204	Misc	Resilient Floor Tile	12x12	Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP204	Misc	Covebase Mastic	4"	Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP242	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP242	Wall(s)	Wallboard Joint Compound		Beige/green	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP242	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP242	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP242	Misc	Covebase Mastic & Glue	4"	Brwon & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP242	Misc	Ceramic Tile & Grout	4X4	White & White	Not Suspect											
2nd Floor	OP268	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X2		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP268	Wall(s)	Ceramic Tile & Grout	12X12	Beige & Beige	Not Suspect											
2nd Floor	OP268	Floor	Ceramic Tille & Grout	16X16	Tan Swirl & Black	Not Suspect											
2nd Floor	OP268	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP268	Misc	Accent Ceramic tile & Grout	1X1X8	Multi Brown & Beige	Not Suspect											
2nd Floor	OP269	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X2		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP269	Wall(s)	Ceramic Tile & Grout	12X12	Beige & Beige	Not Suspect											
2nd Floor	OP269	Floor	Ceramic Tille & Grout	16X16	Tan Swirl & Black	Not Suspect											
2nd Floor	OP269	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP269	Misc	Accent Ceramic tile & Grout	1X1X8	Multi Brown & Beige	Not Suspect											
2nd Floor	OP230	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP230	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP230	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP230	Door/Door Frame	Wood/Metal		Beige & Brown	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP230	Misc	Covebase Mastic	4"	Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP233	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP233	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP233	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						

Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
2nd Floor	OP233	Door/Door Frame	Wood/Metal		Beige & Brown	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP233	Misc	Covebase Mastic	4"	Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP234	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP234	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP234	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP234	Door/Door Frame	Wood/Metal		Beige & Brown	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP234	Misc	Covebase Mastic	4"	Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP237	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP237	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP237	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP237	Door/Door Frame	Wood/Metal		Beige & Brown	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP237	Misc	Covebase Mastic	4"	Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP208	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP208	Wall(s)	Wallboard Joint Compound		Green & Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP208	Floor	Resilient Floor Tile	12X12	Tan with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP208	Door/Door Frame	Wood/Metal		Beige & Beige	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP208	Misc	Covebase Mastic	4"	Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP208	Wall(s)	Ceramic Tile	4X4	Off White	Not Suspect											
2nd Floor	OP209	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP209	Wall(s)	Wallboard Joint Compound		Green & Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP209	Floor	Resilient Floor Tile	12X12	Tan with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP209	Door/Door Frame	Wood/Metal		Beige & Beige	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP209	Misc	Covebase Mastic	4"	Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP209	Misc	Ceramic Tile	4X4	Off White	Not Suspect											
2nd Floor	OP219	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP219	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP219	Floor	Resilient Floor Tile	12X12	Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP219	Door/Door Frame	Wood/Metal		Beige & Beige	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP219	Misc	Covebase Mastic	4"	Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP202	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP202	Wall(s)	Wallboard Joint Compound		Beige & Green	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP202	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP202	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP202	Misc	Covebase Mastic Glue	4"	Beige & off White/ Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP202	Misc	Ceramic Tile & Grout	4X4	White & Off White	Not Suspect											
2nd Floor	OP205	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP205	Wall(s)	Wallboard Joint Compound		Beige & Green	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP205	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP205	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP205	Misc	Covebase Mastic Glue	4"	Beige & off White/ Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP205	Misc	Ceramic Tile & Grout	4X4	White & Off White	Not Suspect											
2nd Floor	OP206	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP206	Wall(s)	Wallboard Joint Compound		Beige & Green	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP206	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP206	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP206	Misc	Covebase Mastic Glue	4"	Beige & off White/ Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP206	Misc	Ceramic Tile & Grout	4X4	White & Off White	Not Suspect											
2nd Floor	OP207	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP207	Wall(s)	Wallboard Joint Compound		Beige & Green	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP207	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP207	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP207	Misc	Covebase Mastic Glue	4"	Beige & off White/ Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP207	Misc	Ceramic Tile & Grout	4X4	White & Off White	Not Suspect											

Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
2nd Floor	OP201	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP201	Wall(s)	Wallboard Joint Compound		Beige & Green	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP201	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP201	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP201	Misc	Covebase Mastic Glue	4"	Beige & off White/ Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP201	Misc	Ceramic Tile & Grout	4X4	White & Off White	Not Suspect											
2nd Floor	2 Fac 1	Ceiling	Wallboard Joint Compound		White	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	2 Fac 1	Wall(s)	Wallboard Joint Compound		White	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	2 Fac 1	Floor	Resilient Floor Tile	12X12	Seafoam Blue	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	2 Fac 1	Door/Door Frame	Wood/Wood		B/B	Not Suspect											Possible Suspect Material In Core
2nd Floor	2 Fac 1	Misc	Covebase Mastic & Glue		? & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP213 Exam Rod	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP213 Exam Rod	Wall(s)	Wallboard Joint Compound			Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP213 Exam Rod	Floor	Resilient Floor Tile	12X12	Beige/ Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP213 Exam Rod	Door/Door Frame	Wood/Metal		Beige & beige	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP213 Exam Rod	Misc	Covebase Mastic	4"	Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP212 Exam Rod	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP212 Exam Rod	Wall(s)	Wallboard Joint Compound			Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP212 Exam Rod	Floor	Resilient Floor Tile	12X12	Beige/ Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP212 Exam Rod	Door/Door Frame	Wood/Metal		Beige & beige	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP212 Exam Rod	Misc	Covebase Mastic	4"	Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP217 Exam Rod	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP217 Exam Rod	Wall(s)	Wallboard Joint Compound			Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP217 Exam Rod	Floor	Resilient Floor Tile	12X12	Beige/ Brown	Y	N/A	Y	No	Good	no	no	yes		yes		
2nd Floor	OP217 Exam Rod	Door/Door Frame	Wood/Metal		Beige & beige	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP217 Exam Rod	Misc	Covebase Mastic	4"	Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP215 Exam Rod	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP215 Exam Rod	Wall(s)	Wallboard Joint Compound			Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP215 Exam Rod	Floor	Resilient Floor Tile	12X12	Beige/ Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP215 Exam Rod	Door/Door Frame	Wood/Metal		Beige & beige	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP215 Exam Rod	Misc	Covebase Mastic	4"	Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP245	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP245	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP245	Floor	Resilient Floor Tile	12X12	Seafoam Blue	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP245	Misc	Covebase Mastic	4"		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP257	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP257	Wall(s)	Wallboard Joint Compound		Green & beige	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP257	Floor	Resilient Floor Tile	12X12	Tan with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP257	Door/Door Frame	Wood/Metal		Beige & beige	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP257	Roof	Covebase Mastic	4"	Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP263	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP263	Wall(s)	Wallboard Joint Compound		Green & beige	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP263	Floor	Resilient Floor Tile	12X12	Tan with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP263	Door/Door Frame	Wood/Metal		Beige & beige	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP263	Misc	Covebase Mastic	4"	Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP243	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP243	Wall(s)	Wallboard Joint Compound		Green & beige	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP243	Floor	Resilient Floor Tile	12X12	Tan with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP243	Door/Door Frame	Wood/Metal		Beige & beige	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP243	Misc	Covebase Mastic	4"	Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP262	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP262	Wall(s)	Wallboard Joint Compound		Green & beige	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP262	Floor	Resilient Floor Tile	12X12	Tan with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP262	Door/Door Frame	Wood/Metal		Beige & beige	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP262	Misc	Covebase Mastic	4"	Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP262	Misc	Ceramic Tile	4X4	Off White	Not Suspect											

Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
2nd Floor	OP231	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP231	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP231	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP231	Door/Door Frame	Wood/Metal		Beige & beige	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP231	Misc	Covebase Mastic	4"	Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP232	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP232	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP232	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP232	Door/Door Frame	Wood/Metal		Beige & beige	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP232	Misc	Covebase Mastic	4"	Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP235	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP235	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP235	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP235	Door/Door Frame	Wood/Metal		Beige & beige	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP235	Misc	Covebase Mastic	4"	Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP236	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP236	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP236	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP236	Door/Door Frame	Wood/Metal		Beige & beige	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP236	Misc	Covebase Mastic	4"	Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP240	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP240	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP240	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP240	Door/Door Frame	Wood/Metal		Beige & beige	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP240	Misc	Covebase Mastic	4"	Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP238	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP238	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP238	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP238	Door/Door Frame	Wood/Metal		Beige & beige	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP238	Misc	Covebase Mastic	4"	Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP252	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP252	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP252	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP252	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP252	Misc	Covebase Mastic & Glue	4"	Brown & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP252	Misc	Ceramic Tile & Grout	4X4	Off White & White	Not Suspect											
2nd Floor	OP253	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP253	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP253	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP253	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP253	Misc	Covebase Mastic & Glue	4"	Brown & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP253	Misc	Ceramic Tile & Grout	4X4	Off White & White	Not Suspect											
2nd Floor	OP251	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP251	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP251	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP251	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP251	Misc	Covebase Mastic & Glue	4"	Brown & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP251	Misc	Ceramic Tile & Grout	4X4	Off White & White	Not Suspect											
2nd Floor	OP237	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP237	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP237	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP237	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP237	Misc	Covebase Mastic & Glue	4"	Brown & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP237	Misc	Ceramic Tile & Grout	4X4	Off White & White	Not Suspect											
2nd Floor	OP234	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP234	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP234	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						

Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
2nd Floor	OP234	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP234	Misc	Covebase Mastic & Glue	4"	Brown & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP234	Misc	Ceramic Tile & Grout	4X4	Off White & White	Not Suspect											
2nd Floor	OP225	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP225	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP225	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP225	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP225	Misc	Covebase Mastic & Glue	4"	Brown & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP225	Misc	Ceramic Tile & Grout	4X4	Off White & White	Not Suspect											
2nd Floor	OP229	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP229	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP229	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP229	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP229	Misc	Covebase Mastic & Glue	4"	Brown & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP229	Misc	Ceramic Tile & Grout	4X4	Off White & White	Not Suspect											
2nd Floor	OP226	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP226	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP226	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP226	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP226	Misc	Covebase Mastic & Glue	4"	Brown & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP226	Misc	Ceramic Tile & Grout	4X4	Off White & White	Not Suspect											
2nd Floor	OP224	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP224	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP224	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP224	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP224	Misc	Covebase Mastic & Glue	4"	Brown & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP224	Misc	Ceramic Tile & Grout	4X4	Off White & White	Not Suspect											
2nd Floor	OP223	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP223	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP223	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP223	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP223	Misc	Covebase Mastic & Glue	4"	Brown & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP223	Misc	Ceramic Tile & Grout	4X4	Off White & White	Not Suspect											
2nd Floor	OP248	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP248	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP248	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP248	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP248	Misc	Covebase Mastic & Glue	4"	Brown & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP248	Misc	Ceramic Tile & Grout	4X4	Off White & White	Not Suspect											
2nd Floor	OP249	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP249	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP249	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP249	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP249	Misc	Covebase Mastic & Glue	4"	Brown & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP249	Misc	Ceramic Tile & Grout	4X4	Off White & White	Not Suspect											
2nd Floor	OP247	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP247	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP247	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP247	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP247	Misc	Covebase Mastic & Glue	4"	Brown & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP247	Misc	Ceramic Tile & Grout	4X4	Off White & White	Not Suspect											
2nd Floor	OP222	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP222	Wall(s)	Wallboard Joint Compound		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP222	Floor	Resilient Floor Tile	12X12	Tan & Seafoam Blue	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP222	Door/Door Frame	Resilient Floor Tile	12X12	Tan & Seafoam Blue	Not Detected	N/A	Y	N/A	N/A	N/A						Possible Suspect Material In Core
2nd Floor	OP222	Misc	Covebase Mastic & Glue	4"	Beige & Gray/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP204A	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						

Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
2nd Floor	OP204A	Wall(s)	Wallboard Joint Compound		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP204A	Floor	Resilient Floor Tile	12X12	Tan & Seafoam Blue	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP204A	Door/Door Frame	Resilient Floor Tile	12X12	Tan & Seafoam Blue	Not Detected	N/A	Y	N/A	N/A	N/A						Possible Suspect Material In Core
2nd Floor	OP204A	Misc	Covebase Mastic & Glue	4"	Beige & Gray/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-7	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-7	Wall(s)	Wallboard Joint Compound		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-7	Floor	Resilient Floor Tile	12X12	Tan & Seafoam Blue	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-7	Door/Door Frame	Resilient Floor Tile	12X12	Tan & Seafoam Blue	Not Detected	N/A	Y	N/A	N/A	N/A						Possible Suspect Material In Core
2nd Floor	CC126OP2-7	Misc	Covebase Mastic & Glue	4"	Beige & Gray/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP246	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP246	Wall(s)	Wallboard Joint Compound		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP246	Floor	Resilient Floor Tile	12X12	Seafoam/Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP246	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP246	Misc	Covebase Mastic & Glue	4"	Gray & Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP258	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP258	Wall(s)	Wallboard Joint Compound		Beige/Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP258	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP258	Door/Door Frame	Wood/Metal		b/b	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP258	Misc	Covebase Mastic & Glue	4"	Beige & Tan/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP258	Wall(s)	Ceramic Tile & Grout	4X4	White & White	Not Suspect											
2nd Floor	OP255	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP255	Wall(s)	Wallboard Joint Compound		Beige/Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP255	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP255	Door/Door Frame	Wood/Metal		b/b	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP255	Misc	Covebase Mastic & Glue	4"	Beige & Tan/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP255	Wall(s)	Ceramic Tile & Grout	4X4	White & White	Not Suspect											
2nd Floor	OP256	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP256	Wall(s)	Wallboard Joint Compound		Beige/Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP256	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP256	Door/Door Frame	Wood/Metal		b/b	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP256	Misc	Covebase Mastic & Glue	4"	Beige & Tan/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP256	Wall(s)	Ceramic Tile & Grout	4X4	White & White	Not Suspect											
2nd Floor	OP260	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP260	Wall(s)	Wallboard Joint Compound		Beige/Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP260	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP260	Door/Door Frame	Wood/Metal		b/b	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP260	Misc	Covebase Mastic & Glue	4"	Beige & Tan/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP260	Wall(s)	Ceramic Tile & Grout	4X4	White & White	Not Suspect											
2nd Floor	OP261	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP261	Wall(s)	Wallboard Joint Compound		Beige/Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP261	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP261	Door/Door Frame	Wood/Metal		b/b	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP261	Misc	Covebase Mastic & Glue	4"	Beige & Tan/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP261	Wall(s)	Ceramic Tile & Grout	4X4	White & White	Not Suspect											
2nd Floor	OP264	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP264	Wall(s)	Wallboard Joint Compound		Beige/Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP264	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP264	Door/Door Frame	Wood/Metal		b/b	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP264	Misc	Covebase Mastic & Glue	4"	Beige & Tan/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP264	Wall(s)	Ceramic Tile & Grout	4X4	White & White	Not Suspect											
2nd Floor	OP265	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP265	Wall(s)	Wallboard Joint Compound		Beige/Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP265	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP265	Door/Door Frame	Wood/Metal		b/b	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP265	Misc	Covebase Mastic & Glue	4"	Beige & Tan/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP265	Wall(s)	Ceramic Tile & Grout	4X4	White & White	Not Suspect											
2nd Floor	OP259	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						

Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
2nd Floor	OP259	Wall(s)	Wallboard Joint Compound		Beige/Tan	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP259	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP259	Door/Door Frame	Wood/Metal		b/b	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP259	Misc	Covebase Mastic & Glue	4"	Beige & Tan/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP259	Wall(s)	Ceramic Tile & Grout	4X4	White & White	Not Suspect											
2nd Floor	OP266	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP266	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP266	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP266	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP266	Misc	Covebase Mastic & Glue	4"	Brown & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP254	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP254	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP254	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP254	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP254	Misc	Covebase Mastic & Glue	4"	Brown & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP211	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP211	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP211	Floor	Resilient Floor Tile	12X12	Beige with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP211	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP211	Misc	Covebase Mastic & Glue	4"	Brown & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP233 Exam Rod	Door/Door Frame	NO ACCESS														Possible Suspect Material In Core
2nd Floor	OP239 Exam Rod	Door/Door Frame	NO ACCESS														Possible Suspect Material In Core
2nd Floor	OP240 Exam Rod	Door/Door Frame	NO ACCESS														Possible Suspect Material In Core
2nd Floor	OP200 Exam Rod	Door/Door Frame	NO ACCESS														Possible Suspect Material In Core
2nd Floor	OP228 Exam Rod	Door/Door Frame	NO ACCESS														Possible Suspect Material In Core
2nd Floor	OP270 Exam Rod	Door/Door Frame	NO ACCESS														Possible Suspect Material In Core
2nd Floor	OP236 Exam Rod	Door/Door Frame	NO ACCESS														Possible Suspect Material In Core
2nd Floor	OP263 Exam Rod	Door/Door Frame	NO ACCESS														Possible Suspect Material In Core
2nd Floor	OP262 Exam Rod	Door/Door Frame	NO ACCESS														Possible Suspect Material In Core
2nd Floor	OP243 Exam Rod	Door/Door Frame	NO ACCESS														Possible Suspect Material In Core
2nd Floor	OP235 Exam Rod	Door/Door Frame	NO ACCESS														Possible Suspect Material In Core
2nd Floor	OP232 Exam Rod	Door/Door Frame	NO ACCESS														Possible Suspect Material In Core
2nd Floor	OP231 Exam Rod	Door/Door Frame	NO ACCESS														Possible Suspect Material In Core
2nd Floor	OP230 Exam Rod	Door/Door Frame	NO ACCESS														Possible Suspect Material In Core
2nd Floor	CC126OP2-14	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-14	Wall(s)	Wallboard Joint Compound Concrete		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-14	Floor	Resilient Floor Tile	12X12	Seafoam Beige & Seafoam Blue	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-14	Door/Door Frame	Resilient Floor Tile			Not Detected	N/A	Y	N/A	N/A	N/A						Possible Suspect Material In Core
2nd Floor	CC126OP2-14	Misc	Covebase Mastic & Glue	4"	Beige & Gray	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-09	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-09	Wall(s)	Wallboard Joint Compound Concrete		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-09	Floor	Resilient Floor Tile	12X12	Seafoam Beige & Seafoam Blue	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-09	Door/Door Frame	Resilient Floor Tile			Not Detected	N/A	Y	N/A	N/A	N/A						Possible Suspect Material In Core
2nd Floor	CC126OP2-09	Misc	Covebase Mastic & Glue	4"	Beige & Gray	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-13	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-13	Wall(s)	Wallboard Joint Compound Concrete		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-13	Floor	Resilient Floor Tile	12X12	Seafoam Beige & Seafoam Blue	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-13	Door/Door Frame	Resilient Floor Tile			Not Detected	N/A	Y	N/A	N/A	N/A						Possible Suspect Material In Core
2nd Floor	CC126OP2-13	Misc	Covebase Mastic & Glue	4"	Beige & Gray	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-15	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-15	Wall(s)	Wallboard Joint Compound Concrete		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-15	Floor	Resilient Floor Tile	12X12	Seafoam Beige & Seafoam Blue	Not Detected	N/A	Y	N/A	N/A	N/A						

Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
2nd Floor	CC126OP2-15	Door/Door Frame	Resilient Floor Tile			Not Detected	N/A	Y	N/A	N/A	N/A						Possible Suspect Material In Core
2nd Floor	CC126OP2-15	Misc	Covebase Mastic & Glue	4"	Beige & Gray	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-12	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-12	Wall(s)	Wallboard Joint Compound Concrete		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-12	Floor	Resilient Floor Tile	12X12	Seafoam Beige & Seafoam Blue	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-12	Door/Door Frame	Resilient Floor Tile			Not Detected	N/A	Y	N/A	N/A	N/A						Possible Suspect Material In Core
2nd Floor	CC126OP2-12	Misc	Covebase Mastic & Glue	4"	Beige & Gray	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-11	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-11	Wall(s)	Wallboard Joint Compound Concrete		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-11	Floor	Resilient Floor Tile	12X12	Seafoam Beige & Seafoam Blue	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-11	Door/Door Frame	Resilient Floor Tile			Not Detected	N/A	Y	N/A	N/A	N/A						Possible Suspect Material In Core
2nd Floor	CC126OP2-11	Misc	Covebase Mastic & Glue	4"	Beige & Gray	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-10	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-10	Wall(s)	Wallboard Joint Compound Concrete		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-10	Floor	Resilient Floor Tile	12X12	Seafoam Beige & Seafoam Blue	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-10	Door/Door Frame	Resilient Floor Tile			Not Detected	N/A	Y	N/A	N/A	N/A						Possible Suspect Material In Core
2nd Floor	CC126OP2-10	Misc	Covebase Mastic & Glue	4"	Beige & Gray	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-2	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-2	Wall(s)	Wallboard Joint Compound Concrete		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-2	Floor	Resilient Floor Tile	12X12	Seafoam Beige & Seafoam Blue	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-2	Door/Door Frame	Resilient Floor Tile			Not Detected	N/A	Y	N/A	N/A	N/A						Possible Suspect Material In Core
2nd Floor	CC126OP2-2	Misc	Covebase Mastic & Glue	4"	Beige & Gray	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-3	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-3	Wall(s)	Wallboard Joint Compound Concrete		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-3	Floor	Resilient Floor Tile	12X12	Seafoam Beige & Seafoam Blue	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-3	Door/Door Frame	Resilient Floor Tile			Not Detected	N/A	Y	N/A	N/A	N/A						Possible Suspect Material In Core
2nd Floor	CC126OP2-3	Misc	Covebase Mastic & Glue	4"	Beige & Gray	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-4	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-4	Wall(s)	Wallboard Joint Compound Concrete		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-4	Floor	Resilient Floor Tile	12X12	Seafoam Beige & Seafoam Blue	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-4	Door/Door Frame	Resilient Floor Tile			Not Detected	N/A	Y	N/A	N/A	N/A						Possible Suspect Material In Core
2nd Floor	CC126OP2-4	Misc	Covebase Mastic & Glue	4"	Beige & Gray	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-1	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-1	Wall(s)	Wallboard Joint Compound Concrete		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-1	Floor	Resilient Floor Tile	12X12	Seafoam Beige & Seafoam Blue	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-1	Door/Door Frame	Resilient Floor Tile			Not Detected	N/A	Y	N/A	N/A	N/A						Possible Suspect Material In Core
2nd Floor	CC126OP2-1	Misc	Covebase Mastic & Glue	4"	Beige & Gray	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-5	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-5	Wall(s)	Wallboard Joint Compound Concrete		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-5	Floor	Resilient Floor Tile	12X12	Seafoam Beige & Seafoam Blue	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-5	Door/Door Frame	Resilient Floor Tile			Not Detected	N/A	Y	N/A	N/A	N/A						Possible Suspect Material In Core
2nd Floor	CC126OP2-5	Misc	Covebase Mastic & Glue	4"	Beige & Gray	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-6	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-6	Wall(s)	Wallboard Joint Compound Concrete		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-6	Floor	Resilient Floor Tile	12X12	Seafoam Beige & Seafoam Blue	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-6	Door/Door Frame	Resilient Floor Tile			Not Detected	N/A	Y	N/A	N/A	N/A						Possible Suspect Material In Core
2nd Floor	CC126OP2-6	Misc	Covebase Mastic & Glue	4"	Beige & Gray	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-8	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						

Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
2nd Floor	CC126OP2-8	Wall(s)	Wallboard Joint Compound Concrete		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-8	Floor	Resilient Floor Tile	12X12	Seafoam Beige & Seafoam Blue	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	CC126OP2-8	Door/Door Frame	Resilient Floor Tile			Not Detected	N/A	Y	N/A	N/A	N/A						Possible Suspect Material In Core
2nd Floor	CC126OP2-8	Misc	Covebase Mastic & Glue	4"	Beige & Gray	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	2 FAC 2	Ceiling	Wallboard Joint Compound		White	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	2 FAC 2	Wall(s)	Wallboard Joint Compound		White	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	2 FAC 2	Floor	Resilient Floor Tile	12X12	Seafoam Blue	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	2 FAC 2	Door/Door Frame	Wood/Wood		B/B	Not Suspect											Possible Suspect Material In Core
2nd Floor	2 FAC 2	Misc	Covebase Mastic & Glue		? & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	2 FAC 3	Ceiling	Wallboard Joint Compound		White	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	2 FAC 3	Wall(s)	Wallboard Joint Compound		White	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	2 FAC 3	Floor	Resilient Floor Tile	12X12	Seafoam Blue	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	2 FAC 3	Door/Door Frame	Wood/Wood		B/B	Not Suspect											Possible Suspect Material In Core
2nd Floor	2 FAC 3	Misc	Covebase Mastic & Glue		? & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	Elevator Lobby O	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	Elevator Lobby O	Wall(s)	Wall Paper Burlap x2		Tan & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	Elevator Lobby O	Floor	Resilient Floor Tile	12X12	Seafoam Beige & Seafoam Blue	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	Elevator Lobby O	Door/Door Frame	Resilient Floor Tile			Not Detected	N/A	Y	N/A	N/A	N/A						Possible Suspect Material In Core
2nd Floor	Elevator Lobby O	Misc	Covebase Mastic & Glue	4"	Gray & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP267	Ceiling	Hard Drywall		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP267	Wall(s)	Wallboard Joint Compound Concrete		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP267	Floor	Carpet		Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP267	Door/Door Frame	Wood/Metal		Bare/Beige	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP267	Ceiling	Acoustic Ceiling Panel Pinhole Big Worm	1X1	White Lay in System no glue	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP267	Misc	Covebase Mastic & Glue	4"	Beige & Gray	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP267A	Ceiling	Hard Drywall		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP267A	Wall(s)	Wallboard Joint Compound Concrete		Beige/Green	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP267A	Floor	Carpet		Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP267A	Door/Door Frame	Wood/Metal		Bare/Beige	Not Suspect											Possible Suspect Material In Core
2nd Floor	OP267A	Misc	Acoustic Ceiling Panel Pinhole Big Worm	1X1	White Lay in System no glue	Not Detected	N/A	Y	N/A	N/A	N/A						
2nd Floor	OP267A	Misc	Covebase Mastic & Glue	4"	Beige & Gray	Not Detected	N/A	Y	N/A	N/A	N/A						
3rd Floor	CC126OP3-01	Ceiling	Acoustic Ceiling Tile	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
3rd Floor	CC126OP3-01	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
3rd Floor	CC126OP3-01	Floor	Resilient Floor Tile x2	12X12	Tan & Brown with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
3rd Floor	CC126OP3-01	Misc	Covebase Mastic & Glue	4"	Beige & Gray	Not Detected	N/A	Y	N/A	N/A	N/A						
3rd Floor	Elev Lobby 3rd Fl	Ceiling	Acoustic Ceiling Tile Pin Big Worm	2X4		Not Detected	N/A	Y	N/A	N/A	N/A						
3rd Floor	Elev Lobby 3rd Fl	Wall(s)	Wallboard Joint Compound Concrete		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
3rd Floor	Elev Lobby 3rd Fl	Floor	Resilient Floor Tile x2	12X12	Tan & Brown with Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
3rd Floor	Elev Lobby 3rd Fl	Wall(s)	Wall Paper Burlap		Tan & Brown	Not Detected	N/A	Y	N/A	N/A	N/A						
3rd Floor	Elev Lobby 3rd Fl	Misc	Covebase Mastic & Glue	4"	Beige & Gray	Not Detected	N/A	Y	N/A	N/A	N/A						
3rd Floor	Elevator Machine	Ceiling	Acoustic Ceiling Tile Pin Big Worm			Not Detected	N/A	Y	N/A	N/A	N/A						
3rd Floor	Elevator Machine	Wall(s)	Wallboard Joint Compound Concrete		Beige	Not Detected	N/A	Y	N/A	N/A	N/A						
3rd Floor	Elevator Machine	Floor	Resilient Floor Tile	12X12	White with Gray	Not Detected	N/A	Y	N/A	N/A	N/A						
3rd Floor	Elevator Machine	Door/Door Frame	Wood/Metal		B/B	Not Suspect											Possible Suspect Material In Core
3rd Floor	Elevator Machine	Misc	Covebase Mastic & Glue	4"	Beige & Gray/Brown	Not Detected	N/A	Y	N/A	N/A	N/A						