

Floor	Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present?	Previously sampled?	Contractor Sampled (Y/N)	Contractor Sample No	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
1st Floor	122A	Floor	Resilient Flooring Tile	12x12	Beige	POS	Yes	Yes	VALB-128-F2.1	no	Good	No	No	yes	no	no	yes
1st Floor	122A	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	122A	Door/Door Frame	Wood and Metal		White/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	122A	Misc	Cove Base	4"	Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	122A	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	122B	Floor	Resilient Flooring Tile	12x12	Beige	POS	Yes	Yes	VALB-128-F2.1	no	Good	No	No	yes	no	no	yes
1st Floor	122B	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	122B	Door/Door Frame	Wood and Metal		White/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	122B	Misc	Cove Base	4"	Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	122B	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	122C	Floor	Resilient Flooring Tile	12x12	Beige	POS	Yes	Yes	VALB-128-F2.1	no	Good	No	No	yes	no	no	yes
1st Floor	122C	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	122C	Door/Door Frame	Wood and Metal		White/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	122C	Misc	Cove Base	4"	Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	122C	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	127A	Floor	Ceramic Tile	2x2	Brown	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	127A	Ceiling	Plaster			None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	127A	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	NN	N/A	N/A	N/A
1st Floor	127A	Misc	Drywall and Joint Compound		Gray and White	None Detected	Yes	Yes	VALB-128-C1			N/A	N/A	N	N/A	N/A	N/A
1st Floor	127A	Wall(s)	Ceramic Tile	4x4	Beige/Yellow	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	127A	Wall(s)	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	128 FEC 1-3	Floor	Resilient Flooring Tile	12x12	Seafoam Blue	None Detected	No	YES	VALB-128-F1			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	128 FEC 1-3	Door/Door Frame	Wood and Metal		Off Wite/Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	128 FEC 1-3	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	128 FEC 1-3	Wall(s)	Wallboard w/ Joint Compound		Off White	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	128 FEC 1-4	Floor	Concrete		Bare	None Detected		N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	128 FEC 1-4	Ceiling	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	128 FEC 1-4	Door/Door Frame	Wood and Metal		Beige/Brown	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	128 FEC 1-4	Misc	Mastic (No Cove Base)		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	128 FEC 1-4	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	128 FEC-1-1	Floor	Resilient Flooring Tile	12x12	Seafoam Blue	None Detected	No	YES	VALB-128-F1			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	128 FEC-1-1	Door/Door Frame	Wood and Metal		Beige/Off WHite	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	128 FEC-1-1	Misc	Mastic No Cove Base		Brown	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	128 FEC-1-1	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	128 FEC-2-1	Floor	Resilient Flooring Tile	12x12	Seafoam Blue	None Detected	No	YES	VALB-128-F1			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	128 FEC-2-1	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	128 FEC-2-1	Wall(s)	Wallboard w/ Joint Compound		Off White	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	128B	Floor	Resilient Flooring Tile	12x12	Beige	POS	Yes	Yes	VALB-128-F2.1	no	Good	No	No	yes	no	no	yes
1st Floor	128B	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	128B	Door/Door Frame	Wood and Metal		White/Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	128B	Misc	Cove Base	4"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A

Floor	Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present?	Previously sampled?	Contractor Sampled (Y/N)	Contractor Sample No	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
1st Floor	128B	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	128C	Floor	Resilient Flooring Tile	12x12	Beige	POS	Yes	Yes	VALB-128-F2.1	no	Good	No	No	yes	no	no	yes
1st Floor	128C	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	128C	Door/Door Frame	Wood and Metal		White/Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	128C	Misc	Cove Base	4"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	128C	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes

Floor	Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present?	Previously sampled?	Contractor Sampled (Y/N)	Contractor Sample No	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
1st Floor	128-FEC 1-2	Floor	Resilient Flooring Tile	9x9	White w/Olive	POS	No	Yes	VALB-128-F4	no	Good	No	No	yes	No	No	yes
1st Floor	128-FEC 1-2	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	128-FEC 1-2	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	128-FEC 1-2	Wall(s)	Wallboard w/ Joint Compound		Off White	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	146A	Floor	Non Skid		Green	Not suspect	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	146A	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	146A	Wall(s)	Ceramic Tile	4x4	Tan	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A101	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A101	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A101	Door/Door Frame	Wood and Metal		Beige/Brown	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A101	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A101	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	A102	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A102	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A102	Door/Door Frame	Wood and Metal		Beige/Brown	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A102	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A102	Misc	TSI		Gray	POS	Yes	No	N/A	Yes	Good	No	No	No	Yes	No	No
1st Floor	A102	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	A103	Floor	Ceramic Tile	2x2	Green	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A103	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A103	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A103	Wall(s)	Ceramic Tile	4x4	Off White/Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A103	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	A110	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A110	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A110	Door/Door Frame	Wood and Metal		Beige/Brown	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A110	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A110	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	A110	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	A112	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A112	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A112	Door/Door Frame	Wood and Metal		Beige/Brown	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A112	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A112	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	A113	Floor	Ceramic Tile	2x2	Gray	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A			
1st Floor	A113	Ceiling	Plaster			None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A113	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A

Floor	Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present?	Previously sampled?	Contractor Sampled (Y/N)	Contractor Sample No	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
1st Floor	A113	Misc	Ceramic Tile	4x4	Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A113	Wall(s)	Plaster		Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A114	Floor	Ceramic Tile	2x2	Gray	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A114	Ceiling	Plaster			None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A114	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A114	Wall(s)	Ceramic Tile	4x4	Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A

Floor	Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present?	Previously sampled?	Contractor Sampled (Y/N)	Contractor Sample No	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
1st Floor	A114	Wall(s)	Plaster		Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A116	Floor	Carpet		Tan	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A116	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A116	Door/Door Frame	Wood and Metal		White/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A116	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	A116A	Floor	Ceramic Tile	1x1	Green/Tan	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A116A	Ceiling	Plaster			None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A116A	Door/Door Frame	Wood and Metal		White/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A116A	Misc	Cove Base - Ceramic Tile	2x2	Green	Not Suspect	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A116A	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	A116B	Floor	Carpet		Tan	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A116B	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A116B	Door/Door Frame	Wood and Metal		White/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A116C	Floor	Carpet		Tan	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A116C	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A116C	Door/Door Frame	Wood and Metal		White/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A116C	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	A118 and A119	Floor	Carpet		Brown	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A118 and A119	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A118 and A119	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A118 and A119	Misc	Cove Base	4"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A118 and A119	Misc	Resilient Floor Tile and Mastic(under carpet)		Gray and Black	POS	Yes	N/A	N/A	No	fair	No	No	No	No	No	yes
1st Floor	A118 and A119	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	A120	Floor	Ceramic Tile	1x1	Gray	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A120	Door/Door Frame	Wood and Metal		Off White/Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A120	Wall(s)	Ceramic Tile	4x4	Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A120	Wall(s)	Plaster		Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A122	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A122	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A122	Door/Door Frame	Wood and Metal		Beige/Brown	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A122	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A122	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	A122A	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A122A	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A122A	Door/Door Frame	Wood and Metal		Beige/Brown	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A122A	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A

Floor	Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present?	Previously sampled?	Contractor Sampled (Y/N)	Contractor Sample No	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
1st Floor	A122a	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	A123	Floor	Resilient Flooring Tile	12x12	Seafoam Blue	None Detected	No	YES	VALB-128-F1			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A123	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4	White	None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A123	Door/Door Frame	Wood and Metal		Beige/Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A123	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A123	Misc	Firestop		Red	None Detected	No	Y	VALB-128-M3			N/A	N/A	N/A	N/A	N/A	NA
1st Floor	A123	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes

Floor	Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present?	Previously sampled?	Contractor Sampled (Y/N)	Contractor Sample No	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
1st Floor	A123A	Floor	Ceramic Tile	2x2	Pink	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A123A	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A123A	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A123A	Wall(s)	Ceramic Tile	4x4	Off White/Pink	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A123A	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	A126	Floor	Resilient Flooring Tile	12x12	Seafoam Blue	None Detected	No	YES	VALB-128-F1			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A126	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A126	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A126	Misc	Covebase and Mastic	4"	Tan and Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A126	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	A126G	Floor	Resilient Flooring Tile	12x12	Seafoam Blue	None Detected	No	YES	VALB-128-F1			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A126G	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A126G	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A126G	Misc	Cove Base	4"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A126G	Wall(s)	Concrete		Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A127E	Floor	Ceramic Tile	2x2	Brown	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A127E	Ceiling	Plaster			None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A127E	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A127E	Wall(s)	Ceramic Tile	4x4	Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A127E	Wall(s)	Plaster		Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A129	Floor	Resilient Flooring Tile with Mastic	12x12	Seafoam Blue	None Detected	No	YES	VALB-128-F1			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A129	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A129	Door/Door Frame	Metal and Metal		Blue/Off White	Not suspect	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A129	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A129	Misc	Resilient Flooring Tile	12x12	White w/Gray	None Detected		N/A	VALB-127-F4			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A129	Wall(s)	Ceramic Tile	4x4	Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A129	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	A130	Floor	Resilient Flooring Tile	12x12	Seafoam Blue	None Detected	No	YES	VALB-128-F1			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A130	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A130	Door/Door Frame	Metal and Metal		Blue/Off White	Not suspect	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A130	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A130	Misc	Resilient Flooring Tile	12x12	White w/Gray	None Detected		N/A	VALB-127-F4			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	A130	Wall(s)	Ceramic Tile	4x4	Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	NA
1st Floor	A130	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	A16,CC3-11 and E100	Misc	Resilient Floor Tile Glue	2000 sq ft.	Yellow	None Detected		Y	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC 128-M1-C1	Floor	Resilient Flooring Tile	12x12	Seafoam Blue	None Detected	No	YES	VALB-128-F1			N/A	N/A	N/A	N/A	N/A	N/A

Floor	Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present?	Previously sampled?	Contractor Sampled (Y/N)	Contractor Sample No	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
1st Floor	CC 128-M1-C1	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC 128-M1-C1	Misc	Cove Base	6"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC 128-M1-C1	Misc	TSI/F +1	4"		POS	Yes	No	N/A	Yes	Good	No	No	No	Yes	No	No
1st Floor	CC 128-M1-C1	Misc	TSI/F +3	2"		POS	Yes	No	N/A	Yes	Good	No	No	No	Yes	No	No
1st Floor	CC 128-M1-C1	Roof	Resilient Flooring Tile	12x12	Beige	POS	Yes	Yes	VALB-127-F5	no	Good	No	No	yes	no	no	yes
1st Floor	CC 128-M1-C1	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes

Floor	Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present?	Previously sampled?	Contractor Sampled (Y/N)	Contractor Sample No	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
1st Floor	CC 128-M1-C2	Floor	Resilient Flooring Tile	12x12	Seafoam Blue	None Detected	No	YES	VALB-128-F1			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC 128-M1-C2	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC 128-M1-C2	Misc	Cove Base	6"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC 128-M1-C2	Misc	Resilient Flooring Tile	12x12	Beige	POS	Yes	N/A	VALB-127-F5	no	Good	No	No	yes	no	no	yes
1st Floor	CC 128-M1-C2	Misc	TSI/F +1	4"		POS	Yes	No	N/A	Yes	Good	No	No	No	Yes	No	No
1st Floor	CC 128-M1-C2	Misc	TSI/F +3	2"		POS	Yes	No	N/A	Yes	Good	No	No	No	Yes	No	No
1st Floor	CC128 M1-C2	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	CC128-4-C1	Floor	Resilient Flooring Tile	12x12	Green	POS	No	Yes	VALB-128-F3.1	no	Good	no	no	yes	no	no	yes
1st Floor	CC128-4-C1	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC128-4-C1	Misc	Cove Base	6"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC128-4-C1	Misc	Resilient Flooring Tile	12x12	Beige	POS	Yes	Yes	VALB-127-F5	no	Good	No	No	yes	no	no	yes
1st Floor	CC128-4-C1	Misc	TSI/F +1	4"		POS	Yes	No	N/A	Yes	Good	No	No	No	Yes	No	No
1st Floor	CC128-4-C1	Misc	TSI/F +3	2"		POS	Yes	No	N/A	Yes	Good	No	No	No	Yes	No	No
1st Floor	CC128-4-C1	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	CC128-4-C2	Floor	Resilient Flooring Tile	12x12	Green	POS	No	Yes	VALB-128-F3.1	no	Good	no	no	yes	no	no	yes
1st Floor	CC128-4-C2	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC128-4-C2	Misc	Cove Base	6"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC128-4-C2	Misc	Resilient Flooring Tile	12x12	Beige	POS	Yes	Yes	VALB-127-F5	no	Good	No	No	yes	no	no	yes
1st Floor	CC128-4-C2	Misc	TSI/F +1	4"		POS	Yes	No	N/A	Yes	Good	No	No	No	Yes	No	No
1st Floor	CC128-4-C2	Misc	TSI/F +3	2"		POS	Yes	No	N/A	Yes	Good	No	No	No	Yes	No	No
1st Floor	CC128-4-C2	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	CC128-C1	Floor	Resilient Flooring Tile	9x9	Off White w/Olive	POS	No	Yes	VALB-128-F4	no	Good	No	No	yes	No	No	yes
1st Floor	CC128-C1	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC128-C1	Misc	Cove Base	6"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	NA
1st Floor	CC128-C1	Wall(s)	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC128-C2	Floor	Resilient Flooring Tile	9x9	Off White w/Olive	POS	No	Yes	VALB-128-F4	no	Good	No	No	yes	No	No	yes
1st Floor	CC128-C2	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC128-C2	Misc	Cove Base	6"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC128-C2	Wall(s)	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC128-C3	Floor	Resilient Flooring Tile	12x12	Seafoam Blue	None Detected	No	YES	VALB-128-F1			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC128-C3	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC128-C3	Misc	Cove Base	6"	White w/Olive	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC128-C3	Misc	Resilient Flooring Tile	9x9	Off White	POS	No	Yes	VALB-128-F4	no	Good	No	No	yes	No	No	yes
1st Floor	CC128-C3	Misc	Resilient Flooring Tile	9x9	White w/Olive	None Detected	No	Yes	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC128-C3	Wall(s)	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC128-C4	Floor	Resilient Flooring Tile	12x12	Seafoam Blue	None Detected	No	YES	VALB-128-F1			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC128-C4	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC128-C4	Misc	Cove Base	4"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC128-C4	Wall(s)	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC128-C5	Floor	Resilient Flooring Tile and Mastic	12x12	Seafoam Blue and Blue	None Determined	No	Y	VALB-128-F1			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC128-C5	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC128-C5	Misc	Cove Base	6"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC128-C5	Wall(s)	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC128-C6	Floor	Resilient Flooring Tile	9x9	White w/Olive	POS	No	Yes	VALB-128-F4	no	Good	No	No	yes	No	No	yes
1st Floor	CC128-C6	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC128-C6	Misc	Cove Base	6"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC128-C6	Wall(s)	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC128-C7	Floor	Resilient Flooring Tile	9x9	White w/Olive	POS	No	Yes	VALB-128-F4	no	Good	No	No	yes	No	No	yes
1st Floor	CC128-C7	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC128-C7	Misc	Cove Base	6"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC128-C7	Wall(s)	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC128-J1-C1	Floor	Resilient Flooring Tile	12x12	Seafoam Blue	None Detected	No	YES	VALB-128-F1			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC128-J1-C1	Ceiling	Acoustic Ceiling Tile Pinhole	2x4	White	None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A

Floor	Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present?	Previously sampled?	Contractor Sampled (Y/N)	Contractor Sample No	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
1st Floor	CC128-J1-C1	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC128-J1-C1	Door/Door Frame	Metal and Metal		Beige/Beige	Not suspect	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC128-J1-C1	Misc	Cove Base	6"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC128-J1-C1	Misc	Cove Baseand Glue	4"	Tan and Yellow	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC128-J1-C1	Misc	Resilient Flooring Tile	12x12	Mauve	None Detected	No	N/A	VALB-128-F6.1			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC128-J1-C1	Misc	Firestop	3"	Red	None Detected	No	Yes	VALB-128-M3			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC128-J1-C1	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	CC128-J1-C1	Wall(s)	Wallboard w/ Joint Compound		Off White	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes

Floor	Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present?	Previously sampled?	Contractor Sampled (Y/N)	Contractor Sample No	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
1st Floor	CC128-J1-C2	Floor	Resilient Flooring Tile	12x12	Seafoam Blue	None Detected	No	YES	VALB-128-F1			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC128-J1-C2	Ceiling	Acoustic Ceiling Tile Pinhole	2x4	White	None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC128-J1-C2	Door/Door Frame	Metal and Metal		Beige/Beige	Not suspect	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC128-J1-C2	Misc	Cove Base and Glue	4"	Tan aad Yellow	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC128-J1-C2	Misc	Resilient Floor Tile and Mastic	12x12	Tan and Tan	None Detected	No	Y	VALB-128-F2.1	no	Good	No	No	yes	No	No	yes
1st Floor	CC128-J1-C2	Misc	Firestop	3"	Red	None Detecteed	No	Yes	VALB-128-M3			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC128-J1-C2	Wall(s)	Wallboard w/ Joint Compound		Off White	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	CC128-J2-C2	Floor	Resilient Flooring Tile	12x12	Seafoam Blue	None Detected	No	YES	VALB-128-F1			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC128-J2-C2	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC128-J2-C2	Door/Door Frame	Metal and Metal		Beige/Beige	Not suspect	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC128-J2-C2	Misc	Cove Base	6"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC128-J2-C2	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	CC1-K1	Floor	Carpet and Glue		Blue and Yellow	None Detected	Y	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC1-K1	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC1-K1	Misc	Cove Base	6"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC1-K1	Wall(s)	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC2-K1	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC2-K1	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC2-K1	Misc	Cove Base	6"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	CC2-K1	Misc	Firestop		Red	None Detected	No	Y	VALB-128-M3			N/A	N/A	N/A	N/A	N/A	NA
1st Floor	CC2-K1	Wall(s)	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	Corridor at C101,C108,C107,M131 and M133	Misc	Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1			No	No	No	Yes	No	Yes
1st Floor	Corridor Room 120	Floor	Resilient Floor Tile-12" x 12"	6000 sq.ft.	Off White with Brown	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	Corridor Room 120	Ceiling	Acoustic Ceiling Tile	6000sq.ft.	White	None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	Corridor Room 120-120A	Misc	Floor Tile Mastic	6000 sq.ft.	Black	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	Hall A-1 & 2	Ceiling	Acoustic Ceiling Tile-Fissured	2' x 4'		POS	Yes	Yes	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J100	Floor	Resilient Sheet Flooring		Wood Grain	None Detected	No	Yes	VALB-128-F8.2			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J100	Ceiling	Plaster			None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J100	Door/Door Frame	Wood and Metal		Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J100	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J100	Misc	Floor Tile Mastic		Black	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J100	Misc	TSI/Pipe Joint			POS	Yes	No	N/A	Yes	Good	No	No	No	Yes	No	No
1st Floor	J100	Wall(s)	Wallboard w/ Joint Compound		Off White	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	J100A	Floor	Terrazo		Gray	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J100A	Ceiling	Plaster			None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J100A	Door/Door Frame	Wood and Metal		Off White/Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J100A	Wall(s)	Ceramic Tile	4x4	Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J100A	Wall(s)	Plaster		Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J103	Floor	Resilient Flooring Tile		Wood Grain	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J103	Ceiling	Plaster			None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J103	Door/Door Frame	Wood and Metal		Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J103	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J103	Misc	Floor mastic		Black	POS	Yes	No	N/A			No	No	No	No	No	Yes
1st Floor	J103	Wall(s)	Wallboard w/ Joint Compound		Off White	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	J106	Floor	Ceramic Tile	1x1	Gray	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J106	Door/Door Frame	Wood and Metal		Off White/Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J106	Misc	Ceramic Tile	2x2	Gray	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J106	Wall(s)	Ceramic Tile	4x4	Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J106	Wall(s)	Plaster		Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J107	Floor	Ceramic Tile	1x1	Gray	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J107	Door/Door Frame	Wood and Metal		Off White/Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J107	Misc	Ceramic Tile	2x2	Gray	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J107	Misc	Conduit Seal		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J107	Wall(s)	Ceramic Tile	4x4	Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A

Floor	Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present?	Previously sampled?	Contractor Sampled (Y/N)	Contractor Sample No	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
1st Floor	J107	Wall(s)	Plaster		Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J108	Floor	Resilient Flooring Tile	12x12	Seafoam Blue	None Detected	No	YES	VALB-128-F1			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J108	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J108	Door/Door Frame	Wood and Metal		Off White/ Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J108	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N A
1st Floor	J108	Wall(s)	Wallboard w/ Joint Compound		Off White	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	J11	Floor	Resilient Sheet Flooring and Glue		Blue and Yellow	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J11	Door/Door Frame	Wood and Metal		Off White/Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J11	Misc	TSI 1+	2"	Beige	POS	Yes	No	N/A	Yes	Good	No	No	No	Yes	No	No
1st Floor	J11	Wall(s)	Ceramic Tile	4x4	Off White/Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A

Floor	Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present?	Previously sampled?	Contractor Sampled (Y/N)	Contractor Sample No	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
1st Floor	J110	Floor	Resilient Flooring Tile		Wood Grain	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J110	Ceiling	Acoustic Ceiling Tile	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J110	Door/Door Frame	Wood and Metal		Off White/Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J110	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J110	Misc	TSI/F Pipe Joint		Beige	POS	Yes	No	N/A	Yes	Good	No	No	No	Yes	No	No
1st Floor	J110	Wall(s)	Wallboard w/ Joint Compound		Off White	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	J111	Ceiling	Wallboard w/ Joint Compound		Off White	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	J112	Floor	Resilient Flooring Tile		Wood Grain	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J112	Ceiling	Acoustic Ceiling Tile Pinhole	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J112	Door/Door Frame	Wood and Metal		Off White/Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J112	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J112	Misc	TSI/F 1+	2"		POS	Yes	No	N/A	Yes	Good	No	No	No	Yes	No	No
1st Floor	J112	Wall(s)	Plaster		Off White	None Detected	Yes	No	N/A			/AN	N/A	N/A	N/A	N/A	N/A
1st Floor	J112	Wall(s)	Wallboard w/ Joint Compound		Off White	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	J114	Floor	Resilient Flooring Tile		Blue Spot	None Detected	Yes	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J114	Ceiling	Wallboard w/ Joint Compound		Off White	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	J114	Door/Door Frame	Wood and Metal		Off White/Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J114	Misc	TSI 1+	2"		POS	Yes	No	N/A	Yes	Good	No	No	No	Yes	No	No
1st Floor	J114	Wall(s)	Ceramic Tile	4x4	Off White/Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J116A	Floor	Resilient Flooring Tile		Blue Spot	None Detected	Yes	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J116A	Floor	Resilient Flooring Tile		Wood Grain	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J116A	Ceiling	Acoustic Ceiling Tile Pinhole	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J116A	Ceiling	Wallboard w/ Joint Compound		Off White	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	J116A	Door/Door Frame	Wood and Metal		Off White/Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J116A	Door/Door Frame	Wood and Metal		Off White/Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J116A	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J116A	Misc	TSI 1+	2"		POS	Yes	No	N/A	Yes	Good	No	No	No	Yes	No	No
1st Floor	J116A	Wall(s)	Ceramic Tile	4x4	Off White/Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J116A	Wall(s)	Wallboard w/ Joint Compound		Off White	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	J117	Floor	Ceramic Tile	1x1	Gray	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J117	Door/Door Frame	Wood and Metal		Off White/Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J117	Misc	Ceramic Tile	2x2	Gray	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J117	Wall(s)	Ceramic Tile	4x4	Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J117	Wall(s)	Plaster		Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J119	Floor	Resilient Flooring Tile	12x12	Gray w/ Bkue	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J119	Ceiling	Acoustic Ceiling Tile Pinhole Worm	2x4	White	None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J119	Door/Door Frame	Wood and Metal		Off White/Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J119	Misc	Cove Base	4"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J119	Misc	Joint Compound			POS	Yes	Yes	VALB-128-C1			No	No	No	Yes	No	Yes
1st Floor	J119	Wall(s)	Wallboard		Tan	None Detected	Yes	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J119A	Floor	Resilient Flooring Tile	12x12	Tan	POS	Yes	No	N/A	no	Good	No	No	yes	No	No	yes
1st Floor	J119A	Ceiling	Acoustic Ceiling Tile Pinhole Worm	2x4	White	None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J119A	Door/Door Frame	Wood and Metal		Off White/Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J119A	Misc	Cove Base	4"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J119A	Misc	Floor Tile Mastic		Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J119A	Wall(s)	Wallboard w/ Joint Compound		Tan	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	J121	Floor	Resilient Flooring Tile		Wood Grain	None Detected	No	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J121	Ceiling	Acoustic Ceiling Tile Pinhole	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J121	Door/Door Frame	Wood and Metal		Off White/Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J121	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J121	Misc	Fire Caulk		Blue	None Determined		Y	N			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J121	Wall(s)	Wallboard w/ Joint Compound		Off White	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	J123	Floor	Ceramic Tile	1x1	Gray	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J123	Door/Door Frame	Wood and Metal		Off White/Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A

Floor	Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present?	Previously sampled?	Contractor Sampled (Y/N)	Contractor Sample No	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
1st Floor	J123	Misc	Ceramic Tile	2x2	Gray	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J123	Wall(s)	Ceramic Tile	4x4	Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	J123	Wall(s)	Plaster		Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K102	Floor	Carpet		Brown	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K102	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K102	Door/Door Frame	Metal and Metal		Beige/Beige	Not suspect	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K102	Misc	Cove Base	4"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K102	Wall(s)	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A

Floor	Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present?	Previously sampled?	Contractor Sampled (Y/N)	Contractor Sample No	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
1st Floor	K127C	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K127C	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K127C	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K127C	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K127C	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K127C	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K127C	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K127C	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	K128	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K128	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K128	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K128	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K128	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	K130	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K130	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K130	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K130	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	NA	N/A	N/A	N/A
1st Floor	K130	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	K130A	Floor	Ceramic Tile	1x1	Gray	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K130A	Floor	Ceramic Tile	2x2	Brown	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K130A	Ceiling	Plaster			None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K130A	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K130A	Wall(s)	Ceramic Tile	4x4	Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K130A	Wall(s)	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K132	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K132	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K132	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K132	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	NN	N/A	N/A
1st Floor	K132	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	K133A	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K133A	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K133A	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K133A	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K133A	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	K135	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K135	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K135	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K135	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K135	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	K136	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K136	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K136	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K136	Misc	Covebase and Mastic	4"	Tan and Brown	None Detected		Y	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K136	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	K137	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K137	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K137	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K137	Misc	Cove Base and Glue	4"	Brown and Tan	None Detected	Yes	Yes	VALB-128-M1			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K137	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	K138	Floor	Ceramic Tile		Gray	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K138	Door/Door Frame	Wood and Metal		Beige/Brown	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A

Floor	Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present?	Previously sampled?	Contractor Sampled (Y/N)	Contractor Sample No	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
1st Floor	K138	Wall(s)	Ceramic Tile		Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K138	Wall(s)	Plaster		Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K139	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K139	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K139	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K139	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K139	Wall(s)	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K140	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K140	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K140	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K140	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K140	Wall(s)	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A

Floor	Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present?	Previously sampled?	Contractor Sampled (Y/N)	Contractor Sample No	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
1st Floor	K140A	Floor	Ceramic Tile	1x1	Gray	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	k140A	Ceiling	Plaster			None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K140A	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K140A	Wall(s)	Ceramic Tile	4x4	Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K140A	Wall(s)	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K141	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K141	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K141	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K141	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K141	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	K145	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K145	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K145	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K145	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	K145	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	L100	Floor	Non Skid		Beige	Not suspect	N/A	N/A	N/A			N/A			N/A	N/A	N/A
1st Floor	L100	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L100	Door/Door Frame	Metal and Metal		Beige	Not suspect	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L100	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	L100A	Floor	Resilient Flooring Tile	4x4	Beige	POS	No	Yes	VALB-128-F5, F7	no	Good	No	No	yes	No	No	yes
1st Floor	L100A	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L100A	Wall(s)	Ceramic Tile		Beige/Green	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L101	Floor	Non Skid		Green	Not suspect	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L101	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L101	Door/Door Frame	Metal and Metal		Beige/Off	Not suspect	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L101	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	L102	Floor	Non Skid		Green	Not suspect	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L102	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L102	Door/Door Frame	Metal and Metal		Beige/Off	Not suspect	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L102	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	L103	Floor	Resilient Flooring Tile	4x4	Beige	POS	No	Yes	VALB-128-F5, F7	no	Good	No	No	yes	No	No	yes
1st Floor	L103	Floor	Resilient Floor Sheeting and Glue		Gray and Yellow	None Detected	yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L103	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L103	Door/Door Frame	Metal and Metal		Beige/Off	Not suspect	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L103	Misc	Covebase and Glue		Off White and Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L103	Wall(s)	Ceramic Tile		Beige/Green	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L103	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	L104	Floor	Resilient Floor Sheeting and Glue		Gray and Yellow	None Detected	yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L104	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L104	Door/Door Frame	Metal and Metal		Beige/Off	Not suspect	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L104	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	L104A	Floor	Resilient Flooring Tile	12x12	Beige	POS	No	Yes	VALB-128-F2.1	no	Good	No	No	yes	No	No	yes
1st Floor	L104A	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L104A	Door/Door Frame	Wood and Metal		Beige/Off WWhite	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L104A	Misc	Cove Base	6"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L104A	Wall(s)	Wallboard w/ Joint Compound		Beige/Green	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	L105	Floor	Resilient Floor Sheeting and Glue		Gray and Yellow	None Detected	yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L105	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L105	Door/Door Frame	Metal and Metal		Beige/Off	Not suspect	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L105	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes

Floor	Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present?	Previously sampled?	Contractor Sampled (Y/N)	Contractor Sample No	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
1st Floor	L106	Floor	Ceramic Tile	1x1	Gray	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L106	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L106	Door/Door Frame	Wood and Metal		Beige/Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L106	Misc	Ceramic Tile	4x4	Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L106	Wall(s)	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L107A	Floor	Ceramic Tile	1x1	Gray	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L107A	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L107A	Door/Door Frame	Wood and Metal		Beige/Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L107A	Misc	Ceramic Tile	4x4	Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L107A	Misc	TSI/F 1-2"			POS	Yes	No	N/A	Yes	Good	No	No	No	Yes	No	No
1st Floor	L107A	Wall(s)	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A

Floor	Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present?	Previously sampled?	Contractor Sampled (Y/N)	Contractor Sample No	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
1st Floor	L108	Floor	Resilient Flooring Tile	12x12	Beige	POS	No	Yes	VALB-128-F2.1	no	Good	No	No	yes	No	No	yes
1st Floor	L108	Ceiling	Acoustic Ceiling Tile Pinhole	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L108	Door/Door Frame	Wood and Metal		Beige/Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L108	Misc	Cove Base	6"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L108	Wall(s)	Wallboard w/ Joint Compound			POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	L109	Floor	Resilient Flooring Tile	12x12	Beige	POS	No	Yes	VALB-128-F2.1	no	Good	No	No	yes	No	No	yes
1st Floor	L109	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L109	Misc	Covebase and Glue	6"	Off White and Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L109	Misc	Resilient Flooring Tile	12x12	Seafoam Blue	None Detected	No	YES	VALB-128-F1			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L109	Misc	Resilient Flooring Tile and Mastic	12x12	Green and Green	POS	No	Y	VALB-128-F3			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L109	Misc	Wallboard w/ Joint Compound		Beige/Brown	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	L109	Wall(s)	Plaster		Green	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L110	Floor	Resilient Flooring Tile	12x12	Beige	POS	No	Yes	VALB-128-F2.1	no	Good	No	No	yes	No	No	yes
1st Floor	L110	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L110	Misc	Cove Base	6"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L110	Misc	Resilient Flooring Tile	12x12	Beige	POS	No	Yes	VALB-128-F2.1	no	Good	No	No	yes	No	No	yes
1st Floor	L110	Misc	Resilient Flooring Tile	12x12	Beige	POS	No	Yes	VALB-128-F2.1	no	Good	No	No	yes	No	No	yes
1st Floor	L110	Misc	Wallboard w/ Joint Compound		Beige/Brown	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	L110	Wall(s)	Plaster		Green	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L111	Floor	Resilient Flooring Tile	12x12	Beige	POS	No	Yes	VALB-128-F2.1	no	Good	No	No	yes	No	No	yes
1st Floor	L111	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6								
1st Floor	L111	Misc	Cove Base	6"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L111	Misc	Wallboard w/ Joint Compound		Beige/Brown	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	L111	Wall(s)	Plaster		Green	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L112	Floor	Resilient Flooring Tile	12x12	Beige	POS	No	Yes	VALB-128-F2.1	no	Good	No	No	yes	No	No	yes
1st Floor	L112	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L112	Misc	Cove Base	6"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L112	Misc	Resilient Flooring Tile	12x12	Beige	POS	No	Yes	VALB-128-F2.1	no	Good	No	No	yes	No	No	yes
1st Floor	L112	Misc	Wallboard w/ Joint Compound		Beige/Brown	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	L112	Wall(s)	Plaster		Green	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L112A	Floor	Ceramic Tile	1x1	Gray	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L112A	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L112A	Wall(s)	Ceramic Tile	4x4	Off Whhite	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L113A	Floor	Resilient Flooring Tile	12x12	Beige	POS	No	Yes	VALB-128-F2.1	no	Good	No	No	yes	No	No	yes
1st Floor	L113A	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L113A	Door/Door Frame	Wood and Metal		Beige/Off WHite	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L113A	Misc	Cove Base	6"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L113A	Wall(s)	Wallboard w/ Joint Compound		Beige/Green	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	L114	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L115	Floor	Resilient Flooring Tile	12x12	Beige	POS	No	Yes	VALB-128-F2.1	no	Good	No	No	yes	No	No	yes
1st Floor	L115	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L115	Misc	Cove Base	6"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L115	Misc	Resilient Flooring Tile	12x12	Beige	POS	No	Yes	VALB-128-F2.1	no	Good	No	No	yes	No	No	yes
1st Floor	L115	Misc	Resilient Flooring Tile	12x12	Beige	POS	No	Yes	VALB-128-F2.1	no	Good	No	No	yes	No	No	yes
1st Floor	L115	Misc	Wallboard w/ Joint Compound		Beige/Brown	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	L115	Wall(s)	Plaster		Green	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L116A	Floor	Resilient Flooring Tile	4x4	Beige	POS	No	Yes	VALB-128-F5, F7	no	Good	No	No	yes	No	No	yes
1st Floor	L116A	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L116A	Wall(s)	Ceramic Tile		Beige/Green	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L117	Floor	Ceramic Tile	1x1	Gray	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L117	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L117	Door/Door Frame	Wood and Metal		Beige/Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L117	Misc	Ceramic Tile	4x4	Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A

Floor	Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present?	Previously sampled?	Contractor Sampled (Y/N)	Contractor Sample No	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
1st Floor	L117	Wall(s)	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L118	Floor	Resilient Flooring Tile		White	POS	No	Yes	VALB-128-F1	no	Good	No	No	yes	No	No	yes
1st Floor	L118	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L118	Door/Door Frame	Wood and Metal		Beige/Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L118	Misc	Cove Base	6"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L118	Misc	TSI/F Elbow (2)		Beige and Gray	POS	Yes	No	N/A	Yes	Good	No	No	No	Yes	No	No
1st Floor	L118	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes

Floor	Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present?	Previously sampled?	Contractor Sampled (Y/N)	Contractor Sample No	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
1st Floor	L120	Floor	Resilient Flooring Tile	12x12	Beige	POS	No	Yes	VALB-128-F2.1	no	Good	No	No	yes	No	No	yes
1st Floor	L120	Ceiling	Acoustic Ceiling Tile Pinhole	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L120	Door/Door Frame	Wood and Metal		Beige/Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L120	Misc	Cove Base	6"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L120	Misc	Floor Tile Mastic		Beige	POS	Yes	Yes	VALB-128-F2.1			No	No	No	No	No	Yes
1st Floor	L120	Wall(s)	Wallboard w/ Joint Compound			POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	L121	Floor	Resilient Flooring Tile	12x12	Beige	POS	No	Yes	VALB-128-F2.1	no	Good	No	No	yes	No	No	yes
1st Floor	L121	Ceiling	Acoustic Ceiling Tile Pinhole	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L121	Door/Door Frame	Wood and Metal		Beige/Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L121	Misc	Cove Base	6"	Off White	None Detected	Yes	No	N/A			NA	N/A	N/A	N/A	N/A	N/A
1st Floor	L121	Wall(s)	Wallboard w/ Joint Compound			POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	L122	Floor	Resilient Flooring Tile	4x4	Beige	POS	No	Yes	VALB-128-F5, F7	no	Good	No	No	yes	No	No	yes
1st Floor	L122	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L122	Wall(s)	Ceramic Tile		Beige/Green	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L124	Floor	Resilient Flooring Tile	12x12	Beige	POS	No	Yes	VALB-128-F2.1	no	Good	No	No	yes	No	No	yes
1st Floor	L124	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L124	Door/Door Frame	Wood and Metal		Beige/Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L124	Misc	Cove Base	6"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	L124	Wall(s)	Wallboard w/ Joint Compound		Beige/Green	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	M106	Floor	Resilient Flooring Tile	12x12	Beige	POS	No	Yes	VALB-128-F2.1	no	Good	No	No	yes	No	No	yes
1st Floor	M106	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M106	Door/Door Frame	Wood and Metal		White/Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M106	Misc	Cove Base	4"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M106	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	M107A	Floor	Resilient Flooring Tile	4x4	Beige	POS	No	Yes	VALB-128-F5, F7	no	Good	No	No	yes	No	No	yes
1st Floor	M107A	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M107A	Wall(s)	Ceramic Tile		Beige/Green	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M122	Floor	Resilient Flooring Tile	12x12	Beige	POS	No	Yes	VALB-128-F2.1	no	Good	No	No	yes	No	No	yes
1st Floor	M122	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M122	Door/Door Frame	Wood and Metal		Beige/Brown	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M122	Misc	Cove Base	4"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M122	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	M124	Floor	Non Skid		Green	Not suspect	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M124	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M124	Wall(s)	Ceramic Tile	4x4	Tan	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M125	Floor	Resilient Flooring Tile	12x12	Beige	POS	No	Yes	VALB-128-F2.1	no	Good	No	No	yes	No	No	yes
1st Floor	M125	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M125	Door/Door Frame	Wood and Metal		White/Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M125	Misc	Cove Base	4"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M125	Misc	TSI/F Elbow		Beige	POS	Yes	No	N/A	Yes	Good	No	No	No	Yes	No	No
1st Floor	M125	Misc	TSI/F Hanger		White	POS	Yes	No	N/A	Yes	Good	No	No	No	Yes	No	No
1st Floor	M125	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	M125A	Floor	Non Skid		Green	Not suspect	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M125A	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M125A	Wall(s)	Ceramic Tile	4x4	Tan	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M127	Floor	Resilient Flooring Tile	12x12	Beige	POS	No	Yes	VALB-128-F2.1	no	Good	No	No	yes	No	No	yes
1st Floor	M127	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M127	Door/Door Frame	Wood and Metal		White/Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M127	Misc	Cove Base	4"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M127	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	M127A	Floor	Resilient Flooring Tile	12x12	Beige	POS	No	Yes	VALB-128-F2.1	no	Good	No	No	yes	No	No	yes

Floor	Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present?	Previously sampled?	Contractor Sampled (Y/N)	Contractor Sample No	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
1st Floor	M127A	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M127A	Door/Door Frame	Wood and Metal		White/Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M127A	Misc	Cove Base	4"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M127A	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	M128	Floor	Resilient Flooring Tile	12x12	Beige	POS	No	Yes	VALB-128-F2.1	no	Good	No	No	yes	No	No	yes
1st Floor	M128	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M128	Door/Door Frame	Wood and Metal		Beige/Brown	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M128	Misc	Cove Base	4"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M128	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes

Floor	Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present?	Previously sampled?	Contractor Sampled (Y/N)	Contractor Sample No	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
1st Floor	M128A	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6								
1st Floor	M128A	Door/Door Frame	Wood and Metal		White/Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M128A	Wall(s)	Ceramic Tile	4x4	Off White/Blue	Not Suspect Material	N/A	N/A	N/A				N/A	N/A	N/A	N/A	N/A
1st Floor	M129	Floor	Ceramic Tile	1x1	Gray	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M129	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M129	Door/Door Frame	Wood and Metal		Beige/Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M129	Misc	Ceramic Tile	4x4	Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M129	Wall(s)	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M130	Floor	Resilient Flooring Tile	12x12	Beige	POS	No	Yes	VALB-128-F2.1	no	Good	No	No	yes	No	No	yes
1st Floor	M130	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M130	Door/Door Frame	Wood and Metal		White/Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M130	Misc	Cove Base	4"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M130	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	M131	Floor	Resilient Flooring Tile	12x12	Beige	POS	No	Yes	VALB-128-F2.1	no	Good	No	No	yes	No	No	yes
1st Floor	M131	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M131	Door/Door Frame	Wood and Metal		Beige/Brown	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M131	Misc	Cove Base	4"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M131	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	M132	Floor	Resilient Flooring Tile	4x4	Beige	POS	No	Yes	VALB-128-F5, F7	no	Good	No	No	yes	No	No	yes
1st Floor	M132	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M132	Wall(s)	Ceramic Tile		Beige/Green	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M133A	Floor	Ceramic Tile	1x1	Gray	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M133A	Floor	Resilient Flooring Tile	12x12	Beige	POS	No	Yes	VALB-128-F2.1	no	Good	No	No	yes	No	No	yes
1st Floor	M133A	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M133A	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M133A	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M133A	Door/Door Frame	Wood and Metal		White/Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M133A	Misc	Cove Base	4"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M133A	Wall(s)	Ceramic Tile	4x4	Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M133A	Wall(s)	Plaster			None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M133A	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	M134	Floor	Resilient Flooring Tile	12x12	Beige	POS	No	Yes	VALB-128-F2.1	no	Good	No	No	yes	No	No	yes
1st Floor	M134	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M134	Door/Door Frame	Wood and Metal		Beige/Brown	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M134	Misc	Cove Base	4"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M134	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	M135	Floor	Resilient Flooring Tile	4x4	Beige	POS	No	Yes	VALB-128-F5, F7	no	Good	No	No	yes	No	No	yes
1st Floor	M135	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M135	Wall(s)	Ceramic Tile		Beige/Green	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M136	Floor	Non Skid		Green	Not suspect	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M136	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M136	Wall(s)	Ceramic Tile	4x4	Tan	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M137	Floor	Resilient Flooring Tile	12x12	Seafoam Blue and Beige	None Detected	No	YES	VALB-128-F1			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M137	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M137	Door/Door Frame	None			Not suspect	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M137	Misc	Cove Base and Glue	4"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M137	Misc	Joint Compound			POS	Yes	Yes	VALB-128-C1			No	No	No	Yes	No	Yes
1st Floor	M137	Misc	TSI?F Hanger		White	POS	Yes	No	N/A	Yes	Good	No	No	No	Yes	No	No
1st Floor	M137	Wall(s)	Wallboard		Beige	None Detected	Yes	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M138	Floor	Resilient Flooring Tile	12x12	Beige	POS	No	Yes	VALB-128-F2.1	no	Good	no	no	yes	no	no	yes
1st Floor	M138	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6								
1st Floor	M138	Door/Door Frame	Wood and Metal		White/Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M138	Misc	Cove Base	4"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M138	Misc	Floor Tile Mastic		Beige	POS	Yes	Yes	VALB-128-F2.1			No	No	No	No	No	Yes

Floor	Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present?	Previously sampled?	Contractor Sampled (Y/N)	Contractor Sample No	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
1st Floor	M138	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	M139	Floor	Ceramic Tile	1x1	Gray	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M139	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M139	Door/Door Frame	Wood and Metal		Beige/Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M139	Misc	Ceramic Tile	4x4	Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M139	Wall(s)	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M140	Floor	Ceramic Tile	1x1	Gray	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M140	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M140	Door/Door Frame	Wood and Metal		Beige/Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M140	Wall(s)	Ceramic Tile	4x4	Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M140	Wall(s)	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A

Floor	Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present?	Previously sampled?	Contractor Sampled (Y/N)	Contractor Sample No	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
1st Floor	M141	Floor	Concrete - Non Skid		Green	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M141	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M141	Door/Door Frame	Metal and Metal		Beige/Off White	Not suspect	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M141	Wall(s)	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M142A	Floor	Non Skid		Green	Not suspect	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M142A	Floor	Resilient Flooring Tile	12x12	Beige	POS	No	Yes	VALB-128-F2.1	no	Good	no	no	yes	no	no	yes
1st Floor	M142A	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M142A	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M142A	Door/Door Frame	Wood and Metal		Beige/Brown	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M142A	Misc	Cove Base	4"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M142A	Wall(s)	Ceramic Tile	4x4	Tan	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M142A	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	M143	Floor	Resilient Flooring Tile	12x12	Beige	POS	No	Yes	VALB-128-F2.1	no	Good	no	no	yes	no	no	yes
1st Floor	M143	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M143	Door/Door Frame	Wood and Metal		Beige/Brown	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M143	Misc	Cove Base	4"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M143	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	M144	Floor	Resilient Flooring Tile	12x12	Beige	POS	No	Yes	VALB-128-F2.1	no	Good	no	no	yes	no	no	yes
1st Floor	M144	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M144	Door/Door Frame	Wood and Metal		White/Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M144	Misc	Cove Base	4"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M144	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	M144A	Floor	Non Skid		Green	Not suspect	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M144A	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M144A	Wall(s)	Ceramic Tile	4x4	Tan	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M145	Floor	Resilient Flooring Tile	12x12	Beige	POS	No	Yes	VALB-128-F2.1	no	Good	no	no	yes	no	no	yes
1st Floor	M145	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M145	Door/Door Frame	Wood and Metal		White/Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M145	Misc	Cove Base	4"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M145	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	M146	Floor	Resilient Flooring Tile	12x12	Beige	POS	No	Yes	VALB-128-F2.1	no	Good	no	no	yes	no	no	yes
1st Floor	M146	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M146	Door/Door Frame	Wood and Metal		White/Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M146	Misc	Cove Base	4"		None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
1st Floor	M146	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
1st Floor	Room 130	Floor	Resilient Floor Tile with Mastic	12" x 12"	White and White	POS		Y	VALB-128-F4	no	Good	No	No	yes	No	No	yes
2nd Floor	A200	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A200	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6								
2nd Floor	A200	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A200	Misc	Cove Base	4"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A200	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	A201	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A201	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A201	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A201	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A201	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	A202	Floor	Ceramic Tile	1x1	Gray/Brown	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A202	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A202	Wall(s)	Ceramic Tile	4x4	Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A202	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	A204	Floor	Ceramic Tile	1x1	Gray/Brown	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A204	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A

Floor	Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present?	Previously sampled?	Contractor Sampled (Y/N)	Contractor Sample No	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
2nd Floor	A204	Wall(s)	Ceramic Tile	4x4	Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A204	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	A206	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A206	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A206	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A206	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A206	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes

Floor	Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present?	Previously sampled?	Contractor Sampled (Y/N)	Contractor Sample No	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
2nd Floor	A207	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A207	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A207	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A207	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A207	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	A208	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A208	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A208	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A208	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A208	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	A209	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A209	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A209	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A209	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A209	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	A210	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A210	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A210	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A210	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A210	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	A211	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A211	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A211	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A211	Misc	*201B has 12x12 Acoustic Ceiling Tile w/Brown Mastic			None Detected	Yes	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A211	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A211	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	A212	Floor	Ceramic Tile	1x1	Gray	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A212	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A212	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A212	Wall(s)	Ceramic Tile	4x4	Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A212	Wall(s)	Plaster			None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A214	Floor	Ceramic Tile	2x2	Gray	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A214	Ceiling	Plaster			None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A214	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A214	Wall(s)	Ceramic Tile	4x4	Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A214	Wall(s)	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A216	Floor	Resilient Flooring Tile	12x12	Seafoam Blue	None Detected	No	YES	VALB-128-F1			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A216	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A216	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A216	Misc	Cove Base	4"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A216	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	A217	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A217	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A217	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A217	Misc	Cove Base		Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A217	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	A225	Floor	Resilient Flooring Tile	12x12	Tan	POS	No	Y	VALB-128-F2.1	no	Good	No	No	yes	No	No	yes
2nd Floor	A225	Ceiling	Acoustic Ceiling Tile Tiny Pinhole	2x2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A225	Misc	Cove Base	4"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A225	Misc	Resilient Flooring Tile	12x12	Gray/Brown	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A225	Misc	Resilient Flooring Tile	12x12	Green	POS	No	Y	VALB-128-F3.1	no	Good	No	No	yes	No	No	yes

Floor	Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present?	Previously sampled?	Contractor Sampled (Y/N)	Contractor Sample No	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
2nd Floor	A225	Wall(s)	Wallboard w/ Joint Compound		Beige/Tan	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	A225A	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A225A	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A225A	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A225A	Misc	Cove Base	4"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A225A	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes

Floor	Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present?	Previously sampled?	Contractor Sampled (Y/N)	Contractor Sample No	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
2nd Floor	A225B	Floor	Resilient Flooring Tile	12x12	Tan	POS	No	Y	VALB-128-F2.1	no	Good	No	No	yes	No	No	yes
2nd Floor	A225B	Ceiling	Acoustic Ceiling Tile Tiny Pinhole	2x2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A225B	Misc	Cove Base	4"	Off White	None Detected	Yes	No				N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A225B	Misc	Resilient Flooring Tile	12x12	Gray/Brown	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A225B	Misc	Resilient Flooring Tile	12x12	Green	POS	No	Y	VALB-128-F3.1	no	Good	No	No	yes	No	No	yes
2nd Floor	A225B	Wall(s)	Wallboard w/ Joint Compound		Beige/Tan	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	A226	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A226	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A226	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A226	Misc	Cove Base	4"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A226	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	A226B	Floor	Resilient Flooring Tile	12x12	Seafoam Blue	None Detected	No	YES	VALB-128-F1			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A226B	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A226B	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A226B	Misc	Cove Base	4"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A226B	Wall(s)	Ceramic Tile	4x4	Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A226B	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	A226C	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A226C	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A226C	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A226C	Misc	Cove Base	4"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A226C	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	A227	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A227	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A227	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A227	Misc	Cove Base	4"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A227	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	A229	Floor	Resilient Flooring Tile	12x12	Seafoam Blue	None Detected	No	YES	VALB-128-F1			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A229	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6								
2nd Floor	A229	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A229	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A229	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	A231	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A231	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A231	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A231	Misc	Cove Base		Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	A231	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	C107	Floor	Resilient Flooring Sheeting and Mastic		Tan and Black	None Determined		Y	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	C107	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	C107	Door/Door Frame	Wood and Metal		Beige and Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	C107	Misc	Cove Base and Mastic	6"	iBeige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	C107	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	C200A	Floor	Carpet		Brown	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	C200A	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	C200A	Door/Door Frame	Wood and Metal		Beige/Brown	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	C200A	Misc	Cove Base	4"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	C200A	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	C201	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	C201	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	C201	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	C201	Misc	Cove Base		Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A

Floor	Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present?	Previously sampled?	Contractor Sampled (Y/N)	Contractor Sample No	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
2nd Floor	C201	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	C201A	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	C201A	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	C201A	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	C201A	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	C201A	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	C202	Floor	Resilient Flooring Tile	12x12	Seafoam Blue	None Detected	No	YES	VALB-128-F1			N/A	N.A	N/A	N/A	N.A	N/A
2nd Floor	C202	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	C202	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N.A	N/A
2nd Floor	C202	Misc	Cove Base	4"		None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	C202	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	C205	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	C205	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	C205	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	C205	Misc	Cove Base	4"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	C205	Wall(s)	Wallboard w/ Joint Compound + Concrete		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	CC128-2-C5	Floor	Resilient Flooring Tile	12x12	Seafoam Blue	None Noteed	No	YES	VALB-128-F1			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	CC128-2-C5	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	CC128-2-C5	Misc	Cove Base	6"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	CC128-2-C5	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	CC128-2-C6	Floor	Resilient Flooring Tile	9x9	Gray/Brown	POS	Yes	No	N/A	no	Good	No	No	yes	No	No	yes
2nd Floor	CC128-2-C6	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	CC128-2-C6	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	CC128-2-C6	Misc	Cove Base	6"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	CC128-2-C6	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	CC128-A2-C2	Floor	Resilient Flooring Tile	9x9	White w/Olive	POS	Yes	No	N/A	no	Good	No	No	yes	No	No	yes
2nd Floor	CC128-A2-C2	Ceiling	Acoustic Ceiling Tile Pinhole	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	CC128-A2-C2	Door/Door Frame	Metal and Metal		Beige/Beige	Not suspect	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	CC128-A2-C2	Misc	Cove Base	6"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	CC128-A2-C2	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	CC128-A2-C3	Floor	Resilient Flooring Tile	12x12	Seafoam Blue	None Detected	No	YES	VALB-128-F1			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	CC128-A2-C3	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	CC128-A2-C3	Misc	Cove Base	6"	White w/Olive	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	CC128-A2-C3	Misc	Resilient Flooring Tile	9x9	Olive	POS	Yes	No	N/A	no	Good	No	No	yes	No	No	yes
2nd Floor	CC128-A2-C3	Misc	Resilient Flooring Tile	9x9		POS	Yes	No	N/A	no	Good	No	No	yes	No	No	yes
2nd Floor	CC128-A2-C3	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	CC128-A2-C7	Floor	Resilient Flooring Tile	9x9	White w/Olive	POS	No	Yes	VALB-128-F4	no	Good	No	No	yes	No	No	yes
2nd Floor	CC128-A2-C7	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	CC128-A2-C7	Misc	Cove Base	6"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	CC128-A2-C7	Wall(s)	Wallboard w/ Joint Compound + Concrete			None Detected	Yes	N/A	N/A	no	Good	no	no	yes	no	no	yes
2nd Floor	CC128-K2-C2	Floor	Resilient Flooring Tile	12x12	Seafoam Blue	None Detected	No	YES	VALB-128-F1			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	CC128-K2-C2	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	CC128-K2-C2	Door/Door Frame	Metal and Metal		Beige/Beige	Not suspect	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	CC128-K2-C2	Misc	Cove Base	6"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	CC128-K2-C2	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	CC128-K2-C3	Floor	Resilient Flooring Tile	12x12	Seafoam Blue	None Detected	No	YES	VALB-128-F1			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	CC128-K2-C3	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	CC128-K2-C3	Door/Door Frame	Metal and Metal		Beige/Beige	Not suspect	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	CC128-K2-C3	Misc	Cove Base	6"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	CC128-K2-C3	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes

Floor	Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present?	Previously sampled?	Contractor Sampled (Y/N)	Contractor Sample No	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
2nd Floor	CC128-L2-C1	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	CC128-L2-C1	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	CC128-L2-C1	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	CC128-L2-C1	Misc	Cove Base	6"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	CC128-L2-C1	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	Corridor at CC128-L2-C1	Misc	Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1			No	No	No	Yes	No	Yes
2nd Floor	Corridor at CC128-L2-C1	Misc	Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1			No	No	No	Yes	No	Yes
2nd Floor	Fan Room East	Floor	Metal		Bare	Not suspect	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	Fan Room East	Ceiling	Metal		Bare	Not suspect	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	Fan Room East	Wall(s)	Metal		Bare	Not suspect	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	Fan Room South	Floor	Metal		Bare	Not suspect	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	Fan Room South	Ceiling	Metal		Bare	Not suspect	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	Fan Room South	Wall(s)	Metal		Bare	Not suspect	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	Fan Room West	Floor	Metal		Bare	Not suspect	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	Fan Room West	Ceiling	Metal		Bare	Not suspect	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	Fan Room West	Wall(s)	Metal		Bare	Not suspect	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	HVAC Store Room	Floor	Rolled Roof		Gray	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	HVAC Store Room	Ceiling	Metal		Bare	Not suspect	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	HVAC Store Room	Wall(s)	Metal		Bare	Not suspect	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J201	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J201	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J201	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J201	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J201	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes

Floor	Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present?	Previously sampled?	Contractor Sampled (Y/N)	Contractor Sample No	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
2nd Floor	J202	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J202	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J202	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J202	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J202	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	J203	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J203	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J203	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J203	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J203	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	J204	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J204	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J204	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J204	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J204	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	J205	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J205	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J205	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J205	Misc	Cove Base		Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J205	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	J207	Floor	Ceramic Tile	1x1	Gray/Brown	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J207	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J207	Wall(s)	Ceramic Tile	4x4	Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J207	Wall(s)	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J208	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J208	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J208	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J208	Misc	Cove Base	4"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J208	Wall(s)	Wallboard w/ Joint Compound		Beige/Green	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	J209	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J209	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J209	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J209	Misc	Cove Base	4"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J209	Wall(s)	Wallboard w/ Joint Compound		Beige/Green	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	J210	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J210	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J210	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J210	Misc	Cove Base	4"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J210	Wall(s)	Wallboard w/ Joint Compound		Beige/Green	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	J211	Floor	Ceramic Tile	1x1	Gray/Brown	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J211	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J211	Wall(s)	Ceramic Tile	4x4	Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J211	Wall(s)	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J212	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J212	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J212	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J212	Misc	Cove Base	4"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J212	Wall(s)	Wallboard w/ Joint Compound		Beige/Green	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	J216	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J216	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J216	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A

Floor	Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present?	Previously sampled?	Contractor Sampled (Y/N)	Contractor Sample No	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
2nd Floor	J216	Misc	Cove Base	6"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J216	Wall(s)	Wallboard w/ Joint Compound		Beige/Green	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	J218	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J218	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J218	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J218	Misc	Cove Base	4"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J218	Wall(s)	Wallboard w/ Joint Compound		Beige/Green	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes

Floor	Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present?	Previously sampled?	Contractor Sampled (Y/N)	Contractor Sample No	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
2nd Floor	J219	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J219	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J219	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J219	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J219	Wall(s)	Wallboard w/ Joint Compound		Beige/Green	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	J221	Floor	Carpet		Brown	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J221	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J221	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J221	Misc	Cove Base	4"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	J221	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	K229	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	K229	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	K229	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	K229	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	K229	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	K235	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	K235	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	K235	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	K235	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	K235	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	K236	Floor	Resilient Flooring Tile	12x12	Seafoam Blue	None Detected	No	YES	VALB-128-F1			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	K236	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	K236	Misc	Cove Base	4"		None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	K236	Wall(s)	Wallboard w/ Joint Compound		Tan	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	K237	Floor	Resilient Flooring Tile	12x12	Seafoam Blue	None Detected	No	YES	VALB-128-F1			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	K237	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	K237	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	K237	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	K237	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	K238	Floor	Ceramic Tile	1x1	Gray	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	K238	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	K238	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	K238	Wall(s)	Ceramic Tile	4x4	Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	K238	Wall(s)	Plaster			None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	K240	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	K240	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	K240	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	K240	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	K240	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	K241	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	K241	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	K241	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	K241	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	K241	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	K244A	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	K244A	Floor	Ceramic Tile	1x1	Gray	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	K244A	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	K244A	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	K244A	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	K244A	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	K244A	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	K244A	Wall(s)	Ceramic Tile	4x4	Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	K244A	Wall(s)	Plaster			None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	K244A	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	K245	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A

Floor	Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present?	Previously sampled?	Contractor Sampled (Y/N)	Contractor Sample No	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
2nd Floor	K245	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	K245	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	K245	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	K245	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	L201	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L201	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L201	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L201	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L201	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes

Floor	Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present?	Previously sampled?	Contractor Sampled (Y/N)	Contractor Sample No	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
2nd Floor	L202	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L202	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L202	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L202	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L202	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	L202A	Floor	Resilient Flooring Tile	12x12	Seafoam Blue	None Detected	No	YES	VALB-128-F1			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L202A	Ceiling	Plaster			None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L202A	Door/Door Frame	Wood and Metal		Beige/Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L202A	Wall(s)	Ceramic Tile	4x4	Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L202A	Wall(s)	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L203	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L203	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L203	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L203	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L203	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	L204	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L204	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L204	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L204	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L204	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	L204A	Floor	Ceramic Tile	1x1	Gray	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L204A	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L204A	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L204A	Wall(s)	Ceramic Tile	4x4	Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L204A	Wall(s)	Plaster			None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L205	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L205	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L205	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L205	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L205	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	L206	Floor	Ceramic Tile	1x1	Gray	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L206	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L206	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L206	Wall(s)	Ceramic Tile	4x4	Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L206	Wall(s)	Plaster			None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L207	Floor	Ceramic Tile	1x1	Gray	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L207	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L207	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L207	Wall(s)	Ceramic Tile	4x4	Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L207	Wall(s)	Plaster			None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L208	Ceiling	Wallboard w/ Joint Compound		Off White	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	L208	Door/Door Frame	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L208	Wall(s)	Resilient Flooring Tile	12x12	Seafoam Blue	None Detected	No	YES	VALB-128-F1			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L209	Ceiling	Wallboard w/ Joint Compound		Off White	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	L209	Door/Door Frame	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L209	Wall(s)	Resilient Flooring Tile	12x12	Seafoam Blue	None Detected	No	YES	VALB-128-F1			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L210	Ceiling	Wallboard w/ Joint Compound		Off White	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	L210	Door/Door Frame	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L210	Wall(s)	Resilient Flooring Tile	12x12	Seafoam Blue	None Detected	No	YES	VALB-128-F1			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L212	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L212	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L212	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L212	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L212	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	L213	Ceiling	Wallboard w/ Joint Compound		Off White	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes

Floor	Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present?	Previously sampled?	Contractor Sampled (Y/N)	Contractor Sample No	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
2nd Floor	L213	Door/Door Frame	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L213	Wall(s)	Resilient Flooring Tile	12x12	Seafoam Blue	None Detected	No	YES	VALB-128-F1			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L215	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L215	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L215	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L215	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L215	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes

Floor	Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present?	Previously sampled?	Contractor Sampled (Y/N)	Contractor Sample No	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
2nd Floor	L216	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L216	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L216	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L216	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L216	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	L218	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L218	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L218	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L218	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L218	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	L221A	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L221A	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L221A	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L221A	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L221A	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	L221B	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L221B	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L221B	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L221B	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L221B	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	L223	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L223	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L223	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L223	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L223	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	M226	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	M226	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	M226	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	M226	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	M226	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	M227	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	M227	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	M227	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	M227	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	NN	N/A	N/A	N/A	N/A
2nd Floor	M227	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	M230	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	M230	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	NA	N/A	N/A	N/A
2nd Floor	M230	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	M230	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	NA
2nd Floor	M230	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	M232	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	M232	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	M232	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	M232	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	M232	Wall(s)	Wallboard w/ Joint Compound		None	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	M233	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	M233	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	M233	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	M233	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A

Floor	Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present?	Previously sampled?	Contractor Sampled (Y/N)	Contractor Sample No	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
2nd Floor	M233	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	M235	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	M235	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	M235	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	NA	N/A	N/A	N/A	N/A
2nd Floor	M235	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	NA	N/A	N/A	N/A	N/A
2nd Floor	M235	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes

Floor	Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present?	Previously sampled?	Contractor Sampled (Y/N)	Contractor Sample No	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
2nd Floor	M236	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	M236	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	M236	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	M236	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	M236	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	M238	Floor	Ceramic Tile	1x1	Gray	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/S	N/A	N/A
2nd Floor	M238	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	M238	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/S	N/A	N/A
2nd Floor	M238	Wall(s)	Ceramic Tile	4x4	Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/S	N/A	N/A
2nd Floor	M238	Wall(s)	Plaster			None Detected	Yes	No	N/A			N/A	N/A	N/A	N/S	N/A	N/A
2nd Floor	M239	Floor	Ceramic Tile	1x1	Gray	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	M239	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	M239	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	M239	Wall(s)	Ceramic Tile	4x4	Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	M239	Wall(s)	Plaster			None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	M240	Floor	Resilient Flooring Tile	12x12	Seafoam Blue	None Detected	No	YES	VALB-128-F1			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	M240	Misc	Cove Base	4"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	M240A	Floor	Ceramic Tile	1x1	Gray	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	M240A	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	M240A	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	M240A	Wall(s)	Ceramic Tile	4x4	Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	M240A	Wall(s)	Plaster			None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	M241	Floor	Resilient Flooring Tile	12x12	Seafoam Blue	None Detected	No	YES	VALB-128-F1			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	M241	Misc	Cove Base	4"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	M241	Misc	Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1			No	No	No	Yes	No	Yes
2nd Floor	M241A	Floor	Ceramic Tile	1x1	Gray	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	M241A	Ceiling	Plaster		Beige	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	M241A	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	M241A	Wall(s)	Ceramic Tile	4x4	Off White	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	M241A	Wall(s)	Plaster			None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	M242	Floor	Resilient Flooring Tile	12x12	Seafoam Blue	None Detected	No	YES	VALB-128-F1			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	M242	Misc	Cove Base	4"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	M243	Floor	Resilient Flooring Tile	12x12	Seafoam Blue	None Detected	No	YES	VALB-128-F1			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	M243	Misc	Cove Base	4"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	M244	Floor	Resilient Flooring Tile	12x12	Seafoam Blue	None Detected	No	YES	VALB-128-F1			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	M244	Misc	Cove Base	4"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	M245	Floor	Carpet		Blue	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	M245	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	M245	Door/Door Frame	Wood and Metal		Beige/Beige	Not Suspect Material	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	M245	Misc	Cove Base	4"	Off White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	M245	Wall(s)	Wallboard w/ Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
2nd Floor	Room 210B	Ceiling	Acoustic Ceiling Tile-Pinhole Worm	1' x 1'	White	None Detected	Yes	Yes	valb-128-C1 - C6								
2nd Floor	Room 210B	Misc	ACT-Mastic		White	None Detected	Yes	Yes	valb-128-m1			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	Room 210B	Misc	Drywall		White	None Detected		Y	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	Room A214	Misc	Covebase Mastic		Black	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	Room A223 and A225	Floor	Resilient Floor Tile with Mastic	12" x 12"	Tan and Tan	POS	No	Y	VALB-128-F2.1	no	Good	No	No	yes	No	No	yes
2nd Floor	Room A223 and A225	Ceiling	Acoustic Ceiling Tile-Pinhole Worm	2' x 4'	White	None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	Room CC128-K2-C3, C204, Roof-AH-1 and B-2	Misc	TSI/p	4000sq.ft.	White	POS	Yes	No	N/A	Yes	Good	No	No	No	Yes	No	No
2nd Floor	Room CC128-A2-C2	Floor	Resilient Floor Tile with Mastic	12" x 12"	Blue and Blue	None Detected		Y	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	Room CC128-J1	Ceiling	Acoustic Ceiling Tile-Pinhole	2' x 4'	White	None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	Room CC-128-L1-C2	Floor	Resilient Floor Tile with Mastic	12" x 12"	Green and Green	POS	No	Y	VALB-128-F3	no	Good	No	No	yes	No	No	yes
2nd Floor	Room FAC@L207	Ceiling	Wallboard		White	None Detected	Yes	Y	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	Room FAC@L207	Misc	Joint Compound		White	POS	Yes	Yes	VALB-128-C1			No	No	No	Yes	No	Yes
2nd Floor	Room 1412, 1464, 1468	Misc	Joint Compound		Beige	POS	Yes	Yes	VALB-128-C1			No	No	No	Yes	No	Yes

Floor	Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
						Asbestos Present?	Previously sampled?	Contractor Sampled (Y/N)	Contractor Sample No	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
2nd Floor	Room L115, C107 and C108	Door/Door Frame	resilient Floor Tile		Gray	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	L215,233A,J209,CC-2121,1419,209,141	Floor	Carpet Glue	9300 sq.ft.	Yellow	None Detected	Y	No	N/A			N/A			N/A	N/A	N/A
2nd Floor	Room P-1	Misc	Floor Tile Mastic		Black	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	Room202	Ceiling	Wallboard		White	None Detected		Y	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	Room202	Misc	Joint Compound		White	POS	Yes	Yes	VALB-128-C1			No	No	No	Yes	No	Yes
2nd Floor	RoomA120,CC3331	Floor	Resilient Floor Tile-12" x 12"	3000 sq.ft.	Blue and Pink	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	RoomC106,10204,1125,228,M204, and M103	Misc	TSI/F-Elbow		Beige,Gray and White	POS	Yes	No	N/A	Yes	Good	No	No	No	Yes	No	No
2nd Floor	RoomC20,CC-K2-C2	Floor	Resilient Floor Tile-12" x 12"	2000 sq.ft.	Light Blue with Blue	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	RoomL123A and C104	Misc	TSI/F Pipe Joint		Beige	POS	Yes	No	N/A	Yes	Good	No	No	No	Yes	No	No
2nd Floor	RoomL123A	Ceiling	Plaster		White	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
2nd Floor	RoomH122B,Common RoomK122P11 and 114007	Misc	TSIF/Hanger		Gray and White	POS	Yes	No	N/A	Yes	Good	No	No	No	Yes	No	No
2nd Floor	RoomK122P11	Floor	Resilient Floor Tile		Orange	None Detected	yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
Basement	B4	Floor	Resilient Flooring Tile	9x9	White w/Olive	POS	Yes	No	N/A	no	Good	No	No	yes	No	No	yes
Basement	B4	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	12x12	White/Brown	None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
Basement	B4	Ceiling	Wallboard w/ Joint Compound			POS	Yes	Yes	VALB-128-C1.2/1.3	no	Good	no	no	yes	no	no	yes
Basement	B4	Door/Door Frame	Metal and Metal		Blue/Orange	Not suspect	N/A	N/A	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A
Basement	B4	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
Basement	B4	Wall(s)	Concrete		Yellow/Orange	Not Suspect Material	N/A	Y	N/A			N/A			N/A	N/A	N/A
Basement	B-C1	Floor	Resilient Flooring Tile	9x9	White w/Olive	POS	Yes	No	N/A	no	Good	No	No	yes	No	No	yes
Basement	B-C1	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4	White	None Detected	Yes	Yes	valb-128-C1 - C6			N/A	N/A	N/A	N/A	N/A	N/A
Basement	B-C1	Door/Door Frame	Metal and Metal		Blue/Off White	Not suspect	N/A	N/A	N/A			N/A	N/A	N/A	N/A	N/A	N/A
Basement	B-C1	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
Basement	B-C1	Wall(s)	Concrete and Plaster		Blue/Gray	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
Basement	B-C2	Floor	Resilient Flooring Tile	9x9	White w/Olive	POS	Yes	No	N/A	no	Good	No	No	yes	No	No	yes
Basement	B-C2	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		None Detected	Yes	Yes	valb-128-C1 - C6	N/A							
Basement	B-C2	Door/Door Frame	Metal and Metal		Blue/Off White	Not suspect	N/A	N/A	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A
Basement	B-C2	Misc	Cove Base	4"	Tan	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
Basement	B-C2	Wall(s)	Concrete and Plaster		Blue/Gray	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
Exterior	West Roof and West Roof Par	Floor	HVAC Duct Sealant		Gray	None Detected	Yes	No	N/A								
Exterior	West Roof Par	Ceiling	Built Up Roof Gravel			None Detected	Y	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
Exterior	West Roof Par	Door/Door Frame	Rolled Roof (Middle) and Pen Mastic		Gray and Gray	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
Exterior	West Roof Par	Misc	ENTIRE ROOF-Mastic		Black and Gray	POS	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
Exterior	West Roof Par	Wall(s)	Pen Mastic		Gray and Black	POS	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
Exterior	Exterior	Misc	Window Putty	2000 Linear Feet	Black and Gray	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
Exterior	Roof-North and South	Floor	HVAC Duct Sealant		Gray	None Detected	Yes	No	N/A								
Exterior	Roof-North and South	Ceiling	Built Up Roof Gravel	46,500 sq.ft.	Gray and Black	None Detected	Y	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
Exterior	Roof-North and South	Door/Door Frame	Rolled Roof (Middle) and Pen Mastic		Gray and Gray	None Detected	Yes	No				N/A	N/A	N/A	N/A	N/A	N/A
Exterior	Roof-North and South	Misc	HVAC Caulking and Sealant	600 Linear Feet	Gray	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
Exterior	Roof-North and South	Misc	Roof Felt	46,500 sq ft..	Black	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
Exterior	Roof-North and South	Misc	TSI/p	2380 sq.ft.	White and Yellow	POS	Yes	No	N/A	Yes	Good	No	No	No	Yes	No	No
Exterior	Roof-North and South	Wall(s)	Pen Mastic	16,000 sq.ft.	Black	POS	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A
Exterior	South,West and North	Misc	Vapor Barrier	300 sq.ft.	Black	None Detected	Yes	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A