

Rm Name/No.		Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT								Comment
						Asbestos Present?	Previously Sampled? (Y/N)	Contractor Sampled?	Contractor Sample No.	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
Corridor at Y23		Misc	Mastic		Black/Orange	1%Chrysotile	Yes	No	No	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Corridor at Y25		Misc	Resilient Floor Tile and Mastic		Beige and Black	2%Chrysotile	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Ext		Door/Door Frame	Metal and Metal		Brown and Brown	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Ext		Misc	Vent Caulking		Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N	
Ext		Wall(s)	Window Sealant at Windows and Doors		Beige and Black	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
EXTERIOR NW,NE and SW ENDS		Misc	Caulkon Exterior Vents	700 Linear Feet	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
EXTERIOR WEST,NORTH and EAST		Misc	Caulk at Window and Doors	29,766 Linear Feet	Gray	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
RF.1E, RF2N, and RF.3S		Misc	Tarpaper on Parapet Wall	610 sq.ft.	Gray	None Detected	Yes	No	N	NF		N/A	N/A	N/A	N/A	N/A	N/A	
RF.1NW, RF2NE, and RF.3SW		Misc	Roof Mastic	100 sq.ft.	Black	5%Chrysotile	Yes	No	N	NF		N/A	N/A	N/A	N/A	N/A	N/A	
RF.7W RM.W681S,RM.X29A		Misc	HVAC Seal	300 sq.ft.	Gray	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
RF1W,RF2ERF3N		Misc	Roof Caulk	100 sq.ft.	White	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
RM.-Y14N,W47W,NW CORRIDOR		Misc	Covebase and Glue	1000 sq.ft.	Tan and White	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Roof		Misc	Roof Tar Sealant on Skylight andon Penetration		Black and Gray	5%Chrysotile	Yes	No	N	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Roof 1,2 and 3-Center		Misc	Built-Up Roof Felt and Insulationm	5382 sq.ft.	Gray	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Roof Main	X,Y, and Z Pods	Roof	Membrane Roof Sealed		White	Not Sampled	N/A	No	N/A	NF		N.A	N/A	N/A	N/A	N/A	N/A	Appears New; unkown conditions beneath
Roof Main		Floor	Roof Edge Top Plate Sealant 50		Gray	None Detected	No	Yes	VALB-133-r1.1	NF	Y	N/A	N/A	N/A	N/A	N/A	N/A	
Roof Main		TSI/F	TSI Hangers	8"	Gray and White	None Detected	Yes	Yes	VALB-133-TSI 1	Y		N/A	N/A	N/A	x	N/A	N/A	
Roof Main		Wall(s)	Pen Mastic Base of Pipe Runs		Black and Gray	None Detected	Yes	Yes	VALB-133-m1.1	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Room Z27 Entry		Misc	Resilient Floor Tile and Mastic		Gray and Black	2%Chrysotile	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Substation 18		Ceiling	Robinson Deck		Bare	Not Suspect	N/A	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Substation 18		Floor	Concrete		Bare	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
Substation 18		Misc	Fire Proofing		Gray	None Detected	No	Yes	VALB-133-FP1.	F		N/A	N/A	N/A	N/A	N/A	N/A	
Substation 18		Wall(s)	CMU		Bare	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W 71		Misc	Mastic		Black	5%Chrysotile	Yes	No	NA	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W41		Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
W41		Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
W41		Floor	Resilient Floor Tile	12x12	Seafoam/Mauve/ Green/Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W41		Misc	Covebase and Glue	4"	Beige and Gray	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W41		Wall(s)	Wallboard with Joint Compound			None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W42		Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x2		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
W42		Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
W42		Floor	Ceramic Tile and Grout	2x2	Pink	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
W42		Wall(s)	Ceramic Tile and Grout	4x4	Biege	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W42		Wall(s)	Wallboard with Joint Compound			None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W43		Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x2		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
W43		Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
W43		Floor	Ceramic Tile and Grout	2x2	Blue	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
W43		Wall(s)	Ceramic Tile and Grout	4x4	Biege	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W43		Wall(s)	Wallboard with Joint Compound			None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W44		Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
W44		Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
W44		Floor	Resilient Floor Tile	12x12	Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W44		Misc	Covebase and Glue	4"	Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W44		Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	

Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT								Comment
					Asbestos Present?	Previously Sampled? (Y/N)	Contractor Sampled?	Contractor Sample No.	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
W45A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material Possible Floor tile/mastic underneath
W45A	Door/Door Frame	Wood and Metal		Beige	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W45A	Floor	Carpet		Black and Black	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
W45A	Misc	Covebase and Glue	4"	Pink	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W45A	Wall(s)	Wallboard with Joint Compound		Biege	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W46	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
W46	Floor	Resilient Floor Tile	12x12	Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W46	Misc	Covebase and Glue	4"	Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W46	Wall(s)	Wallboard with Joint Compound		Beige and Green	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W47	Ceiling	Acoustic Ceiling Tile (Pinhole)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
W47	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Floor tile/mastic underneath
W47	Floor	Carpet		Brown	ACM Underneath	Yes	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
W47	Misc	Covebase and Glue	4"	Beige and Gray	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W47	Wall(s)	Wallboard with Joint Compound		Beige and Green	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W48	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material Possible Floor tile/mastic underneath
W48	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W48	Floor	Carpet		Blue	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
W48	Misc	Covebase and Glue	4"	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W48	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W49	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material Possible Floor tile/mastic underneath
W49	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W49	Floor	Carpet		Blue	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
W49	Misc	Covebase and Glue	4"	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W49	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W51B	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
W51B	Door/Door Frame	Wood and Metal		Blue and Blue	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W51B	Floor	Ceramic Tile and Grout	1x1	Yellow and Gray	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
W51B	Wall(s)	Ceramic Tile and Grout	4x4	Pink	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W51B	Wall(s)	Wallboard with Joint Compound		Off-White	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W52	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material Possible Floor tile/mastic underneath
W52	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W52	Floor	Carpet		Blue	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
W52	Misc	Covebase and Glue	4"	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W52	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W53	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material Possible Floor tile/mastic underneath
W53	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W53	Floor	Carpet		Brown	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
W53	Misc	Covebase and Glue	4"	Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W53	Wall(s)	Wallboard with Joint Compound		Beige and Green	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W54	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
W54	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W54	Floor	Resilient Floor Tile	12x12	Seafoam/Mauve/ Green/Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W54	Misc	Covebase and Glue	4"	Beige and Gray	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W54	Wall(s)	Wallboard with Joint Compound		Beige and Green	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	

Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT								Comment
					Asbestos Present?	Previously Sampled? (Y/N)	Contractor Sampled?	Contractor Sample No.	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
W55	Ceiling	Acoustic Ceiling Tile (Pinhole)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/Z	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
W55	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W55	Floor	Ceramic Tile and Grout	2x2	Pink	Not Suspect	No	No	N/A	N/A		N/Z	N/A	N/A	N/A	NN	N/A	
W55	Wall(s)	Ceramic Tile and Grout	4x4	Off-White	Not Suspect	No	No	N/A	NF		N/Z	N/A	N/A	N/A	N/A	N/A	
W55	Wall(s)	Wallboard with Joint Compound		Off-White	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W56	Ceiling	Acoustic Ceiling Tile (Pinhole)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
W56	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W56	Floor	Ceramic Tile and Grout	2x2	Blue	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
W56	Wall(s)	Ceramic Tile and Grout	4x4	Off-White	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W56	Wall(s)	Wallboard with Joint Compound		Off-White	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W57	Ceiling	Acoustic Ceiling Tile (Pinhole)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
W57	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W57	Floor	Ceramic Tile and Grout	1x1	Blue and Gray	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
W57	Wall(s)	Ceramic Tile and Grout	4x4	Blue	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W57	Wall(s)	Ceramic Tile and Grout	4x4	Light Blue	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W57	Wall(s)	Wallboard with Joint Compound		Off-White	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W58	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		NNone Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
W58	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W58	Floor	Ceramic Tile and Grout	1x1	Yellow and Gray	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
W58	Wall(s)	Wallboard with Joint Compound		Biege	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W58A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
W58A	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W58A	Floor	Ceramic Tile and Grout	1x1	Yellow and Gray	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
W58A	Wall(s)	Wallboard with Joint Compound		Biege	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W59	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
W59	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W59	Floor	Ceramic Tile and Grout	1x1	Yellow and Gray	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
W59	Misc	Ceramic Tile and Grout	4x4	Yellow	None Detected	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W59	Wall(s)	Wallboard with Joint Compound		Biege	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
W59A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
W59A	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W59A	Floor	Ceramic Tile and Grout	1x1	Yellow and Gray	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
W59A	Misc	Ceramic Tile and Grout	4x4	Pink	None Detected	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W59A	Misc	Ceramic Tile and Grout	4x4	Yellow	Nne Notedo	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W59A	Wall(s)	Wallboard with Joint Compound		Biege	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W6	Ceiling	Hardlid Wallboard with Joint Compound	2x4	Off-White	None Detected	Y	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
W6	Floor	Concrete		Bare	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
W6	Wall(s)	Concrete		Off-White	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W61	Ceiling	Hardlid Wallboard with Joint Compound	2x4	Off-White	None Detected	Y	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W61	Door/Door Frame	Metal and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W61	Floor	Concrete		Bare	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
W61	Misc	Fire Stop		Red	None Detected	No	Yes	VALB-133-m1.1	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W61	TSI	TSI/F 6" T West	6"	Gray	None Detected	Yes	Yes	VALB-133-TSI 1	Y		N/A	N/A	N/A	x	N/A	N/A	
W61	TSI	TSI/F 8" T South	8"	Gray	None Detected	Yes	Yes	VALB-133-TSI 1	Y		N/A	N/A	N/A	x	N/A	N/A	

Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT								Comment
					Asbestos Present?	Previously Sampled? (Y/N)	Contractor Sampled?	Contractor Sample No.	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	SignificantlyDamaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
W61	Wall(s)	Concrete		Off-White	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	

Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT								Comment
					Asbestos Present?	Previously Sampled? (Y/N)	Contractor Sampled?	Contractor Sample No.	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
W62	Under Construction	Floor	Concrete		Bare	Not Suspect	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
W62		Misc	Fire Stop		Red	None Detected	No	VALB-133-m1.1	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W62		Wall(s)	Concrete		Off-White White	Not Suspect	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W62		Ceiling	Hardlid Wallboard with Joint Compound	2x4		None Detected	Y	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W67		Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	
W67		Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
W67		Floor	Resilient Floor Tile	12x12	Olive	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	
W67		Misc	Covebase and Glue	4"	Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	
W67		Wall(s)	Wallboard with Joint Compound		Beige and Green	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	
W67A		Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	
W67A		Ceiling	Hardlid Drywall		Off-White	None Detected	Y	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	
W67A		Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
W67A		Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
W67A		Floor	Resilient Floor Tile	12x12	Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	
W67A		Floor	Resilient Floor Tile and Black Mastic	12x12	White with Beige	4%Chrysotile	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	ACM is in mastic
W67A		Misc	Covebase and Glue	4"	Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	
W67A		Misc	Covebase and Glue	4'	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	
W67A		Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	
W67A		Wall(s)	Wallboard with Joint Compound		Off-White	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	
W68		Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	
W68		Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
W68		Floor	Carpet		Blue	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	Possible Floor tile/mastic underneath
W68		Misc	Covebase and Glue	4"	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	
W68		Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	
W69		Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	
W69		Floor	Resilient Floor Tile	12x12	Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	
W69		Misc	Covebase and Glue	4"	Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	
W69		Wall(s)	Wallboard with Joint Compound		Beige and Green	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	
W70		Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	
W70		Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
W70		Floor	Carpet		Blue	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	Possible Floor tile/mastic underneath
W70		Misc	Covebase and Glue	4"	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	
W70		Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	
W71		Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	
W71		Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
W71		Floor	Resilient Floor Tile	12x12	Seafoam/Mauve/ Green/Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	
W71		Misc	Covebase and Glue	4"	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	
W71		Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	
W72		Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	
W72		Floor	Resilient Floor Tile	12x12	Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	
W72		Misc	Covebase and Glue	4"	Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	
W72		Wall(s)	Wallboard with Joint Compound		Beige and Green	None Noyed	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	
W73		Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	
W73		Floor	Resilient Floor Tile	12x12	Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	
W73		Misc	Covebase and Glue	4"	Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	
W73		Wall(s)	Wallboard with Joint Compound		Beige and Green	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	

Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT								Comment
					Asbestos Present?	Previously Sampled? (Y/N)	Contractor Sampled?	Contractor Sample No.	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
W74	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
W74	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W74	Floor	Carpet		Blue	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	Possible Floor tile/mastic underneath
W74	Misc	Covebase and Glue	4"	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W74	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W75	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		NNone Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
W75	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W75	Floor	Carpet		Blue	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	Possible Floor tile/mastic underneath
W75	Misc	Covebase and Glue	4"	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W75	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W76	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
W76	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W76	Floor	Carpet		Blue	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	Possible Floor tile/mastic underneath
W76	Misc	Covebase and Glue	4"	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W76	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W77	Ceiling	Acoustic Ceiling Tile (Pinhole)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
W77	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W77	Floor	Ceramic Tile and Grout	2x2	Brown	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
W77	Wall(s)	Ceramic Tile and Grout	4x4	Beige and Brown	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W77	Wall(s)	Wallboard with Joint Compound		Off-White	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W78	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
W78	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W78	Floor	Carpet		Blue	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	Possible Floor tile/mastic underneath
W78	Misc	Covebase and Glue	4"	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W78	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W79	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		Nonbe Noted	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
W79	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W79	Floor	Carpet		Blue	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	Possible Floor tile/mastic underneath
W79	Misc	Covebase and Glue	4"	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W79	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W80	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
W80	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W80	Floor	Ceramic Tile and Grout	6x6	Tan	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
W80	Wall(s)	Ceramic Tile and Grout	4x4	Beige	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W80	Wall(s)	Plaster		Gray	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W80	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W80B	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
W80B	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W80B	Floor	Ceramic Tile and Grout	6x6	Tan	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
W80B	Wall(s)	Ceramic Tile and Grout	4x4	Red	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W80B	Wall(s)	Plaster		Gray	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W80B	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W80C	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
W80C	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W80C	Floor	Ceramic Tile and Grout	6x6	Tan	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
W80C	Wall(s)	Ceramic Tile and Grout	4x4	White and Gold	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W80C	Wall(s)	Plaster		Gray	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W80C	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W-C1	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
W-C1	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W-C1	Floor	Resilient Floor Tile	12x12	Seafoam/Mauve/ Green/Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	

Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT								Comment
					Asbestos Present?	Previously Sampled? (Y/N)	Contractor Sampled?	Contractor Sample No.	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
W-C1	Misc	Covebase and Glue	4"	Beige and Gray	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W-C1	Wall(s)	Wallboard with Joint Compound		Beige and Green	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W-C2	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
W-C2	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
W-C2	Floor	Resilient Floor Tile	12x12	Seafoam/Mauve/ Green/Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W-C2	Misc	Covebase and Glue	4"	Beige and Gray	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W-C2	Wall(s)	Wallboard with Joint Compound		Beige and Green	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W-C4	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
W-C4	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
W-C4	Floor	Resilient Floor Tile	12x12	Seafoam/Mauve/ Green/Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W-C4	Misc	Covebase and Glue	4"	Beige and Gray	None Noter	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W-C4	Wall(s)	Wallboard with Joint Compound		Beige and Green	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W-C6	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
W-C6	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
W-C6	Floor	Resilient Floor Tile	12x12	Seafoam/Mauve/ Green/Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W-C6	Misc	Covebase and Glue	4"	Beige and Gray	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
W-C6	Wall(s)	Wallboard with Joint Compound		Beige and Green	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
West 61 Corridor	Floor	Resilient Floor Tile and Mastic		Black and Gray	3%Chrysotile	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
WEST WING RM.W62	Misc	TSI at Elbow and Tank	100 sq.ft.	Gray	None Detected	Yes	Yes	VALB-133-TS1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
WEST WING TV ROOM 225	Misc	Resilient Floor Tile and Mastic (Masticis Black- 3%Chrysotile)	35,000 sq.ft.	Multi-Color	3%Chrysotile	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
WEST WING TV ROOM Z39,X2	Door/Door Frame	Wood and Metal		Gray and White	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
WEST WING TV ROOM,Z25,AND X2	Misc	Resilient Floor Tile and Glue (Glue is Yellow)	35,000 sq.ft.	Green,Blue and Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Ww51	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
Ww51	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Ww51	Floor	Carpet		Blue	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	Possible Floor tile/mastic underneath
Ww51	Misc	Covebase and Glue	4"	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Ww51	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X1	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
X1	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X1	Floor	Resilient Floor Tile	12x12	Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X1	Floor	Resilient Floor Tile		Woodgrain	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X1	Misc	Covebase and Glue	4"	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X1	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X10	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
X10	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X10	Floor	Resilient Floor Tile	12x12	Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X10	Floor	Resilient Floor Tile		Woodgrain	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X10	Misc	Covebase and Glue	4"	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X10	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X11A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
X11A	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X11A	Floor	Resilient Floor Tile		Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X11A	Wall(s)	Ceramic Tile and Grout	4x4	Blue	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X11A	Wall(s)	Ceramic Tile and Grout	4x4	Off-White	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X11A	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X12	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
X12	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X12	Floor	Resilient Floor Tile	12x12	Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X12	Floor	Resilient Floor Tile		Woodgrain	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X12	Misc	Covebase and Glue	4"	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X12	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X13	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
X13	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material

Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT								Comment
					Asbestos Present?	Previously Sampled? (Y/N)	Contractor Sampled?	Contractor Sample No.	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
X13	Floor	Ceramic Tile and Grout	2x2	Blue	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
X13	Wall(s)	Ceramic Tile and Grout	4x4	Blue	Not Suspect	No	No	N/A	NF		N/A	B/A	N/A	N/A	N/A	N/A	
X13	Wall(s)	Ceramic Tile and Grout	4x4	Off-White White	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
X15	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X15	Floor	Ceramic Tile and Grout	2x2	Blue	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
X15	Wall(s)	Ceramic Tile and Grout	4x4	Blue	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X15	Wall(s)	Ceramic Tile and Grout	4x4	Off-White White	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X16	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
X16	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
X16	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X16	Floor	Resilient Floor Tile	12x12	Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X16	Floor	Resilient Floor Tile		Woodgrain	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X16	Misc	Covebase and Glue	4"	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X16	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X16A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
X16A	Door/Door Frame	Wood and Metal		Blue and Blue	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X16A	Floor	Ceramic Tile and Grout	2x2	Blue	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
X16A	Wall(s)	Ceramic Tile and Grout	4x4	Blue	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X16A	Wall(s)	Ceramic Tile and Grout	4x4	Off-White	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X16A	Wall(s)	Wallboard with Joint Compound			None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X17	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
X17	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X17	Floor	Resilient Floor Tile		Woodgrain	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X17	Misc	Covebase and Glue	4"	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X17	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X17A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
X17A	Door/Door Frame	Wood and Metal		Blue and Blue	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X17A	Floor	Ceramic Tile and Grout	2x2	Blue	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
X17A	Wall(s)	Ceramic Tile and Grout	4x4	Blue	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X17A	Wall(s)	Ceramic Tile and Grout	4x4	Off-White	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X17A	Wall(s)	Wallboard with Joint Compound			None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X18	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
X18	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X18	Floor	Resilient Floor Tile		Woodgrain	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X18	Misc	Covebase and Glue	4"	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X18	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X18A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
X18A	Door/Door Frame	Wood and Metal		Blue and Blue	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X18A	Floor	Ceramic Tile and Grout	2x2	Blue	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
X18A	Wall(s)	Ceramic Tile and Grout	4x4	Blue	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X18A	Wall(s)	Ceramic Tile and Grout	4x4	Off-White	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X18A	Wall(s)	Wallboard with Joint Compound			None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X19	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
X19	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X19	Floor	Resilient Floor Tile		Woodgrain	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X19	Misc	Covebase and Glue	4"	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X19	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X19A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
X19A	Door/Door Frame	Wood and Metal		Blue and Blue	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X19A	Floor	Ceramic Tile and Grout	2x2	Blue	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
X19A	Wall(s)	Ceramic Tile and Grout	4x4	Blue	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X19A	Wall(s)	Ceramic Tile and Grout	4x4	Off-White	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X19A	Wall(s)	Wallboard with Joint Compound			None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X1A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
X1A	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X1A	Floor	Resilient Floor Tile		Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	

Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT								Comment
					Asbestos Present?	Previously Sampled? (Y/N)	Contractor Sampled?	Contractor Sample No.	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	SignificantlyDamaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
X1A	Wall(s)	Ceramic Tile and Grout	4x4	Blue	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X1A	Wall(s)	Ceramic Tile and Grout	4x4	Off-White	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X1A	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X2	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
X2	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X2	Floor	Resilient Floor Tile	12x12	Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X2	Floor	Resilient Floor Tile		Woodgrain	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X2	Misc	Covebase and Glue	4"	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X2	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X20	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
X20	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X20	Floor	Resilient Floor Tile		Woodgrain	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X20	Misc	Covebase and Glue	4"	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X20	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X20A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
X20A	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X20A	Floor	Resilient Floor Tile		Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X20A	Wall(s)	Ceramic Tile and Grout	4x4	Blue	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X20A	Wall(s)	Ceramic Tile and Grout	4x4	Off-White	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X20A	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X20A	Misc	Resilient Floor Tile and Glue (Glue is Gray)	3192 sq.ft.	Wood Grain	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X21	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
X21	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X21	Floor	Resilient Floor Tile		Woodgrain	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X21	Misc	Covebase and Glue	4"	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X21	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	

Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT								Comment
					Asbestos Present?	Previously Sampled? (Y/N)	Contractor Sampled?	Contractor Sample No.	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
X22	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X22	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X22	Floor	Resilient Floor Tile		Woodgrain	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X22	Misc	Covebase and Glue	4"	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X22	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X22A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X22A	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X22A	Floor	Resilient Floor Tile		Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X22A	Wall(s)	Ceramic Tile and Grout	4x4	Blue	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X22A	Wall(s)	Ceramic Tile and Grout	4x4	Off-White	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X22A	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X23	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X23	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X23	Floor	Resilient Floor Tile		Woodgrain	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X23	Misc	Covebase and Glue	4"	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X23	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X24	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X24	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X24	Floor	Resilient Floor Tile		Woodgrain	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X24	Misc	Covebase and Glue	4"	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X24	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X24A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X24A	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X24A	Floor	Resilient Floor Tile		Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X24A	Wall(s)	Ceramic Tile and Grout	4x4	Blue	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X24A	Wall(s)	Ceramic Tile and Grout	4x4	Off-White	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X24A	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X25	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X25	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X25	Floor	Resilient Floor Tile		Woodgrain	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X25	Misc	Covebase and Glue	4"	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X25	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X26	Ceiling	Acoustic Ceiling Tile (Pinhole)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X26	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X26	Floor	Resilient Floor Tile	12x12	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X26	Misc	Covebase and Glue	6"	Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X26	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X26	Misc	Carpet Glue	4400 sq.ft.	Yellow	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X27	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X27	Door/Door Frame	Wood and Metal		Blue and Blue	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X27	Floor	Ceramic Tile and Grout	2x2	Blue	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
X27	Wall(s)	Ceramic Tile and Grout	4x4	Blue	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X27	Wall(s)	Ceramic Tile and Grout	4x4	Off-White	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X27	Wall(s)	Wallboard with Joint Compound			None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X27A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X27A	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X27A	Floor	Resilient Floor Tile	12x12	Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X27A	Misc	Covebase and Glue	4"	Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X27A	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X28	Ceiling	Acoustic Ceiling Tile (Pinhole)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X28	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X28	Floor	Resilient Floor Tile		Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X28	Misc	Covebase and Glue	6"	Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X28	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X29A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X29A	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X29A	Floor	Resilient Floor Tile	12x12	Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	

Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT								Comment
					Asbestos Present?	Previously Sampled? (Y/N)	Contractor Sampled?	Contractor Sample No.	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
X29A	Misc	Covebase and Glue	4"	Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X29A	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X2A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
X2A	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X2A	Floor	Resilient Floor Tile		Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X2A	Wall(s)	Ceramic Tile and Grout	4x4	Blue	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X2A	Wall(s)	Ceramic Tile and Grout	4x4	Off-White	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X2A	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	

Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT								Comment
					Asbestos Present?	Previously Sampled? (Y/N)	Contractor Sampled?	Contractor Sample No.	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
X3	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X3	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X3	Floor	Resilient Floor Tile	12x12	Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X3	Floor	Resilient Floor Tile		Woodgrain	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X3	Misc	Covebase and Glue	4"	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X3	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X30	Ceiling	Acoustic Ceiling Tile (Pinhole)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X30	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X30	Floor	Resilient Floor Tile		Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X30	Misc	Covebase and Glue	6"	Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X30	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X31	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X31	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X31	Floor	Resilient Floor Tile	12x12	Seafoam Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X31	Misc	Covebase and Glue	6"	Beige and Gray	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X31	Wall(s)	Wallboard with Joint Compound		Beige and Green	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X33	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X33	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X33	Floor	Resilient Floor Tile	12x12	Seafoam Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X33	Misc	Covebase and Glue	6"	Beige and Gray	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X33	Wall(s)	Wallboard with Joint Compound		Beige and Green	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X-33A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X-33A	Door/Door Frame	Wood and Metal		Beige and Beige	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X-33A	Floor	Ceramic Tile and Grout	2x2	Blue	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
X-33A	Wall(s)	Ceramic Tile and Grout	4x4	White and Gold	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X-33A	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X33B	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X33B	Door/Door Frame	Wood and Metal		Beige and Beige	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X33B	Floor	Ceramic Tile and Grout	2x2	Blue and Gray	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
X33B	Wall(s)	Ceramic Tile and Grout	4x4	White with Gold	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X33B	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X35	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X35	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X35	Floor	Resilient Floor Tile		Woodgrain	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X35	Misc	Covebase and Glue	4"	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X35	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X35A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X35A	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X35A	Floor	Resilient Floor Tile		Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X35A	Wall(s)	Ceramic Tile and Grout	4x4	Blue	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X35A	Wall(s)	Ceramic Tile and Grout	4x4	Off-White	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X35A	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X36	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X36	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X36	Floor	Resilient Floor Tile		Woodgrain	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X36	Misc	Covebase and Glue	4"	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X36	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X36A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X36A	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X36A	Floor	Resilient Floor Tile		Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X36A	Wall(s)	Ceramic Tile and Grout	4x4	Blue	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X36A	Wall(s)	Ceramic Tile and Grout	4x4	Off-White	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X36A	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X37	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X37	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X37	Floor	Resilient Floor Tile		Woodgrain	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	

Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT								Comment
					Asbestos Present?	Previously Sampled? (Y/N)	Contractor Sampled?	Contractor Sample No.	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
X37	Misc	Covebase and Glue	4"	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X37	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X38	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
X38	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X38	Floor	Resilient Floor Tile		Woodgrain	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X38	Misc	Covebase and Glue	4"	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X38	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X38A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
X38A	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X38A	Floor	Resilient Floor Tile		Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X38A	Wall(s)	Ceramic Tile and Grout	4x4	Blue	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X38A	Wall(s)	Ceramic Tile and Grout	4x4	Off-White	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X38A	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X39	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
X39	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X39	Floor	Resilient Floor Tile		Woodgrain	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X39	Misc	Covebase and Glue	4"	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X39	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X3A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
X3A	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X3A	Floor	Resilient Floor Tile		Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X3A	Wall(s)	Ceramic Tile and Grout	4x4	Blue	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X3A	Wall(s)	Ceramic Tile and Grout	4x4	Off-White	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X3A	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X4	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
X4	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X4	Floor	Resilient Floor Tile	12x12	Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X4	Floor	Resilient Floor Tile		Woodgrain	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X4	Misc	Covebase and Glue	4"	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X4	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X40	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
X40	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X40	Floor	Carpet		Brown	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	Possible Floor tile/mastic underneath
X40	Misc	Covebase and Glue	4"	Beige and Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X40	Wall(s)	Wallboard with Joint Compound		Beige and Green	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X4A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
X4A	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X4A	Floor	Resilient Floor Tile		Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X4A	Wall(s)	Ceramic Tile and Grout	4x4	Blue	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X4A	Wall(s)	Ceramic Tile and Grout	4x4	Off-White	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X4A	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X5	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
X5	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X5	Floor	Resilient Floor Tile		Woodgrain	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X5	Floor	Resilient Floor Tile and Mastic	12x12	Beige and Black	4%Chrysotile	Yes	Yes	VALB-133-f2.1	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X5	Misc	Covebase and Glue	4"	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X5	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X5A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
X5A	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X5A	Floor	Resilient Floor Tile		Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X5A	Wall(s)	Ceramic Tile and Grout	4x4	Blue	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X5A	Wall(s)	Ceramic Tile and Grout	4x4	Off-White	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X5A	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X6	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
X6	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X6	Floor	Resilient Floor Tile		Woodgrain	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	

Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT								Comment
					Asbestos Present?	Previously Sampled? (Y/N)	Contractor Sampled?	Contractor Sample No.	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
X6	Floor	Resilient Floor Tile and Mastic	12x12	Beige and Black	4%Chrysotile	Yes	Yes	VALB-133-f2.1	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X6	Misc	Covebase and Glue	4"	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X6	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X6A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
X6A	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X6A	Floor	Resilient Floor Tile		Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X6A	Wall(s)	Ceramic Tile and Grout	4x4	Blue	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X6A	Wall(s)	Ceramic Tile and Grout	4x4	Off-White	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X6A	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	

Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT								Comment
					Asbestos Present?	Previously Sampled? (Y/N)	Contractor Sampled?	Contractor Sample No.	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
X7	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X7	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X7	Floor	Resilient Floor Tile	12x12	Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X7	Floor	Resilient Floor Tile		Woodgrain	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X7	Misc	Covebase and Glue	4"	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X7	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X7A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X7A	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X7A	Floor	Resilient Floor Tile		Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X7A	Wall(s)	Ceramic Tile and Grout	4x4	Blue	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X7A	Wall(s)	Ceramic Tile and Grout	4x4	Off-White	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X7A	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X8	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X8	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X8	Floor	Resilient Floor Tile	12x12	Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X8	Floor	Resilient Floor Tile		Woodgrain	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X8	Misc	Covebase and Glue	4"	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X8	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X9	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X9	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X9	Floor	Resilient Floor Tile	12x12	Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X9	Floor	Resilient Floor Tile		Woodgrain	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X9	Misc	Covebase and Glue	4"	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X9	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X9A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X9A	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X9A	Floor	Resilient Floor Tile		Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X9A	Wall(s)	Ceramic Tile and Grout	4x4	Blue	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X9A	Wall(s)	Ceramic Tile and Grout	4x4	Off-White	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X9A	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X-C1	Ceiling	Acoustic Ceiling Tile (Pinhole)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X-C1	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X-C1	Floor	Resilient Floor Tile	12x12	Seafoam/Mauve/ Green/Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X-C1	Misc	Covebase and Glue	6"	Beige and Gray	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X-C1	Wall(s)	Wallboard with Joint Compound		Beige and Green	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X-C3	Ceiling	Acoustic Ceiling Tile (Pinhole)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X-C3	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X-C3	Floor	Resilient Floor Tile	12x12	Seafoam/Mauve/ Green/Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X-C3	Misc	Covebase and Glue	6"	Beige and Gray	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X-C3	Wall(s)	Wallboard with Joint Compound		Beige and Green	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X-C4	Ceiling	Acoustic Ceiling Tile (Pinhole)	2x4		Nonw Noted	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X-C4	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X-C4	Floor	Resilient Floor Tile	12x12	Seafoam/Mauve/ Green/Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X-C4	Misc	Covebase and Glue	6"	Beige and Gray	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X-C4	Wall(s)	Wallboard with Joint Compound		Beige and Green	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X-C5	Ceiling	Acoustic Ceiling Tile (Pinhole)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
X-C5	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X-C5	Floor	Resilient Floor Tile	12x12	Seafoam/Mauve/ Green/Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X-C5	Misc	Covebase and Glue	6"	Beige and Gray	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
X-C5	Wall(s)	Wallboard with Joint Compound		Beige and Green	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	

Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT								Comment
					Asbestos Present?	Previously Sampled? (Y/N)	Contractor Sampled?	Contractor Sample No.	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
Y1	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
Y1	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y1	Floor	Ceramic Tile	12x12	White with Beige	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
Y1	Floor	Resilient Floor Tile	12x12	Mustard	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y1	Floor	Resilient Floor Tile	12x12	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y1	Wall(s)	Wallboard with Joint Compound		Tan and Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y10	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
Y10	Door/Door Frame	Wood and Metal		Beige and Gray	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y10	Floor	Resilient Floor Tile	12x12	Red	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y10	Floor	Resilient Floor Tile	12x12	White with Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y10	Wall(s)	Wallboard with Joint Compound		Tan and Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y11	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
Y11	Door/Door Frame	Wood and Metal		Beige and Gray	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y11	Floor	Resilient Floor Tile	12x12	Red	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y11	Floor	Resilient Floor Tile	12x12	White with Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y11	Wall(s)	Wallboard with Joint Compound		Tan and Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y11A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
Y11A	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y11A	Floor	Ceramic Tile	1x1	Pink and Yellow	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
Y11A	Wall(s)	Ceramic Tile	4x4	Pink	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y11A	Wall(s)	Wallboard with Joint Compound		Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y12	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
Y12	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y12	Floor	Ceramic Tile	1x1	Yellow and Gray	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N	N/A	N/A	
Y12	Wall(s)	Ceramic Tile	4x4	Red and Orange	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y12	Misc	Covebase and Glue			None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y13	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
Y13	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y13	Floor	Ceramic Tile	1x1	Yellow and Gray	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N	N/A	N/A	
Y13	Wall(s)	Ceramic Tile	4x4	Red and Orange	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y13	Wall(s)	Ceramic Tile	4x4	White and Gold	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y15	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
Y15	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y15	Floor	Ceramic Tile	1x1	Yellow and Gray	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
Y15	Wall(s)	Ceramic Tile	4x4	Red and Orange	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y15	Wall(s)	Ceramic Tile	4x4	White and Gold	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y16	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
Y16	Door/Door Frame	Wood and Metal		Beige and Gray	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y16	Floor	Resilient Floor Tile	12x12	Red	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y16	Floor	Resilient Floor Tile	12x12	White with Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y16	Wall(s)	Wallboard with Joint Compound		Tan and Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y16A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
Y16A	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y16A	Floor	Ceramic Tile	1x1	Pink and Yellow	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
Y16A	Wall(s)	Ceramic Tile	4x4	Pink	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y16A	Wall(s)	Wallboard with Joint Compound		Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y17	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
Y17	Door/Door Frame	Wood and Metal		Beige and Gray	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y17	Floor	Resilient Floor Tile	12x12	Red	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y17	Floor	Resilient Floor Tile	12x12	White with Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y17	Wall(s)	Wallboard with Joint Compound		Tan and Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y18	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
Y18	Door/Door Frame	Wood and Metal		Beige and Gray	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y18	Floor	Resilient Floor Tile	12x12	Red	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y18	Floor	Resilient Floor Tile	12x12	White with Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y18	Wall(s)	Wallboard with Joint Compound		Tan and Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	

Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT								Comment
					Asbestos Present?	Previously Sampled? (Y/N)	Contractor Sampled?	Contractor Sample No.	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
Y19	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
Y19	Door/Door Frame	Wood and Metal		Beige and Gray	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y19	Floor	Resilient Floor Tile	12x12	Red	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y19	Floor	Resilient Floor Tile	12x12	White with Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y19	Wall(s)	Wallboard with Joint Compound		Tan and Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	

Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT								Comment
					Asbestos Present?	Previously Sampled? (Y/N)	Contractor Sampled?	Contractor Sample No.	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
Y19A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y19A	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y19A	Floor	Ceramic Tile	1x1	Pink and Yellow	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
Y19A	Wall(s)	Ceramic Tile	4x4	Pink	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y19A	Wall(s)	Wallboard with Joint Compound		Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y1A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y1A	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y1A	Floor	Ceramic Tile	1x1	Yellow and Gray	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
Y1A	Misc	Ceramic Tile	4x4	White and Gold	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y1A	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y2	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y2	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y2	Floor	Ceramic Tile	12x12	White with Beige	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
Y2	Floor	Resilient Floor Tile	12x12	Mustard	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y2	Floor	Resilient Floor Tile	12x12	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y2	Wall(s)	Wallboard with Joint Compound		Tan and Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y20	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y20	Door/Door Frame	Wood and Metal		Beige and Gray	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y20	Floor	Resilient Floor Tile	12x12	Red	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y20	Floor	Resilient Floor Tile	12x12	White with Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y20	Wall(s)	Wallboard with Joint Compound		Tan and Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y20A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y20A	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y20A	Floor	Ceramic Tile	1x1	Pink and Yellow	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
Y20A	Wall(s)	Ceramic Tile	4x4	Pink	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y20A	Wall(s)	Wallboard with Joint Compound		Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y21	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y21	Door/Door Frame	Wood and Metal		Beige and Gray	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y21	Floor	Resilient Floor Tile	12x12	Red	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y21	Floor	Resilient Floor Tile	12x12	White with Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y21	Wall(s)	Wallboard with Joint Compound		Tan and Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y22	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y22	Door/Door Frame	Wood and Metal		Beige and Gray	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y22	Floor	Resilient Floor Tile	12x12	Red	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y22	Floor	Resilient Floor Tile	12x12	White with Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y22	Wall(s)	Wallboard with Joint Compound		Tan and Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y22A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y22A	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y22A	Floor	Ceramic Tile	1x1	Pink and Yellow	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
Y22A	Wall(s)	Ceramic Tile	4x4	Pink	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y22A	Wall(s)	Wallboard with Joint Compound		Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y23	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y23	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y23	Floor	Resilient Floor Tile	12x12	White with Gray	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y23	Misc	Covebase and Glue	4x4	Beige and Gray	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y23	Wall(s)	Wallboard with Joint Compound		Tan and Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y24A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y24A	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y24A	Floor	Ceramic Tile	1x1	Pink and Yellow	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
Y24A	Wall(s)	Ceramic Tile	4x4	Pink	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y24A	Wall(s)	Wallboard with Joint Compound		Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y25	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y25	Door/Door Frame	Wood and Metal		Beige and Gray	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y25	Floor	Resilient Floor Tile	12x12	Red	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y25	Floor	Resilient Floor Tile	12x12	White with Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y25	Wall(s)	Wallboard with Joint Compound		Tan and Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	

Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT								Comment
					Asbestos Present?	Previously Sampled? (Y/N)	Contractor Sampled?	Contractor Sample No.	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	SignificantlyDamaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
Y26	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
Y26	Door/Door Frame	Wood and Metal		Beige and Gray	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y26	Floor	Resilient Floor Tile	12x12	White with Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y26	Wall(s)	Wallboard with Joint Compound		Tan and Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	

Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT								Comment
					Asbestos Present?	Previously Sampled? (Y/N)	Contractor Sampled?	Contractor Sample No.	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
Y27A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y27A	Door/Door Frame	Wood and Metal		Beige and Gray	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y27A	Floor	Resilient Floor Tile	12x12	White with Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y27A	Wall(s)	Wallboard with Joint Compound		Tan and Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y28A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y28A	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y28A	Floor	Resilient Floor Tile	12x12	White with Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y28A	Misc	Covebase and Glue	4"	Beige and Gray	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y28A	Wall(s)	Wallboard with Joint Compound		Off-White	NNone Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y2A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y2A	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y2A	Floor	Ceramic Tile	1x1	Yellow and Gray	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
Y2A	Misc	Ceramic Tile	4x4	White and Gold	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y2A	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y3	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y3	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y3	Floor	Ceramic Tile	12x12	White with Beige	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
Y3	Floor	Resilient Floor Tile	12x12	Mustard	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y3	Floor	Resilient Floor Tile	12x12	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y3	Wall(s)	Wallboard with Joint Compound		Tan and Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y30	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		nonne Noted	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y30	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y30	Floor	Ceramic Tile	1x1	Blue and Gray	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
Y30	Wall(s)	Ceramic Tile	4x4	Blue	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y30	Wall(s)	Ceramic Tile	4x4	Off-White	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y30A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y30A	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y30A	Floor	Ceramic Tile	1x1	Multi Blue and White	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
Y30A	Wall(s)	Ceramic Tile	4x4	Blue	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y30A	Wall(s)	Ceramic Tile	4x4	Off-White	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y31	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y31	Door/Door Frame	Wood and Metal		Beige and Gray	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y31	Floor	Resilient Floor Tile	12x12	White with Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y31	Wall(s)	Wallboard with Joint Compound		Tan and Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y33	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y33	Door/Door Frame	Wood and Metal		Beige and Gray	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y33	Floor	Resilient Floor Tile	12x12	White with Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y33	Wall(s)	Wallboard with Joint Compound		Tan and Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y33A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y33A	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y33A	Floor	Ceramic Tile	1x1	Pink and Yellow	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
Y33A	Floor	Ceramic Tile	1x1	White	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
Y33A	Wall(s)	Ceramic Tile	4x4	Pink	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y33A	Wall(s)	Wallboard with Joint Compound		Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y35	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y35	Door/Door Frame	Wood and Metal		Beige and Gray	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y35	Floor	Resilient Floor Tile	12x12	Red	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y35	Floor	Resilient Floor Tile	12x12	White with Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y35	Wall(s)	Wallboard with Joint Compound		Tan and Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y35A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y35A	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y35A	Floor	Ceramic Tile	1x1	Pink and Yellow	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
Y35A	Wall(s)	Ceramic Tile	4x4	Pink	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y35A	Wall(s)	Wallboard with Joint Compound		Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y36	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	

Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT								Comment
					Asbestos Present?	Previously Sampled? (Y/N)	Contractor Sampled?	Contractor Sample No.	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	SignificantlyDamaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
Y36	Door/Door Frame	Wood and Metal		Beige and Gray	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y36	Floor	Resilient Floor Tile	12x12	Red	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	N/A
Y36	Floor	Resilient Floor Tile	12x12	White with Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y36	Wall(s)	Wallboard with Joint Compound		Tan and Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	

Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT								Comment
					Asbestos Present?	Previously Sampled? (Y/N)	Contractor Sampled?	Contractor Sample No.	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
Y36A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y36A	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y36A	Floor	Ceramic Tile	1x1	Pink and Yellow	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
Y36A	Wall(s)	Ceramic Tile	4x4	Pink	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y36A	Wall(s)	Wallboard with Joint Compound		Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y37	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y37	Door/Door Frame	Wood and Metal		Beige and Gray	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y37	Floor	Resilient Floor Tile	12x12	Red	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y37	Floor	Resilient Floor Tile	12x12	White with Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y37	Wall(s)	Wallboard with Joint Compound		Tan and Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y38	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y38	Door/Door Frame	Wood and Metal		Beige and Gray	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y38	Floor	Resilient Floor Tile	12x12	Red	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y38	Floor	Resilient Floor Tile	12x12	White with Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y38	Wall(s)	Wallboard with Joint Compound		Tan and Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y38A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y38A	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y38A	Floor	Ceramic Tile	1x1	Pink and Yellow	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
Y38A	Wall(s)	Ceramic Tile	4x4	Pink	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y38A	Wall(s)	Wallboard with Joint Compound		Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y39	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y39	Door/Door Frame	Wood and Metal		Beige and Gray	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y39	Floor	Resilient Floor Tile	12x12	Red	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y39	Floor	Resilient Floor Tile	12x12	White with Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y39	Wall(s)	Wallboard with Joint Compound		Tan and Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y3A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y3A	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y3A	Floor	Ceramic Tile	1x1	Yellow and Gray	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
Y3A	Misc	Ceramic Tile	4x4	White and Gold	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y3A	Wall(s)	Wallboard with Joint Compound	N	Beige	None Noted	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y4	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y4	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y4	Floor	Ceramic Tile	12x12	White with Beige	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
Y4	Floor	Resilient Floor Tile	12x12	Mustard	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y4	Floor	Resilient Floor Tile	12x12	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y4	Wall(s)	Wallboard with Joint Compound		Tan and Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y40	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y40	Door/Door Frame	Wood and Metal		Beige and Gray	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y40	Floor	Resilient Floor Tile	12x12	White with Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y40	Wall(s)	Wallboard with Joint Compound		Tan and Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y4A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y4A	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y4A	Floor	Ceramic Tile	1x1	Yellow and Gray	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
Y4A	Misc	Ceramic Tile	4x4	White and Gold	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y4A	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y5	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y5	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y5	Floor	Ceramic Tile	12x12	White with Beige	Not Suspect	No	No	N/A	N/A		N	N/A	N/A	N/A	N/A	N/A	
Y5	Floor	Resilient Floor Tile	12x12	Mustard	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y5	Floor	Resilient Floor Tile	12x12	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y5	Wall(s)	Wallboard with Joint Compound		Tan and Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y5A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y5A	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y5A	Floor	Ceramic Tile	1x1	Yellow and Gray	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/a	N/A	N/A	N/A	
Y5A	Misc	Ceramic Tile	4x4	White and Gold	Not Suspect	No	No	N/A	NF		N/A	N/A	N/a	N/A	N/A	N/A	

Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT								Comment
					Asbestos Present?	Previously Sampled? (Y/N)	Contractor Sampled?	Contractor Sample No.	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
Y5A	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y6	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
Y6	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y6	Floor	Ceramic Tile	12x12	White with Beige	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
Y6	Floor	Resilient Floor Tile	12x12	Mustard	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y6	Floor	Resilient Floor Tile	12x12	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y6	Wall(s)	Wallboard with Joint Compound		Tan and Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	

Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT								Comment
					Asbestos Present?	Previously Sampled? (Y/N)	Contractor Sampled?	Contractor Sample No.	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
Y6A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y6A	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y6A	Floor	Ceramic Tile	1x1	Yellow and Gray	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
Y6A	Misc	Ceramic Tile	4x4	White and Gold	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y6A	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y7	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y7	Door/Door Frame	Wood and Metal		Beige and Gray	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y7	Floor	Resilient Floor Tile	12x12	Red	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y7	Floor	Resilient Floor Tile	12x12	White with Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y7	Wall(s)	Wallboard with Joint Compound		Tan and Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y7A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y7A	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y7A	Floor	Ceramic Tile	1x1	Pink and Yellow	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
Y7A	Wall(s)	Ceramic Tile	4x4	Pink	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y7A	Wall(s)	Wallboard with Joint Compound		Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y7B	Ceiling	Robins on Decking			Not Suspect	No	No	N/A			N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y7B	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y7B	Floor	Concrete		Bare	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
Y7B	Wall(s)	CMU		Bare	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y8	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y8	Door/Door Frame	Wood and Metal		Beige and Gray	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y8	Floor	Resilient Floor Tile	12x12	Red	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y8	Floor	Resilient Floor Tile	12x12	White with Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y8	Wall(s)	Wallboard with Joint Compound		Tan and Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y9	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y9	Door/Door Frame	Wood and Metal		Beige and Gray	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y9	Floor	Resilient Floor Tile	12x12	Red	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y9	Floor	Resilient Floor Tile	12x12	White with Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y9	Wall(s)	Wallboard with Joint Compound		Tan and Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y9A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y9A	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y9A	Floor	Ceramic Tile	1x1	Pink and Yellow	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
Y9A	Wall(s)	Ceramic Tile	4x4	Pink	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y9A	Wall(s)	Wallboard with Joint Compound		Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y-C1	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y-C1	Door/Door Frame	Metal and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y-C1	Floor	Resilient Floor Tile	12x12	White with Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y-C1	Misc	Covebase and Glue	4"	Beige and Gray	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y-C1	Wall(s)	Wallboard with Joint Compound		Tan and Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y-C3	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y-C3	Door/Door Frame	Metal and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y-C3	Floor	Resilient Floor Tile	12x12	Mustard 12	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y-C3	Floor	Resilient Floor Tile	12x12	Red 24	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y-C3	Floor	Resilient Floor Tile	12x12	White with Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y-C3	Misc	Covebase and Glue	4"	Beige and Gray	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y-C3	Wall(s)	Wallboard with Joint Compound		Tan and Brige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y-C5	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Y-C5	Door/Door Frame	Metal and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y-C5	Floor	Resilient Floor Tile	12x12	Mustard 12	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y-C5	Floor	Resilient Floor Tile	12x12	Red 24	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y-C5	Floor	Resilient Floor Tile	12x12	White with Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y-C5	Misc	Covebase and Glue	4"	Beige and Gray	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Y-C5	Wall(s)	Wallboard with Joint Compound		Tan and Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z1	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z1	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF			N/A	N/A	N/A	N/A	N/A	
Z1	Floor	Resilient Floor Tile	12x12	Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	

Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT								Comment
					Asbestos Present?	Previously Sampled? (Y/N)	Contractor Sampled?	Contractor Sample No.	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	SignificantlyDamaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
Z1	Misc	Covebase and Glue	4"	Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z1	Misc	Covebase and Glue	4'	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z1	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	

Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT								Comment
					Asbestos Present?	Previously Sampled? (Y/N)	Contractor Sampled?	Contractor Sample No.	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
Z10	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z10	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z10	Floor	Resilient Floor Tile	12x12	Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z10	Misc	Covebase and Glue	4"	Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z10	Misc	Covebase and Glue	4'	Tan	None Nofed	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z10	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z11	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z11	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z11	Floor	Resilient Floor Tile	12x12	Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z11	Misc	Covebase and Glue	4"	Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z11	Misc	Covebase and Glue	4'	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z11	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z11A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		NA	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z11A	Door/Door Frame	Wood and Metal		Blue and Blue	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z11A	Floor	Resilient Floor Tile		Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z11A	Misc	Ceramic Tile and Grout	4x4	Blue	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z11A	Misc	Ceramic Tile and Grout	4x4	Off-White	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z11A	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z12	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z12	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z12	Floor	Resilient Floor Tile	12x12	Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z12	Misc	Covebase and Glue	4"	Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z12	Misc	Covebase and Glue	4'	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z12	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z13	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z13	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z13	Floor	Ceramic Tile and Grout	2x2	Blue	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
Z13	Wall(s)	Ceramic Tile and Grout	4x4	Blue	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z13	Wall(s)	Ceramic Tile and Grout	4x4	Off-White White	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z15	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z15	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z15	Floor	Ceramic Tile and Grout	2x2	Blue	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
Z15	Wall(s)	Ceramic Tile and Grout	4x4	Blue	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z15	Wall(s)	Ceramic Tile and Grout	4x4	Off-White White	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z16	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z16	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z16	Floor	Resilient Floor Tile		Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z16	Wall(s)	Wallboard with Joint Compound		Off-White	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	Yes	
Z16A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
Z16A	Door/Door Frame	Wood and Metal		Blue and Blue	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z16A	Floor	Ceramic Tile and Grout	2x2	Blue	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
Z16A	Wall(s)	Ceramic Tile and Grout	4x4	Blue	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z16A	Wall(s)	Ceramic Tile and Grout	4x4	Off-White	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z16A	Wall(s)	Wallboard with Joint Compound			None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z17	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z17	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z17	Floor	Resilient Floor Tile	12x12	Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z17	Misc	Covebase and Glue	4"	Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z17	Misc	Covebase and Glue	4'	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z17	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z17A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z17A	Door/Door Frame	Wood and Metal		Blue and Blue	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z17A	Floor	Ceramic Tile and Grout	2x2	Blue	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
Z17A	Wall(s)	Ceramic Tile and Grout	4x4	Blue	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z17A	Wall(s)	Ceramic Tile and Grout	4x4	Off-White	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z17A	Wall(s)	Wallboard with Joint Compound			None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z18	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	

Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT								Comment
					Asbestos Present?	Previously Sampled? (Y/N)	Contractor Sampled?	Contractor Sample No.	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	SignificantlyDamaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
Z18	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z18	Floor	Resilient Floor Tile	12x12	Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z18	Misc	Covebase and Glue	4"	Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z18	Misc	Covebase and Glue	4'	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N	N/A	
Z18	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	

Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT								Comment
					Asbestos Present?	Previously Sampled? (Y/N)	Contractor Sampled?	Contractor Sample No.	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
Z18A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z18A	Door/Door Frame	Wood and Metal		Blue and Blue	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z18A	Floor	Ceramic Tile and Grout	2x2	Blue	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
Z18A	Wall(s)	Ceramic Tile and Grout	4x4	Blue	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z18A	Wall(s)	Ceramic Tile and Grout	4x4	Off-White	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z18A	Wall(s)	Wallboard with Joint Compound			None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z19	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
Z19	Floor	Resilient Floor Tile	12x12	Blue	Yes	Yes	No		NF								
Z19	Misc	Covebase and Glue	4"	Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z19	Misc	Covebase and Glue	4'	Tan		Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z19	Wall(s)	Wallboard with Joint Compound		Beige		Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z19A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		NNone Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
Z19A	Door/Door Frame	Wood and Metal		Blue and Blue	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z19A	Floor	Ceramic Tile and Grout	2x2	Blue	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
Z19A	Wall(s)	Ceramic Tile and Grout	4x4	Blue	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z19A	Wall(s)	Ceramic Tile and Grout	4x4	Off-White	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z19A	Wall(s)	Wallboard with Joint Compound			None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z1A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
Z1A	Door/Door Frame	Wood and Metal		Blue and Blue	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z1A	Floor	Resilient Floor Tile		Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z1A	Wall(s)	Ceramic Tile and Grout	4x4	Blue	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z1A	Wall(s)	Ceramic Tile and Grout	4x4	Off-White	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z1A	Wall(s)	Wallboard with Joint Compound		Beige	Bone Noted	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z2	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
Z2	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z2	Floor	Resilient Floor Tile	12x12	Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z2	Misc	Covebase and Glue	4"	Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z2	Misc	Covebase and Glue	4'	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z2	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z20	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
Z20	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z20	Floor	Resilient Floor Tile	12x12	Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z20	Misc	Covebase and Glue	4"	Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z20	Misc	Covebase and Glue	4'	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z20	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z20A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
Z20A	Door/Door Frame	Wood and Metal		Blue and Blue	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z20A	Floor	Resilient Floor Tile		Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z20A	Misc	Ceramic Tile and Grout	4x4	Blue	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z20A	Misc	Ceramic Tile and Grout	4x4	Off-White	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z20A	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z21	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
Z21	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z21	Floor	Resilient Floor Tile	12x12	Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z21	Misc	Covebase and Glue	4"	Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z21	Misc	Covebase and Glue	4'	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z21	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z22	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
Z22	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z22	Floor	Resilient Floor Tile	12x12	Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z22	Misc	Covebase and Glue	4"	Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z22	Misc	Covebase and Glue	4'	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z22	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z22A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
Z22A	Door/Door Frame	Wood and Metal		Blue and Blue	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z22A	Floor	Resilient Floor Tile		Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z22A	Misc	Ceramic Tile and Grout	4x4	Blue	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z22A	Misc	Ceramic Tile and Grout	4x4	Off-White	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	

Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT								Comment
					Asbestos Present?	Previously Sampled? (Y/N)	Contractor Sampled?	Contractor Sample No.	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	SignificantlyDamaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
Z22A	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z23	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
Z23	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z23	Floor	Resilient Floor Tile	12x12	Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z23	Misc	Covebase and Glue	4"	Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z23	Misc	Covebase and Glue	4'	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z23	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	

Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT								Comment
					Asbestos Present?	Previously Sampled? (Y/N)	Contractor Sampled?	Contractor Sample No.	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
Z24	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z24	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z24	Floor	Resilient Floor Tile	12x12	Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z24	Misc	Covebase and Glue	4"	Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z24	Misc	Covebase and Glue	4'	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z24	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z24A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z24A	Door/Door Frame	Wood and Metal		Blue and Blue	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z24A	Floor	Resilient Floor Tile		Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z24A	Misc	Ceramic Tile and Grout	4x4	Blue	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z24A	Misc	Ceramic Tile and Grout	4x4	Off-White	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z24A	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z25	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/S	N/A	Possible Suspect Core Material
Z25	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z25	Floor	Resilient Floor Tile	12x12	Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/S	N/A	
Z25	Misc	Covebase and Glue	4"	Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/S	N/A	
Z25	Misc	Covebase and Glue	4'	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/S	N/A	
Z25	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z26	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z26	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z26	Floor	Resilient Floor Tile	12x12	Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z26	Misc	Covebase and Glue	4"	Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z26	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z27A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z27A	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z27A	Floor	Resilient Floor Tile	12x12	Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z27A	Misc	Covebase and Glue	4"	Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z27A	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z28	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z28	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z28	Floor	Ceramic Tile and Grout	2x2	Blue	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
Z28	Wall(s)	Ceramic Tile and Grout	4x4	Off-White White	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z29A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
Z29A	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z29A	Floor	Resilient Floor Tile	12x12	Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z29A	Misc	Covebase and Glue	4"	Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z29A	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z2A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
Z2A	Door/Door Frame	Wood and Metal		Blue and Blue	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z2A	Floor	Resilient Floor Tile		Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z2A	Misc	Ceramic Tile and Grout	4x4	Blue	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z2A	Misc	Ceramic Tile and Grout	4x4	Off-White	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z2A	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z3	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z3	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z3	Floor	Resilient Floor Tile	12x12	Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z3	Misc	Covebase and Glue	4"	Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z3	Misc	Covebase and Glue	4'	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z3	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z30A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z30A	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z30A	Floor	Resilient Floor Tile	12x12	Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z30A	Misc	Covebase and Glue	4"	Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z30A	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	

Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT								Comment
					Asbestos Present?	Previously Sampled? (Y/N)	Contractor Sampled?	Contractor Sample No.	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	SignificantlyDamaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
Z31	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
Z31	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z31	Floor	Resilient Floor Tile	12x12	Seafoam Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z31	Misc	Covebase and Glue	6"	Beige and Gray	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z31	Wall(s)	Wallboard with Joint Compound		Beige and Green	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	

Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT								Comment
					Asbestos Present?	Previously Sampled? (Y/N)	Contractor Sampled?	Contractor Sample No.	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
Z33	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z33	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z33	Floor	Resilient Floor Tile	12x12	Seafoam Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z33	Misc	Covebase and Glue	6"	Beige and Gray	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z33	Wall(s)	Wallboard with Joint Compound		Beige and Green	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z-33A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z-33A	Door/Door Frame	Wood and Metal		Beige and Beige	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z-33A	Floor	Ceramic Tile and Grout	1x1	Blue and Gray	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A		N/A	N/A	
Z-33A	Wall(s)	Ceramic Tile and Grout	4x4	Purple	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z-33A	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z33B	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z33B	Door/Door Frame	Wood and Metal		Beige and Beige	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z33B	Floor	Ceramic Tile and Grout	2x2	Blue and Gray	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	
Z33B	Wall(s)	Ceramic Tile and Grout	4x4	Blue	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z33B	Wall(s)	Ceramic Tile and Grout	4x4	Off-White	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z33B	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z35	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z35	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z35	Floor	Resilient Floor Tile	12x12	Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z35	Misc	Covebase and Glue	4"	Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z35	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z35A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z35A	Door/Door Frame	Wood and Metal		Blue and Blue	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z35A	Floor	Resilient Floor Tile		Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z35A	Misc	Ceramic Tile and Grout	4x4	Blue	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z35A	Misc	Ceramic Tile and Grout	4x4	Off-White	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z35A	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z36	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z36	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z36	Floor	Resilient Floor Tile	12x12	Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z36	Misc	Covebase and Glue	4"	Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z36	Misc	Covebase and Glue	4'	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z36	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z36A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z36A	Door/Door Frame	Wood and Metal		Blue and Blue	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z36A	Floor	Resilient Floor Tile		Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z36A	Misc	Ceramic Tile and Grout	4x4	Blue	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z36A	Misc	Ceramic Tile and Grout	4x4	Off-White	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z36A	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z37	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z37	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z37	Floor	Resilient Floor Tile	12x12	Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z37	Misc	Covebase and Glue	4"	Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z37	Misc	Covebase and Glue	4'	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z37	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z38	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/S	Possible Suspect Core Material
Z38	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z38	Floor	Resilient Floor Tile	12x12	Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/S	
Z38	Misc	Covebase and Glue	4"	Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/S	
Z38	Misc	Covebase and Glue	4'	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/S	
Z38	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z38A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z38A	Door/Door Frame	Wood and Metal		Blue and Blue	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z38A	Floor	Resilient Floor Tile		Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z38A	Misc	Ceramic Tile and Grout	4x4	Blue	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z38A	Misc	Ceramic Tile and Grout	4x4	Off-White	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z38A	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z39	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	

Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT								Comment
					Asbestos Present?	Previously Sampled? (Y/N)	Contractor Sampled?	Contractor Sample No.	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	SignificantlyDamaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
Z39	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z39	Floor	Resilient Floor Tile	12x12	Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z39	Misc	Covebase and Glue	4"	Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z39	Misc	Covebase and Glue	4'	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z39	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	

Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT								Comment
					Asbestos Present?	Previously Sampled? (Y/N)	Contractor Sampled?	Contractor Sample No.	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
Z40	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
Z40	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z40	Floor	Carpet		Brown	Not Suspect	No	No	N/A	N/A		N/A	N/A	N/A	N/A	N/A	N/A	Possible Floor tile/mastic underneath
Z40	Floor	Resilient Floor Tile	12x12	Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z40	Misc	Covebase and Glue	4"	Beige and Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z40	Misc	Covebase and Glue	4'	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z40	Wall(s)	Wallboard with Joint Compound		Beige and Green	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z40.W47SW	Misc	Carpet Glue (Under Tan Carpet)	1319 sq.ft.	Yellow	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z4A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
Z4A	Door/Door Frame	Wood and Metal		Blue and Blue	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z4A	Floor	Resilient Floor Tile		Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z4A	Misc	Ceramic Tile and Grout	4x4	Blue	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z4A	Misc	Ceramic Tile and Grout	4x4	Off-White	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z4A	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z5	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
Z5	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z5	Floor	Resilient Floor Tile	12x12	Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z5	Misc	Covebase and Glue	4"	Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z5	Misc	Covebase and Glue	4'	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z5	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z5A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
Z5A	Door/Door Frame	Wood and Metal		Blue and Blue	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z5A	Floor	Resilient Floor Tile		Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z5A	Misc	Ceramic Tile and Grout	4x4	Blue	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z5A	Misc	Ceramic Tile and Grout	4x4	Off-White	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z5A	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z6	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
Z6	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z6	Floor	Resilient Floor Tile	12x12	Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z6	Misc	Covebase and Glue	4'	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z6	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z6A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
Z6A	Door/Door Frame	Wood and Metal		Blue and Blue	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z6A	Floor	Resilient Floor Tile		Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z6A	Misc	Ceramic Tile and Grout	4x4	Blue	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z6A	Misc	Ceramic Tile and Grout	4x4	Off-White	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z6A	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z7	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
Z7	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z7	Floor	Resilient Floor Tile	12x12	Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z7	Misc	Covebase and Glue	4"	Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z7	Misc	Covebase and Glue	4'	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z7	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z71	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
Z71	Ceiling	Hardlid			None Detected	Y	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z71	Floor	Resilient Floor Tile	12x12		None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z71	Misc	Covebase and Glue	4"		None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z71	Wall(s)	Wallboard with Joint Compound			None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z7A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
Z7A	Door/Door Frame	Wood and Metal		Blue and Blue	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z7A	Floor	Resilient Floor Tile		Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z7A	Misc	Ceramic Tile and Grout	4x4	Blue	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z7A	Misc	Ceramic Tile and Grout	4x4	Off-White	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z7A	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z8	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
Z8	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z8	Floor	Resilient Floor Tile	12x12	Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z8	Misc	Covebase and Glu	4"	Beige	None Nmoted	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z8	Misc	Covebase and Glu	4'	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	

Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT								Comment
					Asbestos Present?	Previously Sampled? (Y/N)	Contractor Sampled?	Contractor Sample No.	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
Z8	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z9	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
Z9	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z9	Floor	Resilient Floor Tile	12x12	Blue	None Detected	Yes	No	N/A	NF			N/A	N/A	N/A	N/A	N/A	
Z9	Misc	Covebase and Glu	4"	Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z9	Misc	Covebase and Glu	4'	Tan	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z9	Wall(s)	Wallboard with Joint Compound		Beige	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z9A	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
Z9A	Door/Door Frame	Wood and Metal		Blue and Blue	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z9A	Floor	Resilient Floor Tile		Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z9A	Misc	Ceramic Tile and Grout	4x4	Blue	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z9A	Misc	Ceramic Tile and Grout	4x4	Off-White	Not Suspect	No	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z9A	Wall(s)	Wallboard with Joint Compound		Beige	None Detectedd	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z-C1	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
Z-C1	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z-C1	Floor	Resilient Floor Tile	12x12	Seafoam/Mauve/ Green/Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z-C1	Misc	Covebase and Glu	6"	Beige and Gray	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z-C1	Wall(s)	Wallboard with Joint Compound		Beige and Green	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z-C3	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
Z-C3	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z-C3	Floor	Resilient Floor Tile	12x12	Seafoam/Mauve/ Green/Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z-C3	Misc	Covebase and Glu	6"	Beige and Gray	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z-C3	Wall(s)	Wallboard with Joint Compound		Beige and Green	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z-C4	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
Z-C4	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z-C4	Floor	Resilient Floor Tile	12x12	Seafoam/Mauve/ Green/Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z-C4	Misc	Covebase and Glu	6"	Beige and Gray	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z-C4	Wall(s)	Wallboard with Joint Compound		Beige and Green	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z-C5	Ceiling	Acoustic Ceiling Tile (Pinhole Big Worm)	2x4		None Detected	Y	Y	VALB-133-c1.1	F		N/A	N/A	N/A	N/A	N/A	N/A	
Z-C5	Door/Door Frame	Wood and Metal		Black and Black	not sampled	N/A	N/A	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	Possible Suspect Core Material
Z-C5	Floor	Resilient Floor Tile	12x12	Seafoam/Mauve/ Green/Blue	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z-C5	Misc	Covebase and Glu	6"	Beige and Gray	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	
Z-C5	Wall(s)	Wallboard with Joint Compound		Beige and Green	None Detected	Yes	No	N/A	NF		N/A	N/A	N/A	N/A	N/A	N/A	