

Current Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT							Comment	
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing		Misc
Roof	Roof	Ceiling	Sealed Roof System		White	NOT SAMPLED											
Roof	Roof	Wall(s)	Penetration Mastic	Not Visible		NOT SAMPLED											
Roof	Roof	Floor	HVAC Wrap		Gray	NOT SAMPLED											
Roof	Roof	Door/Door Frame	HVAC Sealant		Gray	NOT SAMPLED											
1st Floor	102	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	102	Door/Door Frame	Wood and Metal		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
1st Floor	102	Floor	Resilient Flooring Tile /Mastic	12x12	Brown/Black	Y	n/a	Y	N	Good - No Damage	n/a	n/a	no	n/a	n/a	Y	ACM is in the mastic
1st Floor	102	Misc	Cove Base	4"	Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	102	Wall(s)	Wallboard Joint Compound		Off/Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	103	Ceiling	Hard Lid		Off	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	103	Door/Door Frame	Wood and Metal			Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
1st Floor	103	Floor	Concrete		Brown	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	103	Wall(s)	Wallboard Joint Compound		Off	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	104	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	104	Door/Door Frame	Wood and Metal		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
1st Floor	104	Floor	Resilient Flooring Tile /Mastic	12x12	Brown/Black	Y	n/a	Y	N	Good - No Damage	n/a	n/a	no	n/a	n/a	Y	ACM is in the mastic
1st Floor	104	Misc	Cove Base	4"	Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	104	Wall(s)	Wallboard Joint Compound		Off/Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	105	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm			N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	105	Door/Door Frame	Wood and Metal		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
1st Floor	105	Floor	Carpet		Brown	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	ACM floor tile/mastic may exist beneath carpet
1st Floor	105	Misc	Cove Base	4"	Off	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	105	Wall(s)	Wallboard Joint Compound		Beige/Green	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	106	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	106	Door/Door Frame	Wood and Metal		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
1st Floor	106	Floor	Resilient Flooring Tile /Mastic	12x12	Brown/Black	Y	n/a	Y	N	Good - No Damage	n/a	n/a	no	n/a	n/a	Y	ACM is in the mastic
1st Floor	106	Misc	Cove Base	4"	Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	106	Wall(s)	Wallboard Joint Compound		Off/Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	109	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	109	Door/Door Frame	Wood and Metal		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
1st Floor	109	Floor	Resilient Flooring Tile /Mastic	12x12	Brown/Black	Y	n/a	Y	N	Good - No Damage	n/a	n/a	no	n/a	n/a	Y	ACM is in the mastic
1st Floor	109	Misc	Cove Base	4"	Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	109	Wall(s)	Wallboard Joint Compound		Off/Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	110	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	110	Door/Door Frame	Wood and Metal		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
1st Floor	110	Floor	Resilient Flooring Tile /Mastic	12x12	Brown/Black	Y	n/a	Y	N	Good - No Damage	n/a	n/a	no	n/a	n/a	Y	ACM is in the mastic
1st Floor	110	Misc	Cove Base	4"	Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	110	Wall(s)	Wallboard Joint Compound		Off/Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	111	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	111	Door/Door Frame	Wood and Metal		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
1st Floor	111	Floor	Resilient Flooring Tile /Mastic	12x12	Brown/Black	Y	n/a	Y	N	Good - No Damage	n/a	n/a	no	n/a	n/a	Y	ACM is in the mastic

Current Rm Name/No.	Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT							Comment		
					Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing		Misc	
1st Floor	111	Misc	Cove Base	4"	Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	111	Wall(s)	Wallboard Joint Compound		Off/Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	112	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	112	Door/Door Frame	Wood and Metal		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
1st Floor	112	Floor	Resilient Flooring Tile /Mastic	12x12	Brown/Black	Y	n/a	Y	N	Good - No Damage	n/a	n/a	no	n/a	n/a	Y	ACM is in the mastic
1st Floor	112	Misc	Cove Base	4"	Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	112	Wall(s)	Wallboard Joint Compound		Off/Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	114	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	114	Door/Door Frame	Wood and Metal		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
1st Floor	114	Floor	Resilient Flooring Tile /Mastic	12x12	Brown/Black	Y	n/a	Y	N	Good - No Damage	n/a	n/a	no	n/a	n/a	Y	ACM is in the mastic
1st Floor	114	Misc	Cove Base	4"	Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	114	Wall(s)	Wallboard Joint Compound		Off/Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	115	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm			N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	115	Door/Door Frame	Wood and Metal			Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
1st Floor	115	Floor	Concrete		Brown	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	115	Wall(s)	Wallboard Joint Compound		Off	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	118	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	118	Door/Door Frame	Wood and Metal		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
1st Floor	118	Floor	Resilient Flooring Tile /Mastic	12x12	Brown/Black	Y	n/a	Y	N	Good - No Damage	n/a	n/a	no	n/a	n/a	Y	ACM is in the mastic
1st Floor	118	Misc	Cove Base	4"	Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	118	Wall(s)	Wallboard Joint Compound		Off/Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	119	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	119	Door/Door Frame	Wood and Metal		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
1st Floor	119	Floor	Resilient Flooring Tile /Mastic	12x12	Brown/Black	Y	n/a	Y	N	Good - No Damage	n/a	n/a	no	n/a	n/a	Y	ACM is in the mastic
1st Floor	119	Misc	Cove Base	4"	Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	119	Wall(s)	Wallboard Joint Compound		Off/Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	120	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm			N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	120	Door/Door Frame	Wood and Metal			Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
1st Floor	120	Floor	Concrete		Brown	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	120	Wall(s)	Wallboard Joint Compound		Off	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	122	Ceiling	Hard Lid		Off	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	122	Door/Door Frame	Wood and Metal			Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
1st Floor	122	Floor	Resilient Flooring Tile		Red/Brown/Rust Multi	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	122	Misc	Cove Base	4"	Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	122	Wall(s)	Wallboard Joint Compound		Off	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	124	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	124	Door/Door Frame	Wood and Metal		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
1st Floor	124	Floor	Ceramic Tile	1x1	Brown	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	124	Wall(s)	Wallboard Joint Compound		Beige	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	124	Wall(s)	Ceramic Tile	4x4	Off	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	125	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	

Current Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT							Comment	
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing		Misc
1st Floor	125	Door/Door Frame	Wood and Metal		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
1st Floor	125	Floor	Ceramic Tile	1x1	Brown	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	125	Misc	Ceramic Tile	4x4	Off	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	125	Wall(s)	Wallboard Joint Compound		Off	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	126	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	126	Door/Door Frame	Wood and Metal		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
1st Floor	126	Floor	Ceramic Tile	1x1	Brown	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	126	Misc	Ceramic Tile	4x4	Off	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	126	Wall(s)	Wallboard Joint Compound		Beige	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	128	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	128	Door/Door Frame	Wood and Metal		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
1st Floor	128	Floor	Resilient Flooring Tile /Mastic	12x12	Brown/Black	Y	n/a	Y	N	Good - No Damage	n/a	n/a	no	n/a	n/a	Y	ACM is in the mastic
1st Floor	128	Misc	Cove Base	4"	Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	128	Wall(s)	Wallboard Joint Compound		Off/Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	129	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	129	Door/Door Frame	Wood and Metal		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
1st Floor	129	Floor	Resilient Flooring Tile /Mastic	12x12	Brown/Black	Y	n/a	Y	N	Good - No Damage	n/a	n/a	no	n/a	n/a	Y	ACM is in the mastic
1st Floor	129	Misc	Cove Base	4"	Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	129	Wall(s)	Wallboard Joint Compound		Off/Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	130	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4	Off/Brown	N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	130	Door/Door Frame	Wood and Metal		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
1st Floor	130	Floor	Carpet		Brown/Yellow	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	130	Misc	Cove Base	4"	Beige/Green	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	130	Wall(s)	Wallboard Joint Compound		Off/Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	131	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	131	Door/Door Frame	Wood and Metal		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
1st Floor	131	Floor	Resilient Flooring Tile /Mastic	12x12	Brown/Black	Y	n/a	Y	N	Good - No Damage	n/a	n/a	no	n/a	n/a	Y	ACM is in the mastic
1st Floor	131	Misc	Cove Base	4"	Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	131	Wall(s)	Wallboard Joint Compound		Off/Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	132	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	132	Door/Door Frame	Wood and Metal			Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
1st Floor	132	Floor	Resilient Flooring Tile /Mastic	12x12	Brown/Black	Y	n/a	Y	N	Good - No Damage	n/a	n/a	no	n/a	n/a	Y	ACM is in the mastic
1st Floor	132	Misc	Cove Base	4"	Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	132	Wall(s)	Wallboard Joint Compound		Off	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	133	Ceiling	Hard Lid		Off	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	133	Door/Door Frame	Wood and Metal			Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
1st Floor	133	Floor	Concrete		Brown	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	133	Wall(s)	Wallboard Joint Compound		Off	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	134	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	134	Door/Door Frame	Wood and Metal		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
1st Floor	134	Floor	Resilient Flooring Tile /Mastic	12x12	Brown/Black	Y	n/a	Y	N	Good - No Damage	n/a	n/a	no	n/a	n/a	Y	ACM is in the mastic

Current Rm Name/No.	Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT							Comment		
					Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing		Misc	
1st Floor	134	Misc	Cove Base	4"	Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	134	Wall(s)	Wallboard Joint Compound		Off/Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	135	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	135	Door/Door Frame	Wood and Metal		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
1st Floor	135	Floor	Resilient Flooring Tile /Mastic	12x12	Brown/Black	Y	n/a	Y	N	Good - No Damage	n/a	n/a	no	n/a	n/a	Y	ACM is in the mastic
1st Floor	135	Misc	Cove Base	4"	Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	135	Wall(s)	Wallboard Joint Compound		Off/Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	136	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	136	Door/Door Frame	Wood and Metal			Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
1st Floor	136	Floor	Resilient Flooring Tile /Mastic	12x12	Brown/Black	Y	n/a	Y	N	Good - No Damage	n/a	n/a	no	n/a	n/a	Y	ACM is in the mastic
1st Floor	136	Misc	Cove Base	4"	Off Beige	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	136	Wall(s)	Wallboard Joint Compound		Beige/Green	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	137	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	137	Door/Door Frame	Wood and Metal		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
1st Floor	137	Floor	Carpet		Brown/Yellow	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	137	Misc	Cove Base	4"	Beige/Green	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	137	Wall(s)	Wallboard Joint Compound		Off/Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	138	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	138	Door/Door Frame	Wood and Metal		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
1st Floor	138	Floor	Resilient Flooring Tile /Mastic	12x12	Brown/Black	Y	n/a	Y	N	Good - No Damage	n/a	n/a	no	n/a	n/a	Y	ACM is in the mastic
1st Floor	138	Misc	Cove Base	4"	Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	138	Wall(s)	Wallboard Joint Compound		Off/Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	139	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	139	Door/Door Frame	Wood and Metal		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
1st Floor	139	Floor	Resilient Flooring Tile /Mastic	12x12	Brown/Black	Y	n/a	Y	N	Good - No Damage	n/a	n/a	no	n/a	n/a	Y	ACM is in the mastic
1st Floor	139	Misc	Cove Base	4"	Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	139	Wall(s)	Wallboard Joint Compound		Off/Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	141	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	141	Door/Door Frame	Wood and Metal		Seafoam Beige	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
1st Floor	141	Floor	Resilient Flooring Tile	12x12	Bare/White	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	141	Misc	Cove Base	4"	Black	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	141	Misc	Lab Sink		Black(new)	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	141	Wall(s)	Wallboard Joint Compound		Off	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	142	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	142	Door/Door Frame	Wood and Metal		Seafoam Beige	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
1st Floor	142	Floor	Resilient Flooring Tile	12x12	Bare/White	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	142	Misc	Cove Base	4"	Black	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	142	Misc	Lab Sink		Black(new)	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	142	Wall(s)	Wallboard Joint Compound		Off	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	143	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	143	Door/Door Frame	Wood and Metal		Seafoam Beige	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
1st Floor	143	Floor	Resilient Flooring Tile	12x12	Bare/White	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	143	Misc	Cove Base	4"	Black	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	143	Misc	Lab Sink		Black(new)	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	143	Wall(s)	Wallboard Joint Compound		Off	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	111A	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	111A	Door/Door Frame	Wood and Metal		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
1st Floor	111A	Floor	Resilient Flooring Tile /Mastic	12x12	Brown/Black	Y	n/a	Y	N	Good - No Damage	n/a	n/a	no	n/a	n/a	Y	ACM is in the mastic
1st Floor	111A	Misc	Cove Base	4"	Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	111A	Wall(s)	Wallboard Joint Compound		Off/Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	113A	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	113A	Door/Door Frame	Wood and Metal		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
1st Floor	113A	Floor	Carpet		Brown/Yellow	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	113A	Misc	Cove Base	4"	Beige/Green	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
1st Floor	113A	Wall(s)	Wallboard Joint Compound		Off/Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
2nd Floor	201	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
2nd Floor	201	Door/Door Frame	Wood and Metal			Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core

Current Rm Name/No.	Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								Comment	
					Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc		
2nd Floor	226	Wall(s)	Wallboard Joint Compound		Beige	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
2nd Floor	227	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
2nd Floor	227	Door/Door Frame	Wood and Metal		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
2nd Floor	227	Floor	Resilient Flooring Tile /Mastic	12x12	Brown/Black	Y	n/a	Y	N	Good - No Damage	n/a	n/a	no	n/a	n/a	Y	ACM is in the mastic
2nd Floor	227	Misc	Cove Base	4"	Beige	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
2nd Floor	227	Wall(s)	Wallboard Joint Compound		Off	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
2nd Floor	228	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
2nd Floor	228	Door/Door Frame	Wood and Metal			Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
2nd Floor	228	Floor	Resilient Flooring Tile /Mastic	12x12	Brown/Black	Y	n/a	Y	N	Good - No Damage	n/a	n/a	no	n/a	n/a	Y	ACM is in the mastic
2nd Floor	228	Misc	Cove Base	4"	Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
2nd Floor	228	Wall(s)	Wallboard Joint Compound		Off	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
2nd Floor	229	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
2nd Floor	229	Door/Door Frame	Wood and Metal			Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
2nd Floor	229	Floor	Resilient Flooring Tile /Mastic	12x12	Brown/Black	Y	n/a	Y	N	Good - No Damage	n/a	n/a	no	n/a	n/a	Y	ACM is in the mastic
2nd Floor	229	Misc	Cove Base	4"	Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
2nd Floor	229	Wall(s)	Wallboard Joint Compound		Off	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
2nd Floor	230	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
2nd Floor	230	Door/Door Frame	Wood and Metal			Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
2nd Floor	230	Floor	Carpet		Brown/Yellow	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	ACM floor tile/mastic may exist beneath carpet
2nd Floor	230	Misc	Cove Base	4"	Beige	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
2nd Floor	230	Wall(s)	Wallboard Joint Compound		Off	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
2nd Floor	231	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
2nd Floor	231	Door/Door Frame	Wood and Metal			Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
2nd Floor	231	Floor	Resilient Flooring Tile /Mastic	12x12	Brown/Black	Y	n/a	Y	N	Good - No Damage	n/a	n/a	no	n/a	n/a	Y	ACM is in the mastic
2nd Floor	231	Misc	Cove Base	4"	Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
2nd Floor	231	Wall(s)	Wallboard Joint Compound		Off	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
2nd Floor	232	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
2nd Floor	232	Door/Door Frame	Wood and Metal			Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
2nd Floor	232	Floor	Resilient Flooring Tile /Mastic	12x12	Brown/Black	Y	n/a	Y	N	Good - No Damage	n/a	n/a	no	n/a	n/a	Y	ACM is in the mastic
2nd Floor	232	Misc	Cove Base	4"	Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
2nd Floor	232	Wall(s)	Wallboard Joint Compound		Off	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
2nd Floor	233	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
2nd Floor	233	Door/Door Frame	Wood and Metal			Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
2nd Floor	233	Floor	Carpet		Brown	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	ACM floor tile/mastic may exist beneath carpet
2nd Floor	233	Misc	Cove Base	4"	Off	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
2nd Floor	233	Wall(s)	Wallboard Joint Compound		Beige/Green	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
2nd Floor	234	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
2nd Floor	234	Door/Door Frame	Wood and Metal			Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
2nd Floor	234	Floor	Resilient Flooring Tile /Mastic	12x12	Brown/Black	Y	n/a	Y	N	Good - No Damage	n/a	n/a	no	n/a	n/a	Y	ACM is in the mastic
2nd Floor	234	Misc	Cove Base	4"	Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
2nd Floor	234	Wall(s)	Wallboard Joint Compound		Off	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
2nd Floor	235	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
2nd Floor	235	Door/Door Frame	Wood and Metal			Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
2nd Floor	235	Floor	Carpet		Brown	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	ACM floor tile/mastic may exist beneath carpet
2nd Floor	235	Misc	Cove Base	4"	Off	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
2nd Floor	235	Wall(s)	Wallboard Joint Compound		Beige/Green	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
2nd Floor	236	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
2nd Floor	236	Door/Door Frame	Wood and Metal			Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
2nd Floor	236	Floor	Resilient Flooring Tile /Mastic	12x12	Brown/Black	Y	n/a	Y	N	Good - No Damage	n/a	n/a	no	n/a	n/a	Y	ACM is in the mastic
2nd Floor	236	Misc	Cove Base	4"	Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
2nd Floor	236	Wall(s)	Wallboard Joint Compound		Beige/Green	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
2nd Floor	237	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
2nd Floor	237	Door/Door Frame	Wood and Metal			Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core

Current Rm Name/No.	Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT							Comment		
					Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing		Misc	
2nd Floor	Stairwell #2-1	Wall(s)	Concrete		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	
2nd Floor	Stairwell #2-1	Wall(s)	Wallboard Joint Compound		White	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
2nd Floor	Stairwell #2-2	Ceiling	Fire Proofing No Basement		Tan	N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
2nd Floor	Stairwell #2-2	Door/Door Frame	Metal and Metal		Beige/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
2nd Floor	Stairwell #2-2	Floor	Resilient Flooring Tile /Mastic	12x12	Brown/Black	Y	n/a	Y	N	Good - No Damage	n/a	n/a	no	n/a	n/a	Y	ACM is in the mastic
2nd Floor	Stairwell #2-2	Floor	Resilient Flooring Tile Landings	12x12	Tan w/White Swirl	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
2nd Floor	Stairwell #2-2	Misc	Cove Base	4"	Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
2nd Floor	Stairwell #2-2	Wall(s)	Concrete		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	
2nd Floor	Stairwell #2-2	Wall(s)	Wallboard Joint Compound		White	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
2nd Floor	Stairwell #B-1	Ceiling	Fire Proofing No Basement		Tan	N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
2nd Floor	Stairwell #B-1	Door/Door Frame	Metal and Metal		Beige/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
2nd Floor	Stairwell #B-1	Floor	Resilient Flooring Tile /Mastic	12x12	Brown/Black	Y	n/a	Y	N	Good - No Damage	n/a	n/a	no	n/a	n/a	Y	ACM is in the mastic
2nd Floor	Stairwell #B-1	Floor	Resilient Flooring Tile Landings	12x12	Tan w/White Swirl	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
2nd Floor	Stairwell #B-1	Misc	Cove Base	4"	Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
2nd Floor	Stairwell #B-1	Wall(s)	Concrete		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	
2nd Floor	Stairwell #B-1	Wall(s)	Wallboard Joint Compound		White	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
2nd Floor	Stairwell #B-2	Ceiling	Fire Proofing No Basement		Tan	N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
2nd Floor	Stairwell #B-2	Door/Door Frame	Metal and Metal		Beige/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
2nd Floor	Stairwell #B-2	Floor	Resilient Flooring Tile /Mastic	12x12	Brown/Black	Y	n/a	Y	N	Good - No Damage	n/a	n/a	no	n/a	n/a	Y	ACM is in the mastic
2nd Floor	Stairwell #B-2	Floor	Resilient Flooring Tile Landings	12x12	Tan w/White Swirl	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
2nd Floor	Stairwell #B-2	Misc	Cove Base	4"	Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
2nd Floor	Stairwell #B-2	Wall(s)	Concrete		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	
2nd Floor	Stairwell #B-2	Wall(s)	Wallboard Joint Compound		White	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B10	Ceiling	Hard Lid / Wallboard Joint Compound			N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B10	Door/Door Frame	Wood and Metal		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
Basement	B10	Floor	Epoxy		Brown	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B10	Wall(s)	Plaster		Beige	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B11	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm			N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B11	Door/Door Frame	Metal and Wood		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
Basement	B11	Floor	Resilient Flooring Tile /Mastic	12x12	Brown/Black	Y	n/a	Y	N	Good - No Damage	n/a	n/a	no	n/a	n/a	Y	ACM is in the mastic
Basement	B11	Misc	Cove Base	4"	Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B11	Wall(s)	Wallboard Joint Compound		Off White	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B12	Ceiling	Hard Lid / Wallboard Joint Compound			N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B12	Door/Door Frame	Wood and Metal		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
Basement	B12	Floor	Epoxy		Brown	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B12	Wall(s)	Plaster		Beige	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B13	Ceiling	Hard Lid / Wallboard Joint Compound			N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B13	Door/Door Frame	Wood and Metal		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
Basement	B13	Floor	Epoxy		Brown	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B13	Wall(s)	Plaster		Beige	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B14	Ceiling	Hard Lid		Off	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B14	Door/Door Frame	Metal and Wood		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
Basement	B14	Floor	Resilient Flooring Tile		Tan	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B14	Wall(s)	Plaster		Off	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B15	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm			N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B15	Door/Door Frame	Metal and Wood		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
Basement	B15	Floor	Resilient Flooring Tile /Mastic	12x12	Brown/Black	Y	n/a	Y	N	Good - No Damage	n/a	n/a	no	n/a	n/a	Y	ACM is in the mastic
Basement	B15	Misc	Cove Base	4"	Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B15	Wall(s)	Wallboard Joint Compound		Off White	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B16	Ceiling	Hard Lid		Off	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B16	Door/Door Frame	Metal and Wood		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
Basement	B16	Floor	Resilient Flooring Tile		Tan	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B16	Wall(s)	Plaster		Off	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B17	Ceiling	Hard Lid / Wallboard Joint Compound			N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B17	Door/Door Frame	Wood and Metal		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
Basement	B17	Floor	Epoxy		Brown	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B17	Wall(s)	Plaster		Beige	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B18	Ceiling	Hard Lid		Off	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B18	Door/Door Frame	Metal and Wood		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core

Current Rm Name/No.	Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT							Comment		
					Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing		Misc	
Basement	B18	Floor	Resilient Flooring Tile		Tan	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B18	Wall(s)	Plaster		Off	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B18A	Ceiling	Hard Lid		Off	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B18A	Door/Door Frame	Metal and Wood		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
Basement	B18A	Floor	Resilient Flooring Tile		Tan	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B18A	Wall(s)	Plaster		Off	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B19	Ceiling	Hard Lid / Wallboard Joint Compound			N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B19	Door/Door Frame	Wood and Metal		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
Basement	B19	Floor	Epoxy		Brown	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B19	Wall(s)	Plaster		Beige	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B2	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm			N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B2	Door/Door Frame	Metal and Wood		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
Basement	B2	Floor	Resilient Flooring Tile /Mastic	12x12	Brown/Black	Y	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	ACM is in the mastic
Basement	B2	Misc	Cove Base	4"	Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B2	Wall(s)	Wallboard Joint Compound		Off Beige	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B21	Ceiling	Hard Lid / Wallboard Joint Compound			N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B21	Door/Door Frame	Wood and Metal		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
Basement	B21	Floor	Epoxy		Brown	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B21	Wall(s)	Plaster		Beige	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B23	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B23	Door/Door Frame	Wood and Metal		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
Basement	B23	Floor	Ceramic Tile	1x1	Brown	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B23	Misc	Ceramic Tile	4x4	Off	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B23	Wall(s)	Wallboard Joint Compound		Beige	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B25	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B25	Door/Door Frame	Wood and Metal		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
Basement	B25	Floor	Ceramic Tile	1x1	Brown	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B25	Misc	Ceramic Tile	4x4	Off	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B25	Wall(s)	Wallboard Joint Compound		Beige	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B26	Ceiling	Hard Lid / Wallboard Joint Compound			N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B26	Door/Door Frame	Wood and Metal		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
Basement	B26	Floor	Epoxy		Brown	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B26	Wall(s)	Plaster		Beige	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B27	Ceiling	Hard Lid / Wallboard Joint Compound			N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B27	Door/Door Frame	Wood and Metal		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
Basement	B27	Floor	Epoxy		Brown	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B27	Wall(s)	Plaster		Beige	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B29	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B29	Door/Door Frame	Wood and Metal		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
Basement	B29	Floor	Epoxy		Tan/Brown	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B29	Wall(s)	Plaster		Off	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B3	Ceiling	Hard Lid / Wallboard Joint Compound			N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B3	Door/Door Frame	Wood and Metal		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
Basement	B3	Floor	Epoxy		Brown	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B3	Wall(s)	Plaster		Beige	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B30	Ceiling	Hard Lid / Wallboard Joint Compound			N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B30	Door/Door Frame	Wood and Metal		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
Basement	B30	Floor	Epoxy		Brown	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B30	Wall(s)	Plaster		Beige	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B30A	Ceiling	Hard Lid / Wallboard Joint Compound			N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B30A	Door/Door Frame	Wood and Metal		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
Basement	B30A	Floor	Epoxy		Brown	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B30A	Wall(s)	Plaster		Beige	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B31	Ceiling	Hard Lid / Wallboard Joint Compound			N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B31	Door/Door Frame	Wood and Metal		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
Basement	B31	Floor	Epoxy		Brown	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B31	Wall(s)	Plaster		Beige	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B32	Ceiling	Hard Lid / Wallboard Joint Compound			N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B32	Door/Door Frame	Wood and Metal		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
Basement	B32	Floor	Epoxy		Brown	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B32	Wall(s)	Plaster		Beige	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B32A	Ceiling	Hard Lid / Wallboard Joint Compound			N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B32A	Door/Door Frame	Wood and Metal		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core

Current Rm Name/No.	Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT							Comment		
					Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing		Misc	
Basement	B32A	Floor	Epoxy		Brown	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B32A	Wall(s)	Plaster		Beige	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B33	Ceiling	Hard Lid / Wallboard Joint Compound			N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B33	Door/Door Frame	Wood and Metal		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
Basement	B33	Floor	Epoxy		Brown	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B33	Wall(s)	Plaster		Beige	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B35	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B35	Door/Door Frame	Wood and Metal		Bare White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
Basement	B35	Floor	Epoxy		Brown	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B35	Wall(s)	Wallboard Joint Compound		Off	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B38	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B38	Door/Door Frame	Metal and Wood		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
Basement	B38	Floor	Carpet		Brown	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B38	Misc	Cove Base	4"	Beige	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B38	Wall(s)	Wallboard Joint Compound		Beige/Green	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B39	Ceiling	Hardlid Pinhole Worm		Beige	N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B39	Door/Door Frame	Wood and Metal		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
Basement	B39	Floor	Resilient Flooring Tile	12x12	Brown Marble	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B39	Misc	Cove Base	4"	Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B39	Wall(s)	Concrete		Beige	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B4	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm			N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B4	Door/Door Frame	Metal and Wood		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
Basement	B4	Floor	Resilient Flooring Tile /Mastic	12x12	Brown/Black	Y	n/a	Y	N	Good - No Damage	n/a	n/a	no	n/a	n/a	Y	ACM is in the mastic
Basement	B4	Misc	Cove Base	4"	Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B4	Wall(s)	Wallboard Joint Compound		Off White	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B40	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B40	Door/Door Frame	Wood and Metal		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
Basement	B40	Floor	Resilient Flooring Tile	12x12	Tan	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B40	Misc	Cove Base	4"	Beige	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B40	Wall(s)	Wallboard Joint Compound		Beige/Green	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B4A	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm			N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B4A	Door/Door Frame	Metal and Wood		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
Basement	B4A	Floor	Resilient Flooring Tile /Mastic	12x12	Brown/Black	Y	n/a	Y	N	Good - No Damage	n/a	n/a	no	n/a	n/a	Y	ACM is in the mastic
Basement	B4A	Misc	Cove Base	4"	Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B4A	Wall(s)	Wallboard Joint Compound		Off White	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B5	Ceiling	Hard Lid / Wallboard Joint Compound			N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B5	Door/Door Frame	Wood and Metal		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
Basement	B5	Floor	Epoxy		Brown	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B5	Wall(s)	Plaster		Beige	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B6	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm			N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B6	Door/Door Frame	Metal and Wood		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
Basement	B6	Floor	Resilient Flooring Tile /Mastic	12x12	Brown/Black	Y	n/a	Y	N	Good - No Damage	n/a	n/a	no	n/a	n/a	Y	ACM is in the mastic
Basement	B6	Misc	Cove Base	4"	Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B6	Wall(s)	Wallboard Joint Compound		Off White	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B7	Ceiling	Hard Lid / Wallboard Joint Compound			N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B7	Door/Door Frame	Wood and Metal		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
Basement	B7	Floor	Epoxy		Brown	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B7	Wall(s)	Plaster		Beige	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B8	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm			N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B8	Door/Door Frame	Metal and Wood		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
Basement	B8	Floor	Resilient Flooring Tile /Mastic	12x12	Brown/Black	Y	n/a	Y	N	Good - No Damage	n/a	n/a	no	n/a	n/a	Y	ACM is in the mastic
Basement	B8	Misc	Cove Base	4"	Brown	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B8	Wall(s)	Wallboard Joint Compound		Off Beige	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B9	Ceiling	Hard Lid / Wallboard Joint Compound			N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B9	Door/Door Frame	Wood and Metal		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core
Basement	B9	Floor	Epoxy		Brown	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	B9	Wall(s)	Plaster		Beige	N	n/a	Y	N		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	C1-1	Ceiling	Acoustic Ceiling Tile Pinhole Big Worm	2x4		N	n/a	Y	Y		n/a	n/a	n/a	n/a	n/a	n/a	
Basement	C1-1	Door/Door Frame	Wood and Metal		Bare/White	Not Suspect	n/a	n/a	n/a		n/a	n/a	n/a	n/a	n/a	n/a	Possible suspect material in core

