

Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
First Floor	134	Ceiling	Fiberglass Insulation		Silver	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	134	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	VALB-149-C1.1 - C1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	134	Floor	Concrete		Bare	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	134	Door/Door Frame	Roll Up		Gray	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Possible suspect material in core
First Floor	134	Wall(s)	Concrete		Off White	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	134	Misc	Covebase Mastic & Glue	4"	Green & Tan	Not Detected	VALB-149-M2.1 - M2.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	134	Misc	HVAC Duct Sealant		Green	Not Detected	VALB-149-R4.1 - R4.2	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	128	Ceiling	Fiberglass Insulation		Silver	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	128	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	VALB-149-C1.1 - C1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	128	Floor	Concrete		Bare	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	128	Door/Door Frame	Roll Up		Gray	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Possible suspect material in core
First Floor	128	Wall(s)	Concrete		Off White	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	128	Misc	Covebase Mastic & Glue	4"	Green & Tan	Not Detected	VALB-149-M2.1 - M2.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N / A	
First Floor	128	Misc	HVAC Duct Sealant		Green	Not Detected	VALB-149-R4.1 - R4.2	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N / A	
First Floor	133	Ceiling	Fiberglass Insulation		Silver	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	133	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	VALB-149-C1.1 - C1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N / A	
First Floor	133	Floor	Concrete		Bare	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	133	Door/Door Frame	Roll Up		Gray	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A		N/A	N/A	Possible suspect material in core
First Floor	133	Wall(s)	Concrete		Off White	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N / A	
First Floor	133	Misc	Covebase Mastic & Glue	4"	Green & Tan	Not Detected	VALB-149-M2.1 - M2.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	NN	N/A	
First Floor	133	Misc	HVAC Duct Sealant		Green	Not Detected	VALB-149-R4.1 - R4.2	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	125	Ceiling	Wallboard Joint Compound		Off White	Not Detected	VALB-149-C1.1 - C1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N / A	
First Floor	125	Wall(s)	Wallboard Joint Compound	2X2	Off White	Not Detected	VALB-149-C1.1 - C1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	125	Door/Door Frame	Wood/Metal		White & White	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Possible suspect material in core
First Floor	125	Floor	Resilient Floor Tile	12X12		Not Detected	VALB-149-F1.1 - F1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N / A	
First Floor	125	Misc	Covebase & Grout	4"	Gray & Tan	Not Detected	VALB-149-M2.1 - M2.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	124	Ceiling	Wallboard Joint Compound		Off White	Not Detected	VALB-149-C1.1 - C1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	124	Wall(s)	Wallboard Joint Compound	2X2	Off White	Not Detected	VALB-149-C1.1 - C1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	124	Floor	Ceramic Tile & Grout		Gray & Gray	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	124	Door/Door Frame	Wood/Metal		White & White	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Possible suspect material in core
First Floor	124	Misc	Ceramic Tile & Grout	4X4	Gray & Gray	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N / A	
First Floor	I	Ceiling	Wallboard Joint Compound		Off White	Not Detected	VALB-149-C1.1 - C1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	I	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	VALB-149-C1.1 - C1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	I	Floor	Resilient Floor Tile	12X12	White with Gray	Not Detected	VALB-149-F1.1 - F1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	I	Door/Door Frame	Wood/Metal		White/White	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Possible suspect material in core
First Floor	I	Misc	Covebase Mastic & Glue	4"	Gray & Tan	Not Detected	VALB-149-M2.1 - M2.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	I	Wall(s)	Ceramic Tile & Grout	4X4	Gray & Gray	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	Exterior	Ceiling	Concrete		Beige/Green/Off White	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	Exterior	Floor	Window Sealant No Windows with window putty. Outer edge has window caulk. Interior seal is rubber. I haven't	1/2"X150'	Black	15% Chrysotile	N/A	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	Exterior	Door/Door Frame	Metal Panels (Southeast Entrance) One panel up the wall & over the top of parapit		Off White	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Possible suspect material in core
First Floor	Exterior	Misc	Metal Panels (Roof Line)		Green	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	Exterior	Misc	Building Joint Sealant		Black	Not Detected	VALB-149-C1.1 - C1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Roof	Office Roof	Roof	Built Up Roof Under Reflecting Spray		Black	Not Detected	VALB-149-R3.1 - R3.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Roof	Office Roof	Roof	Reflecting Roof Spray		White	Not Detected	VALB-149-R2.1 - R2.3	Y	N/A	N/A	N/A	N/A	High	N/A	N/A	N/A	

Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT							Comment	
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing		Misc
Roof	Office Roof	Roof	Flashig Sealant		Black	Not Detected	VALB-149-R3.1 - R3.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Roof	Office Roof	Roof	Flashing Top Plate Sealant		Black	Not Detected	VALB-149-R5.1 - R6.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Possible suspect material in core
Roof	Office Roof	Roof	Roof Penetration Mastic Under Reflecting Spray			Not Detected	VALB-149-R2.5	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Roof	Office Roof	Roof	Waking Pads Under Reflecting Spray		Black	Not Detected	VALB-149-R7.1 - R7.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Roof	Office Roof	Roof	HVAC Duct Sealant		Gray	Not Detected	VALB-149-R4.1 - R4.2	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Roof	Warehouse Roof West	Roof	Built Up Roof Rolled Roof Material		Gray	Not Detected	VALB-149-R3.1 - R3.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Roof	Warehouse Roof West	Roof	Roof Penetration Mastic		Silver/Black	Not Detected	VALB-149-R2.5	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Roof	Warehouse Roof West	Roof	Rolled Roof Sealant		Black	Not Detected	VALB-149-R3.1 - R3.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Roof	Warehouse Roof West	Roof	Penetrating Mastic		Black	5%Chrysotile	VALB-149-R2.6	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Roof	Warehouse Roof West	Roof	Rolled Roof Sealant		Black	Not Detected	VALB-149-R3.1 - R3.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Roof	Roof Southwest	Roof	Flashing Sealant		Brown	Not Detected	VALB-149-R1.1 - R1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Roof	Roof Southwest	Roof	Flashing Top Plate Sealant		Black	Not Detected	VALB-149-R5.1 - R6.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Roof	Roof North	Roof	Flashing Top Plate Sealant and Reflective Roof Spray		Black	Not Detected	VALB-149-R5.1 - R6.3	Y	N/A	N/A	Not Detected	N/A	N/A	N/A	N/A	N/A	
Roof	Roof North	Roof	Built-Up Roof and Core		White/Black	Not Detected	VALB-149-R8.1 - R9.5	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Roof	Roof North	Roof	Flashing Sealant		Brown	Not Detected	VALB-149-R1.1 - R1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Roof	Roof North	Roof	Fibrous Layer and Roofing (North Center)		Black and White	Not Detected	VALB-149-R8.1 - R9.5	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Roof	Roof Southeast	Roof	Flashing Sealant		Brown	Not Detected	VALB-149-R1.1 - R1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Roof	Roof Southeast	Roof	Rolled Roof Sealant		Black	Not Detected	VALB-149-R3.1 - R3.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Roof	Roof Northeas and Northwest	Roof	Reflective Spray/Penetrating Mastic		Black	Not Detected	VALB-149-R2.1 - R2.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Roof	Roof AC #2 AND #6	Roof	Reflective Spray/Penetrating Mastic		Black	Not Detected	VALB-149-R5.1 - R6.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Roof	Warehouse Roof North	Roof	Penetrating Mastic		Black	2%Chrysotile	VALB-149-R2.4	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Roof	Warehousr Roof North	Roof	Rolled Roof Sealant		Black	Not Detected	VALB-149-R3.1 - R3.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Roof	Roof East	Roof	Walking Pad at ACF4		Black	Not Detected	VALB-149-R7.1 - R7.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Roof	Roof East	Roof	HVAC #1 Sealant		Gray	Not Detected	VALB-149-R4.1 - R4.2	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Roof	Roof East	Roof	Built-Up Roof Core		White and Black	Not Detected	VALB-149-R8.1 - R9.5	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Roof	Roof East	Roof	Walking Pad		Black	Not Detected	VALB-149-R7.1 - R7.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Roof	Roof West	Roof	Built-Up Roof Core, Roofing, and Fibrous Layer		Black	Not Detected	VALB-149-R8.1 - R9.5	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Roof	Warehouse Northeast	Roof	Sealant		Gray	Not Detected	VALB-149-R4.1 - R4.2	Y	N/A	N/A	Not Detected	N/A	N/A	N/A	N/A	N/A	
Roof	Roof East South	Roof	Flashing Top Plate Sealant and Reflective Roof Spray		Black and White	Not Detected	VALB-149-R5.1 - R6.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	Room 17	Ceiling	Ceiling Wallboard With Joint Compound-Texture and Tape		White	Not Detected	VALB-149-C1.1 - C1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	Room 17	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	VALB-149-C1.1 - C1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	Room 17	Floor	Ceramic Tile & Grout	12X12	Brown / Gray	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	Room 17	Door/Door Frame	Metal/Metal			Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Possible suspect material in core
First Floor	Room 106 Northeast	Ceiling	Ceiling Wallboard With Joint Compound-Texture and Tape		Whita	Not Detected	VALB-149-C1.1 - C1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	Room 106 Northeast	Wall(s)	Wallboard Joint Compound			Not Detected	VALB-149-C1.1 - C1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	Room 106 Northeast	Floor	Ceramic Tile & Grout	2x2	Gray and Black	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	Room 106 Northeast	Door/Door Frame	Wood/Metal			Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Possible suspect material in core
First Floor	Room 106 Northeast	Misc	Ceramic Tile & Grout	4X4	Gray and Off White	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	Room 3 North	Ceiling	Acoustical Ceiling Tiles	2x2		Not Detected	N/A	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	Room 3 North	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	VALB-149-C1.1 - C1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	Room 3 North	Floor	Carpet		Gray	Not Detected	N/A	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	Room 3 North	Door/Door Frame	Wood/Metal			Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Possible suspect material in core
First Floor	Room 3 North	Misc	Covebase and Mastic	6"	Blue/Gray	Not Detected	VALB-149-M1.1 - M1.3	Y	N/A	N/A	Not Detected	N/A	N/A	N/A	N/A	N/A	
First Floor	Room 107 Northwest	Ceiling	Ceiling Wallboard With Joint Compound-Texture and Tape		White	Not Detected	VALB-149-C1.1 - C1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	

[illegible]

Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
First Floor	Rm.111 West & Rm.101 South and Rm. 104 North	Ceiling	Acoustical Ceiling Tiles	2x2		Not Detected	N/A	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	Rm.111 West & Rm.101 South and Rm. 104 North	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	VALB-149-C1.1 - C1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	Rm.111 West & Rm.101 South and Rm. 104 North	Floor	Carpet		Brown	Not Detected	N/A	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	Rm.111 West & Rm.101 South and Rm. 104 North	Door/Door Frame	Wood/Metal			Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Possible suspect material in core
First Floor	Rm.111 West & Rm.101 South and Rm. 104 North	Misc	Covebase and Mastic	4"	Brown and Tan	Not Detected	VALB-149-M2.1 - M2.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	Roof Center	Roof	Built-Up RoofCore-Roofing And Fibrous Layer		Black	Not Detected	VALB-149-R8.1 - R9.5	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	Roof South	Roof	Built-Up Roof Core,		Black	Not Detected	VALB-149-R8.1 - R9.5	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	CC130-2 at Rms. 8 and 15	Misc	Resilient Floor Tile and Glue (Both Rooms)	12X12	Gray and Yellow	Not Detected	VALB-149-F1.1 - F1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	CC130-2 at Rm. 17	Misc	Resilient Floor Tile and Glue	12X12	Gray and Yellow	Not Detected	VALB-149-F1.1 - F1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	111A	Ceiling	Acoustical Ceiling Tiles	2x2		Not Detected	N/A	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	111A	Wall(s)	Wallboard Joint Compound		Beige	Not Detected	VALB-149-C1.1 - C1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	111A	Floor	Carpet		Brown	Not Detected	N/A	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	111A	Door/Door Frame	Wood/Metal			Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Possible suspect material in core
First Floor	111A	Misc	Covebase and Mastic	4"	Brown and Tan	Not Detected	VALB-149-M2.1 - M2.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	113	Ceiling	Acoustical Ceiling Tiles	2x2		Not Detected	N/A	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	113	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	VALB-149-C1.1 - C1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	113	Floor	Carpet		Brown	Not Detected	N/A	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	113	Door/Door Frame	Wood/Metal			Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Possible suspect material in core
First Floor	113	Misc	Covebase and Mastic	4"	Brown and Tan	Not Detected	VALB-149-M2.1 - M2.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	114	Ceiling	Acoustical Ceiling Tiles	2x2		Not Detected	N/A	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	114	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	VALB-149-C1.1 - C1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	114	Floor	Carpet		Brown	Not Detected	N/A	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	114	Door/Door Frame	Wood/Metal			Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Possible suspect material in core
First Floor	114	Misc	Covebase and Mastic	4"	Brown and Tan	Not Detected	VALB-149-M2.1 - M2.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	115	Ceiling	Acoustical Ceiling Tiles	2x2		Not Detected	N/A	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	115	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	VALB-149-C1.1 - C1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	115	Floor	Carpet		Brown	Not Detected	N/A	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	115	Door/Door Frame	Wood/Metal			Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Possible suspect material in core
First Floor	115	Misc	Covebase and Mastic	4"	Brown and Tan	Not Detected	VALB-149-M2.1 - M2.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	120	Ceiling	Acoustical Ceiling Tiles	2x2		Not Detected	N/A	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	120	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	VALB-149-C1.1 - C1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	120	Floor	Carpet		Brown	Not Detected	N/A	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	120	Door/Door Frame	Wood/Metal			Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Possible suspect material in core
First Floor	120	Misc	Covebase and Mastic	4"	Brown and Tan	Not Detected	VALB-149-M2.1 - M2.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	103	Ceiling	Acoustical Ceiling Tiles	2x2		Not Detected	N/A	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	103	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	VALB-149-C1.1 - C1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	103	Floor	Carpet		Brown	Not Detected	N/A	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	103	Door/Door Frame	Wood/Metal			Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Possible suspect material in core
First Floor	103	Misc	Covebase and Mastic	4"	Brown and Tan	Not Detected	VALB-149-M2.1 - M2.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	121	Ceiling	Acoustical Ceiling Tiles	2x2		Not Detected	N/A	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	121	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	VALB-149-C1.1 - C1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	121	Floor	Carpet		Brown	Not Detected	N/A	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	

[illegible]

Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
First Floor	122	Ceiling	Acoustical Ceiling Tiles	2x2		Not Detected	N/A	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	122	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	VALB-149-C1.1 - C1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	122	Floor	Carpet		Brown	Not Detected	N/A	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	122	Door/Door Frame	Wood/Metal			Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Possible suspect material in core
First Floor	122	Misc	Covebase and Mastic	4"	Brown and Tan	Not Detected	VALB-149-M2.1 - M2.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	116	Ceiling	Acoustical Ceiling Tiles	2x2		Not Detected	N/A	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	116	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	VALB-149-C1.1 - C1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	116	Floor	Carpet		Brown	Not Detected	N/A	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	116	Door/Door Frame	Wood/Metal			Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Possible suspect material in core
First Floor	116	Misc	Covebase and Mastic	4"	Brown and Tan	Not Detected	VALB-149-M2.1 - M2.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	119	Ceiling	Acoustical Ceiling Tiles	2x2		Not Detected	N/A	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	119	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	VALB-149-C1.1 - C1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	119	Floor	Carpet		Brown	Not Detected	N/A	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	119	Door/Door Frame	Wood/Metal			Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Possible suspect material in core
First Floor	119	Misc	Covebase and Mastic	4"	Brown and Tan	Not Detected	VALB-149-M2.1 - M2.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	102	Ceiling	Acoustical Ceiling Tiles	2x4		Not Detected	N/A	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	102	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	VALB-149-C1.1 - C1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	102	Floor	Carpet		Brown	Not Detected	N/A	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	102	Door/Door Frame	Wood/Metal			Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Possible suspect material in core
First Floor	102	Misc	Covebase and Mastic	4"	Brown and Tan	Not Detected	VALB-149-M2.1 - M2.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	105	Ceiling	Acoustical Ceiling Tiles	2x2		Not Detected	N/A	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	105	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	VALB-149-C1.1 - C1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	105	Floor	Carpet		Brown	Not Detected	N/A	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	105	Door/Door Frame	Wood/Metal			Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Possible suspect material in core
First Floor	105	Misc	Covebase and Mastic	4"	Brown and Tan	Not Detected	VALB-149-M2.1 - M2.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	135	Wall(s)	Wallboard Joint Compound		Bare	Not Detected	VALB-149-C1.1 - C1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	135	Floor	Concrete		Bare	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	136	Wall(s)	Wallboard Joint Compound		Bare	Not Detected	VALB-149-C1.1 - C1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	136	Floor	Concrete		Bare	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	137	Wall(s)	Wallboard Joint Compound		Bare	Not Detected	VALB-149-C1.1 - C1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	137	Floor	Concrete		Bare	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	129	Ceiling	Fiberglass Insulation		Silver	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	129	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	VALB-149-C1.1 - C1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	129	Floor	Concrete		Bare	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	129	Door/Door Frame	Wood/Metal		Beige	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Possible suspect material in core
First Floor	129	Wall(s)	Concrete		Off White	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	129	Misc	Covebase Mastic & Glue	4"	Green & Tan	Not Detected	VALB-149-M2.1 - M2.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N /A	
First Floor	129	Misc	HVAC Duct Sealant		Green	Not Detected	VALB-149-R4.1 - R4.2	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N /A	
First Floor	Room 105 East	Ceiling	Wallboard Joint Compound		White	Not Detected	VALB-149-C1.1 - C1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	Room 105 East	Wall(s)	Wallboard Joint Compound														
First Floor	Room 105 East	Floor	Ceramic Tile & Grout	2x2	Gray and Black	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	Room 105 East	Door/Door Frame	Wood/Metal			Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Possible suspect material in core
First Floor	Room 105 East	Misc	Ceramic Tile & Grout	4X4	Gray and Off White	Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	Room 108 East	Ceiling	Wallboard Joint Compound		White	Not Detected	VALB-149-C1.1 - C1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	

[illegible]

Rm Name/No.		Surface	Material	Size	Color	Sample Info			HAZARD ASSESSMENT								Comment
						Asbestos Present	Contractor Sample No.	Previously Sampled (Y/N)	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	Significantly Damaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc	
First Floor	11	Door/Door Frame	Wood/Metal			Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Possible suspect material in core
First Floor	12	Ceiling	Acoustical Ceiling Tiles	2x2		Not Detected	N/A	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	12	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	VALB-149-C1.1 - C1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	12	Floor	Resilient Floor Tile	12X12		Not Detected	VALB-149-F1.1 - F1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	12	Door/Door Frame	Wood/Metal			Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Possible suspect material in core
First Floor	13	Ceiling	Acoustical Ceiling Tiles	2x2		Not Detected	N/A	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	13	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	VALB-149-C1.1 - C1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	13	Floor	Resilient Floor Tile	12X12		Not Detected	VALB-149-F1.1 - F1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	13	Door/Door Frame	Wood/Metal			Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Possible suspect material in core
First Floor	14	Ceiling	Acoustical Ceiling Tiles	2x2		Not Detected	N/A	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	14	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	VALB-149-C1.1 - C1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	14	Floor	Resilient Floor Tile	12X12		Not Detected	VALB-149-F1.1 - F1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	14	Door/Door Frame	Wood/Metal			Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Possible suspect material in core
First Floor	15	Ceiling	Acoustical Ceiling Tiles	2x2		Not Detected	N/A	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	15	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	VALB-149-C1.1 - C1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	15	Floor	Resilient Floor Tile	12X12		Not Detected	VALB-149-F1.1 - F1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	15	Door/Door Frame	Wood/Metal			Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Possible suspect material in core
First Floor	16	Ceiling	Acoustical Ceiling Tiles	2x2		Not Detected	N/A	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	16	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	VALB-149-C1.1 - C1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	16	Floor	Resilient Floor Tile	12X12		Not Detected	VALB-149-F1.1 - F1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	16	Door/Door Frame	Wood/Metal			Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Possible suspect material in core
First Floor	130	Ceiling	Acoustical Ceiling Tiles	2x2		Not Detected	N/A	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	130	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	VALB-149-C1.1 - C1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	130	Floor	Resilient Floor Tile	12X12		Not Detected	VALB-149-F1.1 - F1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	130	Door/Door Frame	Wood/Metal			Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Possible suspect material in core
First Floor	3	Ceiling	Acoustical Ceiling Tiles	2x4		Not Detected	N/A	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	3	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	VALB-149-C1.1 - C1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	3	Floor	Carpet		Gray	Not Detected	N/A	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	3	Door/Door Frame	Wood/Metal			Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Possible suspect material in core
First Floor	3	Misc	Covebase and Mastic	6"	Gray and Tan	Not Detected	VALB-149-M2.1 - M2.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	4	Ceiling	Acoustical Ceiling Tiles	2x4		Not Detected	N/A	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	4	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	VALB-149-C1.1 - C1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	4	Floor	Carpet		Gray	Not Detected	N/A	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	4	Door/Door Frame	Wood/Metal			Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Possible suspect material in core
First Floor	4	Misc	Covebase and Mastic	6"	Gray and Tan	Not Detected	VALB-149-M2.1 - M2.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	5	Ceiling	Acoustical Ceiling Tiles	2x4		Not Detected	N/A	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	5	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	VALB-149-C1.1 - C1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	5	Floor	Carpet		Gray	Not Detected	N/A	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	5	Door/Door Frame	Wood/Metal			Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Possible suspect material in core
First Floor	5	Misc	Covebase and Mastic	6"	Gray and Tan	Not Detected	VALB-149-M2.1 - M2.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	6	Ceiling	Acoustical Ceiling Tiles	2x4		Not Detected	N/A	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	6	Wall(s)	Wallboard Joint Compound		Off White	Not Detected	VALB-149-C1.1 - C1.3	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	6	Floor	Carpet		Gray	Not Detected	N/A	Y	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
First Floor	6	Door/Door Frame	Wood/Metal			Not Suspect	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Possible suspect material in core

[illegible]