



	Page 2 of 8
FILE NAME: Site Observation Photos_Armand_VA_Lake View NY_5-18-15_VA101V-15-F-0891	-

<image/>	
LOCATION- REAR OF HOME DESCRIPTION- LOOKING WEST, POOL TO BE REMOVED; NEW ADDITON TO THE LEFT; NEW RAMP WILL RUN PARALLEL ALONG THE REAR WALL OF THE NEW ADDITION AND END LEVEL WITH THE CONCRETE HERE	PHOTO 005
LOCATION- EAST SIDE YARD DESCRIPTION- EXISTING CONCRETE TO REMAIN AND INTEGRATED WITH NEW WALK	РНОТО 006

DATE OF INSPECTION

05/18/2015

VA-Department of Veterans Affairs 1528 Evergreen Drive, Lake View NY 10485

LOCATION- EAST SIDE YARD DESCRIPTION- EXISTING CONCRETE TO REMAIN AND INTEGRATED WITH NEW WALK	РНОТО 007
	DUOTO
LOCATION- EAST SIDE YARD DESCRIPTION- LOCATION OF NEW CONCRETE WALK	РНОТО 008



FILE NAME: Site Observation Photos_Armand_VA_Lake View NY_5-18-15_VA101V-15-F-0891





VA-Department of Veterans Affairs	DATE OF INSPECTION
1528 Evergreen Drive, Lake View NY 10485	05/18/2015

