

VA Ann Arbor Healthcare System
Construct North Parking Structure

Existing Parking Garage – Level D
Masonry Restoration Work

Photo Index



VA Ann Arbor Healthcare System
Construct North Parking Structure

Existing Parking Garage – Level D
Masonry Restoration Work

Photo Index



APPENDIX F

Extra Material | Attic Stock

VA Ann Arbor Healthcare System
Construct North Parking Structure

Extra Material | Attic Stock

Photo Index




APPENDIX G

**Existing Parking Garage
Miscellaneous Work**

VA Ann Arbor Healthcare System
Construct North Parking Structure

Existing Parking Garage Miscellaneous Work

Photo Index



Level A

VA Ann Arbor Healthcare System
Construct North Parking Structure

Existing Parking Garage Miscellaneous Work

Photo Index



Level B

VA Ann Arbor Healthcare System
Construct North Parking Structure

Existing Parking Garage Miscellaneous Work

Photo Index



Level C

VA Ann Arbor Healthcare System
Construct North Parking Structure

Existing Parking Garage Miscellaneous Work

Photo Index



Level D

APPENDIX H

Existing Security Camera Conduit System

VA Ann Arbor Healthcare System
Construct North Parking Structure

Existing Security Camera Conduit System

Photo Index

Typical PVC
branch conduit

Typical PVC
conduit up to
Level B




Level A | Column Mark C-15

VA Ann Arbor Healthcare System
Construct North Parking Structure

Existing Security Camera Conduit System

Photo Index



Level A | Column Mark D-15

VA Ann Arbor Healthcare System
Construct North Parking Structure

Existing Security Camera Conduit System

Photo Index

Typical PVC junction
box and PVC conduit
up to Level C



Typical PVC conduit
down to Level A

Level B | Column Mark C-15

VA Ann Arbor Healthcare System
Construct North Parking Structure

Existing Security Camera Conduit System

Photo Index

Typical PVC
branch conduit

Typical PVC junction
box and PVC conduit
up to Level C




Level B | Column Mark D-15

VA Ann Arbor Healthcare System
Construct North Parking Structure

Existing Security Camera Conduit System

Photo Index



Level C | Column Mark C-15


Typical PVC conduit
down to Level B

VA Ann Arbor Healthcare System
Construct North Parking Structure

Existing Security Camera Conduit System

Photo Index

Existing PVC conduit feeder routed
to Level A Existing Electric Room –
1995 Parking Garage.
Refer to drawing E-201.



Level C | Stair 2 Existing PVC Conduit Feeder

VA Ann Arbor Healthcare System
Construct North Parking Structure

Existing Security Camera Conduit System

Photo Index

Existing PVC conduit feeder routed
to Level A Existing Electric Room –
1995 Parking Garage.
Refer to drawing E-201.



Level C | Stair 2 Existing PVC Conduit Feeder

VA Ann Arbor Healthcare System
Construct North Parking Structure

Existing Security Camera Conduit System

Photo Index



Level C | Typical Double Tee

Typical PVC junction box
and PVC conduits.

Typical PVC conduit for
power wiring.