



Building 1, Floor 10 - Specific Survey Findings
Project No. VAMC:10013.00-IN

1511 Route 22, Suite C24, Brewster, NY 10509
Phone: 845.278.7710 Fax: 845.278.7750

Project: Main Building, 10th Floor
VA Medical Center
Wilkes-Barre, PA

Inspector(s): James Reber
Thomas Ferro
Date(s): 2/2010-3/2010

LOCATION	MATERIAL	QUANTITY	CONDITION	SAMPLE #	HOMOGENEOUS WITH SAMPLE #	ASBESTOS CONTENT
10th Floor, Main Corridor East-West						
Floor	12" X 12" floor tile	2500 ft ² not incl. elevator area	N/A	N/A	10-52	None detected
	Floor tile mastic		N/A	N/A	10-53	2% Chrysotile
Walls	Tile and Plaster	N/A	N/A	N/A	N/A	Non-suspect
Ceilings	2' X 4' ceiling tile	N/A	N/A	10-48	N/A	None detected
Above ceiling	Pipe insulation – black mastic over cork from closet C10-6 to C10-12 and C10-14 to C10-56. 100-200 LF					Assumed
10th Floor, Dayroom, W end and 10-01A (C10-02, C10-03)						
Floor	Carpet over 12" X 12" floor tile	1426 ft ²	N/A	N/A	10-52	None detected
	Floor tile mastic	1426 ft ²	N/A	N/A	10-53	2% Chrysotile
Walls	Sheetrock joint material	N/A	N/A	N/A	10-47	None detected
	Block	N/A	N/A	N/A	N/A	Non-suspect
Ceilings	2' X 4' ceiling tile	N/A	N/A	10-48	N/A	None detected
	Metal deck	N/A	N/A	N/A	N/A	Non-suspect



Building 1, Floor 10 - Specific Survey Findings
Project No. VAMC:10013.00-IN

10th Floor, room 10-02						
Floor	Rug over wood	N/A	N/A	N/A	N/A	Non-suspect
Walls	Sheetrock joint material	N/A	N/A	N/A	N/A	Non-suspect
Ceilings	2' X 4' ceiling tiles	N/A	N/A	N/A	10-41	None detected
10th Floor, room 10-04						
Floor	Carpet over 12" X 12" floor tile	272 ft ²	N/A	N/A	10-52	None detected
	Floor tile mastic	272 ft ²	N/A	N/A	10-53	2% Chrysotile
Walls	Sheetrock joint material	N/A	N/A	N/A	10-47	None detected
Ceilings	2' X 4' Ceiling tile	N/A	N/A	N/A	10-41	None detected
Above ceiling tile	Plaster	N/A	N/A	N/A	N/A	Non-suspect
10th Floor, room 10-05						
Floor	Carpet over 12' X 12" floor tile	N/A	V	N/A	10-52	None detected
	Floor tile mastic	N/A	N/A	N/A	10-53	2% Chrysotile
Walls	Sheetrock joint material	N/A	N/A	N/A	10-47	None detected
	Plaster	N/A	N/A	N/A	N/A	Non-suspect
Ceilings	2' X 4' ceiling tile	N/A	N/A	N/A	10-41	None detected
Vertical pipe chase, SW corner	Pipe insulation – can be seen in bathroom chase – heads across hallway and down into wall. Cannot see extent or condition.	N/A	N/A	N/A	N/A	Assumed



Building 1, Floor 10 - Specific Survey Findings
Project No. VAMC:10013.00-IN

10th Floor, room 10-06						
Floor	Concrete	N/A	N/A	N/A	N/A	Non-suspect
Walls	Block	N/A	N/A	N/A	N/A	Non-suspect
Ceilings	Concrete	N/A	N/A	N/A	N/A	Non-suspect
Pipes at floor & ceiling	Pipe insulation (tar over cork)	2 LF	Good	N/A	6-96	8% Chrysotile
Pipe is duct taped	Pipe insulation (perlite)	6 LF	Significantly damaged	10-49	N/A	None detected
10th Floor, room 10-07						
Floor	Carpet over 12' X 12" floor tile	145 ft ²	Good	N/A	10-52	None detected
	Floor tile mastic	145ft ²	N/A	N/A	10-53	2% Chrysotile
Walls	Plaster	N/A	N/A	N/A	N/A	Non-suspect
	Sheetrock joint material	N/A	N/A	N/A	10-47	None detected
Ceilings	2' X 4' ceiling tile	N/A	N/A	N/A	10-41	None detected
10th Floor, room 10-08						
Floor	12" X 12" floor tile	80 ft ²	N/A	N/A	10-52	None detected
	Floor tile mastic	80 ft ²	N/A	N/A	10-53	2% Chrysotile
Walls	Plaster	N/A	N/A	N/A	N/A	Non-suspect
	Sheetrock joint material	N/A	N/A	N/A	10-47	None detected
Ceilings	2' X 4' ceiling tile	N/A	N/A	N/A	10-41	None detected



Building 1, Floor 10 - Specific Survey Findings
Project No. VAMC:10013.00-IN

10th Floor, room 10-09						
Floor	Ceramic tile	N/A	N/A	N/A	N/A	Non-suspect
Walls	Ceramic tile/ plaster/brick	N/A	N/A	N/A	N/A	Non-suspect
10th Floor, room 10-10						
Floor	12" X 12" floor tile under carpet & in bathroom	324 ft ²	N/A	N/A	10-52	None Detected
	Floor tile mastic	324 ft ²	N/A	N/A	10-53	2% Chrysotile
Walls	Sheetrock joint material	N/A	N/A	10-50	N/A	None detected
Ceilings	2' X 4' ceiling tile	N/A	N/A	N/A	10-41	None detected
10th Floor, room 10-11						
Floor	12" X 12" floor tile under carpet	200 ft ²	N/A	N/A	10-52	None detected
	Floor tile mastic	200 ft ²	N/A	N/A	10-53	2% Chrysotile
Walls	Sheetrock joint material	N/A	N/A	N/A	N/A	Non-suspect
Ceilings	2' X 4' ceiling tile	N/A	N/A	N/A	10-41	None detected
Chase at NW corner	Pipe insulation inside chase	N/A	N/A	N/A	N/A	Assumed
10th Floor, room 10-12						
Floor	Ceramic flooring	200 ft ²	N/A	N/A	N/A	Non-suspect
Walls	Tile and plaster	N/A	N/A	N/A	N/A	Non-suspect
Ceilings	Plaster	N/A	N/A	N/A	N/A	Non-suspect
Above ceiling	Pipe insulation – mastic over cork	N/A	N/A	N/A	N/A	Assumed



Building 1, Floor 10 - Specific Survey Findings
Project No. VAMC:10013.00-IN

10th Floor, room 10-14						
Floor	Carpet over 12" X 12" floor tile	288 ft ²	N/A	N/A	10-52	None detected
	Floor tile mastic	288 ft ²	N/A	N/A	10-53	2% Chrysotile
Walls	Plaster	N/A	N/A	N/A	N/A	Non-suspect
	Sheetrock joint material	N/A	N/A	N/A	10-47	None detected
Ceilings	2'X 4' ceiling tile	N/A	N/A	10-51	N/A	None detected
10th Floor, room 10-15						
Floor	Carpet over 12" X12" floor tile (not in bathroom)	160 ft ²	N/A	N/A	10-52	None Detected
	Floor tile mastic	160 ft ²	N/A	N/A	10-53	2% Chrysotile
Walls	Plaster	N/A	N/A	N/A	N/A	Non-suspect
	Sheetrock joint material	N/A	N/A	N/A	10-47	None detected
Ceilings	2' X 4' ceiling tile	N/A	N/A	N/A	10-41	None detected
10th Floor, room 10-16						
Floor	Carpet over 12' X 12" floor tile (not in bathroom)	288 ft ²	N/A	N/A	10-52	None detected
	Floor tile mastic	288 ft ²	N/A	N/A	10-53	2% Chrysotile
Walls	Sheetrock joint material	N/A	N/A	N/A	10-47	None detected
Ceilings	2' X 4' ceiling tiles	N/A	N/A	N/A	10-41	None detected
10th Floor, room 10-17						
Floor	Carpet over 12" X 12" floor tile (in bathroom also)	432 ft ²	N/A	N/A	10-52	None detected
	Floor tile mastic	432 ft ²	N/A	N/A	10-53	2% Chrysotile



Building 1, Floor 10 - Specific Survey Findings
Project No. VAMC:10013.00-IN

Walls	Plaster	N/A	N/A	N/A	N/A	Non-suspect
	Sheetrock joint material	N/A	N/A	N/A	10-47	None detected
Ceilings	2' x 4' ceiling tile	N/A	Good	N/A	10-41	None detected
Pipe chase, SE corner	Pipe insulation	20 LF	N/A	N/A	N/A	Assumed
10th Floor, room 10-18						
Floor	Rug over concrete w/ mastic – residual left from inadequate abatement	80 ft ²	N/A	N/A	N/A	2% Chrysotile
Walls	Sheetrock joint material	N/A	N/A	N/A	10-47	None detected
Ceilings	2' X 4' ceiling tile	80 ft ²	N/A	N/A	10-41	None detected
10th Floor, room 10-19 and C10-19A						
Floor	Carpet over 12" X 12' floor tile	220 ft ²	N/A	N/A	10-52	None detected
	Floor tile mastic	220 ft ²	N/A	N/A	10-53	2% Chrysotile
Ceilings	2' X 4' ceiling tile	220 ft ²	N/A	N/A	10-41	None detected
10th Floor, room 10-43 Electric/Telephone closet						
Floor	Metal grating	N/A	N/A	N/A	N/A	Non-suspect
Walls	CMU	N/A	N/A	N/A	N/A	Non-suspect
Ceilings	Metal Grating	N/A	N/A	N/A	N/A	Non-suspect
Comment: Chase has no suspect ACM						



Building 1, Floor 10 - Specific Survey Findings
Project No. VAMC:10013.00-IN

10th Floor, room 10-20						
Floor	Rug over concrete w/ mastic – residual left from inadequate abatement	144 ft ²	N/A	N/A	N/A	2% Chrysotile
Walls	Sheetrock joint material	N/A	N/A	N/A	10-47	None detected
Ceilings	2' X 4' ceiling tile	N/A	N/A	N/A	10-41	None detected
	12" X 12' ceiling tile	144 ft ²	N/A	N/A	10-41	None detected
10th Floor, room 10-21						
Floor	Carpet over 12" X 12' floor tile (in bathroom also)	150 ft ²	Good	N/A	10-52	None detected
	Floor tile mastic	150 ft ²	N/A	N/A	10-53	2% Chrysotile
Walls	Sheetrock joint material	N/A	N/A	N/A	10-47	None detected
Ceilings	2' X 4' ceiling tile	N/A	N/A	N/A	10-41	None detected
10th Floor, room 10-22						
Floor	Rug over concrete w/ mastic – residual left from inadequate abatement	100 ft ²	N/A	N/A	N/A	2% Chrysotile
Walls	Sheetrock joint material	N/A	N/A	N/A	10-47	None detected
Ceilings	2' X 4' ceiling tile	90-100 ft ²	N/A	N/A	10-41	None detected
10th Floor, room 10-23						
Floor	Rug over ceramic	N/A	N/A	N/A	N/A	Non-suspect
Walls	Sheetrock joint material	N/A	N/A	N/A	10-47	None detected
Ceilings	2' x 4' ceiling tile	90-100 ft ²	N/A	N/A	10-41	None detected



Building 1, Floor 10 - Specific Survey Findings
Project No. VAMC:10013.00-IN

10th Floor, room 10-24						
Floor	Rug over ceramic	N/A	N/A	N/A	N/A	Non-suspect
Walls	Sheetrock joint material	N/A	N/A	N/A	10-47	None detected
Ceilings	2' X 4' ceiling tile	200 ft ²	N/A	N/A	10-41	None detected
10th Floor, room 10-25						
Floor	12" X 12' floor tile	63 ft ²	N/A	N/A	10-52	None detected
	Floor tile mastic	63 ft ²	N/A	N/A	10-53	2% Chrysotile
Walls	Sheetrock joint material	N/A	Good	10-47	N/A	None detected
Ceilings	2' X 4' ceiling tile	N/A	N/A	N/A	10-41	None detected
10th Floor, room 10-26						
Floor	Rug over ceramic	N/A	N/A	N/A	N/A	Non-suspect
Walls	Sheetrock joint material	N/A	N/A	N/A	10-47	None detected
Ceilings	2' x 4' ceiling tile	140 ft ²	N/A	N/A	10-41	None detected
10th Floor, room 10-28						
Floor	Concrete	N/A	N/A	N/A	N/A	Non-suspect
Walls	Block	N/A	N/A	N/A	N/A	Non-suspect
Ceilings	Concrete	N/A	N/A	N/A	N/A	Non-suspect
Pipe at floor level – SE corner	Pipe insulation @ sleeves for floor penetration	<1LF	Damaged	N/A	N/A	Assumed



Building 1, Floor 10 - Specific Survey Findings
Project No. VAMC:10013.00-IN

10th Floor, room 10-29						
Floor	12" X 12" floor tile	108 ft ²	Good	N/A	10-52	None detected
	Floor tile mastic	108 ft ²	N/A	N/A	10-53	2% Chrysotile
Walls	Plaster	N/A	N/A	N/A	N/A	Non-suspect
Ceilings	2' X 4' ceiling tile	N/A	N/A	N/A	10-41	None detected
10th Floor, room 10-30						
Floor	12" X 12" floor tile	56 ft ²	Good	N/A	10-52	None detected
	Floor tile mastic	56 ft ²	N/A	N/A	10-53	2% Chrysotile
Walls	Block	N/A	N/A	N/A	N/A	Non-suspect
	Sheetrock joint material	N/A	N/A	N/A	10-47	None detected
Ceilings	Concrete	N/A	N/A	N/A	N/A	Non-suspect
10th Floor, rooms 10-35, 10-34, 10-33, 10-32, 10-31						
Floor	Rug over concrete w/ mastic – residual left from inadequate abatement (10-32 no mastic)	600 ft ²	N/A	N/A	N/A	2% Chrysotile
	Leveling compound	N/A	N/A	N/A	N/A	Non-suspect
Walls	Plaster	N/A	N/A	N/A	N/A	Non-suspect
Ceilings	2' X 4' ceiling tile	616 ft ²	Good	N/A	10-41	None detected
Note: Cannot lift rug in 10-32 and 10-35						



Building 1, Floor 10 - Specific Survey Findings
Project No. VAMC:10013.00-IN

10th Floor, room 10-36						
Floor	12" X 12" floor tile	96 ft ²	Good	N/A	10-52	None detected
	Floor tile mastic	96 ft ²	N/A	N/A	10-53	2% Chrysotile
Walls	Sheetrock joint material	N/A	N/A	10-46	N/A	None detected
	Plaster	N/A	N/A	N/A	N/A	Non-suspect
Ceilings	2' X 4' ceiling tile	N/A	N/A	N/A	10-41	None detected
10th Floor, hallway by main elevators						
Floor	12" X 12" floor tile	720 ft ²	N/A	N/A	10-52	None detected
	Floor tile mastic	720ft ²	N/A	N/A	10-52	2% Chrysotile
Walls	Plaster /ceramic tile	N/A	N/A	N/A	N/A	Non-suspect
Ceilings	2' X 4' ceiling tiles	N/A	N/A	N/A	10-41	None detected
10th Floor, room 10-37						
Floor	Metal	N/A	N/A	N/A	N/A	Non-suspect
Walls	Block	N/A	N/A	N/A	N/A	Non-suspect
Ceilings	Metal	N/A	N/A	N/A	N/A	Non-suspect
Pipe riser in chase	Pipe insulation (tar over cork)	12 LF	Good	N/A	6-96	8% Chrysotile



Building 1, Floor 10 - Specific Survey Findings
Project No. VAMC:10013.00-IN

10th Floor, work station and small adjoining rooms 10-38A and 10-38B (as shown on drawings)						
Floor	Rug over floor tile (work station)	N/A	N/A	N/A	N/A	Non-suspect
	12" x 12" floor tile (work station)	180-200 ft ²	N/A	N/A	10-52	None detected
	Floor tile mastic	180-200 ft ²	N/A	N/A	10-53	2% Chrysotile
	12" X 12" Floor tile (10-38A/10-38B)	52 ft ² 10-38A 40 ft ² 10-38B	Good	N/A	10-52	None detected
	Floor tile mastic	92 ft ²	N/A	N/A	10-53	2% Chrysotile
Walls	Sheetrock joint material	N/A	N/A	N/A	10-47	None detected
Ceilings	2' X 4' ceiling tile	N/A	N/A	N/A	10-41	None detected
10 Floor, room 10-39						
Floor	12" X 12" floor tile (white w/tan & gray mottles)	117 ft ²	Good	10-44	N/A	None detected
	Floor tile mastic	117 ft ²	N/A	10-44	N/A	None detected
Walls	Plaster	N/A	N/A	N/A	N/A	Non-suspect
Ceilings	2' X 4' ceiling tile	N/A	Good	N/A	10-41	None detected
10th Floor, room 10-40						
Floor	12" X 12" floor tile	42 ft ²	Good	N/A	10-52	None detected
	Floor tile mastic	42 ft ²	N/A	N/A	10-52	2% Chrysotile
Walls	Plaster	N/A	N/A	N/A	N/A	Non-suspect
Ceilings	Plaster	N/A	N/A	N/A	N/A	Non-suspect



Building 1, Floor 10 - Specific Survey Findings
Project No. VAMC:10013.00-IN

10th Floor, room 10-41						
Floor	Terrazzo tile	N/A	N/A	N/A	N/A	Non-suspect
Walls	Plaster	N/A	N/A	N/A	N/A	Non-suspect
Ceilings	2' X 4' ceiling tile	48 ft ²	N/A	N/A	10-41	None detected
10th Floor, room 10-42						
Floor	12" X 12" floor tile under carpet	270 ft ²	N/A	N/A	10-52	None detected
	Floor tile mastic	270 ft ²	N/A	N/A	10-53	2% Chrysotile
Walls	Plaster	N/A	N/A	N/A	N/A	Non-suspect
Ceilings	2' X 4' Ceiling tile	N/A	N/A	N/A	10-41	None detected
10 floor, hallway by service elevator						
Floor	12" X 12" floor tile	200 ft ²	N/A	N/A	10-52	None detected
	Floor tile mastic	200 ft ²	Good	N/A	10-53	2% Chrysotile
Walls	Brick / sheetrock	N/A	N/A	N/A	N/A	Non-suspect
Ceilings	2' X 4' ceiling tile	N/A	N/A	10-43	N/A	None detected
Above ceiling tile	Spray-on fireproofing	N/A	N/A	10-42	N/A	None detected
10th Floor, rooms 10-49, 10-48, 10-47, 10-46, 10-45, and 10-44						
Floor	12" X 12" Floor tile – under carpet (10-44, 10-46) (10-47&10-48 tile in bath) (10-45 ceramic tile in bath) (10-49 no bath)	150 – 400 ft ² /room	N/A	10-52	N/A	None detected
	Floor tile mastic	150 – 400 ft ² /room	N/A	10-53	N/A	2% Chrysotile



Building 1, Floor 10 - Specific Survey Findings
Project No. VAMC:10013.00-IN

Walls	Plaster	N/A	N/A	N/A	N/A	Non-suspect
Ceilings	2' X 4' ceiling tile	N/A	N/A	N/A	10-41	None detected
10th Floor, room 10-51 and 10-53						
Floor	Ceramic tile	N/A	N/A	N/A	N/A	Non-suspect
Walls	Plaster/ceramic tile	N/A	N/A	N/A	N/A	Non-suspect
Ceilings	Plaster	N/A	N/A	N/A	N/A	Non-suspect
Comment: Assume chase have pipe insulation						
10th Floor, room 10-52						
Floor	Carpet over 12" X 12" floor tile	250 ft ²	N/A	N/A	10-52	None detected
	Floor tile mastic	250 ft ²	N/A	N/A	10-53	2% Chrysotile
Walls	Plaster	N/A	N/A	N/A	N/A	Non-suspect
Ceilings	2' X 4' ceiling tile	N/A	N/A	N/A	10-41	None detected
10th Floor, room 10-56						
Floor	Concrete	N/A	N/A	N/A	N/A	Non-suspect
Walls	Block	N/A	N/A	N/A	N/A	Non-suspect
Ceilings	Concrete	N/A	N/A	N/A	N/A	Non-suspect
Pipe	Pipe insulation (tar over cork) at ceiling and floor	10 LF	Damaged	N/A	6-96	8% Chrysotile



Building 1, Floor 10 - Specific Survey Findings
Project No. VAMC:10013.00-IN

10th Floor, supply room next to room 10-56 – (C10-54A)						
Floor	12" X 12" floor tile	72 ft ²	N/A	N/A	10-52	None detected
	Floor tile mastic	72 ft ²	N/A	N/A	10-53	2%Chrysotile
Ceilings	2' X 4' ceiling tile	N/A	N/A	N/A	10-41	None detected
Comment: C10-54 has ceramic tile						
10th Floor, room 10-57						
Floor	Carpet over 12" X 12' floor tile (light tan w/ dark tan/white/gray mottles)	350 ft ²	Good	N/A	10-52	None detected
	Floor tile mastic	350 ft ²	N/A	N/A	10-53	2% Chrysotile
Walls	Sheetrock joint material	N/A	N/A	N/A	10-46	None detected
	Plaster	N/A	N/A	N/A	N/A	Non-suspect
Ceilings	Concrete	N/A	N/A	N/A	N/A	Non-suspect
	2' X 4' ceiling tile (off-white w/perforation markings)	N/A	Good	10-41	N/A	None detected
Pipe chase – SW corner - sealed	Pipe insulation	>8 LF	N/A	N/A	N/A	Assumed
10th Floor, main E hallway						
Floor	12" X 12" floor tile	N/A	N/A	N/A	10-52	None detected
	Floor tile mastic	N/A	N/A	N/A	10-53	2% Chrysotile
Walls	Plaster/ceramic tile	N/A	N/A	N/A	N/A	Non-suspect
Ceilings	2' X 4' ceiling tile	N/A	N/A	N/A	10-41	None detected
Above ceiling	Pipe insulation – mastic over cork – from C10-56 to C10-14	200 LF	Good	N/A	N/A	Assumed



Building 1, Floor 10 - Specific Survey Findings
Project No. VAMC:10013.00-IN

10 th Floor, room 10-58						
Floor	Carpet over 12' X 12" floor tile (Floor tile in bathroom also)	400 ft ²	N/A	N/A	10-52	None detected
	Floor tile mastic	400 ft ²	N/A	N/A	10-53	2% Chrysotile
Walls	Plaster	N/A	N/A	N/A	N/A	Non-suspect
Ceilings	2' X 4' ceiling tile	N/A	N/A	N/A	10-41	None detected
Above ceiling tile	Plaster	N/A	N/A	N/A	N/A	Non-suspect
Comments: Fiberglass insulation is located in bathroom area above plaster ceilings.						