

Homogenous Area No.	Material Description	Approximate Quantity	Friable		Current Classification	Hazard Ranking	Disturbance Potential			Potential Hazard Ranking	August 2017 Inspection
			Yes	No			Contact	Vibration	Air Erosion		
Building 22											
2	Floor Mastic Under Tile Black Basement and 1st	350 SF		X	Significantly Damaged	1	Low	High	Low	6	1st floor abated save for east foyer. Basement significant damage
5	Floor Tile 9"x9" (Does Not Include Mastic) Green 1st	450 SF		X	Significantly Damaged	1	High	High	Low	7	1st floor abated save for east foyer. Basement significant damage
6	Floor Mastic Under Black Tile 1st	450 SF		X	Good	1	Low	High	Low	3	Abated save for east foyer
10	Piping Insulation Magnesia-Type (Heating System) basement	200 SF		X	Damaged	1	Low	High	High	3	Damaged, partially remediated
11	Piping Insulation Aircell -Type (Domestic Water) basement	250 SF		X	Damaged	1	Low	High	High	3	Damaged, partially remediated
12	Piping Fitting Insulation On Magnesia-Type (Heating System) basement	10 EA		X	Damaged	1	Low	High	High	3	Damaged, partially remediated
17	Piping Insulation Magnesia-Type (Heating System) fire door basement	1 EA	X		Good	4	Low	High	High	3	Repaired
18	Exterior window glazing basement and 1st	2000 LF		X	Good	1	Low	High	Low	3	Some damage on a few windows
19	exterior paint white.	10000 SF	X		Damaged	4	Low	High	High	3	Painted over

Homogenous Area No.	Material Description	Approximate Quantity	Friable		Current Classification	Hazard Ranking	Disturbance Potential			Potential Hazard Ranking	August 2017 Inspection
			Yes	No			Contact	Vibration	Air Erosion		
Building 58											
4	Floor Mastic Under Tile Black fifth floor	520 SF		X	Good	1	Low	High	Low	3	Good
15	Floor Tile 9"X9" (Does Not Include Mastic) Tan, Brown & Green Basement through fifth	19000 SF		X	Damaged	1	High	High	High	3	Basement damaged,1-3 abated. Some 9x9 remains in path lab. 9x9 remains in some stair wells. Recommend removal of 9x9 in West stairwell.
16	Floor Mastic Under Tile Black 1st through 5th	19000 SF		X	Good	1	Low	High	Low	3	1-3 abated, 4-5 good.
29	Mastic On Sink Black 1st through 5th	7 EA		X	Damaged	1	Low	High	Low	3	Several damaged
32	Piping Insulation Magnesia-Type (Heating System) crawlspace and attic	3000 LF	X		Significantly Damaged	4	Low	High	High	6	Attic 90% abated, remainder damaged. crawl space unchanged, significantly damaged
33	Piping Insulation Aircell-Type (Domestic Waterline) crawlspace	350 LF	X		Damaged	4	Low	High	High	6	Damaged
36	Debris Soil Debris (MAG) crawlspace	12500 SF	X		Damaged	4	Low	High	High	6	Damaged
37	Thermal Taping Compound Tape attic	7000 SF	X		Damaged	4	Low	High	High	6	90% abated, remainder damaged
38	Pipe Support Insulation On Fiberglass Insulated Lines attic	350 EA	X		Damaged	4	Low	High	High	6	90% abated; remainder damaged
39	Pipe Fitting Insulation On Fiberglass Run (Chilled Waterline) crawlspace and attic	500 EA	X		Damaged	4	Low	High	High	6	Attic 90% abated, remainder damaged. Crawlspace unchanged, significantly damaged
42	Caulking/Putties Fire Stop, On Fan Coil Unit exterior windows	400 LF		X	Damaged	1	Low	High	High	3	Several damaged
43	Floor Mastic Under Tile Black 5th floor	500 SF		X	Good	1	Low	High	Low	3	Good
48	Pipe Fitting Insulation On Blk Styrofoam Lines (Domestic/Chilled Lines) basement	40 EA	X		Damaged	4	Low	High	High	6	Damaged
49	Floor Tile 12"X12" (Does Not Include Mastic) Tan With Brown & Yellow Streaks basement	500 SF		X	Damaged	1	High	High	High	3	Damaged
102	Elevator Brake Shoes attic	10 SF		X	Good	1	High	High	High	3	Good

Homogenous Area No.	Material Description	Approximate Quantity	Friable		Current Classification	Hazard Ranking	Disturbance Potential			Potential Hazard Ranking	August 2017 Inspection
			Yes	No			Contact	Vibration	Air Erosion		
Building 64											
3	Floor Tile 12"X12" (Does Not Include Mastic) White With Grey Streaks	18 SF		X	Good	1	High	High	High	3	Good Condition
4	Floor Mastic Under Tile Black	18 SF		X	Good	1	Low	High	Low	3	Good Condition
5	Floor Tile 12"X12" (Does Not Include Mastic) White With Brown Streaks	120 SF		X	Good	1	High	High	High	3	Good Condition
6	Floor Mastic Under Tile Black	120 SF		X	Good	1	Low	High	Low	3	Good Condition
7	Vinyl Sheet Flooring (Does Not Include Mastic) Brown	300 SF	X		Good	4	Low	High	High	6	Good Condition
16	Piping Insulation Aircell-Type (Heating System)	140 LF		X	Damaged	1	Low	High	High	3	Damaged in attic, partially abated. May need further abatement.
18	Floor Mastic Under Tile Black	300 SF		X	Good	1	Low	High	Low	3	Good Condition

Homogenous Area No.	Material Description	Approximate Quantity	Friable		Current Classification	Hazard Ranking	Disturbance Potential			Potential Hazard Ranking	August 2017 Inspection
			Yes	No			Contact	Vibration	Air Erosion		
Building 69											
3	Floor Mastic under tile Black	220 SF		X	Damaged	1	Low	High	Low	3	Damaged
6	Piping insulation Magnesia-Type (Heating System)	400 LF	X		Damaged	4	Low	High	High	6	Damaged
7	PipingInsulation, Aircell-Type	100 LF		X	Damaged	4	Low	High	High	6	Damaged
10	Debris Pipe Debris In Soil	60 SF	X		Removed						Removed
11	Floor Mastic under tile Black	500 SF		X	Damaged	1	Low	High	Low	3	Damaged
15	Textured paint Exterior Paint (White)	10000 SF		X	Good	1	High	High	High	3	Painted over.

Homogenous Area No.	Material Description	Approximate Quantity	Friable		Current Classification	Hazard Ranking	Disturbance Potential			Potential Hazard Ranking	August 2017 Inspection
			Yes	No			Contact	Vibration	Air Erosion		
Building 72											
1	Floor Tile 12"x12" (does not include mastic) Tan	800 SF		X	Good	1	High	High	High	3	Good Condition
3	Floor Tile 12"x12" (does not include mastic) Gray	90 SF		X	Good	1	High	High	High	3	Good Condition
16	Piping insulation Aircell-Type (Heating System)	200 LF	X		Good	2	Low	High	High	3	Good, appears to have been partially abated
21	Window caulking Window Glazing (Gray)	1500 LF		X	Good	1	Moderate	High	High	3	Good Condition

Homogenous Area No.	Material Description	Approximate Quantity	Friable		Current Classification	Hazard Ranking	Disturbance Potential			Potential Hazard Ranking	August 2017 Inspection
			Yes	No			Contact	Vibration	Air Erosion		
Building 98											
8	Floor Mastic Under Tile Black 2nd floor	1800 SF		X	Good	1	Low	High	Low	3	Abated, although some 12x12 floor tile still exists in remote areas, all in good condition. Areas noted on 'Asbestos' drawings on S: drive.
17	Floor Tile 9"x9" (Does Not Include Mastic) Tan - Basement	6000 SF		X	Good	1	High	High	High	3	(12x12) in basement - all in good condition
17	Floor Tile 9"x9" (Does Not Include Mastic) Tan - 1st			X	Good	1	High	High	High	3	(12x12) in remote areas - all in good condition. Shown on 'Asbestos' drawings on S: drive. 2nd floor was renovated.
17	Floor Tile 9"x9" (Does Not Include Mastic) Tan - 2nd			X	Good	1	High	High	High	3	(12x12) in remote areas - all in good condition. Shown on 'Asbestos' drawings on S: drive. 2nd floor was renovated.
17	Floor Tile 9"x9" (Does Not Include Mastic) Tan - 3rd			X	Good	1	High	High	High	3	(12x12) on third floor - all in good condition
18	Floor Mastic Under Tile Black - Basement	6000 SF		X	Good	1	Low	High	Low	3	See above
18	Floor Mastic Under Tile Black - 2nd			X	Good	1	Low	High	Low	3	See above
18	Floor Mastic Under Tile Black - 3rd			X	Good	1	Low	High	Low	3	See above
21	Piping Insulation Magnesia-Type (Heating System) Basement	350 LF	X		Damaged	4	Low	High	High	6	In locked crawl space. Significantly damaged
22	Emergency Generator Muffler Insulation Grey Generator Room	100 SF	X		Damaged	4	Low	Low	Low	4	Repaired. Not marked as containing or not containing asbestos
30	Debris Soil Debris (MAG) Basement	10000 SF	X		Damaged	4	Low	High	High	6	In locked crawl space. Significantly damaged
32	Firestop Caulking/Putties On Fan Coil Unit Exterior Windows - 1st floor	250 LF		X	Good	1	Low	High	High	3	
32	Firestop Caulking/Putties On Fan Coil Unit Exterior Windows - 2nd floor			X	Damaged	1	Low	High	High	3	Visible damage to exterior window caulking on 2nd floor.
32	Firestop Caulking/Putties On Fan Coil Unit Exterior Windows - 3rd floor			X	Damaged	1	Low	High	High	3	Visible damage to exterior window caulking on 3rd floor.
35	Pipe Fitting Insulation On Roof Drain Penthouse	12 EA	X		Damaged	4	Low	High	High	6	
36	Pipe Fitting Insulation On Fiberglass Run (Domestic & Chilled Water Line) - Basement	80 EA	X		Damaged	4	Low	High	High	6	
36	Pipe Fitting Insulation On Fiberglass Run (Domestic & Chilled Water Line) - 1st	80 EA	X		Damaged	4	Low	High	High	6	
36	Pipe Fitting Insulation On Fiberglass Run (Domestic & Chilled Water Line) - 2nd	80 EA	X		Good	4	Low	High	High	6	
37	Pipe Fitting Insulation On Foam Rubber Piping Insulation - Penthouse	600 EA	X		Damaged	4	Low	High	High	6	On the survey, HO37 is the asbestos debris in the basement: "98-CRAWL-37-01", ...-02", ...-03".
102	Elevator Brake Shoes Penthouse	10 SF		X	Good	1	High	High	High	3	

Homogenous Area No.	Material Description	Approximate Quantity	Friable		Current Classification	Hazard Ranking	Disturbance Potential			Potential Hazard Ranking	August 2017 Inspection
			Yes	No			Contact	Vibration	Air Erosion		
Building 101											
23	Joint Compound On Gypsum Board White	2500 SF		X	Good	1	Moderate	m	Low	2	Abated as part of halls and walls project??
25	Pipe Fitting Insulation On Fiberglass Line (Htg, Domes/Chilled Water Line)	1500 EA	X		Damaged	4	Low	High	High	6	Still damaged throughout. Some piece meal abatement has occurred in response to specific issues. Some removal possibly necessary.
26	Tank Insulation Gray	120 SF		X	Significantly Damaged	1	Moderate	Low	Low	7	?? There is a tank in utility room that has fresher insulation on it. Utility room appears to have had fairly recent abatement performed
27	Window Caulking Exterior Window Glazing	8000 LF		X	Good	1	Low	Moderate	High	3	Good. Some minor damage in peace garden
29	Piping Insulation Roof Drain Insulation (Assumed)	15 LF	X		Damaged	4	Low	High	Low	3	Damaged

Homogenous Area No.	Material Description	Approximate Quantity	Friable		Current Classification	Hazard Ranking	Disturbance Potential			Potential Hazard Ranking	August 2017 Inspection
			Yes	No			Contact	Vibration	Air Erosion		
Building 102											
2	Floor Mastic on HA#1	1000SF		X	Good	1	Low	High	Low	3	Approximately 50% abated, 50%good
5	Floor Tile 12"X12",	1000 SF		X	Good	1	High	High	High	3	Approximately 50% abated, 50%good
12&13	Viny Sheet Flooring, Brown Mastic	1000 SF		X	Good	1	High	High	High	3	Could not locate. Abated?
18	Pipe Fitting Insulation On Fiberglass Run (Htg, Domes/Chilled Water Line)	300 EA	X		Damaged	4	Low	High	High	6	Damaged
27	Window Caulking Gray	8000 LF	X		Damaged	4	Low	High	High	6	Appears to have been repaired at some point
28	Window Caulking Gray	200 LF		X	Good	1	Low	Moderate	High	3	Good
106	Mastic on Fan Coil Unit	75 SF		X	Good	1	Low	High	High	3	Good
202	Mastic under gold sheet flooring	750 LF		X	Good	1	Low	High	Low	3	Could not locate. Abated?

Homgenou s Area No.	Material Description	Approximat e Quantity	Friable		Current Classification	Hazard Ranking	Disturbance Potential			Potential Hazard Ranking	August 2017 Inspection
			Yes	No			Contact	Vibration	Air Erosion		
			Building 103								
19	Pipe Fitting Insulation On Fiberglass Run (Htg, Domes/Chilled Water Line)	1300 EA	X		Damaged	4	Low	High	high	6	Per notations on drawings, information on this insulation was provided to the contractor by the VA and not examined in either the 2010 or 2007 assessments.

Homogenous Area No.	Material Description	Approximate Quantity	Friable		Current Classification	Hazard Ranking	Disturbance Potential			Potential Hazard Ranking	August 2017 Inspection
			Yes	No			Contact	Vibration	Air Erosion		
Building 104											
2	Floor Mastic Under Tile Black	5800 SF		X	Good	1	Low	High	Low	3	Hallways abated, some floor tiles remain in offices.
4	Floor Mastic Under Tile Black	1500 SF		X	Good	1	Low	High	Low	3	Hallways abated, some floor tiles remain in offices.
6	Floor Mastic Under Tile Black	5000 SF		X	Good	1	Low	High	Low	3	Hallways abated, some floor tiles remain in offices.
7	Floor Tilew 12"x12", Orange/Mastic	500 SF		X	Good	1	High	High	High	3	Hallways abated, some floor tiles remain in offices.
14	Pipe Fitting Insulation On Fiberglass Run (Heating & Domestic Waterline)	450 EA	X		Damaged	4	Low	High	High	6	Approximately 75% abated, 25 % damaged
18	Mastic On Sink Black	3 EA		X	Good	1	Low	High	Low	3	Good
19	Transite-Type Panels	1200 SF		X	Good	1	Low	High	High	3	Good, but not all is transite
20	Tank Insulation Gray	50 SF	X		Damaged	4	Moderate	Low	Moderate	5	Removed
21	Generator Insulation Emergency Muffler Generator Insulation	300 SF	X		Damaged	4	Low	High	High	6	Damaged
103	Vibration Dampening cloth	25 SF		X	Good	1	Low	High	High	3	Good