

VA Medical Center - Ann Arbor, MI - 2009 Asbestos Room Inventory

Bldg	Floor	Room No	HA	Material Type	Homogeneous Area Description	Location	Qty	Unit	Response Category	AHERA Assessment	Comments
4	1	NS Corridor	3	MM/Non-Friable	Mastic under HA # 1	floor	121	SF	4		
4	1	NS Corridor	6	TSI/Friable	Mudded pipe fittings on steam lines; <2" diameter pipes	above ceiling	15	FTG	2	1	
4	1	NS Corridor	70	TSI/Friable	Straight run millboard insulation <2" diameter pipes	above ceiling	1	LF	3	5	
4	1	Stair Landing	1	MM/Non-Friable	1' x 1' Floor tile; Cream with brown streaks (light and dark)	floor	120	SF	4		Stair #2, NE Corner of Bldg., Former Room 114
4	1	Stair Landing	3	MM/Non-Friable	Mastic under HA # 1	floor	120	SF	4		Stair #2, NE Corner of Bldg., Former Room 114
4	1	Stair Landing	6	TSI/Friable	Mudded pipe fittings on steam lines; <2" diameter pipes		12	FTG	3	5	Stair #2, NE Corner of Bldg., 2' High @ each Level, Former Room 114
22	G	G1	20	MM/Non-Friable	1' x 1' Floor tile; White with grey flecks	floor	617	SF	4		
22	G	G1	23	MM/Non-Friable	Mastic under HA # 20	floor	617	SF	4		
22	G	G1a	20	MM/Non-Friable	1' x 1' Floor tile; White with grey flecks	floor	166	SF	4		
22	G	G1a	23	MM/Non-Friable	Mastic under HA # 20	floor	166	SF	4		
22	G	G3	20	MM/Non-Friable	1' x 1' Floor tile; White with grey flecks	floor	351	SF	4		
22	G	G3	23	MM/Non-Friable	Mastic under HA # 20	floor	351	SF	4		
22	G	G4	20	MM/Non-Friable	1' x 1' Floor tile; White with grey flecks	floor	365	SF	4		3 Tiles Damaged at Rear Counter
22	G	G4	23	MM/Non-Friable	Mastic under HA # 20	floor	365	SF	4		
22	G	G4	239	MM/Non-Friable	Black Lab Tops with groove under lip	counter tops	50	SF	5		
22	G	G5	20	MM/Non-Friable	1' x 1' Floor tile; White with grey flecks	floor	270	SF	4		
22	G	G5	23	MM/Non-Friable	Mastic under HA # 20	floor	270	SF	4		
22	G	G6	1	MM/Non-Friable	1' x 1' Floor tile; Cream with brown streaks (light and dark)	floor	232	SF	4		

VA Medical Center - Ann Arbor, MI - 2009 Asbestos Room Inventory

Bldg	Floor	Room No	HA	Material Type	Homogeneous Area Description	Location	Qty	Unit	Response Category	AHERA Assessment	Comments
22	G	G6	3	MM/Non-Friable	Mastic under HA # 1	floor	232	SF	4		
22	G	G6b	1	MM/Non-Friable	1' x 1' Floor tile; Cream with brown streaks (light and dark)	floor	79	SF	4		
22	G	G6b	3	MM/Non-Friable	Mastic under HA # 1	floor	79	SF	4		
22	G	G8	20	MM/Non-Friable	1' x 1' Floor tile; White with grey flecks	floor	380	SF	4		
22	G	G8	23	MM/Non-Friable	Mastic under HA # 20	floor	380	SF	4		
22	G	G8a	20	MM/Non-Friable	1' x 1' Floor tile; White with grey flecks	floor	44	SF	4		Damaged - Missing Tiles
22	G	G8a	23	MM/Non-Friable	Mastic under HA # 20	floor	95	SF	4		Exposed mastic - Approx. 25% missing
22	G	G8c	20	MM/Non-Friable	1' x 1' Floor tile; White with grey flecks	floor	81	SF	4		
22	G	G8c	23	MM/Non-Friable	Mastic under HA # 20	floor	81	SF	4		
22	G	G10	20	MM/Non-Friable	1' x 1' Floor tile; White with grey flecks	floor	587	SF	4		
22	G	G10	23	MM/Non-Friable	Mastic under HA # 20	floor	587	SF	4		
22	G	G12	1	MM/Non-Friable	1' x 1' Floor tile; Cream with brown streaks (light and dark)	floor	180	SF	4		Abrasion near lab bench on north wall
22	G	G12	3	MM/Non-Friable	Mastic under HA # 1	floor	180	SF	4		
22	G	G12a	1	MM/Non-Friable	1' x 1' Floor tile; Cream with brown streaks (light and dark)	floor	216	SF	4		Rooms 12a & 12b Combined, Abrasion at desk
22	G	G12a	3	MM/Non-Friable	Mastic under HA # 1	floor	216	SF	4		Rooms 12a & 12b Combined
22	G	G21	1	MM/Non-Friable	1' x 1' Floor tile; Cream with brown streaks (light and dark)	floor	36	SF	4		
22	G	G21	3	MM/Non-Friable	Mastic under HA # 1	floor	36	SF	4		
22	G	G23	1	MM/Non-Friable	1' x 1' Floor tile; Cream with brown streaks (light and dark)	floor	220	SF	4		
22	G	G23	3	MM/Non-Friable	Mastic under HA # 1	floor	220	SF	4		

March 12, 2010

VA Medical Center - Ann Arbor, MI - 2009 Asbestos Room Inventory

Bldg	Floor	Room No	HA	Material Type	Homogeneous Area Description	Location	Qty	Unit	Response Category	AHERA Assessment	Comments
22	1	104	20	MM/Non-Friable	1' x 1' Floor tile; White with grey flecks	floor	12	SF	4		Under Fume Hood
22	1	104	23	MM/Non-Friable	Mastic under HA # 20	floor	12	SF	4		Under Fume Hood
22	1	105	20	MM/Non-Friable	1' x 1' Floor tile; White with grey flecks	floor	528	SF	4		Abrasion at desks near hall
22	1	105	23	MM/Non-Friable	Mastic under HA # 20	floor	528	SF	4		
22	1	105a	20	MM/Non-Friable	1' x 1' Floor tile; White with grey flecks	floor	93	SF	4		
22	1	105a	23	MM/Non-Friable	Mastic under HA # 20	floor	93	SF	4		
22	1	108	20	MM/Non-Friable	1' x 1' Floor tile; White with grey flecks	floor	12	SF	4		Under Fume Hood
22	1	108	23	MM/Non-Friable	Mastic under HA # 20	floor	12	SF	4		Under Fume Hood
22	1	108a	20	MM/Non-Friable	1' x 1' Floor tile; White with grey flecks	floor	145	SF	4		
22	1	108a	23	MM/Non-Friable	Mastic under HA # 20	floor	145	SF	4		
22	1	109	20	MM/Non-Friable	1' x 1' Floor tile; White with grey flecks	floor	12	SF	4		Under Fume Hood
22	1	109	23	MM/Non-Friable	Mastic under HA # 20	floor	12	SF	4		Under Fume Hood
22	1	111	20	MM/Non-Friable	1' x 1' Floor tile; White with grey flecks	floor	520	SF	4		
22	1	111	23	MM/Non-Friable	Mastic under HA # 20	floor	520	SF	4		
22	1	111a	20	MM/Non-Friable	1' x 1' Floor tile; White with grey flecks	under carpet	90	SF	4		
22	1	111a	23	MM/Non-Friable	Mastic under HA # 20	floor	90	SF	4		
22	1	113	20	MM/Non-Friable	1' x 1' Floor tile; White with grey flecks	floor	234	SF	4		
22	1	113	23	MM/Non-Friable	Mastic under HA # 20	floor	234	SF	4		
22	1	114	20	MM/Non-Friable	1' x 1' Floor tile; White with grey flecks	floor	179	SF	4		Tile Damaged: cracking & pulling up from floor

VA Medical Center - Ann Arbor, MI - 2009 Asbestos Room Inventory

Bldg	Floor	Room No	HA	Material Type	Homogeneous Area Description	Location	Qty	Unit	Response Category	AHERA Assessment	Comments
22	1	114	23	MM/Non-Friable	Mastic under HA # 20	floor	179	SF	4		
22	1	Corridor	20	MM/Non-Friable	1' x 1' Floor tile; White with grey flecks	floor	862	SF	4		All 4 Corridors Combined
22	1	Corridor	23	MM/Non-Friable	Mastic under HA # 20	floor	862	SF	4		All 4 Corridors Combined
22	G	Corridor to Building 1	1	MM/Non-Friable	1' x 1' Floor tile; Cream with brown streaks (light and dark)	floor	472	SF	4		
22	G	Corridor to Building 1	3	MM/Non-Friable	Mastic under HA # 1	floor	472	SF	4		
22	G	Corridor to Building 1	6	TSI/Friable	Mudded pipe fittings on steam lines; <2" diameter pipes	Riser	3	FTG	3	5	By Register Closest to Building 1
22	G	Stair #1	6	TSI/Friable	Mudded pipe fittings on steam lines; <2" diameter pipes	above ceiling & 2 Risers	15	FTG	1	1	Damaged at Floor Level, Formerly Room G18
22	G	Stair #1	20	MM/Non-Friable	1' x 1' Floor tile; White with grey flecks	floor	36	SF	4		Formerly Room G18
22	G	Stair #1	23	MM/Non-Friable	Mastic under HA # 20	floor	36	SF	4		Formerly Room G18
22	1	Stair #1	20	MM/Non-Friable	1' x 1' Floor tile; White with grey flecks	floor	140	SF	4		Damaged floor tile peeling up, Formerly Room 119
22	1	Stair #1	23	MM/Non-Friable	Mastic under HA # 20	floor	140	SF	4		Formerly Room 119
22	Roof	Penthouse	297	MM	Duct Putty: Light Brown	HVAC Ductwork	33	LF	4		Possibly more underneath fiberglass insulation
22	Roof	Penthouse	298	MM	Spray-on insulation: Stairwell	Top of Stairwell & Chase	20	SF	2	2	Poor Condition Appears to be more in Chase
22	Roof	Penthouse	299	MM	Expansion Cloth, Woven Heavy Weave	HVAC Ductwork Close to Floor Penetration	21	LF	4		Localized Damaged
22	Roof	Penthouse	305	TSI	Steam Line, Straight Run Performed Block >2" <4"	East West Run in South Half Along Ductwork	50	LF	2	1	Localized Damaged
22	Roof	Penthouse	306	TSI	Steam Line Mud Fittings on Straight Run Performed Block >2" <4"	East West Run in South Half Along Ductwork	6	FTG	2	1	Localized Damaged

VA Medical Center - Ann Arbor, MI - 2009 Asbestos Room Inventory

Bldg	Floor	Room No	HA	Material Type	Homogeneous Area Description	Location	Qty	Unit	Response Category	AHERA Assessment	Comments
22	Roof	Penthouse	311	TSI	Hot Water Tank Insulation: Mud over Fiberglass	Near Center of South Side	2	LF	3	5	
28	1	Stair #1	224	MM/Non-Friable	Linoleum, Beige with brown streaks	floor	244	SF	4		
28	1	Stair #2	224	MM/Non-Friable	Linoleum, Beige with brown streaks	floor	153	SF	4		

