




Photograph 41: Rusted Shelf Angles




Photograph 48: Stain from Ladder




Photograph 49: Stained Parapet




Photograph 50: Typical Façade Staining




Photograph 51: Stain at Louver




Photograph 52: Typical Plaster Crack




Photograph 53: Plaster Cracking at Parapet




Photograph 54: Typical Stucco Crack




Photograph 55: Typical Stucco Crack



Photograph 56: Cracked Sealant at Louver



Photograph 57: Typical Peeling Coating



Photograph 58: Typical Peeling Coating



Photograph 59: Organic Growth on Canopy Roof