




① Head Detail @ Beam - One Hour
1 1/2" = 1'-0"




② Head Detail @ Metal Deck (Parallel) - Non-Rated
1 1/2" = 1'-0"




③ Head Detail @ Metal Deck (Parallel) - One Hour
1 1/2" = 1'-0"




④ Head Detail @ Metal Deck (Parallel) - Smoke Resistant
1 1/2" = 1'-0"




⑤ Head Detail @ Metal Deck (Perpendicular) - Non-Rated
1 1/2" = 1'-0"




⑥ Head Detail @ Metal Deck (Perpendicular) - One Hour
1 1/2" = 1'-0"




⑦ Head Detail @ Metal Deck (Perpendicular) - Smoke Resistant
1 1/2" = 1'-0"



⑧ Head Detail @ Slab - Non-Rated
1 1/2" = 1'-0"



⑨ Head Detail @ Slab - One Hour
1 1/2" = 1'-0"



⑩ Head Detail @ Slab - Smoke Resistant
1 1/2" = 1'-0"

Revisions:	Date

Architect/Engineer:

willow design
Architecture
SERVICE DISABLED VETERAN OWNED SMALL BUSINESS

Seal:

Drawing Title Typical Metal Stud Details		Project Title Expand and Renovate Urgent Care Area - 15E at Castle Point		Date March 22, 2013
Scale As Noted		Building Number 15	Checked Checker	Drawn Author
Issued For Final Contract Documents		Location 100 Route 9D Castle Point, NY 12511		Drawing No. AE-505