B.42 CL02 water softener header Upgrade

all fittings to be
grooved victaulic (or equal)