



Metals Analysis of Paints

VA Palo Alto HCSES
Project Manager
3801 Miranda Ave (SAFE)

Palo Alto, CA 94304

Client ID: 1682
Report Number: M128550
Date Received: 04/16/12
Date Analyzed: 04/17/12
Date Printed: 04/17/12
First Reported: 04/17/12

Job ID / Site: PAD
Date(s) Collected: 4/13/12

FALI Job ID: 1682
Total Samples Submitted: 3
Total Samples Analyzed: 3

Sample Number	Lab Number	Analyte	Result	Result Units	Reporting Limit*	Method Reference
D725	30431178	Pb	< 0.006	wt%	0.006	EPA 3050B/6010B
Comment:	Insufficient sample size for repeatable analysis.					
D726	30431179	Pb	0.02	wt%	0.02	EPA 3050B/6010B
Comment:	Insufficient sample size for repeatable analysis.					
D727	30431180	Pb	0.18	wt%	0.002	EPA 3050B/6010B

* The Reporting Limit represents the lowest amount of analyte that the laboratory can confidently detect in the sample, and is not a regulatory level. The Units for the Reporting Limit are the same as the Units for the Final Results.

Daniele Siu, Laboratory Supervisor, Hayward Laboratory

Analytical results and reports are generated by Forensic Analytical at the request of and for the exclusive use of the person or entity (client) named on such report. Results, reports or copies of same will not be released by Forensic Analytical to any third party without prior written request from client. This report applies only to the sample(s) tested. Supporting laboratory documentation is available upon request. This report must not be reproduced except in full, unless approved by Forensic Analytical. The client is solely responsible for the use and interpretation of test results and reports requested from Forensic Analytical. Forensic Analytical is not able to assess the degree of hazard resulting from materials analyzed. Forensic Analytical reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified. Any modifications that have been made to referenced test methods are documented in Forensic Analytical's Standard Operating Procedures Manual. Sample results have not been blank corrected. Quality control and sample receipt condition were acceptable unless otherwise noted.