


INSTALL FOUR (4) KEYSTONE JACKS AND (4) USB PORTS AT COMPUTER WORKSTATION. CONNECT WORKSTATION TO EACH CAMERA LOCATION WITH CATEGORY 6 WIRE (WHITE) AND USB CABLE.



INSTALL SINGLE KEYSTONE JACK AND USB PORT AT EACH CAMERA LOCATION.