

APR. 1<sup>ST</sup> 2014

VA ASSUMED RBS

APR. 9<sup>TH</sup> 2014

EV-7 VALVE NOT WORKING CORRECT - REPAIRED

APR 12<sup>TH</sup> 2014

TRIPPED off LINE - RESET - STORM

APR 13<sup>TH</sup> 2014

SOLENOID BURN OUT - REPAIRED

APR 15<sup>TH</sup> 2014

DRAIN LINE STOPPED UP - CLEARED

APR 22<sup>ND</sup> 2014

DRAIN LINE STOPPED UP - CLEARED

APR 23<sup>RD</sup> 2014

CHANGED OUT CUTTER BASE, CUTTER HEAD, SHIMS

MAY 2<sup>ND</sup> 2014

EV-17 NOT WORKING - REPAIRED

MAY 7<sup>TH</sup> 2014

DOWN UNKNOWN REASONS

MAY 15<sup>TH</sup>

VENT STOPPED UP - CLEARED

MAY 18<sup>TH</sup>

DRAIN STOPPED UP - CLEARED

MAY 20<sup>TH</sup> 2014

DRAIN STOPPED UP - CLEARED

MAY 24 2014

ADJUSTED CUTTER HEAD

MAY 28<sup>th</sup> 2014

SHEARED OFF 11 bolts on BASE PLATE REPAIRED

JUNE 8<sup>th</sup> 2014

ADJUSTED CUTTER HEAD

June 20, 2014

adjusted cutter head

June 24, 2014

Changed out Base Plate + Cutter Head on RBS machine

June 26, 2014

working on RBS machine, replace circuit Board +.

July 1, 2014

Seal is leaking, replaced seal and new shaft in pump

July 23, 2014

re-installed new Seal + pump assable  
new cutter head and Blade.

Aug 5, 2014

adjusted cutter head

AUG 12<sup>th</sup>, 2014

Changed Cutter head Base plate + ADJUSTED Blade