



CABLES SHALL BE TERMINATED PER 568A.

SINGLE CIRCUIT LOW VOLTAGE
OCCUPANCY SENSOR WIRING DIAGRAM

(F1) SCALE: NONE SEE SYMBOL LEGEND FOR OCCUPANCY SENSOR REQUIREMENTS.

