



NOTES:

- 1 REPAIR DOWNSPOUT PER DET B7/3001-301.
- 2 SEE DET F4/3001-505 FOR FURTHER INFORMATION.
- 3 REPLACE FASCIA & RESTRICHMENT CUTTERS TO MATCH EXISTING.
SEE DET B7/3001-301 & F7/3001-505
- 4 INSTALL ALUM CLOSURE FLASHING OVER ABANDONED VENT HOLES IN ROOF.
PANT TO MATCH EXISTING ROOF, SEE DET F7/3001-505
- 5 REPLACE MISSING ALUM RIDGE CAP PIECES TO MATCH EXISTING.
SEE DET C7/3001-505
- 6 RE-STRAIGHTEN EXISTING FASCIA & PROVIDE NEW GUTTERS & DOWNSPOUTS
- 7 REMOVE AND REPLACE EXISTING ROLL-ROOFING

- 2 REPLACE FASCIA & RESTRAIGHTEN GUTTERS TO MATCH EXISTING

- 3 INSTALL ALUM CLOSURE FLASHING OVER ABANDONED VENT HOLES IN ROOF.

- 4 REPLACE MISSING ALUM RIDGE CAP PIECES TO MATCH EXISTING,

- 5 RE-STRAIGHTEN EXISTING FASCIA & PROVIDE NEW GUTTERS & DOWNSPOUTS
SEE DET C / 3001-303

- 6 REMOVE AND REPLACE EXISTING ROLL-ROOFING**

CONSULTANTS:

ARCHITECT/ENGINEERS

Drawing Title
MAINTENANCE FACILITY -
ROOF PLAN

Project Title
National Memorial Cemetery of the Pacific Columbarium Expansion and Cemetery Improvements

Project Number	899-M&R-FY15-00
Building Number	

Approved: Project Director

Location	Honolulu, Hawaii
----------	------------------

Drawing Number

Office of
Construction
and Facilities
Management

Date _____

VA FORM 08-623