

DOOR SCHEDULE

DOOR		FRAME		Type	Assembly Rating	Notes
Door No	Size (W x H)	Type	Glass			
DB2-205	3'-0" x 7'-0"	Wood		Existing to Remain		(1)
DB2-229	3'-4" x 7'-0"	Wood		Existing to Remain		(1)
DB2-231	3'-0" x 7'-0"	Wood		Existing to Remain		(1)
DB2-232	3'-4" x 7'-0"	Wood	Narrow Lt	Existing to Remain		(1) (7)
A1031	3'-0" x 7'-0"	Wood		Existing to Remain		(2) (3) (6)
B2054	3'-0" x 7'-0"	Wood		Existing to Remain		(1)
B2055	(2) 3'-0" x 7'-0"	Wood	Narrow Lt	Existing to Remain		(2) (3) (7)
D2208	(2) 2'-0" x 7'-0"	Wood		Existing to Remain		(1)
D2209	(2) 2'-0" x 7'-0"	Wood		Existing to Remain		(1)
D2210	(2) 2'-0" x 7'-0"	Wood		Existing to Remain		(1)
D2211	(2) 2'-0" x 7'-0"	Wood		Existing to Remain		(1)
D2214	3'-8"x7'-0"	Wood	Narrow Lt	Existing to Remain		(1) (7)
D2215	3'-8"x7'-0"	Wood	Narrow Lt	Existing to Remain		(1) (7)
D2216	3'-8"x7'-0"	Wood	Narrow Lt	Existing to Remain		(1) (7)
D2217	3'-8"x7'-0"	Wood	Narrow Lt	Existing to Remain		(1) (7)
D2218	(2) 2'-0" x 7'-0"	Wood		Existing to Remain		(1)
D2219	(2) 2'-0" x 7'-0"	Wood		Existing to Remain		(1)
D2220	(2) 2'-0" x 7'-0"	Wood		Existing to Remain		(1)
D2221	3'-8"x7'-0"	Wood	Narrow Lt	Existing to Remain		(1) (7)
D2222	3'-8"x7'-0"	Wood	Narrow Lt	Existing to Remain		(1) (7)
D2224	3'-8"x7'-0"	Wood	Narrow Lt	Existing to Remain		(1) (7)
D2225	(2) 2'-0" x 7'-0"	Wood		Existing to Remain		(1)
D2226	(2) 2'-0" x 7'-0"	Wood		Existing to Remain		(1)
D2228	(2) 2'-0" x 7'-0"	Wood		Existing to Remain		(1)
D2232	3'-8"x7'-0"	Wood	Narrow Lt	Existing to Remain		(1) (7)
D2233	3'-8"x7'-0"	Wood	Narrow Lt	Existing to Remain		(1) (7)
D2234	3'-0"x7'-0"	Wood		Existing to Remain		(1)
D2235	(2) 2'-0" x 7'-0"	Wood		Existing to Remain		(1)
D2236	(2) 3'-0" x 7'-0"	Wood		Existing to Remain		(1)
B3110	(2) 2'-0" x 7'-0"	Wood		Existing to Remain		(1)
D3204	3'-0"x7'-0"	Wood		Existing to Remain		(1)
D3208	3'-0"x7'-0"	Wood		Existing to Remain		(1)
B5055	3'-0"x7'-0"	Wood		Existing to Remain		(1)
B5055A	3'-0"x7'-0"	Wood		Existing to Remain		(1)
B5055B	3'-0"x7'-0"	Wood		Existing to Remain		(1)
B5093	2'-8"x7'-0"	Wood	Narrow Lt	Existing to Remain		(1) (7)
B5104	3'-8"x7'-0"	Wood	Narrow Lt	Existing to Remain		(1) (7)
B5112	3'-0"x7'-0"	Wood	Narrow Lt	Existing to Remain		(1) (7)
B6108	3'-0"x7'-0"	Wood	Narrow Lt	Existing to Remain		(1) (7)
B7052	3'-0"x7'-0"	Wood		Existing to Remain		(1)
B7052A	3'-0"x7'-0"	Wood		Existing to Remain		(1)
16BLDG2	3'-8"x7'-0"	Metal		Replace Frame		(3) (4) (6) (8)
31BLDG12	3'-0"x7'-0"	Metal		Replace Frame		(3) (5) (6) (9)
1CBLDG12	3'-8"x7'-0"	Metal		Replace Frame		(3) (5) (6) (9)

Contractor shall field verify door/frame swing and dimensions prior to ordering/submittals.

Doors are located in Building 1, unless otherwise noted.

Notes:

- (1) Install VA provided SARGENT 10 Line Cylindrical Lock. Reinstall core into new hardware set
- (2) Provide and install Trilogy DL2700 with Medeco ASSA ABLOY X4, 6-Pin removeable core, keyway ident
- (3) Provide and install LCN Door Closing Device
- (4) Replace door and frame. Provide and install SARGENT 10 Line, Institutional lockset. Provide and instal
- (5) Replace door and frame. Provide and install SARGENT 10 Line, Classroom lockset.
- (6) Non-asbestos containing door.
- (7) Provide and install glazing as indicated
- (8) Building 2 ground floor.
- (9) Building 12 exterior door.