

## **TABLES**

TABLE 1 – ASBESTOS SAMPLING RESULTS

Existing Room Number(s)	Sample ID	Sample Description, and approximate quantity	Asbestos content and type
B0520/B0515 /B0526	VA-001A, B, C, D, E	Plaster ceilings	None Detected
B0520	VA-002A, B, C	Light yellow ceramic wall tile	None Detected
B0526/B0515	VA-003A, B, C	Grey ceramic wall tile	None Detected
B0522	VA-004A, B, C	Plaster wall system	None Detected
B0524	VA-005A, B	Off white ceramic wall tile	None Detected
Between B0524/B0522	VA-006A, B, C	Wall covering	None Detected
B0515/B0526	VA-007A, B, C	1" x 1" grey ceramic floor tile	None Detected
<b>B0522</b>	<b>VA-008A, B, C</b>	<b>Tan VCT, approximately 110 sq ft</b>	<b>2% Chrysotile</b>
<b>B0522</b>	<b>VA-008AM, BM, CM</b>	<b>Mastic, approximately 110 sq ft</b>	<b>10% Chrysotile</b>
<b>B0525</b>	<b>VA-009A, B, C</b>	<b>Blue/green VCT , approximately 300 sq ft</b>	<b>2% Chrysotile</b>
<b>B0525</b>	<b>VA-009AM, BM, CM</b>	<b>Mastic, approximately 300 sq ft</b>	<b>10% Chrysotile</b>
B0525	VA-010A, B, C	1" x 1" brown/tan ceramic floor tile	None Detected
B0525	VA-011A, B, C	Composite wall system	None Detected
<b>See Below</b>	<b>NOT SAMPLED</b>	<b>Hard pipe fittings, approximately six (6)</b>	<b>Presumed to be asbestos containing</b>