

Correct Elevator Deficiencies

Project 564-16-104

RFI 001: Building 2 Service Elevator Number 1 (Manufacturer: Cetek Flex-H. Serial Number: 183799-1) and 2 (Manufacturer: Cetek Flex-H. Serial Number: 183799-2) existing floor buttons do not match the hospital floors. Are the buttons to be changed to the correct floors?

ANSWER: Yes, the Contractor shall correct the buttons and voice notification as follows:

	<u>Existing Button and voice notification</u>	<u>New Button and voice notification</u>
1 st Floor	G (Ground)	1 (Floor One)
Loading Dock	No Change	No Change
2 nd Floor	1 (Floor One)	2 (Floor Two)
3 rd Floor	2 (Floor Two)	3 (Floor Three)

RFI002: Building 2 Service Elevator Number 2 (Manufacturer: Cetek Flex-H. Serial Number: 183799-2), shall the Contractor be required to correct deficiencies?

ANSWER: Yes, the Contractor shall install cartop hand rail system per Part 2.14.1.7.4.