



20" chilled water lines.
Leak caused by a wood 2x4 support that was left under the chilled water line during construction.