

**REQUEST FOR INFORMATION (RFI)
VA250-16-B-0589**

PROJECT NUMBER:	553-304	Please ensure that before submitting questions or requests for clarification that you thoroughly read the solicitation, specifications, drawings and other pertinent documents. When submitting questions on this project the Government requires contractors to specifically identify the specification and/or solicitation section(s) or drawing number(s) in reference to the question or request for clarification submitted. No question or request for clarification will be answered by the Government unless the above requirements are met. Failure to comply may prevent the Government from responding in a timely manner.	
PROJECT TITLE:	Renovate South Lobby		
PROJECT LOCATION:	Department of Veterans Affairs John D. Dingell, VA Medical Center 4646 John R. Street Detroit, MI 48201-1916		
SUBMITTED BY:	Antler	City/State:	Canton, MI
PHONE NO.:	734-404-6459		

TO:

Kyle Lipper, Contracting Officer
Department of Veterans Affairs
Attn: 90 CSC
24 Frank Lloyd Wright Dr.
Lobby M, Suite M2200
Ann Arbor, MI 48105
Kyle.lipper@va.gov

RFI NO.:2	DATE:11/18/2016	SPEC/DWG. REFERENCE:
REPLY NEEDED BY:		

INFORMATION NEEDED:

What is the bottom panel of the curtainwall made of? I had a question from a contractor about it, and I am unable to find any information on it in the plans or specs.

REPLY:

The bottom glazing is called out on Sheet A600. The bottom rail is a combination of two framing members with bent aluminum trim (to match framing)and mineral fiber insulation.

REPLY FROM: Gregg Jones, C2AE	DATE: November 30, 2016
ATTACHMENTS:	COPY TO: