

**REQUEST FOR INFORMATION (RFI)**  
**VA250-17-B-0049**

PROJECT NUMBER:	655-13-113	<b>Please ensure that before submitting questions or requests for clarification that you thoroughly read the solicitation, specifications, drawings and other pertinent documents. When submitting questions on this project the Government requires contractors to specifically identify the specification and/or solicitation section(s) or drawing number(s) in reference to the question or request for clarification submitted. No question or request for clarification will be answered by the Government unless the above requirements are met. Failure to comply may prevent the Government from responding in a timely manner.</b>	
PROJECT TITLE:	Nurse Call System		
PROJECT LOCATION:	Department of Veterans Affairs Aleda E. Lutz Medical Center 1500 Weiss Street Saginaw, MI 48602		
SUBMITTED BY:	Robbert Construction	City/State:	Lakeview, Michigan
PHONE NO.:	989-287-7612		

**TO:**

Kyle Lipper, Contracting Officer  
Department of Veterans Affairs  
Attn: 90 CSC  
24 Frank Lloyd Wright Dr.  
Lobby M, Suite M2200  
Ann Arbor, MI 48105  
[Kyle.lipper@va.gov](mailto:Kyle.lipper@va.gov)

<b>RFI NO.: 015</b>	<b>DATE: 01/10/17</b>	<b>SPEC/DWG. REFERENCE:</b>
<b>REPLY NEEDED BY:</b>		

**INFORMATION NEEDED:**

Confirm ⑦ represents

- 351300 Touch Screen Staff Terminal
- Confirm location - inside room or outside in corridor.
- Manufacturer requirement for Vista EMR All-Touch integration requires one-to-one ratio of 351300 Touch Screen Staff Terminal to patient beds. Would you want us to meet the manufacturer requirement?

**REVIEWED**

**By Tom Belongia at 4:40 pm, Jan 13, 2017**

**REPLY:**

- Confirmed, that symbol represents the staff terminal station.
- In building 22, they are expected to be installed outside the room. This decision was made based on the ability to rough-in the necessary boxes and conduits with existing conditions (framing, other devices, etc.)
- That is news to us. If one staff terminal cannot support dual occupancy that is unfortunate, but having a second staff terminal appears to be the only option. Please proceed with providing two for double-occupancy rooms.

REPLY FROM: Phillip Nicholson	DATE: 2017.01.12
ATTACHMENTS:	COPY TO: