

Questions:

Building #9

1. Please clarify if ALL existing EPDM roofs (4 areas shown on drawings) are replaced with new ballasted .045 white EPDM.
2. Please clarify if new EPDM roof system includes tapered iso insulation, or if existing deck contains sufficient slope for drainage.
3. Please clarify if work scope includes new hanging copper gutters and downspouts with new brackets around entire perimeter of sloped roofs.
4. Please clarify if all EPDM roof ventilators replace with new ventilators.
5. Please clarify if existing roof hatch is to remain or replaces with new.
6. Please confirm that existing shingles remain and are NIC.

Building #35

1. Please clarify if the work scope for Building 35 is limited to the "Building 35 Construction Notes" in the middle of sheet 2012-1.5, or if ALL notes on the entire sheet apply to the intended work scope on Building 35.

Answers:

Work at each building is listed in 'Construction Notes' for that particular building.

From information that is available, Building 9 low-sloped flat roof decks are sloped.

Tapered insulation will be necessary to provide proper drainage to roof drains, around vents, etc.