

Explanation:

- GD04 Room Numbers
- Asbestos-containing duct sealant
- Asbestos-containing Pipe Support Insulation
- Asbestos-containing Pipe and Fitting Insulation Above Hard Ceiling
- Asbestos-containing Pipe Insulation
- Asbestos-containing Wall Mastic
- xx Number of Asbestos-containing Pipe Fittings in The Area
- Asbestos-containing Floor Tile and/or Mastic
- Asbestos-containing Floor Mastic (Under Carpet or Non-ACM Floor Tile)
- Asbestos-containing Ceramic Tile (Assumed)
- ⊕ Asbestos-containing Friable Pipe Fitting and Lagging Insulation Embedded in Wall

Note : The interior surface of all exterior brick work is coated with an asbestos-containing black tar vapor barrier.

Ceramic Tile Walls only

