



←
NORTH

PHASING PLAN - OPTION
10-14-16 NMR

PHASING SCHEDULE

PHASE 1	PHASE 7	DENOTES PHASE BY COLOR AREA TO BE WORKED ON 2 CONSECUTIVE SHIFTS. NORMAL AND 2ND SHIFT. Note: Number sequence may change for patient care needs.
PHASE 2	PHASE 8	
PHASE 3	PHASE 9	
PHASE 4	PHASE 10	
PHASE 5	PHASE 11	
PHASE 6	PHASE 12	
	PHASE 13	

EXHIBIT A 10-20-16
Revised 10-28-16 NMR