

Attachment B

Changes to Improved Security Access Control & Monitoring System JLM

This is about the Improved Security Access Control/Monitoring System for JLM. On the last page of the prints page TY502. Please review the changes below when making your bid for this contract.

Site Plan column indicates 44 Sony SNC-EM632RC's. New total for the Site Plan should be 12 Sony SNC-EM632RC's.

Site Plan column indicates 32 Sony SNC-EB632R's. New total for the Site Plan should be 64 Sony SNC-EB632R's.

Second Floor column indicates 26 Sony SNC-XM631's. New total for the Second Floor should be 24 Sony SNC-XM631's.

Parking Garage column indicates 32 Sony SNC-XM631's. New total for the Parking Garage should be 0 Sony SNC-XM631's.

Parking Garage column indicates 0 Sony SNC-EM632RC's. New total for the Parking Garage should be 32 Sony SNC-EM632RC's.

Quantity in Building column totals needs changing in 3 rows. Sony SNC-XM631's from 205 to 171. Sony SNC-EB632R's from 34 to 66. Total proposed camera count from 302 to 300.

Important Bidding Note: when bidding on the access control portion for this contract each bid needs to be based on the access control chart located on sheet TY502. The different floor plans DO NOT show the specific locations of where access control is required.