

Monday Jan
3:03 PM

Main gate Traffic Arms

11 total arms

MFG: Magnetic Automation

Model: Access PRO-L-RC02040

- **Condition Found:** All Arms working without fault codes. Minor adjustment and parts need replaced. (see Below)
- **Condition Found:** Locks hard to operate due to weatherization
- **Action:** Lubricate all locks and service access bolts
- **Condition Found:** Wasps living in several Traffic Arms
- **Action:** Clear insects with non-damaging spray.
- **Condition Found:** NE Traffic Arm mount is loose and arm is twisted (Figure 2)
- **Action:** Adjust Traffic Arm housing so it is square with remaining arms and tighten Bolts. Replace bolts with new anchor bolts if necessary.
- **Condition Found:** Arm mount damaged near bracket heel
- **Action:** Replace with Microdrive VarioBoom Section With Hardware (See Figure 1)

Damaged Boom Mount



Figure 1 Damaged Arm Mounting bracket (VerioBoom)



Figure 2 Housing loose and twisted