

Monday Jan
3:03 PM

Service Entrance Traffic Arms

3 total arms

MFG: Magnetic Automation

Model: Access PRO-L-RC02040

- **Condition Found:** Lanes 1 and 2 are working without fault codes. Lane 3 Missing entire Boom assembly
- Lane 3 Traffic Arm seems to be fine other than the missing arm S/N U20033978
- **Condition Found:** Locks hard to operate due to weatherization
- **Action:** Lubricate all locks and service access bolts
- **Condition Found:** Wasps living in Traffic Arms
- **Action:** Clear insects with non-damaging spray.
- **Condition Found:** Lane 3 Traffic Arm mount and arm missing
- **Action:** Replace with Microdrive VarioBoom Section, Breakaway kit and 11' arm (See Figure 1)



Figure 1 Missing 11' arm and mount