

REQUEST FOR INFORMATION/GOVERNMENT'S RESPONSE

ATTACHMENT E

**RFQ No. 36C24818Q0631
Gate Repair Lake Baldwin**

No.	REFERENCE (PWS, SOW, CLIN Structure, etc.)	COMMENT(s)/QUESTION(s)	GOVERNMENT'S RESPONSE
1	PWS, II. a.	Can the VA please provide the exact model number desired for the Pelco External IP PTZ Domes Referenced in the Solicitation?	Pelco P1220-ESRO
2	PWS, II. b.	Can the VA please provide the exact model number for the POE line extender with the Manufacturer desired in the solicitation?	Enable IT824WP
3	PWS, II. c.	Can the VA please provide the exact model number of the Altronix AC Power supply to be used for this solicitation?	T1250C
4	PWS, II. d.	Can the VA please provide the exact model number for the Altronix DC power supply to be used for this solicitation?	AL600XPD8220
5	PWS, II. e.	Can the VA please provide the exact model number for the Gate Release button desired?	CX-30EE
6	PWS, II. f.	Can the VA please provide the model number for the HID FIPS Card Reader as indicated in solicitation?	RP40
7	PWS, II. g.	Can the VA please provide the Model number or spec on the Securitron Gate Maglock?	M62FG-SASM
8	General Question	Can the VA determine if the current gates in place are functioning and operable?	The VA cannot determine if the current gates in place are functioning without connecting to a power source.
9	General Question	Can the VA determine the cause of failure of current system and the extent within the system?	Yes, the entire system was struck by lightning and this resulted in a short circuit to the entire system.
10	General Question	Has troubleshooting been done to the electrical system as well as the communication system from the gates to the source?	Yes
11	General Question	How long ago where the gates or system damaged?	Last year during Hurricane IRMA
12	PWS II. a.	Can you clarify by a site survey where the exact gates and camera domes are located?	Yes, see attached as built drawings.

REQUEST FOR INFORMATION/GOVERNMENT'S RESPONSE

ATTACHMENT E

RFQ No. 36C24818Q0631

Gate Repair Lake Baldwin

13	PWS II. h.	Can you provide a site drawing with as built containing conduit, power, and communication cables back to the original source and desired landing?	Yes, see attached as built drawings.
14	General Question	Can the VA provide the approximate footage on a print or site survey since there were no accurate specs on the solicitation/PWS?	Yes, see attached as built drawings.
15	General Question	How many gates are requiring power/COMM?	All three gates are controlled from the main controller which were damaged by lightning.
16	General Question	Is there a spec'd COMM cable to be used at the VA or special rated per engineer requests as with other VA locations?	All direct burial cables, CAT5, 18-2 and 22-4 with shield.
17	General Question	Is there a power protection system in place or is there one desired to protect the gates operating system in the future?	Yes, there were power protection system in place, surge protection and ground rods, however the power protection system was destroyed during Hurricane IRMA. The VA is expecting brand name or equal power protection system.
18	General Request	Since the POC was not present for the site visit, is it possible to schedule another one for 5/14-5/16 early AM?	Site visit is re-scheduled for Monday May 21, 2018 at 10:00 AM. Please submit Request for Information (RFI) by utilizing ATTACHMENT C, no later than 1:00 PM May 23, 2018 to rohan.mckenzie@va.gov .