

**RFP 36E77618R0077 SIOUX FALLS REPAIR EXTERIOR DEFICIENCIES D\_B TECHNICAL QUESTIONS AND VA RESPONSE TRACKING SHEET**

ITEM NO.	DATE QUESTION RECEIVED	DATE QUESTION ANSWERED	QUESTION	GOVERNMENT RESPONSE
1.	6.19.18		Tasks 6-10 do not appear to correspond with written descriptions. Task 10 does not appear on key map. Please clarify.	
2.	6.19.18		Assume that the VA will provide the legal description/title work to aid the completion of the boundary survey. Please confirm	
3.	6.19.18	7/3/2018	Assume that the VA will provide existing utility mapping of the campus. Please confirm.	The following documents are included in Amendment 0001: Topo (Phase 1- 3) 3d Areas 1-4 (1) Topo (Phase 1- 3) 3d
4.	6.21.18		In the solicitation documents, SOW Attachment #2, page 2, Task 10 Add Sidewalk, there is a reference to “sidewalk with retaining....” Please clarify/confirm the location of Task 10 in the SOW Site Drawings document also provided as part of the solicitation documents.	
5.				
6.				
7.				
8.				
9.				
10.				
11.				
12.				
13.				
14.				

<b>ITEM NO.</b>	<b>DATE QUESTION RECEIVED</b>	<b>DATE QUESTION ANSWERED</b>	<b>QUESTION</b>	<b>GOVERNMENT RESPONSE</b>
15.				
16.				
17.				
18.				
19.				
20.				
21.				
22.				

23.				
-----	--	--	--	--

