



NOTES:

Approved:

Overseeing Title

BUILDING 25
MENTAL HEALTH
SECOND FLOOR (B-WING)

COMPLETION ITEMS
ACUTE PSYCH UNIT

PROGRAM MANAGER, PROJECTS
SAFETY/INDUSTRIAL HYGIENE
HEALTH SYSTEM SPECIALIST
MAINTENANCE SUPERVISOR
MAINTENANCE FOREMAN

Approved: Service Director

Building Number
B25

Project No.
520-13-122

Checked
Drawn


Location
VAMC BLOOM, MS

DATE
12/12/12

Project No.
520-13-122

25-AR2

Page 1 of 1



Department of Veterans Affairs

EXISTING DOOR SCHEDULE														From Room: Name		To Room: Name	
DOOR NO.	DOOR WIDTH	DOOR HEIGHT	HOME TYPE	TYPE	MAT'L	FIN.	TYPE	MAT'L	FIN.	FRAME HEAD	JAMB	HOUR	Label				
2B100	3'-0"	7'-0"	W004	A	W00	SE-1	B	HM	P-2	118	11A	20 mm	LABORATORY				
2B101	3'-0"	7'-0"	W005	A	W00	P-2	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B102	3'-0"	7'-0"	W006	A	W00	P-2	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B103	3'-0"	7'-0"	W007	A	W00	P-2	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B104	3'-0"	7'-0"	W008	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B105	3'-0"	7'-0"	W009	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B106	3'-0"	7'-0"	W010	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B107	3'-0"	7'-0"	W011	A	W00	P-2	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B108	3'-0"	7'-0"	W012	A	W00	P-2	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B109	3'-0"	7'-0"	W013	A	W00	P-2	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B110	3'-0"	7'-0"	W014	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B111	3'-0"	7'-0"	W015	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B112	3'-0"	7'-0"	W016	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B113	3'-0"	7'-0"	W017	A	W00	P-2	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B114	3'-0"	7'-0"	W018	A	W00	P-2	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B115	3'-0"	7'-0"	W019	A	W00	P-2	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B116	3'-0"	7'-0"	W020	A	W00	P-2	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B117	3'-0"	7'-0"	W021	A	W00	P-2	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B118	3'-0"	7'-0"	W022	A	W00	P-2	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B119	3'-0"	7'-0"	W023	A	W00	P-2	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B120	3'-0"	7'-0"	W024	A	W00	P-2	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B121	3'-0"	7'-0"	W025	A	W00	P-2	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B122	3'-0"	7'-0"	W026	A	W00	P-2	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B123	3'-0"	7'-0"	W027	A	W00	P-2	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B124	3'-0"	7'-0"	W028	A	W00	P-2	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B125	3'-0"	7'-0"	W029	A	W00	P-2	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B126	3'-0"	7'-0"	W030	A	W00	P-2	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B127	3'-0"	7'-0"	W031	A	W00	P-2	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B128	3'-0"	7'-0"	W032	A	W00	P-2	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B129	3'-0"	7'-0"	W033	A	W00	P-2	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B130	3'-0"	7'-0"	W034	A	W00	P-2	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B131	3'-0"	7'-0"	W035	A	W00	P-2	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B132	3'-0"	7'-0"	W036	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B133	3'-0"	7'-0"	W037	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B134	3'-0"	7'-0"	W038	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B135	3'-0"	7'-0"	W039	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B136	3'-0"	7'-0"	W040	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B137	3'-0"	7'-0"	W041	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B138	3'-0"	7'-0"	W042	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B139	3'-0"	7'-0"	W043	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B140	3'-0"	7'-0"	W044	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B141	3'-0"	7'-0"	W045	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B142	3'-0"	7'-0"	W046	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B143	3'-0"	7'-0"	W047	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B144	3'-0"	7'-0"	W048	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B145	3'-0"	7'-0"	W049	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B146	3'-0"	7'-0"	W050	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B147	3'-0"	7'-0"	W051	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B148	3'-0"	7'-0"	W052	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B149	3'-0"	7'-0"	W053	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B150	3'-0"	7'-0"	W054	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B151	3'-0"	7'-0"	W055	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B152	3'-0"	7'-0"	W056	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B153	3'-0"	7'-0"	W057	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B154	3'-0"	7'-0"	W058	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B155	3'-0"	7'-0"	W059	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B156	3'-0"	7'-0"	W060	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B157	3'-0"	7'-0"	W061	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B158	3'-0"	7'-0"	W062	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B159	3'-0"	7'-0"	W063	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B160	3'-0"	7'-0"	W064	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B161	3'-0"	7'-0"	W065	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B162	3'-0"	7'-0"	W066	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B163	3'-0"	7'-0"	W067	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B164	3'-0"	7'-0"	W068	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B165	3'-0"	7'-0"	W069	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B166	3'-0"	7'-0"	W070	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B167	3'-0"	7'-0"	W071	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B168	3'-0"	7'-0"	W072	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B169	3'-0"	7'-0"	W073	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B170	3'-0"	7'-0"	W074	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B171	3'-0"	7'-0"	W075	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B172	3'-0"	7'-0"	W076	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B173	3'-0"	7'-0"	W077	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B174	3'-0"	7'-0"	W078	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B175	3'-0"	7'-0"	W079	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B176	3'-0"	7'-0"	W080	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B177	3'-0"	7'-0"	W081	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B178	3'-0"	7'-0"	W082	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B179	3'-0"	7'-0"	W083	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B180	3'-0"	7'-0"	W084	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B181	3'-0"	7'-0"	W085	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B182	3'-0"	7'-0"	W086	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B183	3'-0"	7'-0"	W087	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B184	3'-0"	7'-0"	W088	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B185	3'-0"	7'-0"	W089	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B186	3'-0"	7'-0"	W090	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B187	3'-0"	7'-0"	W091	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B188	3'-0"	7'-0"	W092	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B189	3'-0"	7'-0"	W093	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B190	3'-0"	7'-0"	W094	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B191	3'-0"	7'-0"	W095	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B192	3'-0"	7'-0"	W096	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B193	3'-0"	7'-0"	W097	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B194	3'-0"	7'-0"	W098	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B195	3'-0"	7'-0"	W099	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B196	3'-0"	7'-0"	W100	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B197	3'-0"	7'-0"	W101	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B198	3'-0"	7'-0"	W102	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B199	3'-0"	7'-0"	W103	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B200	3'-0"	7'-0"	W104	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B201	3'-0"	7'-0"	W105	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B202	3'-0"	7'-0"	W106	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B203	3'-0"	7'-0"	W107	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B204	3'-0"	7'-0"	W108	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B205	3'-0"	7'-0"	W109	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B206	3'-0"	7'-0"	W110	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B207	3'-0"	7'-0"	W111	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B208	3'-0"	7'-0"	W112	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B209	3'-0"	7'-0"	W113	A	W00	SE-1	B	HM	P-2	118	11A	45 NMN	LABORATORY				
2B210	3'-0"	7'-0"	W114	A	W00	SE-1											