

1. Tan paint on plaster exterior walls on front (south) porch	22. White paint on interior wood window sashes on 2FL windows
2. Tan paint on exterior plaster/concrete columns on front (south) porch	23. White paint on interior wood window sills on 2FL windows
3. Grey paint on exterior wood window casings on front (south) porch	24. White paint on interior wood window aprons on 2FL windows
4. Grey paint on exterior plaster/concrete window aprons on front (south) porch	25. White paint on interior wood window casings on 2FL windows
5. Grey paint on exterior wood window sills on front (south) porch	26. White paint on interior wood window stops/troughs/guides on 2FL windows
6. Grey paint on exterior wood window stops/troughs/guides on front (south) porch	27. Brown paint on wood window sash in 2FL bathroom
7. Grey paint on exterior wood window sashes on front (south) porch	28. Brown paint on wood window sill in 2FL bathroom
8. Grey paint on exterior wood window sashes on rear (north) porch	29. Brown paint on wood window casing in 2FL bathroom
9. Grey paint on exterior wood window stops/troughs/guides on rear (north) porch	30. White paint on plaster chimney walls in 1FL living room
10. Grey paint on exterior wood window sills on rear (north) porch	31. White paint on interior wood window sashes on 1FL windows
11. Grey paint on exterior wood window casings on rear (north) porch	32. White paint on interior wood window sills on 1FL windows
12. Grey paint on exterior wood door and framing at northeast basement entrance	33. White paint on interior wood window aprons on 1FL windows
13. Grey paint on exterior wood window casings on basement windows	34. White paint on interior wood window sashes on 1FL windows
14. Grey paint on exterior wood window sills on basement windows	35. White paint on interior wood window stops/troughs/guides on 1FL windows
15. Grey paint on exterior wood window sashes on basement windows	36. White paint on interior wood window casings on 1FL rear porch (north)
16. Grey paint on exterior wood window sills on 2FL windows	37. White paint on interior wood window sills on 1FL rear porch (north)
17. Grey paint on exterior wood window sashes on 2FL windows	38. White paint on interior wood window sashes on 1FL rear porch (north)
18. Grey paint on exterior wood window stops/troughs/guides on 2FL windows	39. White paint on interior plaster walls on 1FL rear porch (north)
19. Cream paint on transite shingles on 2FL exterior siding	40. White paint on interior wood basement stairwell steps
20. Grey paint on exterior wood crown molding between 1FL and 2FL elevations	41. White paint on interior plaster walls in basement stairwell
21. Grey paint on wood front door (south)	42. White paint on interior wood door and casing in basement

- A. Stabilize LBP Matrix and Encapsulate
- B. Total Removal and Disposal of Component
- C. Chemically Strip LBP From Substrate
- D. Component To Be Remediated Off Site by Others
- E. No Remediation Necessary


CONSULTANTS:	
1139 Olive Street, Ste. 300 - Saint Louis, MO 63101	
ph 314-436-9492 - fx 314-436-9733	
RiverfrontEnvironmental.com	
A Service Disabled Veteran Owned Small Business	

ARCHITECT/ENGINEERS:

FOURFRONT
DESIGN INC.

517 7th street
rapid city sd 57701
p 605.342.9470
f 605.342.2377
www.4front.biz

Project Title		
NASHVILLE NATIONAL CEMETERY ADMIN DEMOLITION AND FACILITY UPGRADES		
Location		
MADISON, TENNESEE		
Date	Checked	Drawn
7/20/2015	DJ	BW

		<h1>BID DOCUMENTS</h1>	
Project Number 865CM3029	NCA DESIGN AND CONSTRUCTION SERVICE		
Building Number			
Drawing Number IH-1			
Dwg. 89 of 90	 Department of Veterans Affairs		

